

卓亚水喷漆公司 TOH AH SWEE SPRAY PAINTING CO.

BLK 2, KRANJI LOOP #01-02 (OFF KRANJI ROAD), SINGAPORE 739538.

TEL: 63660115 (WORKSHOP), 63660286 (OFFICE) FAX: 63685943

EMAIL: claims@tohahswee.com.sg

BUSINESS REG. NO: 09935300L

GST REG. NO: 09-935300-L

25/01/2018

AIG ASIA PACIFIC INSURANCE PTE LTD

AIG BUILDING

78 SHENTON WAY #07-16

SINGAPORE 079120

ATTN : MOTOR CLAIMS DEPT.

Sebastian.
2 days.
- Lump Sum Repair
- Question mark
Item Photo
- Photo After Paint
90036121

ESTIMATED REPAIR BILL

YOUR REF : SGX4884E Sebastianyeang @
TYPE OF CLAIM : THIRD PARTY CLAIM lkkauto.com
CLAIMANT : CHAN LOY TUCK
VEHICLE NO. : SGQ7173R
MAKE/ MODEL : TOYOTA HARRIER
ACCIDENT DATE : 24/01/2018

Lkn' Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MATERIAL COST

1PC	FRONT BUMPER ✓ cut	\$	1,523.00
1PC	FRONT BUMPER SIDE BRACKET LH ?	\$	215.00
1PC	FRONT BUMPER LOWER LID LH ✓ cut	\$	468.00
		\$	2,206.00
	LESS : DISCOUNT 25%	\$	(551.50)
		\$	1,654.50

LABOUR CHARGE

TO REMOVE DAMAGED PARTS, TO KNOCK OUT DENTS, TO STRAIGHTEN, ADJUST, CHECK, RESHAPE INCLUDING CUTTING AND WELDING WHERE NECESSARY, TO REMOVE AND REINSTALL NECESSARY FITTINGS TO FACILITATE REPAIRS, TO REPLACE AND ALIGN THE ABOVE PARTS.

PUTTY AND SPRAY PAINTING ON ABOVE NEW AND REPAIRED PARTS INCLUDING SUPPLY OF PAINT MATERIALS

ADD : GST 7%

TOTAL :

	300	\$	600.00
	400	\$	750.00
		\$	3,004.50
		\$	210.32
		\$	3,214.82

SINGAPORE DOLLARS : THREE THOUSAND TWO HUNDRED FOURTEEN AND CENTS EIGHTY TWO ONLY

NOTE: THE ESTIMATED PERIOD OF REPAIRS IS FOUR (4) DAYS

TOH AH SWEE SPRAY PAINTING CO.

Hweekem (TEL : 63660286)