

ASS. REC. BY:

REF: CS/ASM18001618 / Ktb

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

Smart claim

From (Person):

Kitty Teo

of

ASM

Date/Time: 26/01/2018 1:45pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDR 280R

Insured:

at Workshop m/s

Ah Lim motor

Tel:

6456 3637

of

Blk 176 Sin ming Drive #05-12

Policy No:

Claim No:

S8M00790

Sum Insured:

Excess:

\$2900.00

Make of Veh:

D.O.A.

24/01/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 26/01/2018 2:08pm

Person Contacted:

Jane

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SDR 280R - CS/INC12011706/Kbn
29/1-	Revert preli advise.
	Part by Part \$7905/- (Red: 30/11/27%)

SA: 230472



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/ASM18001618/Ktb

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 26-01-2018



Code : ASM

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SDR 280R
Policy No.	Coverage (\$)	0.00
Claim No. S8M007SO	Excess (\$)	2,900.00
Assign From SMART CLAIM (KITTY TEO)	Assign Date	26/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date 24/01/2018	Inspection Date 26/01/2018
Survey held at AH LIM MOTOR COMPANY 176 SIN MING DRIVE #05-12 SIN MING AUTOCARE SINGAPORE 575721	

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--



Service Request Details

Claim

S8M007SO

Reference

None 

Loss Date

January 24, 2018

Request Date

January 26, 2018

Due Date

February 2, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SDR280R

Make

AUDI

Service Address

176 Sin Ming Drive #05-12, , , 575721

Primary Contact/Insured

KWOK WING CHEONG
134 KING'S ROAD, 268168, Singapore, Singapore

cheongkw1@yahoo.com.sg

Claim Handler

Kitty TEO
6568804602
kitty.teo@axa.com.sg

Additional Instructions

EXCESS \$400 + \$2500(UNNAMED YOUNG) = \$2900

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/01/2018 14:06
Date Of Accident	24/01/2018 20:10
Exact Location Of Accident	CLEMENTI AVE 6
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDR280R
Insured/Policyholder	
Name Of Registered Owner	CHEONG KWOK WING
NRIC No	S1744542A
Email Address	CHEONGKW1@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-96388845
Alternative Phone No	OTHERS-NOPHONE

Vehicle Particulars

Manufacturer	AUDI
Model	A6-2.0 TFSI MU S-LINE (C6) (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA124211
Cover Note Number	

Driver

Name of Driver	CHEONG NING
NRIC No	S9713278Z
Date Of Birth	19/04/1997
Occupation	INDOOR
Date Of Driving Pass	09/12/2017
Driving Experience	0 YEAR AND 1 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-92969631
Fax Number	
Contact Number	
Email Address	CHEONGNINGG@GMAIL.COM

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

 25 JAN 2018
12pm.
Policyholder's Signature
Date & Time:

 12pm
25/01/2018
Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4542A
Vehicle Details	
Vehicle No.:	SDR280R
Vehicle to be Exported:	No
Intended De-registration Date:	29 Jan 2018
Vehicle Make:	AUDI
Vehicle Model:	A6 2.0L TFSI MU S-LINE CVT TC D/AB HID
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	BPJ159376
Chassis No.:	WAUZZZ4F8AN010776
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$45,477.00
Original Registration Date:	18 Sep 2009
First Registration Date:	18 Sep 2009
Transfer Count:	3
Actual ARF Paid:	\$45,477.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Sep 2019
PARF Rebate Amount:	\$25,012.00
Intended COE Rebate Details	
COE Expiry Date:	17 Sep 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$17,905.00
COE Rebate Amount:	\$2,664.00
Total Rebate Amount:	\$27,676.00

The information contained herein is correct as at 29 Jan 2018

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 4542A

Vehicle Details

Vehicle No.: SDR280R

Vehicle to be Exported: No

Intended De-registration Date: 26 Jan 2018

Vehicle Make: AUDI

Vehicle Model: A6 2.0L TFSI MU S-LINE CVT TC D/AB HID

Primary Colour: Black

Manufacturing Year: 2009

Engine No.: BPJ159376

Chassis No.: WAUZZZ4F8AN010776

Maximum Power Output: 125.0 kW (167 bhp)

Open Market Value: \$45,477.00

Original Registration Date: 18 Sep 2009

First Registration Date: 18 Sep 2009

Transfer Count: 3

Actual ARF Paid: \$45,477.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 17 Sep 2019

PARF Rebate Amount: \$25,012.00

Intended COE Rebate Details

COE Expiry Date: 17 Sep 2019

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$17,905.00

COE Rebate Amount: \$2,678.00

Total Rebate Amount: \$27,690.00

The information contained herein is correct as at 25 Jan 2018

OK



redefining / insurance

AXA Insurance Pte Ltd
☎ 1800 880 4888 (Within Singapore)
(65) 6880 4888 (International)
☎ (65) 6880 4740
✉ customer.care@axa.com.sg
🌐 www.axa.com.sg

Certificate of Insurance

account number
05579

-Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) - Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 - Road Transport Act, 1987 (Malaysia)
-Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Policy details

Policyholder name	CHEONG KWOK WING	Certificate number	GA124211 / 1
Cover	Comprehensive	Chassis number	WAUZZZ4FBAN010776
Plan name	Essential	Engine number	BPJ159376
NCD applicable	50%		
Vehicle registration number	SDR280R		
Period of Insurance	from 18/09/2017 to 17/09/2018 (both dates inclusive)		
Finance loan company	Nil		

Persons or classes of persons entitled to drive*

- (a) The Policyholder
- (b) Any Named Driver as stated in the Policy:
 - 1. NG YIN
- (c) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS	Basic Own Damage Excess	SGD 400.00
	Windscreen Excess	SGD 100.00

An Additional Excess is applicable as follows:

1. S\$500 for unnamed *Authorised Driver*
2. S\$500 for declared *Young and Inexperienced Driver*
3. S\$5,000 for undeclared *Young and Inexperienced Drivers*. This additional excess is reduced to S\$2,500 if You have chosen AXA Premium Workshops.

Additional clauses & endorsements to your policy

Nil

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

Authorised signature

Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation Act (Cap. 189).

The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, endorsement etc.

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S9713278Z



Name

CHEONG NING

张 宁

Race

CHINESE

Date of birth

19-04-1997

Sex

F

S9713278Z

Country of birth

SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S9713278Z

Name:

CHEONG NING

Birth Date: 19 Apr 1997

Issue Date: 09 Dec 2017



S9713278Z

NRIC No. S9713278Z



Date of issue

20-06-2012

Address

134 KING'S ROAD
SINGAPORE 268168

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3A Motor cars without clutch pedals (Auto) with unladen weight $\leq$ 3000kg with $\leq$ 7 passengers, exclusive of driver; and other motor vehicles without clutch pedals with unladen weight $\leq$ 2500kg 09 Dec 2017

NP 428A





AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721

TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg

GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : AXA INSURANCE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Estimate No: MCS1102267

Date: 26 Jan 2018

Policy No: GA124211

Veh Reg No: SDR280R

Make/Model: AUDI A6 2.0L TFSI MU S-LINE

Your Ref No: SDR280R

Claim Type: Own Damage

Accident Date: 24/01/2018

Authorised

Repair B4 paint

6 days

Ex 82900/-

FM
187

Estimate Repair Cost to Vehicle No :SDR280R

Est: 625643.5

Description	U/Price	Quantity	Cost	Amount
			SS	SS
SPARE PARTS				
1 FRONT BONNET		1 PC	1,400.00	✓
2 FRONT BONNET INSULATOR CLIP		17 PC	51.00	✓
3 FRONT BUMPER		1 PC	950.00	✓
4 FRONT BUMPER SIDE RETAINER LH		1 PC	20.00	X
5 FRONT BUMPER SIDE RETAINER RH		1 PC	20.00	✓
6 FRONT BUMPER CENTER RETAINER LH		1 PC	15.00	?
7 FRONT BUMPER CENTER RETAINER RH	SVC	1 PC	15.00	✓
8 FRONT BUMPER REINFORCEMENT		1 PC	300.00	✓
9 FRONT BUMPER CENTER LOWER GARNISH		1 PC	145.00	✓
10 FRONT BUMPER CENTER LOWER GRILLE - CEHCK PRICE	SVC	1 PC	0.0000	✓
11 FOGLAMP COVER RH		1 PC	80.00	?
12 TOWING COVER		1 PC	24.00	✓
13 HEADLAMP LH		1 PC	1,100.00	?
14 HEADLAMP RH	mf. m	1 PC	1,100.00	✓
15 HEADLAMP LOWER BRACKET RH		1 PC	40.00	?
16 RADIATOR GRILLE		1 PC	220.00	✓
17 RADIATOR GRILLE BASE		1 PC	60.00	✓
18 RADIATOR SUPPORT PANEL		1 PC	360.00	✓
19 RADIATOR	CRA	1 PC	380.00	?
20 RADIATOR TOPBUSH		2 PC	12.00	?
21 RADIATOR TOP CLIP	4	2 PC	8.00	?
22 RADIATOR FAN COWLING		1 PC	230.00	✓
23 RADIATOR FAN MOTOR		1 PC	360.00	?
24 AIR CON CONDENSER		1 PC	400.00	✓
25 AIR CON CONDENSER FAN MOTOR		1 PC	320.00	?
26 TURBO COOLER		1 PC	300.00	?
27 RADIATOR SUPPORT PANEL TOP COVER		1 PC	50.00	✓
28 AIR INTAKE DUCT OUTER		1 PC	20.00	✓
29 AIR INTAKE DUCT		1 PC	60.00	✓
30 HORN BRACKET (CENTER)		1 PC	40.00	?
31 NO PLATE GARNISH	SVC	1 PC	60.00	✓
32 FRONT FENDER RH		1 PC	480.00	X

8,620.00

Special Nett

33 RADIATOR COOLANT

34 NUMBER PLATE - FRONT

1 PC 35.00

1 PC 35.00

205m



AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721

TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg

GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Estimate No: MCS1102267

Date: 26 Jan 2018

Policy No: GA124211

Veh Reg No: SDR280R

Make/Model: AUDI A6 2.0L TFSI MU
S-LINE

Your Ref No: SDR280R

Claim Type: Own Damage

Accident Date: 24/01/2018

Estimate Repair Cost to Vehicle No :SDR280R

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
				70.00
LABOUR				
35 TO CHECK WIRING AND REFOCUS HEADLAMP		1 PC	30.00	200
36 TO REMOVE AND REPLACE A/C CONDENSER, PIPES AND RADIATOR, VACUUM A/C SYSTEM AS WELL AS		1 EA	120.00	1000
37 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD FRONT SUPPORT PANEL & HEADLAMP PANEL. TO KNOCK & REPAIR FRONT INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	1,000.00	6000
38 TO SPRAY FRONT BONNET, FRONT BUMPER, FRONT FENDER LH & RH, FRONT DOOR RH, FRONT SUPPORT PANEL, BUMPER REINFORCEMENT AND EFFECTED AREAS		1 PC	1,000.00	6000
				2,150.00

Amount Before Excess SS 10,840.00

Add GST @ 7% 758.80

Total Amount payable SS 11,598.80

TOTAL: SINGAPORE DOLLAR ELEVEN THOUSAND FIVE HUNDRED NINETY EIGHT AND CENTS EIGHTY ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

10916

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation.
- Third party survey is on a "Without Prejudice" basis.
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

Need assessment later
in sus ID 27379
(net 27511)

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Claim No: MCS1102267

Ref No: MFS1102003

Date: 15 Mar 2018

Policy No: GA124211

Veh Reg No: SDR280R

Make/Model: AUDI A6 2.0L TFSI MU
S-LINE

Your Ref No: S8M007SO

Claim Type: Own Damage

Accident Date: 24/01/2018

Repair Cost to Vehicle No (For Finalization):SDR280R

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
SPARE PARTS				
1 FRONT BONNET		1 PC	1,400.00	
2 FRONT BONNET INSULATOR CLIP		17 PC	51.00	
3 FRONT BUMPER		1 PC	950.00	
4 FRONT BUMPER SIDE RETAINER RH		1 PC	20.00	
5 FRONT BUMPER REINFORCEMENT		1 PC	300.00	
6 FRONT BUMPER CENTER LOWER GARNISH		1 PC	145.00	
7 TOWING COVER		1 PC	24.00	
8 HEADLAMP RH		1 PC	1,100.00	
9 RADIATOR GRILLE		1 PC	220.00	
10 RADIATOR GRILLE BASE		1 PC	60.00	
11 RADIATOR SUPPORT PANEL		1 PC	360.00	
12 RADIATOR		1 PC	380.00	
13 RADIATOR TOP CLIP RH		1 PC	4.00	
14 RADIATOR FAN COWLING		1 PC	230.00	
15 RADIATOR FAN MOTOR		1 PC	360.00	
16 AIR CON CONDENSER		1 PC	400.00	
17 AIR CON CONDENSER FAN MOTOR		1 PC	320.00	
18 RADIATOR SUPPORT PANEL TOP COVER		1 PC	50.00	
19 AIR INTAKE DUCT OUTER		1 PC	20.00	
20 AIR INTAKE DUCT		1 PC	60.00	
21 RADIATOR AIR GUIDE RH		1 PC	20.00	
22 FRONT BUMPER HOLDER LH		1 PC	18.00	
23 FRONT BUMPER HOLDER RH		1 PC	18.00	
24 FRONT BUMPER REINFORCEMENT HOLDER BRACKET LH		1 PC	10.00	
25 FRONT BUMPER REINFORCEMENT HOLDER BRACKET RH		1 PC	10.00	
				6,530.00
Special Nett				
26 RADIATOR COOLANT		1 PC	20.00	
27 NUMBER PLATE - FRONT		1 PC	35.00	
				55.00
LABOUR				
28 TO CHECK WIRING AND REFOCUS HEADLAMP		1 PC	20.00	
29 TO REMOVE AND REPLACE A/C CONDENSER, PIPES AND RADIATOR, VACUUM A/C SYSTEM AS WELL AS		1 EA	100.00	



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimumo@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINANCIAL

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Claim No: MCS1102267

Ref No: MFS1102003

Date: 15 Mar 2018

Policy No: GA124211

Veh Reg No: SDR280R

Make/Model: AUDI A6 2.0L TFSI MU
S-LINE

Your Ref No: S8M007SO

Claim Type: Own Damage

Accident Date: 24/01/2018

Repair Cost to Vehicle No (For Finalization):SDR280R

Description	U/Price	Quantity	Cost	Amount
			S\$	S\$
30 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD FRONT SUPPORT PANEL & HEADLAMP PANEL. TO KNOCK & REPAIR FRONT INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	600.00	
31 TO SPRAY FRONT BONNET, FRONT BUMPER, FRONT FENDER LH & RH, FRONT DOOR RH, FRONT SUPPORT PANEL, BUMPER REINFORCEMENT AND EFFECTED AREAS		1 PC	600.00	
				1,320.00

Amount Before Excess	S\$ 7,905.00
Less Excess	S\$ 2,900.00
Amount Before GST	S\$ 5,005.00
Add GST @ 7%	350.35
Total Amount payable	S\$ 5,355.35

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND THREE HUNDRED FIFTY FIVE AND CENTS THIRTY FIVE ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 26/01/2018

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE



AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721
 TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S: AXA INSURANCE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811

TEL: 63387288
 ATTN: Motor Claim Department

FAX: 63382522

Estimate No: MCS1102267

Date: 26 Jan 2018

Policy No: GA124211

Veh Reg No: SDR280R

Make/Model: AUDI A6 2.0L TFSI MU
 S-LINE

Your Ref No: SDR280R
 Claim Type: Own Damage
 Accident Date: 24/01/2018

Authorised
Repair B4 paint 6 days
Ex 829006



Estimate Repair Cost to Vehicle No :SDR280R

Fax: 62564315

Description	U/Price	Quantity	Cost	Amount
			SS	SS
SPARE PARTS				
1 FRONT BONNET		1 PC	1,400.00	✓
2 FRONT BONNET INSULATOR CLIP		17 PC	51.00	✓
3 FRONT BUMPER		1 PC	950.00	✓
4 FRONT BUMPER SIDE RETAINER LH		1 PC	20.00	✓
5 FRONT BUMPER SIDE RETAINER RH		1 PC	20.00	✓
6 FRONT BUMPER CENTER RETAINER LH		1 PC	15.00	✓
7 FRONT BUMPER CENTER RETAINER RH		1 PC	15.00	✓
8 FRONT BUMPER REINFORCEMENT		1 PC	300.00	✓
9 FRONT BUMPER CENTER LOWER GARNISH		1 PC	145.00	✓
10 FRONT BUMPER CENTER LOWER GRILLE CHECK PRICE		1 PC	0.0000	✓
11 FOGLAMP COVER RH		1 PC	80.00	✓
12 TOWING COVER		1 PC	24.00	✓
13 HEADLAMP LH		1 PC	1,100.00	✓
14 HEADLAMP RH		1 PC	1,100.00	✓
15 HEADLAMP LOWER BRACKET RH		1 PC	40.00	✓
16 RADIATOR GRILLE		1 PC	220.00	✓
17 RADIATOR GRILLE BASE		1 PC	60.00	✓
18 RADIATOR SUPPORT PANEL		1 PC	360.00	✓
19 RADIATOR		1 PC	380.00	Photo
20 RADIATOR TOP BUSH		2 PC	12.00	Photo
21 RADIATOR TOP CLIP - missing		2 PC	8.00	Photo
22 RADIATOR FAN COWLING		1 PC	230.00	✓
23 RADIATOR FAN MOTOR		1 PC	360.00	Photo
24 AIR CON CONDENSER		1 PC	400.00	✓
25 AIR CON CONDENSER FAN MOTOR		1 PC	320.00	Photo
26 TURBO COOLER		1 PC	300.00	✓
27 RADIATOR SUPPORT PANEL TOP COVER		1 PC	50.00	✓
28 AIR INTAKE DUCT OUTER		1 PC	20.00	✓
29 AIR INTAKE DUCT		1 PC	60.00	✓
30 HORN BRACKET (CENTER)		1 PC	40.00	✓
31 NO PLATE GARNISH		1 PC	60.00	✓
32 FRONT FENDER RH		1 PC	480.00	✓

8,620.00

Special Nett

33 RADIATOR COOLANT
 34 NUMBER PLATE - FRONT

1 PC 35.00 205m
 1 PC 35.00 ✓



AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721
TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Estimate No: MCS1102267

Date: 26 Jan 2018

Policy No: GA124211

Veh Reg No: SDR280R

Make/Model: AUDI A6 2.0L TFSI MU
S-LINE

Your Ref No: SDR280R

Claim Type: Own Damage

Accident Date: 24/01/2018

Estimate Repair Cost to Vehicle No :SDR280R

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
				70.00
LABOUR				
35 TO CHECK WIRING AND REFOCUS HEADLAMP		1 PC	30.00	200
36 TO REMOVE AND REPLACE A/C CONDENSER, PIPES AND RADIATOR, VACUUM A/C SYSTEM AS WELL AS		1 EA	120.00	1000
37 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD FRONT SUPPORT PANEL & HEADLAMP PANEL. TO KNOCK & REPAIR FRONT INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	1,000.00	6000
38 TO SPRAY FRONT BONNET, FRONT BUMPER, FRONT FENDER LH & RH, FRONT DOOR RH, FRONT SUPPORT PANEL, BUMPER REINFORCEMENT AND EFFECTED AREAS		1 PC	1,000.00	6000
				2,150.00

Amount Before Excess S\$ 10,840.00

Add GST @ 7% 758.80

Total Amount payable S\$ 11,598.80

TOTAL: SINGAPORE DOLLAR ELEVEN THOUSAND FIVE HUNDRED NINETY EIGHT AND CENTS EIGHTY ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE



AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721
TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Estimate No: MCS1102267

Date: 05 Feb 2018

Policy No: GA124211

Veh Reg No: SDR280R

Make/Model: AUDI A6 2.0L TFSI MU
S-LINE

Your Ref No: S8M007SO
Claim Type: Own Damage
Accident Date: 24/01/2018

Estimate Repair Cost to Vehicle No :SDR280R

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
SMART CLAIM REF NO:S8M007SO				
Supplementary Parts to Repair				
SPARE PARTS				
1 RADIATOR AIR GUIDE RH		1 PC	20.00	—
2 FRONT BUMPER HOLDER LH		1 PC	18.00	—
3 FRONT BUMPER HOLDER RH		1 PC	18.00	—
4 FRONT BUMPER REINFORCEMENT HOLDER BRACKET LH		1 PC	10.00	—
5 FRONT BUMPER REINFORCEMENT HOLDER BRACKET RH	— missing	1 PC	10.00	—
				76.00

Amount Before Excess	S\$ 76.00
GST Amount	S\$ 5.32
Total Amount payable	<u>S\$ 81.32</u>

The above vehicle was surveyed by KENNETH KONG -LKK on 26/01/2018

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 8791 / 8745 9839



Dept Direct: 8305 9813

Dept Direct: 6305 9811

Dept Direct: 6417 8792



Dept Direct: 6417 8794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 8793

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea).

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

AH LIM MOTOR COMPANY(SIN MING)
176 SIN MING AUTOCARE #05-12

SINGAPORE 575721
TEL : 6456 3637 FAX : 6456 3686
ATTN : WONG/KEONG

WAUZZZ4F8AN010776

TAX INVOICE : AR201801-16904
DATE : 29/01/2018
CUSTOMER ID : AHL012
VEH REG. NO. : SDR280R
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 2
CURR : SS

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. 4F0823029F	FRT BONNET	CC CC5-J-040	1	1400.00	1,400.00
2. 8E0863727A	BONNET INSULATOR CLIP	CC CC5-B-08AP	17	3.00	51.00
3. 4F0807111E	FRT BUMPER REINFORCEMENT	CC CC5-F-070	1	300.00	300.00
4. 4F0941030EQ/DF	HEADLAMP RH	CC CC5-D-07B	1	1100.00	1,100.00
5. 4F0853651AQ1QP/AN1QP	RADIATOR GRILLE	CC CC5-B-09A	1	220.00	220.00
6. 4F0807285BS1QP	RADIATOR GRILLE BASE	CC CC5-C-07AB	1	60.00	60.00
7. 4F0805594D	SUPPORT PANEL	CC CC5-D-06D	1	360.00	360.00

CONTINUE NEXT PAGE

[P] 29/01/2018 9:38:46AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL

[E] 29/01/2018 9:11:39AM



日美汽車私人有限公司

JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Deu' Direct: 6417 9191 / 6745 9639



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Sliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

AH LIM MOTOR COMPANY(SIN MING)
176 SIN MING AUTOCARE #05-12

SINGAPORE 575721
TEL : 6456 3637 FAX : 6456 3686
ATTN : WONG/KEONG

WAUZZZ4F8AN010776

TAX INVOICE : AR201801-16904
DATE : 29/01/2018
CUSTOMER ID : AHL012
VEH REG. NO. : SDR280R
TERMS : 30 days
PO NO. :
PAGE NO. : Page 2 of 2
CURR : S\$

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
8.	4F0260403P	A/C CONDENSER	CC CC5-E-04B	1	400.00	400.00
9.	4F0129521B	AIR INTAKE DUCT	CC CC5-D-06AC	1	60.00	60.00
10.	4F0121284AR	RADIATOR AIR GUIDE RH	CC CC5-E-08BA	1	20.00	20.00
11.	4F0807771	FRT BUMPER HOLDER LH	CC CC5-E-08AI	1	18.00	18.00
12.	4F0807772	FRT BUMPER HOLDER RH	CC CC5-F-07AA	1	18.00	18.00

SUB-TOTAL : 4,007.00
ADD GST 7.00 % 280.49

E. & O.E TOTAL AMOUNT S\$: 4,287.49

[P] 29/01/2018 9:38:46AM

[E] 29/01/2018 9:11:39AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: ANN

This is computer generated document.

No signature is required.



ORIGINAL

Goods Received in Good Order

[Signature]

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9701 / 6745 9939



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9796

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

=====
AH LIM MOTOR COMPANY(SIN MING)
176 SIN MING AUTOCARE #05-12

SINGAPORE 575721
TEL : 6456 3637 FAX : 6456 3686
ATTN : WONG/KEONG
WAUZZZ4F8AN010776

TAX INVOICE : AR201801-16919
DATE : 29/01/2018
CUSTOMER ID : AHL012
VEH REG. NO. : SDR280R
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SS

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1	4F0807105ADGRU	FRT BUMPER	U1	1	950.00	950.00
			SUPPLIER			
2	4F0807228	FRT BUMPER SIDE RETAINER RH	U1	1	20.00	20.00
			2C3-D			
3	4F0959455A	A/C CONDENSER FAN MOTOR	U1	1	320.00	320.00
			1J7			
4	4F0129617C	AIR INTAKE DUCT OUTER	U1	1	20.00	20.00
			2I11-E			

SUB-TOTAL : 1,310.00
ADD GST 7.00 % 91.70

E. & O.E

TOTAL AMOUNT S\$: 1,401.70

[P] 29/01/2018 9:36:14AM

[E] 29/01/2018 9:14:07AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : ANN



* AR201801-16919 *

This is computer generated document.

No signature is required.

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9809



Dept Direct: 6305 9810

Dept Direct: 6305 9811

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

AHLIM MOTOR COMPANY(SIN MING)
176 SIN MING AUTOCARE #05-12

SINGAPORE 575721
TEL: 6456 3637 FAX: 6456 3686
ATTN: WONG/KEONG
WAUZZZ4F8AN010776

TAX INVOICE : AR201801-18727
DATE : 31/01/2018
CUSTOMER ID : AHL012
VEH REG. NO. : SDR280R
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : S\$

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. 4F0807110C 1RR	FRT BUMPER CENTER LOWER GARNISH	U1	1	145.00	145.00
2. 4F0807441G GRU	FRT BUMPER TOW COVER	U1	1	24.00	24.00
3. 4F0121251AE/R	RADIATOR	U1	1	380.00	380.00
4. 8D0121200	RADIATOR TOP PIN	U1	1	4.00	4.00
5. 4F0807081	SUPPORT PANEL TOP COVER	U1	1	50.00	50.00
6. 4F0807255	FRONT REINFORCEMENT HOLDER BRACKET LH/RH	U1	2	10.00	20.00

SUPPLIER

SUPPLIER

SUPPLIER

SUPPLIER

SUPPLIER

SUPPLIER

SUB-TOTAL : 623.00
ADD GST 7.00 % 43.61

E. & O.E

TOTAL AMOUNT S\$: 666.61

[P] 31/01/2018 10:51:29AM

[E] 31/01/2018 10:48:49AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : ANN



* AR201801-18727 *

This is computer generated document.
No signature is required.

ORIGINAL

Goods Received in Good Order

[Signature]

Signature / Co Stamp / Date



日美汽車私人有限公司 3

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@paciflc.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 6791 / 6746 6632



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

AH LIM MOTOR COMPANY(SIN MING)
176 SIN MING AUTOCARE #05-12

SINGAPORE 575721
TEL : 6456 3637 FAX : 6456 3686
ATTN : WONG/KEONG
WAUZZZ4F8AN010776

P.5

TAX INVOICE : AR201801-18805
DATE : 31/01/2018
CUSTOMER ID : AHL012
VEH REG. NO. : SDR280R
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : S\$

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. 4F0959455	RADIATOR FAN MOTOR	UI	1	360.00	360.00
		SUPPLIER			

[Handwritten signature]

SUB-TOTAL : 360.00
ADD GST 7.00 % 25.20

E. & O.E TOTAL AMOUNT S\$: 385.20

[P] 31/01/2018 11:24:57AM

[E] 31/01/2018 11:24:26AM

Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.
Sales Executive : ANN



* AR 201801-18805 *

This is computer generated document.
No signature is required.

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

=====

AH LIM MOTOR COMPANY(SIN MING)
176 SIN MING AUTOCARE #05-12

SINGAPORE 575721

TEL : 6456 3637 FAX : 6456 3686

ATTN : WONG/KEONG

WAUZZZ4F8AN010776

P-6

WINDSCREEN GLASS
Dept Direct: 6417 8791 / 6745 9839



Dept Direct: 6417 8794

Dept Direct: 6417 8795

Dept Direct: 6417 8796

Dept Direct: 6417 8798

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201802-01680
DATE : 03/02/2018
CUSTOMER ID : AHL012
VEH REG. NO. : SDR280R
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : S\$

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. 4F0121207E	FAN COWLING	U1	1	230.00	230.00
		SUPPLIER			

SUB-TOTAL : 230.00
ADD GST 7.00 % 16.10

E. & O.E TOTAL AMOUNT S\$: 246.10

[P] 03/02/2018 9:52:56AM

[E] 03/02/2018 9:49:05AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : ANN



* A R 2 0 1 8 0 2 - 0 1 6 8 0 *

This is computer generated document.
No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date

SERVICE REQUESTSMESSAGESCLAIMS

Service Request Details

Claim	S8M007SO	Vehicle Information	
Reference	None 	Incident Vehicle	SDR280R
		Registration #	176 Sin
		Make	AUDI
		Address	A6 2.0
January 24, 2018	Request Date	Ming Drive #05-12, . . .	
January 26, 2018	Due Date	575721	
April 26, 2018	Vendor Name	Primary Contact/Insured	
LKK AUTO CONSULTANTS PTE LTD (OD)	Type of Loss	CHEONG KWOK WING 134 KING'S ROAD, 268168, Singapore	
Own Damage	Services	cheongkw1@yahoo.com.sg	

Actions

Next Step

Finish the work

Complete Work

More

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
SDR 280R EST.pdf	Forms / Claim Documents	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (OD)	January 29, 2018
PRELI ADVISED SDR 280R.pdf	Forms / Claim Documents	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (OD)	January 29, 2018
SJN8166K TP GIA.PDF	Forms / Claim Documents	Claim Form	PATIL Amol	January 26, 2018
Email received from workshop with OD GIA & Estimate.msg	Letters and Correspondence	Others	PATIL Amol	January 26, 2018

SERVICE REQUESTS

MESSAGES

CLAIMS

<<

Service Request Details

Claim	S8M007SO
Reference	
None 	Loss Date
January 24, 2018	Request Date
January 26, 2018	Due Date
April 26, 2018	Vendor Name
LKK AUTO CONSULTANTS PTE Loss LTD (OD)	Type of Services
Own Damage	

Vehicle Information			
Incident Vehicle	SDR280R		
Registration #	Make	Service Address	
	AUDI		176 Sin
Model	A6 2.0		
	Ming Drive #05-12, , ,		
575721			
Primary Contact/Insured			
CHEONG KWOK WING			
134 KING'S ROAD, 268168, Singapore			
cheongkw1@yahoo.com.sg			

Actions

Next Step

Finish the work

Complete Work

More

SERVICE REQUESTS MESSAGES CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Vehicle & Driver Details

Summary

Vehicle

SDR280R

Registration#

Purchase Date

mm/dd/yyyy

Registration
State

Registration
Date *

mm/dd/yyyy

Mileage

Age of Vehicle

8

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
----------	--------------------	------------------------

Manufacturing
Year

2009

Make

AUDI

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	CHEONG NING	
Date of Birth	April 19, 1997	mm/dd/yyyy
Age	20	
Occupation	Unknown	
Education Qualification	Other	Primary ▼
Driving Experience	0	
Driver License #		
License Type		1 ▼
License Issue Date	January 1, 2018	mm/dd/yyyy

SERVICE REQUESTS MESSAGES CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Spare wheel

Rear Tyre Size

Rear left side

Rear right side

SERVICE REQUESTS MESSAGES CLAIMS

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPRJ BTR%	DISC OUNTY%	SALV AGE%	PART PRICE(NET)
	1	1			FRONT BONNET			Buckled	1400				1400
	2	17			FRONT BONNET INSULATOR CLIP			Necessary	3				51
	3	1			FRONT BUMPER			Cracked	950				950
	4	1			FRONT BUMPER SIDE RETAINER LH			Serviceable	0				0
	5	1			FRONT BUMPER SIDE RETAINER RH			Damaged	20				20
	6	1			FRONT BUMPER CENTER RETAINER LH			Serviceable	0				0
	7	1			FRONT BUMPER CENTER RETAINER RH			Serviceable	0				0
	8	1			FRONT BUMPER REINFORCEMENT			Bent	300				300
	9	1			FRONT BUMPER CENTER LOWER GARNISH			Cracked	145				145

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
	25	1			AIR CON CONDENSER FAN MOTOR			Cracked	320				320
	26	1			TURBO COOLER			Serviceable	0				0
	27	1			RADIATOR SUPPORT PANEL TOP COVER			Cracked	50				50
	28	1			AIR INTAKE DUCT OUTER			Cracked	20				20
	29	1			AIR INTAKE DUCT			Damaged	60				60
	30	1			HORN BRACKET (CENTER)			Repair	0				0
	31	1			NO PLATE GARNISH			Serviceable	0				0
	32	1			FRONT FENDER RH			Repair	0				0
	33	1			RADIATOR COOLANT (SN)			Necessary	20				20
	34	1			NUMBER PLATE - FRONT (SN)			Bent	35				35
	35	1			RADIATOR AIR GUIDE RH			Cracked	20				20
	36	1			FRONT BUMPER HOLDER LH			Cracked	18				18
	37	1			FRONT BUMPER HOLDER RH			Cracked	18				18
	38	1			FRONT BUMPER REINFORCEMENT HOLDER BRACKET LH			Damaged	10				10

SERVICE REQUESTS MESSAGES CLAIMS

<< Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

EDIT SR NO NAME ACTION AMOUNT COMMENT REMOVE

☐		1	DAYS OF REPAIR	Reviewing	6	
--------------------------	--	---	----------------	-----------	---	--

SERVICE REQUESTS MESSAGES CLAIMS

<< **Assessment Details**

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary Claim Amount \$5,005.00

CATEGORY ESTIMATE REVISED AMOUNT

Labour \$2,150.00 \$1,320.00

Spare Parts \$8,690.00 \$6,585.00

Excess -\$2,900.00 -\$2,900.00