

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ong Chin Kiat

Date: 30 Jan 2018

Preliminary Advice

Vehicle No	: EF88G	Accident Date	: 24/01/2018
Make	: MERCEDES-BENZ E300 AMG LINE (R19 LED)	Policy No.	: A29021463QMY
Assignment Date	: 29/01/2018	Excess	: S\$700.00
Date of Inspection	: 29/01/2018	Est. Duration of Repair	: 5.00
Inspection At	: OPTIMA WERKZ PTE LTD (HQ) 9A SERANGOON NORTH AVE 5 SINGAPORE 554500		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,869.20
Revised Amount	:S\$	9,641.50
Check Items (Estimated)	:S\$	2,493.90
Total	:S\$	12,135.40

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	265,000.00
COE / PARF Rebate	:S\$	116,937.00
Salvage Value	:S\$	
Margin for Repair	:S\$	148,063.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.