



VEHICLE NO.: SBY358M

MAKE: AUDI

MODEL: A6

YEAR OF MAKE: 2011

CHASSIS NO.: WAUZZZ4G5CN082501

SUPPLIERS : HEXING

Authorised
click
before photo before job
3d
2/2/18
Express N.C.

S/N	Parts Description	QTY	Amount
PARTS			
1	REAR BUMPER <i>new</i>	1	\$1,450.00 ✓
2	REAR BUMPER RETAINER RH <i>new</i>	1	\$125.00 ✓
3	REAR BUMPER CLIP <i>new</i>	10	\$25.00 ✓
4	REAR BUMPER REINFORCEMENT	1	\$450.00 ?
5	REAR BUMPER REVERSE SENSOR <i>Shovel</i>	1	\$125.00 ✓
6	REAR BUMPER LOWER DIFFUSER <i>Defense</i>	1	\$350.00 ✓
7	REAR BUMPER LOWER DIFFUSER CTR GARNISH <i>new</i>	1	\$200.00 ✓
8			
9			
10			
11			
12			
13			
14			
15			
16			
17			
18			
19			
20			
TOTAL PARTS			\$2,725.00
S/N			
1			
2			
TOTAL S/N			
LABOUR :			
1	WIRE CHECKING		\$20.00 ✓
2	LABOUR CHARGE		\$450.00 250
3	SPRAY PAINTING		\$450.00 300
4			
5			
6			
TOTAL LABOUR			\$920.00
TOTAL			\$3,645.00
GST 7%			\$255.15
			\$3,900.15

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1 Kaki Bukit Ave 6, Bldg D, #02-16, AutoBay@Kaki Bukit, Singapore 417883. Tel: 6747 6106 (6 Lines) Fax: 6744 2368

Co. Reg. No.: 201119451E GST Reg. No.: 201119451E