

INS. CASE OWNER:

Jowyn

CC 6/CTI18001702

1 Un33

LKK:

IDAC:

Surveyor:

MARCUS

DOI:

29/01/18

Date / Time:

29/01/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBA 7383U

Claim No.:

SNM18D0515C02/3/4KDS

Name of Insured:

MT SINGAPORE CAR RENTAL PTE LTD

Policy No.:

DMCUN1802041800

Insured Tel No.:

HP:

Make / Model:

TOYOTA HIACE

Excess Sec II :S\$

D.O.A.:

25/01/18

Place of Accident:

TOA PAYOH LORONG 2 TOWARDS PL

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age: NGIRWAN BIN HAMZAH

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

9364 6631

(V/L YES / NO)

Insured Liability:

%

Final ? Yes / No

SKS 9626E



INSRS:

WSP: Hup motor

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SKS 9626E - X

GBA 7383U - CCU/ATG15007555/KH0552 DM364

01/02/18 (TUE PM) \* Letter from Cheonghoh Law for your necessary action.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

28/03/18

AFTER REVIEW TO CHECK WITH CH'S CLAIM RESULT. IF CH'S CLAIM IS SUCCESSFUL, WE STAND FIRM, BASED ON DAMAGE PROFILE &amp; POSITION OF TP'S VEHICLE, WE HAVE GROUNDS OF REJECTION.

ORIGINAL DOCUMENT WITH FILE

RECEIVED 30 JUL 2018

PRELIMINARY ADVICE

Date/Time: 30/01/18

Sent By:

Shirley Hwee

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

(Tick only one)

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$ 400.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

TOTAL



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI18001702/Uus3

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 29-01-2018



Code : CTI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBA 7383U	Veh. Inspected	SKS 9626E
Policy No.	DMCVSN1803041800	Coverage (\$)	0.00
Claim No.	SNM18D00515C02/3/LKKDS	Excess (\$)	0.00
Assign From		Assign Date	29/01/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	25/01/2018	Inspection Date	29/01/2018
Survey held at	HUP MOTOR TRADING & SERVICE BLK 9004 TAMPINES ST 93 #01-120 SINGAPORE 528838		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 LEBI AVE. L, #02-25 PAYA LEBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA  
Our ref: CC6/CTI18001702/Uus3

Date: 30.01.2018

The Motor Claims Department  
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SKS 9626E**

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 29.01.2018 at the premises of M/s Hup Motor Trading & Service (Tampines) and have the following to report:-

Workshop Estimate Amount	: S\$	4,363.04
Revised Estimate Amount	: S\$	1,707.84
"Check" Items Amount	: S\$	1,193.60
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the  
Front O/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3.0 days

Yours faithfully,

MARCUS CHUA  
Licensed Appraiser

# Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	5462M
Vehicle Details	
Vehicle No.:	SKS9626E
Vehicle to be Exported:	No
Intended De-registration Date:	29 Jan 2018
Vehicle Make:	SUBARU
Vehicle Model:	SUBARU XV 1.6i AWD CVT
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	FB161614393
Chassis No.:	JF1GP3KC5EG147097
Maximum Power Output:	84.0 kW (112 bhp)
Open Market Value:	\$16,405.00
Original Registration Date:	18 May 2015
First Registration Date:	18 May 2015
Transfer Count:	1
Actual ARF Paid:	\$11,405.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 May 2025
PARF Rebate Amount:	\$8,553.00
Intended COE Rebate Details	
COE Expiry Date:	17 May 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$68,589.00
COE Rebate Amount:	\$50,059.00
Total Rebate Amount:	\$58,612.00

The information contained herein is correct as at 29 Jan 2018

OK

## Enquire Transfer Fee

Vehicle Details	
Vehicle No. :	SKS9626E
Vehicle Type :	Z11 - Private Hire (Chauffeur) Station Wagon/Jeep/Land Rover
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	SUBARU
Vehicle Model :	SUBARU XV 1.6I AWD CVT
Chassis No. :	JF1GP3KC5EG147097
Propellant :	Petrol
Engine No. :	FB161614393
Engine Capacity :	1600 cc
Maximum Power Output :	84.0 kW ( 112 bhp )
Maximum Laden Weight :	2000 kg
Unladen Weight :	1480 kg
Year Of Manufacture :	2015
Original Registration Date :	18 May 2015
Lifespan Expiry Date :	-
COE Category :	A - Car up to 1600cc & 97kW (130bhp)
Quota Premium :	\$68,589.00
COE Expiry Date :	17 May 2025
Road Tax Expiry Date :	17 May 2018
PARF Eligibility Expiry Date :	17 May 2025

# 哈 汽 車 貿 易 服 務

## HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2881/01/18

Your Ref:

Date: 26th JAN 2018

M/S BEST GARB SERVICE  
BLK 406, #10-834  
SEMBAWANG DRIVE, S (750406)

Estimate cost of repair to SUBARU XV 1.6 (A) MPV - SKS 9626 E

- |  |            |
|--|------------|
| 1 pc front bumper                          |            |
| 8 pcs front bumper clips                   | @ \$ 3.40  |
| 1 pc front bumper towing bar cover         |            |
| 2 pcs front bumper o/s & n/s side retainer | @ \$ 26.00 |
| 1 pc front bumper o/s fog lamp garnish     |            |
| 1 pc front bumper sponge damper            |            |
| 1 pc front bumper reinforcement            |            |
| 1 pc o/s head lamp assy                    |            |
| 1 pc front grille frame moulding           |            |
| 1 pc front support panel                   |            |
| 1 pc front number plate & frame            |            |

DIS \$ 659.40 ✓  
 27.20 ✓  
 18.00 ✓  
 52.00 ✓  
 31.00 ✓  
 79.20 ✓  
 288.00 ✓  
 900.00 ✓  
 304.00 ✓  
 520.00 ✓  
 50.00 ✓

\$ 2,928.80  
 Less 20% \$ 585.76  
 \$ 2,343.04

- |   |             |     |
|---|-------------|-----|
| To wiring check up & adjust headlight alignment.  | 50.00       | 20  |
| To remove & refix air cond parts & refill R134 gas.   | 11 150.00   | X   |
| To check & adjust front wheel alignment & balancing.  | 11 120.00   | X   |
| To respray Tuff-Kote on all affected accident parts.  | 11 50.00    | X   |
| Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out front fender & necessary parts, to weld, renew & align above parts. | 750.00      | 400 |
| To putty & respray painting on all affected accident parts.   | 900.00      | 600 |
|   | \$ 4,363.04 |     |

Dollars : Four Thousand Three Hundred Sixty Three And Cents Four Only.

### HUP MOTOR TRADING & SERVICE

- KK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Not Ackd  
 3 day  
 29/1/18  
 1951.04



# 哈 汽 車 貿 易 服 務

## HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2881/01/18 Your Ref: Date: 26th JAN 2018

M/S BEST GARB SERVICE  
BLK 406, #10-834  
SEMBAWANG DRIVE, S (750406)

Estimate cost of repair to SUBARU XV 1.6 (A) MPV - SKS 9626 E

1 pc front bumper		DIS \$ 659.40	✓
8 pcs front bumper clips	@ \$ 3.40	27.20	✓
1 pc front bumper towing bar cover		18.00	✓
2 pcs front bumper o/s & n/s side retainer	@ \$ 26.00	52.00	✓
1 pc front bumper o/s fog lamp garnish		31.00	✓
1 pc front bumper sponge damper		79.20	✓
1 pc front bumper reinforcement		288.00	?
1 pc o/s head lamp assy		900.00	?
1 pc front grille frame moulding		304.00	?
1 pc front support panel		520.00	✓
1 pc front number plate & frame		50.00	✓
		\$ 2,928.80	
	Less 20%	\$ 585.76	
		\$ 2,343.04	
To wiring check up & adjust headlight alignment.		50.00	20
To remove & refix air cond parts & refill R134 gas.		150.00	✓
To check & adjust front wheel alignment & balancing.		120.00	✓
To respray Tuff-Kote on all affected accident parts.		50.00	✓
Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out front fender & necessary parts, to weld, renew & align above parts.		750.00	400
To putty & respray painting on all affected accident parts.		900.00	600
		\$ 4,363.04	
		=====	

Dollars : Four Thousand Three Hundred Sixty Three And Cents Four Only.

### HUP MOTOR TRADING & SERVICE

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Ackd  
2/1/18  
3 dy.  
29/1/18



## **Cheonghoh Law Corporation**

(Incorporated with limited liability) Blk 53 Chin Swee Road #03-05 Singapore 160053  
Co. Reg No. 201108070G Tel: 63378700 Fax: 63373700 E-mail: mail@cheonghoh.sg

In reply, please quote our Reference Number

Our Ref: LCH.Ig/SMSL-80081.18  
Your Ref: To be advised

30 January 2018

China Taiping Insurance (Singapore) Pte Ltd  
3 Anson Road #15-00  
Springleaf Tower  
Singapore 079909

18 / 515 / 3  
**BY FAX & BY HAND**  
Fax No - 6224 7478

Dear Sirs

**ACCIDENT INVOLVING VEHICLES NO GBA 7383 U AND SKS 9626 E ON 25 JANUARY 2018 AT/ALONG TOA PAYOH LORONG 2 TOWARDS THE PIE -**

We refer to the above matter.

We act for **MT SINGAPORE CAR RENTAL PTE LTD** the owner of **GBA 7383 U**, your insured in his claim against the third party for the damages and losses sustained by him in consequence of the above accident.

We would appreciate if you could keep us informed of any claims by the third party against our mutual client. However, if you are minded to settle the third party's claim in exercise of your subrogation rights, kindly ensure that such settlement is made on a without prejudice basis so that it would not jeopardise our client's claim against the third party.

Please be informed that as the report of the accident was made by our client via Idac electronic filing system / police station, we will proceed to apply for the opposite party's motor accident report without delay.

Please do not hesitate to contact us if you have any clarification.

Yours faithfully

**CHEONGHOH LAW CORPORATION**

This is a computer-generated document and requires no signature

cc: client - via fax only (GBA 7383 U)

31 JAN 2018

## Shirley Hiew (LKK Auto)

---

**From:** Angie Foo <angie.foo@sg.cntaiping.com>  
**Sent:** Wednesday, 31 January 2018 6:02 PM  
**To:** Shirley Hiew (LKK Auto)  
**Cc:** Thin Thin (LKKAuto); Jas Khine (LKKAuto); Admin A; Jowyn Tay  
**Subject:** OUR REF: SNM18D00515C02/3/LKKDS & YR REF- (TP : CC6/CTI18001702/Uus3) on 25/01/2018  
**Attachments:** SNM18D00515C01 20180131 TO INSURED -LKKDirectSettlementAccidentLtr.pdf; MKKH18013173-GBA7383U.pdf; SNM18D00515C01 20180130 FR CHEONGHOH LAW -LTR ACTING FOR INSD.pdf

Dear Shirley,

We refer to your email of 30<sup>th</sup> January 2018.

We attached our Insured's SAS Report , Assignment Letter and letter from Cheonghoh Law for your necessary action.

Kindly take note, our Insured is claiming Third Party SKS9626E -NTUC and the claim handler on this case is Ms Jowyn Tay 6389 6171.

Thank you.

Regards,  
Angie Foo  
Executive  
Motor Division  
Claims Department  
China Taiping Insurance (Singapore) Pte Ltd  
3 Anson Road #16-00  
Springleaf Tower  
Singapore 079909  
Co.Reg.No.200208384E  
DID: 6389 6186  
Fax: 6224 7478 /6224 7175  
Email: [angie.foo@sg.cntaiping.com](mailto:angie.foo@sg.cntaiping.com)  
Email: [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

Disclaimer:

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

**From:** Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]  
**Sent:** Tuesday, 30 January, 2018 3:57 PM  
**To:** Claims Dept of CTI; Jowyn Tay  
**Cc:** Thin Thin (LKKAuto); Jas Khine (LKKAuto); Admin A  
**Subject:** Direct Settlement - Accident Involving GBA7383U (OI : CTI - TBA) AND SKS9626E (TP : CC6/CTI18001702/Uus3) on 25/01/2018

**WITHOUT PREJUDICE**

Dear Sir/Madam,

We refer to the above matter.

We have inspected TP vehicle SKS 9626E at M/s Hup Motor Trading & Service - Tampines.

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Thin Thin and she can be contacted at DID: 6841 2360.

*To check availability of the case handler , you may contact the undersigned.*

Thank you.

Best Regards,

Shirley Hiew | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6356-0055 | email: [ShirleyHiew@lkkauto.com](mailto:ShirleyHiew@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

# 哈 汽 車 貿 易 服 務

## HUP MOTOR TRADING & SERVICE


Email : hupmotor@gmail.com

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 WEB SITE: <http://hupmotor.com.sg> Reg. No. 378091/00W

Our Ref: TP 2881/01/18

Your Ref: \_\_\_\_\_

Date: 1st February 2018

 The Claim's Manager  
Motor Claims Dept.  
CHINA TAIPING INSURANCE (S) PTE LTD  
3, Anson Rd, #16-00,  
SpringLeaf Tower, Singapore 079909

Dear Sirs,

RE : ACCIDENT ON 25/01/18 ALONG LORONG 2 TOA PAYOH TOWARDS P.I.E.  
INVOLVING : SKS 9626 E & YOUR INSURED : GBA 7383 U

We act for M/S Best Garb Service., ROC : 53365462M  
Who is the registered owner of Veh. No : SKS 9626 E Which was involved  
in the above accident with Veh. No : GBA 7383 U Which we understand  
is insured with you.

Your appointed surveyor had surveyed our client's damaged vehicle and  
we had repaired the vehicle.

The accident was clearly caused by your insured's negligence, I am,  
therefore, seeking compensation from you for my financial losses as  
itemised below : -

Cost of repair	\$ 1,951.04
Loss of Use for 3 days ( 1 day X \$ 120.00 )	360.00
LTA Search Fee & GIA-RMC Search Fee	2.00
Survey Fee	0.00

\$ 2,313.04

=====

We have enclosed copies of relevant documents to support my client's  
claim, There was no receipt enclosed, as my client's did not pay us  
any single amount.

Your prompt settlement of our claim would be much appreciated.

Yours faithfully,

HUP MOTOR TRADING & SERVICE

  
Mr David Ang B. Y.

Encl : Final Bill, ~~Car Rental Bill~~, LTA Search Fee, Owner Authorisation  
Letter, GIA Report, Survey Report & Ins. Cert.

Remark : Kindly acknowledge receipt.

哈 汽 車 貿 易 服 務

## HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TF 2881/01/18 Your Ref: \_\_\_\_\_ Date: 1st Feb 2018

M/S BEST GARB SERVICE  
BLK 406, #10-834  
SEMBAWANG DRIVE,  
SINGAPORE 750406

Cost of repair to SUBARU XV 1.6 (A) MPV - SKS 9626 E

1 pc front bumper		\$ 659.40
8 pcs front bumper clips	@ \$ 3.40	27.20
1 pc front bumper tow bar cover		18.00
1 pc front bumper o/s side retainer		26.00
1 pc front bumper sponge damper		79.20
1 pc front grille frame moulding		304.00
1 pc front number plate & frame		50.00
		<hr/>
		\$ 1,163.80
	Less 20%	\$ 232.76
		<hr/>
		\$ 931.04
To wiring check up & adjust headlight alignment		20.00
Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out front support panel, front bumper reinforcement & necessary parts, to weld, renew & align above parts.		400.00
To putty & respray painting on all affected accident parts.		600.00
		<hr/>
		\$ 1,951.04
		=====

Dollars : One Thousand Nine Hundred Fifty One And Cents Four Only.

HUP MOTOR TRADING & SERVICE

.....  
.....  
.....



## GENERAL INSURANCE ASSOCIATION OF SINGAPORE

### RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

RECORDS MANAGEMENT CENTRE

## Third Party Insurer Enquiry

Our Ref No: GR-18-014455

Date of Request: 26/01/2018

Your Ref No:

Online Purchase

Hup Motor Trading & Service  
Blk 9004 Tampines Street 93  
#01-120  
Singapore 528838

Dear Sir/Madam,

Enquiry Date 26/01/2018  
Enquiry By David Ang Beng Yeow  
TP Vehicle No. GBA7383U  
Accident Date 25/01/2018

### Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
GBA7383U	China Taiping Insurance (Singapore) Pte. Ltd.	19/01/2018-18/01/2019	6389 6111

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

TO: CHINA TAIPING INSURANCE (S) PTE. LTD.

## AUTHORIZATION TO ACT

I, BEST GARB SERVICE (ROC : 53365462M) ("the third party claimant")

of Blk 406, #10-834, Sembawang Drive, S (750406) (address),

owner of SKS 9626 E (vehicle no.) hereby authorize

Hup Motor Trading & Service,

("The workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my

Vehicle No. SKS 9626 E that was damaged pursuant to the

accident which occurred on 25/01/18 (date) along Lorong 2,

Toa Payoh Towards P.I.E. (location)

involving Vehicle No/s GBA 7383 U

("The accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 29th day of January (month) 20 18 (year)




Ms Low Ai Nee (S7413391F)

Signed by "the third party claimant"  
Owner Of : SKS 9626 E

HUP MOTOR TRADING & SERVICE

[Signature]  
Signed by "the workshop"





## Thin Thin (LKKAUTO)

**From:** Thin Thin (LKKAUTO)  
**Sent:** Tuesday, 6 March 2018 6:56 PM  
**To:** 'David Ang'  
**Cc:** Admin A; Jas Khine (LKKAUTO); assignments; Marcus Chua (LKKAUTO)  
**Subject:** RE: RE : YOUR REF : CC6/CTI18001702/Uus3, ACCIDENT ON : 25/01/18, INVOLVING CLIENT'S (SKS 9626 E) & THIRD PARTY (GBA 7383 U) INSURED BY CHINA TAIPING, ALONG LORONG 2 TOA PAYOH TOWARDS P.I.E. \*\*\* LKK REF - CC6/CTI18001702/Uus3  
**Attachments:** IMG-20180202-WA0039.jpg; OI Sketch Plan.pdf

"Without Prejudice"

Dear David,

**ACCIDENT ON 25/01/2018 INVOLVING VEHICLES GBA 7383U AND SKS 9626E**

We refer to the below matter.

Our insured has reiterated that the accident was caused due to the negligence of your client.

Our insured vehicle was travelling along the main road and your client vehicle turning out from minor road and collided onto our insured vehicle.

Attached herewith our insured's sketch plan for your perusal.

Under such a circumstances, we are denying liability and unable to look into your client's claim, unless you have concrete evidence to prove otherwise.

Best Regards,

**Thin Thin Hlaing** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2360 | email: [thinthin@lkkauto.com](mailto:thinthin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Thin Thin (LKKAUTO)  
**Sent:** Monday, 5 March 2018 9:10 AM  
**To:** 'David Ang' <hupmotor@gmail.com>  
**Cc:** Admin A <admin-a@lkkauto.com>; Jas Khine (LKKAUTO) <jaskhine@lkkauto.com>; assignments <assignments@lkkauto.com>; Marcus Chua (LKKAUTO) <MarcusChua@lkkauto.com>  
**Subject:** RE: RE : YOUR REF : CC6/CTI18001702/Uus3, ACCIDENT ON : 25/01/18, INVOLVING CLIENT'S (SKS 9626 E) & THIRD PARTY (GBA 7383 U) INSURED BY CHINA TAIPING, ALONG LORONG 2 TOA PAYOH TOWARDS P.I.E. \*\*\* LKK REF - CC6/CTI18001702/Uus3

"Without Prejudice"

Dear Mr David,

We refer to the below matter.

Please be inform that we are still pending for our Principal instruction.

We will follow up with our Principal and will revert back to you.

Thanks.

Best Regards,

**Thin Thin Hlaing** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2360 | email: [thinthin@lkkauto.com](mailto:thinthin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** David Ang [<mailto:hupmotor@gmail.com>]

**Sent:** Saturday, 3 March 2018 5:20 PM

**To:** Thin Thin (LKKAuto) <[thinthin@lkkauto.com](mailto:thinthin@lkkauto.com)>

**Cc:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Jas Khine (LKKAuto) <[jaskhine@lkkauto.com](mailto:jaskhine@lkkauto.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>; Marcus Chua (LKKAuto) <[MarcusChua@lkkauto.com](mailto:MarcusChua@lkkauto.com)>

**Subject:** Re: RE : YOUR REF : CC6/CTI18001702/Uus3, ACCIDENT ON : 25/01/18, INVOLVING CLIENT'S (SKS 9626 E) & THIRD PARTY (GBA 7383 U) INSURED BY CHINA TAIPING, ALONG LORONG 2 TOA PAYOH TOWARDS P.I.E. \*\*\* LKK REF - CC6/CTI18001702/Uus3

Dear Thin Thin,

Any reply & outcome for us ? Please revert,



Virus-free. [www.avg.com](http://www.avg.com)

On 2 February 2018 at 15:59, Thin Thin (LKKAuto) <[thinthin@lkkauto.com](mailto:thinthin@lkkauto.com)> wrote:

**"Without Prejudice"**

Dear David,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both party, the liability is unclear for the above mentioned case. There is no conclusive evidence to substantiate either party's version. Enclosed herewith is a copy of our insured's accident report for your perusal.

We are in a course of investigating into the circumstances of the accident. After verifying further with our OI we will revert with our opinion on the cause of the accident. Kindly do not refer to any party for legal assistance until you heard further from us.

Meanwhile, we would like to request the CCTV footage / accident scene photos / evidence in order to seek further instruction from our principal.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,

**Thin Thin Hlaing** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2360 | email: [thinthin@lkkauto.com](mailto:thinthin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Thin Thin (LKKAuto)

**Sent:** Thursday, 1 February 2018 11:53 AM

**To:** 'David Ang' <[hupmotor@gmail.com](mailto:hupmotor@gmail.com)>

**Cc:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Jas Khine (LKKAuto) <[jaskhine@lkkauto.com](mailto:jaskhine@lkkauto.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>; Marcus Chua (LKKAuto) <[MarcusChua@lkkauto.com](mailto:MarcusChua@lkkauto.com)>

**Subject:** RE: RE : YOUR REF : CC6/CTI18001702/Uus3, ACCIDENT ON : 25/01/18, INVOLVING CLIENT'S (SKS 9626 E) & THIRD PARTY (GBA 7383 U) INSURED BY CHINA TAIPING, ALONG LORONG 2 TOA PAYOH TOWARDS P.I.E. \*\*\* LKK REF - CC6/CTI18001702/Uus3

Dear David,

We acknowledge your email below.

We will look into the matter and will revert back to you in due course.

Best Regards,

**Thin Thin Hlaing** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2360 | email: [thinthin@lkkauto.com](mailto:thinthin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** David Ang [<mailto:hupmotor@gmail.com>]

**Sent:** Thursday, 1 February 2018 11:47 AM

**To:** Thin Thin (LKKAuto) <[thinthin@lkkauto.com](mailto:thinthin@lkkauto.com)>

**Cc:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Jas Khine (LKKAuto) <[jaskhine@lkkauto.com](mailto:jaskhine@lkkauto.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>; Marcus Chua (LKKAuto) <[MarcusChua@lkkauto.com](mailto:MarcusChua@lkkauto.com)>

**Subject:** RE : YOUR REF : CC6/CTI18001702/Uus3, ACCIDENT ON : 25/01/18, INVOLVING CLIENT'S (SKS 9626 E) & THIRD PARTY (GBA 7383 U) INSURED BY CHINA TAIPING, ALONG LORONG 2 TOA PAYOH TOWARDS P.I.E. \*\*\* LKK REF - CC6/CTI18001702/Uus3

Dear Thin Thin,

Attach our letter of demand, final bill, GIA third party insurer search fee & owner authorisation letter for your reference & attention, Please let us have your settlement soonest, we will forwards the original documents to you by mail. Kindly acknowledge receipt,

On 29 January 2018 at 15:14, Shirley Hiew (LKK Auto) <[ShirleyHiew@lkkauto.com](mailto:ShirleyHiew@lkkauto.com)> wrote:

Dear David,

We refer to the above matter.

Please be informed that we are currently pending for our insured's GIA report.

Kindly note that for liability, claim negotiation and settlement, please contact Thin Thin at 6841 2360.

Our respective case handler will look into the matter and revert to you in due course.

*To check availability of the case handler, you may contact the undersigned.*

Thank you.

Best Regards,

Shirley Hiew | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [ShirleyHiew@lkkauto.com](mailto:ShirleyHiew@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** David Ang [mailto:[hupmotor@gmail.com](mailto:hupmotor@gmail.com)]

**Sent:** Friday, 26 January 2018 6:30 PM

**To:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Admin-B <[admin-b@lkkauto.com](mailto:admin-b@lkkauto.com)>

**Cc:** Jas Khine (LKKAuto) <[jaskhine@lkkauto.com](mailto:jaskhine@lkkauto.com)>; Vic (LKKAuto) <[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)>; Marcus Chua (LKKAuto) <[MarcusChua@lkkauto.com](mailto:MarcusChua@lkkauto.com)>

**Subject:** RE : ACCIDENT ON : 25/01/18, INVOLVING CLIENT'S (SKS 9626 E) & THIRD PARTY (GBA 7383 U) INSURED BY CHINA TAIPING, ALONG LORONG 2 TOA PAYOH TOWARDS P.I.E.

Dear Sirs,

Attach our estimate bill, GIA third party insurer search fee, owner GIA report & log card for your reference & attention,

Kindly revert & confirm client's third party claims liability, reference & OIC, as we are looking for direct settlement,

For your info, We had assign your in-house surveyor (Mr Marcus Chua) to survey client's damage vehicle on : 29/01/18

**Best Regards**

**David Ang**

**Tel : 6784 0039, Fax : 6784 0076  
HP : 9815 4655**

**Hup Motor Trading & Service  
Blk 9004 Tampines St 93  
#01-120  
Singapore 528838**

--  
**Best Regards**

**David Ang**

**Tel : 6784 0039, Fax : 6784 0076  
HP : 9815 4655**

**Hup Motor Trading & Service  
Blk 9004 Tampines St 93  
#01-120  
Singapore 528838**



Virus-free. [www.avg.com](http://www.avg.com)

--  
**Best Regards**

**David Ang**

**Tel : 6784 0039, Fax : 6784 0076**



**HP : 9815 4655**

**Hup Motor Trading & Service  
Blk 9004 Tampines St 93  
#01-120  
Singapore 528838**

## Thin Thin (LKKAUTO)

---

**From:** Claims Dept of CTI <claimsdept@sg.cntaiping.com>  
**Sent:** Monday, 5 March 2018 10:11 AM  
**To:** Thin Thin (LKKAUTO); Admin A  
**Cc:** Jowyn Tay; Alfred Toh; Hsiao Tong (LKKAUTO)  
**Subject:** RE: OUR REF: SNM18D00515C02/3/LKKDS & YR REF- (TP : CC6/CTI18001702/Uus3) on 25/01/2018

LKK REF: CC6/CTI18001702/Uus3  
CTI REF: SNM18D00515C02/3 (GBA7383U)

Dear Thin Thin

We refer to your emails pertaining to the above matter.

Please proceed to reject the third party property damage claim in the first instance.

Meanwhile, please assist to check with Insured on the outcome of their claim against SKS9626E.

Regards

Alfred Toh  
Senior Executive  
Claims Department  
China Taiping Insurance (Singapore) Pte Ltd  
3 Anson Road  
#15-00 Springleaf Tower  
Singapore 079909  
Co. Reg. No. 200208384E  
DID : +65 6389 6183  
FAX: +65 6224 7175/6224 7478  
Email: [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)  
[alfred.toh@sg.cntaiping.com](mailto:alfred.toh@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

**From:** Thin Thin (LKKAUTO) [mailto:thinthin@lkkauto.com]  
**Sent:** Monday, March 05, 2018 9:46 AM  
**To:** Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Jowyn Tay <jowyn.tay@sg.cntaiping.com>  
**Subject:** FW: OUR REF: SNM18D00515C02/3/LKKDS & YR REF- (TP : CC6/CTI18001702/Uus3) on 25/01/2018  
**Importance:** High

Dear Sir / Madam,

We refer to the below matter.

Kindly let us have your instruction as TP is chasing us for liability.

Thanks.

Best Regards,

**Thin Thin Hlaing** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2360 | email: [thinthin@lkkauto.com](mailto:thinthin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Thin Thin (LKKAuto)

**Sent:** Monday, 5 February 2018 11:39 AM

**To:** Jowyn Tay <[jowyn.tay@sg.cntaiping.com](mailto:jowyn.tay@sg.cntaiping.com)>

**Cc:** Jas Khine (LKKAuto) <[jaskhine@lkkauto.com](mailto:jaskhine@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Shirley Hiew (LKK Auto) <[ShirleyHiew@lkkauto.com](mailto:ShirleyHiew@lkkauto.com)>; 'Claims Dept of CTI' <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>

**Subject:** RE: OUR REF: SNM18D00515C02/3/LKKDS & YR REF- (TP : CC6/CTI18001702/Uus3) on 25/01/2018

**Importance:** High

Your Ref: SNM18D00515C02/3/LKKDS

Our Ref: CC6/CTI18001702/Uus3

Dear Jowyn,

**ACCIDENT ON 25/01/2018 INVOLVING VEHICLES GBA 7383U AND SKS 9626E**

We refer to the above matter.

TP reported that he was driving along Lor 2 Toa Payoh left lane, suddenly our insured cut into his lane and collided onto his vehicle. Please see attached TP's statement.

OI reported that he was travelling straight along Toa Payoh Lor 2 towards PIE. Suddenly TP came out from minor road beside of BLK 84B and collided onto his vehicle. Please see attached OI's statement.

We did call OI to verify the nature of accident. OI disputed on the liability and he mentioned that he was travelling straight and TP is coming out from minor road, fail to stop at the stop line and collided onto his vehicle left rear portion.

Meantime, we have requested the evidence from TP and they provide us the accident photo. Based on photos provided by TP, TP vehicle position is slanting position. Please see the photos provide from TP.

Based on the circumstances of accident, scenario from both parties, we are of opinion that our insured version is more credible and accurate.

As such, we intend to reject the claim and kindly let us have your instruction / approval please.

Best Regards,

**Thin Thin Hlaing** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2360 | email: [thinthin@lkkauto.com](mailto:thinthin@lkkauto.com) | fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shirley Hiew (LKK Auto)

**Sent:** Wednesday, 31 January 2018 6:07 PM

**To:** Angie Foo <[angie.foo@sg.cntaiping.com](mailto:angie.foo@sg.cntaiping.com)>

**Cc:** Thin Thin (LKKAuto) <[thinthin@lkkauto.com](mailto:thinthin@lkkauto.com)>; Jas Khine (LKKAuto) <[jaskhine@lkkauto.com](mailto:jaskhine@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Jowyn Tay <[jowyn.tay@sg.cntaiping.com](mailto:jowyn.tay@sg.cntaiping.com)>

**Subject:** FW: OUR REF: SNM18D00515C02/3/LKKDS & YR REF- (TP : CC6/CTI18001702/Uus3) on 25/01/2018

Dear Angie,

Thanks and received.

Thank you.

Best Regards,

Shirley Hiew | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [ShirleyHiew@lkkauto.com](mailto:ShirleyHiew@lkkauto.com) | fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Angie Foo [<mailto:angie.foo@sg.cntaiping.com>]

**Sent:** Wednesday, 31 January 2018 6:02 PM

**To:** Shirley Hiew (LKK Auto) <[ShirleyHiew@lkkauto.com](mailto:ShirleyHiew@lkkauto.com)>

**Cc:** Thin Thin (LKKAuto) <[thinthin@lkkauto.com](mailto:thinthin@lkkauto.com)>; Jas Khine (LKKAuto) <[jaskhine@lkkauto.com](mailto:jaskhine@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Jowyn Tay <[jowyn.tay@sg.cntaiping.com](mailto:jowyn.tay@sg.cntaiping.com)>

**Subject:** OUR REF: SNM18D00515C02/3/LKKDS & YR REF- (TP : CC6/CTI18001702/Uus3) on 25/01/2018

Dear Shirley,

We refer to your email of 30<sup>th</sup> January 2018.

We attached our Insured's SAS Report , Assignment Letter and letter from Cheonghoh Law for your necessary action.

Kindly take note, our Insured is claiming Third Party SKS9626E -NTUC and the claim handler on this case is Ms Jowyn Tay 6389 6171.

Thank you.

Regards,  
Angie Foo  
Executive  
Motor Division  
Claims Department  
China Taiping Insurance (Singapore) Pte Ltd  
3 Anson Road #16-00  
Springleaf Tower  
Singapore 079909  
Co.Reg.No.200208384E  
DID: 6389 6186  
Fax: 6224 7478 /6224 7175

Email: [angie.foo@sg.cntaiping.com](mailto:angie.foo@sg.cntaiping.com)  
Email: [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

*Disclaimer:*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

**From:** Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]  
**Sent:** Tuesday, 30 January, 2018 3:57 PM  
**To:** Claims Dept of CTI; Jowyn Tay  
**Cc:** Thin Thin (LKKAuto); Jas Khine (LKKAuto); Admin A  
**Subject:** Direct Settlement - Accident Involving GBA7383U (OI : CTI - TBA) AND SKS9626E (TP : CC6/CTI18001702/Uus3) on 25/01/2018

**WITHOUT PREJUDICE**

Dear Sir/Madam,

We refer to the above matter.

We have inspected TP vehicle SKS 9626E at M/s Hup Motor Trading & Service - Tampines.

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Thin Thin and she can be contacted at DID: 6841 2360.

***To check availability of the case handler , you may contact the undersigned.***

Thank you.

Best Regards,

Shirley Hiew | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366-0055 | email: [ShirleyHiew@lkkauto.com](mailto:ShirleyHiew@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI18001702/Uub3q2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 31-07-2018		
		Code : CTI		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBA 7383U	Veh. Inspected	SKS 9626E	
Policy No.	DMCVSN1803041800	Coverage (\$)	0.00	
Claim No.	SNM18D00515C02/3/LKKDS	Excess (\$)	0.00	
Assign From		Assign Date	29/01/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	SUBARU XV (A)	c.c	1600	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JF1GP3KC5EG147097	Colour	GREY	
Odometer	74142	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/55Z R17	ROADSTONE	6 mm	
L/H Front Tyre	225/55Z R17	ROADSTONE	6 mm	
R/H Rear Tyre	225/55Z R17	ROADSTONE	6 mm	
L/H Rear Tyre	225/55Z R17	ROADSTONE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	25/01/2018	Inspection Date	29/01/2018	
Survey held at	HUP MOTOR TRADING & SERVICE BLK 9004 TAMPINES ST 93 #01-120 SINGAPORE 528838			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 9626E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT BUMPER	DISTORTED	659.40	659.40
8	FRONT BUMPER CLIPS @\$3.40	NECESSARY	27.20	27.20
1	FRONT BUMPER TOWING BAR COVER	TORN	18.00	18.00
2	FRONT BUMPER O/S & N/S SIDE RETAINER @\$26.00	O/S BENT	52.00	26.00
1	FRONT BUMPER O/S FOG LAMP GARNISH	NO SUCH PARTS	31.00	-
1	FRONT BUMPER SPONGE DAMPER	TORN	79.20	79.20
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	288.00	-
1	O/S HEAD LAMP ASSY	SERVICEABLE	900.00	-
1	FRONT GRILLE FRAME MOULDING	SCRATCHED	304.00	304.00
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	520.00	-
1	FRONT NUMBER PLATE & FRAME	SCRATCHED	50.00	50.00
	LESS 20% DISCOUNT		-585.76	-232.76
			2,343.04	931.04
<b>LABOUR</b>				
	TO WIRING CHECK UP & ADJUST HEADLIGHT ALIGNMENT .		50.00	20.00
	TO REMOVE & REFIX AIR COND PARTS & REFILL RA134 GAS.	NOT NECESSARY	150.00	-
	TO CHECK & ADJUST FRONT WHEEL ALIGNMENT & BALANCING.	NOT NECESSARY	120.00	-
	TO RESPRAY TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS.	NOT NECESSARY	50.00	-
	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS ,TO JACK,STRAIGHTEN & KNOCKING OUT FRONT FENDER & NECESSARY PARTS ,TO WELD,RENEW & ALIGN ABOVE PARTS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT AND FRONT SUPPORT PANEL .		750.00	400.00
	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS.		900.00	600.00
			2,020.00	1,020.00
<b>GRAND TOTAL</b>			<b>4,363.04</b>	<b>1,951.04</b>

Report Ref No. CC6/CT118001702/Uub3q2



RECOMMENDED COST OF REPAIRS			1,951.04
-----------------------------	--	--	----------

Report Ref No. CC6/CT118001702/Uub3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.