



潘發展私人有限公司
A. S. PHOON PTE LTD
'cos no one else

Head Off : 399, Changi Road S'pore 419846. Tel: (65) 6747 0770 Fax: (65) 6841 1263
Ubi : Blk 3007 #01-432/436 Ubi Road 1, S'pore 408701. Tel: (65) 6744 0770 Fax: (65) 6742 0250
Toh Guan : Blk 36 Toh Guan Road East #01-35 S'pore 608580 Tel: (65) 6515 0770 Fax: (65) 6515 0779
Website : www.asphoon.com Email: Enquiry@asphoon.com Co Reg No: 197701213H

FR5690J RXZ BLUE REPAIR ESTIMATE 29JAN2018

ITEM	DESCRIPTION	AMOUNT SGD
1	GEAR PEDAL	\$68.00 <i>bt✓</i>
2	BRAKE LEVER	\$25.00 <i>bt✓</i>
3	FUEL TANK ASSY	\$390.00 <i>Rx</i>
4	SIDE MIRRORS	\$50.00 <i>bro✓</i>
5	FRONT COWLING	\$85.00 <i>bro✓</i>
6	WINDSHIELD	\$38.00 <i>mis✓</i>
7	FRONT LICENCE PLATE	\$15.00 <i>mis✓</i>
8	STAY, FRONT COWLING	\$85.00 <i>bt✓</i>
9	METER ASSY	\$350.00 <i>ant✓</i>
10	CABLE METER	\$25.00 <i>mis✓</i>
11	CLUTCH LEVER	\$20.00 <i>bro✓</i>
12	CLUTCH LEVER HOLDER	\$38.00 <i>one✓</i>
13	HANDLEBAR	\$110.00 <i>bt✓</i>
14	SWITCH LH	\$95.00 <i>ant✓</i>
15	HANDLE GRIP	\$20.00 <i>ent✓</i>
16	BALANCER	\$40.00 <i>ant✓</i>
17	FRONT FORK CROWN	\$80.00 ?
18	FRONT FORK ASSY RH & LH	\$440.00 ?
19	STEM STEERING	\$145.00 ?
20	CONE BEARING SET	\$60.00 ?
21	LOWER SPOILER	\$60.00 <i>ant✓</i>
22	GEAR PEDAL	\$65.00 <i>x</i>
23	SIDE STAND	\$35.00 <i>bt✓</i>
24	SPRING SIDE STAND	\$25.00 <i>x</i>
25	MAINSTAND	\$105.00 <i>Rx</i>
26	FRONT FOOTREST ASSY	\$68.00 <i>bro✓</i>
27	FRONT FOOTREST BRACKET	\$90.00 <i>one✓</i>
28	REAR FOOTREST	\$38.00 <i>ant✓</i>
29	REAR WHEEL AXLE	\$25.00 <i>del✓</i>
30	REAR SIDE FAIRING LH	\$125.00 <i>ent✓</i>
31	REAR LICENCE PLATE	\$28.00 <i>bt✓</i>
32	SPRAY PAINTING	\$450.00 <i>300</i>
33	WORKMANSHIP	\$350.00 <i>250</i>
34	TRANSPORTATION TP-IDAC-BIKESHOP	\$100.00 <i>80</i>
35	BODY CHASSIS REPAIR	\$280.00 <i>180</i>
36	TRANSPORTATION 2 WAY TO REPAIR CHASSIS	\$100.00 <i>80</i>

TOTAL \$4,123.00

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

5 days
hurry
Resurvey after repair
29/1/18 @ 1715
Tanpin 97495749