

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Joslin Lim

Date: 31 Jan 2018

Preliminary Advice

Vehicle No	: SLG4485D	Accident Date	: 25/01/2018
Make	: VOLKSWAGEN JETTA TSI	Policy No.	: A28832438AVW
Assignment Date	: 29/01/2018	Excess	: S\$500.00
Date of Inspection	: 30/01/2018	Est. Duration of Repair	: 8.00
Inspection At	: VOLKSWAGEN CENTRE SINGAPORE (MACPHERSON) (HQ) VOLKSWAGEN CENTRE SINGAPORE (MACPHERSON), 1 KAMPONG AMPAT SINGAPORE 368314		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,710.95
Revised Amount	:S\$	10,322.21
Check Items (Estimated)	:S\$	6,817.52
Total	:S\$	17,139.73

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	92,000.00
COE / PARF Rebate	:S\$	59,215.00
Salvage Value	:S\$	
Margin for Repair	:S\$	32,785.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.