

Surveyor

REF:

CC3/ALH18001750/Ad

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bel. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SGK93R

Yr Regn:

2016 March

Type: M.Cab / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A4

cc 1395

Colour

white

A/C

Insured / Std / NI / NA

Sp Reading

18759

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WAU222F406A039359

Gen Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16

R:

205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal

06

mm

R/Bal

06

mm

L/Bal

06

mm

L/Bal

06

mm

D.O.A

D.O.I

29/01/18

Survey held at

Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

OD A16

SGK93R - 15/15810011111 / Rvk3

DN 16-03-2010

20/1/18 @ 4.05pm Verat to Victor via Message

31/1/18 @ 1.09pm Lois Chang informed c/a via Message

01/2/18 @ 12.13pm Informed Kae Seng c/a & EX: \$600 by email

11/2/18 @ 5.29pm Final 15810011111, 6 days. Confirmed with Mr 000 (Fed 55848.72, 31/-)

RECEIVED 23 MAR 2018

Date/Time: File Pass to?

☐

: Prelim Report

11/2/18 by Mr

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair:

6

Resurvey No. of Trip:

Survey Fee:

Transportation

Add Fee:

☐

: Site Insp

\$

☐

: Interview

\$

☐

: Tech Insp

\$

☐

: Weekend

\$

) \$ + RS \$

) Photo

) Chair

TOTAL

Report Format:

MOB-OD

Lump Sum (I.B.):

\$ 12747.28

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 1 February 2018 12:13 PM
To: 'Claims Department'; SUR
Subject: RE: SGK 93 R Own Damage Claims (Vehicle IN)

Dear Kee Siang,

As instructed by our client AIG , please proceed to repair the insured vehicle **SGK 93R (Excess \$600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Department [mailto:claims@premiumauto.com.sg]
Sent: Thursday, 1 February 2018 12:05 PM
To: SUR <sur@lkkauto.com>
Cc: 'Claims' <claims@premiumauto.com.sg>
Subject: RE: SGK 93 R Own Damage Claims (Vehicle IN)

Dear all,

Kindly assist for above mention case.

Owner had receive call from AIG and understand approval have been given.

Kindly let us have the approval.

Thank you and have a nice day ahead !

Best Regards,

Claims Advisor

Kee Siang

Premium Automobiles Pte Ltd (Reg No 189902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183 m. +65 8777 0600

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		
1	27 Jan 2018 17:23	Cim Veh Model Changed			[] Merimen Administrator
2	27 Jan 2018 17:23	Cim Created	Reg No: SGK93R, Policy No: 2100459496-01000, Acct Date: 2018/01/26, Claim Type: SC, Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG), Ins.Status => Notification, Created from SAS:MPA118013381		[I] Merimen Administrator
3	29 Jan 2018 17:31	Cim Registration Modified	Setl.Type:3->0, Claim Type:SC->OD.		[] CATHERINE CHONG KAI LING
4	29 Jan 2018 17:31	Adj Cim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)		[] CATHERINE CHONG KAI LING
5	29 Jan 2018 17:31	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):		[A] CATHERINE CHONG KAI LING
6	29 Jan 2018 17:31	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/02/07		[A] CATHERINE CHONG KAI LING
7	29 Jan 2018 17:31	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.		[A] CATHERINE CHONG KAI LING
8	29 Jan 2018 17:31	Cim Registration Modified	Rep:1137->200611.		[A] CATHERINE CHONG KAI LING
9	29 Jan 2018 17:31	Cim Veh Model Changed	(204616) AUDI A4 1.4 TFSI S TRONIC (A).		[A] CATHERINE CHONG KAI LING
10	29 Jan 2018 17:32	Adj Adjuster Assigned	[None] -> ADRIAN LING		[A] CATHERINE CHONG KAI LING
11	30 Jan 2018 15:52	Adj Rpt Initiated			[A] SHIAU CHAN
12	30 Jan 2018 15:52	Cim Details Notified			[A] SHIAU CHAN
13	30 Jan 2018 16:00	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/02/07		[A] SHIAU CHAN
14	30 Jan 2018 16:05	Adj Mandate Request	Cur.Req:15434.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.		[A] SHIAU CHAN
15	31 Jan 2018 09:28	Cim Registration Modified	Init.Est.->5,000 - 6,000. Excess: -> 600.00, 2F Remarks: -> Not Applicable. GST: -> 7.00.		[I] Loo, Tong Shing
16	31 Jan 2018 09:28	Label Added	(20226):Coverage Confirmed.		[A] Merimen Administrator
17	31 Jan 2018 13:09	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/02/07. Mandate Remarks: RE-INSPECTION REQUIRE ON SUPPLEMENTARY PARTS AND HIDDEN PARTS.		[I] Chang, Lois-KL
18	31 Jan 2018 13:09	Adj Mandate Set	Approved:14567.00:RE-INSPECTION REQUIRE ON SUPPLEMENTARY PARTS AND HIDDEN PARTS.Reinsp:Yes.		[I] Chang, Lois-KL

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1709655	30/01/2018 15:52	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SGK93R		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 30 Jan 2018

Preliminary Advice

Vehicle No	: SGK93R	Accident Date	: 26/01/2018
Make	: AUDI A4	Policy No.	: 2100459496-01000
Assignment Date	: 29/01/2018	Excess	: S\$0.00
Date of Inspection	: 29/01/2018	Est. Duration of Repair	: 6.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s portion, undercarriage and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,596.00
Revised Amount	:S\$	14,567.00
Check Items (Estimated)	:S\$	867.00
Total	:S\$	15,434.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	120,000.00
COE / PARF Rebate	:S\$	59,056.00
Salvage Value	:S\$	
Margin for Repair	:S\$	60,944.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4326C
Vehicle Details	
Vehicle No.:	SGK93R
Vehicle to be Exported:	No
Intended De-registration Date:	30 Jan 2018
Vehicle Make:	AUDI
Vehicle Model:	A4 1.4 TFSI S TRONIC
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	CVN004995
Chassis No.:	WAUZZZF40GA039359
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$32,076.00
Original Registration Date:	31 Mar 2016
First Registration Date:	31 Mar 2016
Transfer Count:	0
Actual ARF Paid:	\$26,907.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Mar 2026
PARF Rebate Amount:	\$20,180.00
Intended COE Rebate Details	
COE Expiry Date:	30 Mar 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$48,002.00
COE Rebate Amount:	\$38,876.00
Total Rebate Amount:	\$59,056.00

The information contained herein is correct as at 30 Jan 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/01/2018 13:25
Date Of Accident	26/01/2018 18:45
Exact Location Of Accident	ALONG AMK AVE 6 TURNING TO AVE 9
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGK93R
Insured/Policyholder	
Name Of Registered Owner	LEE HENG THYE
NRIC No	S0044326C
Email Address	YWCT521@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-90077819
Alternative Phone No	OFFICE-64824679

Vehicle Particulars

Manufacturer	AUDI
Model	A4 SEDAN 1.4 TSFI S TRONIC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100459496-01000
Cover Note Number	

Driver


Name of Driver	LEE HENG THYE
NRIC No	S0044326C
Date Of Birth	09/01/1946
Occupation	INDOOR
Date Of Driving Pass	15/03/1966
Driving Experience	51 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90077819
Fax Number	
Contact Number	OFFICE-64824679
Email Address	YWCT521@YAHOO.COM.SG

No. Of Passenger (Including Driver)

Sketch Plan #2

SKETCH PLAN

A: G4K 93R
B: SLD 1261T



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At about 6:40 pm (26/01/2018), I was travelling along Hin Chee Kang to the direction of Ang Mo Kio Ave 6. As I was travelling travelling left to Ang Mo Kio Ave 6, trying to keep to the right lane travelling right to Ang Mo Kio Ave 9. My vehicle was suddenly hit by the other party vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Policyholder's Signature
Name: Lim Ee Seng
NRIC/IN No.: 255256114



CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1969 (MALAYSIA)

M.X.1

AUDI AUTO PROTECTOR

OWN DAMAGE EXCESS S\$600.00 (1)
WINDSCREEN EXCESS S\$100.00

(for policies with effect from 1st November 2002)

CERTIFICATE NO. 2100459496-01000

SUM INSURED Market Value
INSURING WITH COE/PAF Yes
SGK93R

1) VEHICLE REGISTRATION NO.

2) NAME OF INSURED

LEE HENG THYE

3) EFFECTIVE DATE OF THE COMMENCEMENT
OF INSURANCE FOR THE PURPOSES OF THE ACT

31 Mar 2017

4) DATE OF EXPIRY OF INSURANCE

30 Mar 2018

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE *
SUBJECT TO AGE CONDITION :All Age Condition

a) The Insured.

b) Any other person who is driving on the Insured's order or with his permission.

This policy will indemnify the insured or any authorised driver only if he/she meets the age conditions.

A Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00, in addition to the Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle

6) LIMITATION AS TO USE *

Use only for social, domestic and pleasure purposes and for the Insured's business.

The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / AUDI AUTHORISED REPAIRERS

1. Audi Customer Service Center - 55 Ubi Road 1 (Tel: 63662323)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501)

4. Ethoz - 30 Bukit Batok Cres (Tel: 66547777) 5. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only

6. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560) 7. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)

8. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)

10. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE Loss Of Use 15 days Replacement Car only for repairs at Audi Customer Service Centre

NAMED DRIVER NA

HIRE PURCHASE COMPANY DBS BANK LTD
/ EMPLOYER'S LOAN

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 2 Mar 2017

AIG Asia Pacific Insurance Pte. Ltd.

504125-206
PREMIUM LEASING - SP
281 ALEXANDRA ROAD
AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

AUTHORISED REPRESENTATIVE

ORIGINAL

SSCSAN

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0119/2018/GW
Date	:	27-Jan-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Lee Heng Thye
Address	:	26 Cactus Crescent Singapore 809728
Telephone	:	HP +65 90077819
Type of Claim	:	Own Damage Claims
Policy No.	:	2100459496-01000
Vehicle No	:	SGK 93 R
Model Code	:	Audi A4 Sedan 1.4 TFSI S
Model / Year	:	Mar-16
Engine No	:	CVN 004995
Chassis No	:	WAUZZZF40GA039359
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	26-Jan-18
Place of Accident	:	Along AMK AVE 6 Turning To AVE 9

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGK 93 R

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlamps, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓
2	To remove all front fittings, include both headlamps. Remove and renew bumper, radiator grille, rhs front fender and connecting parts. Alin to position, reinstall all parts removed.	\$ 2,400.00	1500 ✓
3	To renew rhs front wheel and carry out alignment.	S/N \$ 280.00	✓
4	To respray paint on front bumper, rhs front fender, bonnet.	\$ 2,200.00	1650 ✓
5	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 5,432.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGK 93 R.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>del</i>	\$ 1,849.00	<i>1479.70</i>
2	FRONT BUMPER AIR GUIDE GRILLE-RH <i>del</i>	\$ 118.00	<i>+</i>
3	FRONT BUMPER GRILLE <i>del</i>	\$ 171.00	<i>+</i>
4	FRONT BUMPER CLOSING ELEMENT <i>del</i>	\$ 180.00	<i>+</i>
5	FRONT BUMPER AIR GUIDE-RH <i>del</i>	\$ 73.00	<i>?</i>
6	FRONT BUMPER SECURING STRIP <i>del</i>	\$ 30.00	<i>+</i>
7	RADIATOR GRILLE <i>del</i>	\$ 972.00	<i>+</i>
8	FRONT BUMPER BRACKET LOCK CARRIER <i>del</i>	\$ 118.00	<i>94</i>
9	FRONT BUMPER SUPPORT-RH <i>del</i>	\$ 24.00	<i>?</i>
10	FOAM FILLER PIECE <i>del</i>	\$ 107.00	<i>89.70</i>
11	FRONT BUMPER GUIDE SECTION-RH <i>del</i>	\$ 32.00	<i>75.36</i>
12	FOAM FILLER PIECE - RH <i>del</i>	\$ 15.00	<i>?</i>
13	FRONT BUMPER TOP COVER <i>del</i>	\$ 109.00	<i>+</i>
14	FRONT FENDER -RH <i>del</i>	\$ 665.00	<i>532</i>
15	FRONT FENDER ATTACHMENT PARTS-RH <i>del</i>	\$ 45.00	<i>+</i>
16	FRONT FENDER BRACKET-RH <i>del</i>	\$ 31.00	<i>24.16</i>
17	FRONT FENDER CLOSING ELEMENT-RH <i>del</i>	2 \$ 73.00	<i>?</i>
18	FRONT FENDER BRACE-RH <i>del</i>	\$ 103.00	<i>82.40</i>
19	FRONT FENDER BRACKET-RH <i>del</i>	\$ 27.00	<i>?</i>
20	FRONT FENDER DEFORMATION ELEMENT BRACKET-RH <i>del</i>	\$ 43.00	<i>24.16</i>
21	FRONT FENDER COVER-RH <i>del</i>	\$ 13.00	<i>9.68</i>
SUB-TOTAL SPARE PARTS CHARGES		\$ 4,798.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGK 93 R.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
22	FRONT WHEEL SPOILER-RH <i>Porn</i>	\$ 63.00	? 50.16 ✓
23	FRONT STONE CHIP GUARD-RH <i>in</i>	\$ 44.00	✓ 34.56
24	FRONT FENDER SPOILER-RH <i>Not New</i>	\$ 31.00	? X
25	FRONT WHEEL HOUSING LINER-RH <i>Rehnd</i>	\$ 209.00	✓ 167.20
26	WHEEL HOUSING LINER ATTACHMENT PARTS <i>Not New</i>	\$ 78.00	? X
27	LED HEADLIGHT-RH <i>cut cracked</i>	\$ 6,973.00	✓ 5,473.40
28	FRONT ALUMINIUM TRIM-RH <i>cut</i>	\$ 563.00	✓ 450
29	FRONT NO.PLATE <i>Not a</i>	S/N \$ 25.00	✓
30	SUNDRIES <i>Not</i>	\$ 380.00	? 118.80 ✓
TOTAL SPARE PARTS CHARGES		\$ 13,164.00	
TOTAL LABOUR CHARGES		\$ 5,432.00	
GRAND TOTAL		\$ 18,596.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian*
Surveyed Date : *29/01/18*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, 06 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0119/2018/GW
Date	:	27-Jan-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

6 days - ok - jb - 19 Mar 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Lee Heng Thye
Address	:	26 Cactus Crescent Singapore 809728
Telephone	:	HP +65 90077819
Type of Claim	:	Own Damage Claims
Policy No.	:	2100459496-01000
Vehicle No	:	SGK 93 R
Model Code	:	Audi A4 Sedan 1.4 TFSI S
Model / Year	:	Mar-16
Engine No	:	CVN 004995
Chassis No	:	WAUZZZF40GA039359
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	26-Jan-18
Place of Accident	:	Along AMK AVE 6 Turning To AVE 9

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGK 93 R

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlamps , horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$	360.00	\$ 360.00
2	To remove all front fittings, include both headlamps. Remove and renew bumper, radiator grille, rhs front fender and connecting parts. Alin to position , reinstall all parts removed .	\$	2,400.00	\$ 1,500.00
3	To renew rhs front wheel and carry out alignment.	S/N \$	280.00	\$ 280.00
4	To respray paint on front bumper, rhs front fender, bonnet.	\$	2,200.00	\$ 1,650.00
5	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 5,432.00</u>	<u>\$ 3,982.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGK 93 R.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 1,849.00	\$ 1,479.20
2	FRONT BUMPER AIR GUIDE GRILLE-RH	\$ 118.00	
3	FRONT BUMPER GRILLE	\$ 171.00	
4	FRONT BUMPER CLOSING ELEMENT	\$ 180.00	
5	FRONT BUMPER AIR GUIDE-RH	\$ 73.00	
6	FRONT BUMPER SECURING STRIP	\$ 30.00	
7	RADIATOR GRILLE	\$ 972.00	
8	FRONT BUMPER BRACKET LOCK CARRIER	\$ 118.00	\$ 94.00
9	FRONT BUMPER SUPPORT-RH	\$ 24.00	
10	FOAM FILLER PIECE	\$ 107.00	\$ 85.20
11	FRONT BUMPER GUIDE SECTION-RH	\$ 32.00	\$ 25.36
12	FOAM FILLER PIECE - RH	\$ 15.00	
13	FRONT BUMPER TOP COVER	\$ 109.00	
14	FRONT FENDER -RH	\$ 665.00	\$ 532.00
15	FRONT FENDER ATTACHMENT PARTS-RH	\$ 45.00	
16	FRONT FENDER BRACKET-RH	\$ 31.00	\$ 24.16
17	FRONT FENDER CLOSING ELEMENT-RH	2 \$ 73.00	
18	FRONT FENDER BRACE-RH	\$ 103.00	\$ 82.40
19	FRONT FENDER BRACKET-RH	\$ 27.00	
20	FRONT FENDER DEFORMATION ELEMENT BRACKET-RH	\$ 43.00	\$ 34.16
21	FRONT FENDER COVER-RH	\$ 13.00	\$ 9.68
SUB-TOTAL SPARE PARTS CHARGES		\$ 4,798.00	\$ 2,366.16

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Material List for Accident Vehicle Regn No. SGK 93 R.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Netf.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SGK 93 R

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0119/2018/MAS

29 March 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SGK 93 R, Audi A4 Sedan 1.4 TFSI S-Tro

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

With reference to the above-mentioned vehicle, no. **SGK 93 R**, claimant, **Mr. Lee Heng Thye**, please find the related document per attached.

1. A copy of the Original invoice no. 85012297 – S\$12,997.59
2. A copy of the Discharge Voucher duly signed by client.

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SGK 93 R

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: **S0044326C**

Name: **LEE HENG THYE**

Birth Date: **09 Oct 1946**
Issue Date: **06 May 2003**

000464977K




REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S0044326C**



Name: **LEE HENG THYE**

Race: **CHINESE**
Date of Birth: **09-10-1946** Sex: **M**
Country of Birth: **SINGAPORE**




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES

Class 3 **Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms**

PASS DATE: **15 Mar 1996**

NP 428A

License No: **S0044326C**



0671469



NRC No: **S0044326C**



Blood Group: **O+** Date of Issue: **29-06-1994**

Address:
**26 CACTUS CRESCENT
SINGAPORE 2880**



CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.X.1

AUDI AUTO PROTECTOR

CERTIFICATE NO. 2100459496-01000

OWN DAMAGE EXCESS S\$600.00 (1)
WINDSCREEN EXCESS S\$100.00

(for policies with effect from 1st November 2002)

SUM INSURED Market Value
INSURING WITH COE/PARF Yes

- 1) VEHICLE REGISTRATION NO. SGK93R
2) NAME OF INSURED LEE HENG THYE
3) EFFECTIVE DATE OF THE COMMENCEMENT OF INSURANCE FOR THE PURPOSES OF THE ACT 31 Mar 2017
4) DATE OF EXPIRY OF INSURANCE 30 Mar 2018
5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE *
SUBJECT TO AGE CONDITION :All Age Condition

- a) The Insured.
b) Any other person who is driving on the Insured's order or with his permission.
This policy will indemnify the insured or any authorised driver only if he/she meets the age conditions.
A Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00, in addition to the Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE *

Use only for social, domestic and pleasure purposes and for the Insured's business.
The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / AUDI AUTHORISED REPAIRERS

1. Audi Customer Service Center - 55 Ubi Road 1 (Tel: 63662323)
APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)
2. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501)
4. Ethoz - 30 Bukit Batok Cres (Tel: 66547777) 5. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only
6. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560) 7. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)
8. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)
10. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE Loss Of Use 15 days Replacement Car only for repairs at Audi Customer Service Centre

NAMED DRIVER NA

HIRE PURCHASE COMPANY DBS BANK LTD
/ EMPLOYER'S LOAN

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 2 Mar 2017

AIG Asia Pacific Insurance Pte. Ltd.

504125-206
PREMIUM LEASING - SP
281 ALEXANDRA ROAD
AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

AUTHORISED REPRESENTATIVE

ORIGINAL

SECTION



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6886 2223
Main Telefax: 6471 2733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6886 2223
Telefax: 6475 1023

UBi Service Centre
55 Ubi Road 1
Singapore 408620
Telephone: 6106 2723

Customer Service
Service Appointment
24-hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6366 2323
6828 1233

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 1 14:50

AIG ASIA PACIFIC INSURANCE PTE LTD	Invoice: 85012297	Account: A0006 (T 0)
MOTOR CLAIM DEPT	Date : 28/03/2018	AIG ASIA PACIFIC INSURANCE PTE LTD
AIG BUILDING	Order : SGK0093R	MOTOR CLAIM DEPT
78 SHENTON WAY	Term : 30	AIG BUILDING
#07-16		78 SHENTON WAY
SINGAPORE 079120 079120		#07-16
		SINGAPORE 079120

Regn No.: SGK0093R (V 29354)	Regn Date: 31/03/2016	Mileage: 18761	WIP No.: 53830
Model: A4 SEDAN 1.4 TFSI S tronic	Chassis: WAUZZZF40GA039359	Engine: CVN 004995	Dept: U
VSB No.:			
You have been assisted by :- UB-Carrine	()		

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	368.00	1.00	368.00
Q	EXC	M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	M: TO REMOVE ALL FRONT FITTINGS, INCLUDE BOTH HEADLAM REMOVE AND RENEW BUMPER, RHS FRONT FENDER AND CONNECTING PARTS. ALIGN TO POSITION, REINSTALL ALL PARTS REMOVED.	1500.00	1.00	1,500.00
S	BODYWORK	M: TO RENEW RHS FRONT WHEEL AND CARRY OUT ALIGNMENT.	280.00	1.00	280.00
S	BODYWORK	M: TO RESPRAY PAINT ON FRONT BUMPER, RHS FRONT FENDER AND BONNET.	1650.00	1.00	1,650.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK.	192.00	1.00	192.00

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159338
Main Telephone: 6836 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159338
Telephone: 6888 2223
Telefax: 6475 1623

Ubi Service Centre
55 Ubi Road 1
Singapore 408020
Telephone: 6388 2223
Telefax: 6388 2223

Customer Service
Service Appointment
24-hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6388 2223
6828 1233

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 2 14:50

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012297 Date : 28/03/2016 Order : SGH0093R Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SGH0093R (V 29354) Regn Date: 31/03/2016 Mileage: 18761 WIP No.: 53830

Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF40GA039359 Engine: CVN 004995 Dept: U

USB No.:

You have been assisted by :- UB-Carrine ()

		Details	Qty	Unit Price	Amount
X	ABW0601025B	RIM 16" CAM	1.00	562.50	450.00
X	ABW0821654	COVER	1.00	12.10	9.68
X	ABW0941774A	HEADLIGHT	1.00	6973.00	5,578.40
X	ABW0821172A	WHEEL HOUS	1.00	209.00	167.20
X	ABW0853888A	SPOILER	1.00	62.70	50.16
X	ABW0821106A	FENDER	1.00	665.00	532.00
X	ABW0807550A	FOAM INSER	1.00	106.50	85.20
X	ABW0807065C GRU	COVER	1.00	1849.00	1,479.20
X	ABW0821468	BRACKET	1.00	30.20	24.16
X	ABW0821470	BRACKET	1.00	42.70	34.16
X	ABW0807284	GUIDE	1.00	31.70	25.36
X	ABW0821032	PLATE	1.00	43.20	34.56
X	ABW0821136C	SUPPORT	1.00	103.00	82.40
X	ABW0823746	COVER	1.00	19.20	15.36
X	ABW0807277	STRIP	2.00	29.90	47.84
X	ABW0853824A 9B9	STONEGUARD	1.00	43.20	34.56
X	ABW0820582B	COVER	1.00	26.30	21.04
X	ABW0807771	BRACKET	1.00	117.50	94.00

Parts 8,765.28
Labour 0.00
Sublet 3,982.00
Menus 0.00
Lubricant 0.00

Sub-Total 12,147.28

7% GST 850.31

Grand Total 12,997.59



28/3

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SGK 93 R

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0119/2018/GW
8 February 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages


RE : CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 Sedan 1.4 TFSI S-tronic
Vehicle Chassis No. : WAUZZZF40GA039359
Vehicle Regn No. : SGK 93 R
Vehicle Mileage : 18759 KM
Vehicle Owner : Mr. Lee Heng Thye
Certificate No : 2100459496-01000
Policy Excess : \$642 (inclusive 7% GST)
Accident Date : 26-January-18
Place : Along Amk Ave 6 Turning To Ave 9
Repair Cost : \$ 12,997.59
WIP No. : 53830
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time :
Date : 2/3/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jan 2018 15:52		29 Jan 2018 17:31 Edit Adj Rpt	S\$12,747.28 Edit Estimates	S\$12,747.28 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: LEE HENG THYE , ID: S0044326C, Tel: +6590077819, Email: ywct521@yahoo.com.sg									
Vehicle Reg. No.: SGK93R		Date of Loss: 26/01/2018 18:00 - :59 [21 Months and 26 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 0971503155SG		Policy/Cover Note No.: 2100459496-01000 (Comprehensive)							
		Excess: S\$600.00							
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 07/02/2018]									
Driver/Custodian: LEE HENG THYE (72 / Male), NRIC: S0044326C, Tel: +6590077819									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (31/01/2018): Alert - Adj Mandate Approved (S\$14567.00) - SGK93R - Claim Handler: Loo, Tong Sh... - AIG_SG (31/01/2018): SGK93R / OD / 26/01/2018 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGK93R (0971503155SG)
 OD
 Jan 26 2018 6:45PM
 [LEE HENG THYE]
 Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Video															1 per page		v	☒		
No	Finalized On		Premium Automobiles Pte Ltd (UBI)												Thumbnail		Print			
1	27/01/18 17:22		Video - Accident [Linked Accident Report Documents]												1		Load AVI			
Assessment Reports															1 per page		v	☒		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	30/01/18 16:00		Adjuster Immediate Advice												1		Load HTM			
Photos/Images															3 per page		v	☒		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	30/01/18 16:04		General View												1		Load JPG			
2	30/01/18 16:04		Chassis Number												1		Load JPG			
3	30/01/18 16:04		General View												1		Load JPG			
4	30/01/18 16:04		General View												1		Load JPG			
5	30/01/18 16:04		General View												1		Load JPG			
6	30/01/18 16:04		General View												1		Load JPG			
7	30/01/18 16:04		General View												1		Load JPG			
8	30/01/18 16:04		General View												1		Load JPG			
9	30/01/18 16:04		General View												1		Load JPG			
10	30/01/18 16:04		General View												1		Load JPG			
11	30/01/18 16:04		General View												1		Load JPG			
12	30/01/18 16:04		General View												1		Load JPG			
13	30/01/18 16:04		General View												1		Load JPG			
14	30/01/18 16:04		General View												1		Load JPG			
15	30/01/18 16:04		General View												1		Load JPG			
16	30/01/18 16:04		General View												1		Load JPG			
17	30/01/18 16:04		General View												1		Load JPG			
18	30/01/18 16:04		General View												1		Load JPG			
19	30/01/18 16:04		General View												1		Load JPG			
20	30/01/18 16:04		General View												1		Load JPG			
21	30/01/18 16:04		General View												1		Load JPG			
22	30/01/18 16:04		General View												1		Load JPG			
23	30/01/18 16:04		General View												1		Load JPG			
24	30/01/18 16:04		General View												1		Load JPG			
25	30/01/18 16:04		General View												1		Load JPG			
26	30/01/18 16:04		General View												1		Load JPG			
27	02/04/18 11:57		Reinspection Photo												1		Load JPG			
28	02/04/18 11:57		Reinspection Photo												1		Load JPG			
29	02/04/18 11:57		Reinspection Photo												1		Load JPG			
30	02/04/18 11:57		Reinspection Photo												1		Load JPG			

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/01/18 16:04	Singapore Accident Statement	 Load PDF	
2	30/01/18 16:04	Certificate of Insurance	 Load PDF	
3	30/01/18 16:04	Driver's Driving License	 Load PDF	
4	30/01/18 16:04	WORKSHOP ESTIMATE	 Load PDF	
5	03/04/18 14:01	WORKSHOP INVOICE	 Load PDF	
6	03/04/18 14:01	DISCHARGE VOUCHER	 Load PDF	

Linked Accident Report Documents

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	27/01/18 17:22	Video - Accident	 Load AVI	
Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	27/01/18 17:23	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	27/01/18 17:17	Accident Photo	 Load JPG	☒
2	27/01/18 17:17	Accident Photo	 Load JPG	☒
3	27/01/18 17:17	Accident Photo	 Load JPG	☒
4	27/01/18 17:17	Accident Photo	 Load JPG	☒
5	27/01/18 17:17	Accident Photo	 Load JPG	☒
6	27/01/18 17:17	Accident Photo	 Load JPG	☒
7	27/01/18 17:17	Accident Photo	 Load JPG	☒
8	27/01/18 17:17	Accident Photo	 Load JPG	☒
9	27/01/18 17:17	Accident Photo	 Load JPG	☒
10	27/01/18 17:17	Accident Photo	 Load JPG	☒
11	27/01/18 17:17	Accident Photo	 Load JPG	☒
12	27/01/18 17:17	Accident Photo	 Load JPG	☒
13	27/01/18 17:17	Accident Photo	 Load JPG	☒
14	27/01/18 17:17	Accident Photo	 Load JPG	☒
15	27/01/18 17:17	Accident Photo	 Load JPG	☒
16	27/01/18 17:17	Accident Photo	 Load JPG	☒
17	27/01/18 17:17	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	27/01/18 17:20	Sketch Plan	 Load JPG	☒
2	27/01/18 17:20	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note:

Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18001750/AQBQ2

Date: 03/04/2018

REFERENCE

Insured/Claimant: LEE HENG THYE Policy No: 2100459496-01000
Date of Loss: 26/01/2018 Nature of Claim: OD Claim No: 0971503155SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGK93R**
Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A) Engine No: CVN004995
Reg. Date: 31/03/2016 (Man. Year: 2016) Chassis No: WAUZZZF40GA039359
Colour: White Odometer: 18759 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$120,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,164.00	8,765.28	4,398.72	33.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,432.00	3,982.00	1,450.00	26.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,596.00	12,747.28	5,848.72	31.45
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	17,996.00	12,147.28	5,848.72	32.50
+ GST 7.00/7.00% (S\$)	1,259.72	850.31	409.41	32.50
Nett Amount (S\$)	19,255.72	12,997.59	6,258.13	32.50

INSPECTION

Date of Assignment: 29/01/2018
Date Inspected: 29/01/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,849.00 FS	*1,479.20 FS
2	1		*FRONT BUMPER AIR GUIDE GRILLE-RH	Not Necessary	118.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE	Not Necessary	171.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	180.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE RH	Not Necessary	73.00 FS	*- FS
6	1		*FRONT BUMPER SECURING STRIP	Not Necessary	30.00 FS	*- FS
7	1		*RADIATOR GRILLE	Not Necessary	972.00 FS	*- FS
8	1		*FRONT BUMPER BRACKET LOCK CARRIER	Cracked	118.00 FS	*94.00 FS
9	1		*FRONT BUMPER SUPPORT RH	Not Necessary	24.00 FS	*- FS
10	1		*FOAM FILLER PIECE	Necessary	107.00 FS	*85.20 FS
11	1		*FRONT BUMPER GUIDE SECTION -RH	Damaged	32.00 FS	*25.36 FS
12	1		*FOAM FILLER PIECE -RH	Not Necessary	15.00 FS	*- FS
13	1		*FRONT BUMPER TOP COVER	Not Necessary	109.00 FS	*- FS
14	1		*FRONT FENDER -RH	Distorted	665.00 FS	*532.00 FS
15	1		*FRONT FENDER ATTACHMENT PARTS-RH	Not Necessary	45.00 FS	*- FS
16	1		*FRONT FENDER BRACKET -RH	Bent	31.00 FS	*24.16 FS
17	2		*FRONT FENDER CLOSING ELEMENT -RH	Not Necessary	73.00 FS	*- FS
18	1		*FRONT FENDER BRACE-RH	Bent	103.00 FS	*82.40 FS
19	1		*FRONT FENDER BRACKET -RH	Not Necessary	27.00 FS	*- FS
20	1		*FRONT FENDER DEFORMATION ELEMENT BRACKET -RH	Necessary	43.00 FS	*34.16 FS
21	1		*FRONT FENDER COVER-RH	Necessary	13.00 FS	*9.68 FS
22	1		*FRONT WHEEL SPOILER -RH	Torn	63.00 FS	*50.16 FS
23	1		*FRONT STONE CHIP GUARD-RH	Necessary	44.00 FS	*34.56 FS
24	1		*FRONT FENDER SPOILER -RH	Not Necessary	31.00 FS	*- FS
25	1		*FRONT WHEEL HOUSING LINER -RH	Deformed	209.00 FS	*167.20 FS
26	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	78.00 FS	*- FS
27	1		*LED HEADLIGHT -RH	Cracked	6,973.00 FS	*5,578.40 FS
28	1		*FRONT ALUMINIUM TRIM -RH	Cut	563.00 FS	*450.00 FS
29	1		*FRONT NO.PLATE	Not Necessary	25.00 FS	*- FS
30	1		*SUNDRIES	Necessary	380.00 FS	*118.80 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 13,164.00 8,765.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,FOG LAMPS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE ALL FRONT FITTINGS ,INCLUDE BOTH HEADLAMPS ,REMOVE AND RENEW BUMPER ,RADIATOR GRILLE ,RHS FRONT FENDER AND CONNECTING PARTS ,ALIGN TO POSITION ,REINSTALL ALL PARTS REMOVED	New	2,400.00	1,500.00
3	TO RENEW RHS FRONT WHEEL AND CARRY OUT ALIGNMENT	New	280.00	280.00
4	TO RESPRAY PAINT ON FRONT BUMPER ,RHS FRONT FENDER ,BONNET	New	2,200.00	1,650.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,432.00	3,982.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >