

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E**29 JAN 2018**

Estimate No. : b1 45684
Date Estimated : 29/01/2018
Prepared By : Merina Chia San San

Page No. : 1 of 1

- ESTIMATE REPAIR FOR -
Chia See Nia
1 Lorong G Telok Kurau

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 426162

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SCL7873C	DZ10416	06/09/2012	640iA GC	0

DESCRIPTION

To making good on front bumper including remove and
install attachments to facilitate with repair work

VALUE

1,700.00

To paint front bumper

1,038.00

To check electrical wiring systems at the front section
for proper function including adjustments of headlights.

177.00

Sundries.

80.00

Total Labour 1: 2,995.00

DESCRIPTION

BUMPER PDC SENSOR (A96 MINERALWEIS)

QTY	PRIC	VALUE
1	368.80	368.80

Total Parts : 368.80

Labour 1	:	2,995.00
Parts	:	368.80
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	235.47
Grand Total	:	3,599.27