

ASS. REC. BY:

REF: CS/QBE/8001812/Krbz

Special Instruction:

ASSIGNMENT (Office)

From (Person): Syahreda Othman of QBE Date/Time: 30/12/18

Estimated Cost: Bill to:

OD/TP+WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLV 2994K Insured:

at Workshop m/s Optima Werkz Tel:

of 9A Serangoon North Ave 5

Policy No: Claim No:

Sum Insured: Excess:

Make of Veh: D.O.A. 26/12/18
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: Person Contacted: Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	Revert call Syahreda - 9233 8824
	SLV 2994K - CS/QBE/8001812/Krbz D.O.A. 26/12/18
30.01.2018	Spoke with Syahreda, Report sent through email.
(4.00 pm)	Has revert through phone, Syahreda said can authorise @ qbe.com

13/6 @ Fort-85 Car hire (12 (And: \$1495.70, 22%).)

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$250k

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

1.B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLV 2994K

Yr Regn:

12, 17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

M. E250

cc

1991

Colour:

M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading:

3312

T/Radio: Insured / Std / NI / NA

Eng No:

C/No:

W00 2130452A 297229

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/40R19

R:

275/35R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

9

mm

Rear

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

28/1/18

D.O.I.

29/1/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S R

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

30/1 File 199120 Catherine

RECEIVED 4 JUN 2018

Date/Time, File Pass to?

11 PM

Date/Time, File Return to?



: Prell. Report



: Final Report

Days Of Repair:

4

Resurvey No. of Trip:

2

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

300

Transportation:

S - RS \$

Phone

Others

TOTAL

300

Report Format:

017

Lump Sum / I.B.I. (\$

7087.45



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

QBE INSURANCE (SINGAPORE) PTE LTD

Ref : CS/QBE18001812/Krb

1 RAFFLES QUAY #29-10 SOUTH
TOWERSINGAPORE 048583

Date : 30-01-2018



Code : QBE

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SLV 2994K
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	30/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

5. General Information

Accident Date	26/01/2018	Inspection Date	30/01/2018
Survey held at	OPTIMA WERKZ PTE LTD 9A SERANGOON NORTH AVE 5 SINGAPORE 554500		

5a. Remarks

- A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Tuesday, January 30, 2018 4:13 PM
To: 'Syaheeda Nacah Binte Mohamed Othman'
Cc: SUR
Subject: SLV 2994K QBE OD DOA: 26.01.2018

Dear Syaheeda,

As spoken, we have inform repairer to proceed for repair.

Kindly sent us the claim number and the excess.

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Tuesday, January 30, 2018 4:14 PM
To: 'Sharon Peh'
Cc: SUR
Subject: SLV 2994K QBE OD DOA: 26.01.2018

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLV 2994K (excess TBA)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/01/2018 11:26
Date Of Accident	26/01/2018 03:05
Exact Location Of Accident	GEYLANG ROAD TOWARDS SIMS WAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLV2994K
Insured/Policyholder	
Name Of Registered Owner	GUO MENGXIANG
NRIC No	S9171664Z
Email Address	MEXX_GUO@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-97589712
Alternative Phone No	OTHERS-97589712

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E250 AMG
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	QBE INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	8-V0016896-MVA
Cover Note Number	

Driver

Name of Driver	GUO MENGXIANG
NRIC No	S9171664Z
Date Of Birth	17/03/1991
Occupation	INDOOR
Date Of Driving Pass	26/08/2011
Driving Experience	6 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97589712
Fax Number	
Contact Number	OTHERS-97589712
EMail Address	MEXX_GUO@HOTMAIL.COM

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 2/7/19 Jan 2017, Sunday, I was changing from Fall to Winter gear when the traffic was halted. There was a huge gap of more than 1 car's length in front of S114516. I signaled early and when I heard squeal I noticed that the driver of S114516 had not seen my car. Instead of backing up, S114516 continued moving forward. I turned back and when it was immediately behind me I hit the brakes and slammed forward and the front right bumper of S114516 struck right headlight.

DECLARATION

11 We declare the foregoing particulars are true in every respect.

Pharmacokinetics: Summary

Culver & Turner

Downloaded At: 11:52 11 September 2009

It serves as the policyholder's

James R. Thompson

Reporting Centre Personnel's Signature: _____

Page 11 of 11

R4R4C/FIN %NO

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1664Z
Vehicle Details	
Vehicle No.:	SLV2994K
Vehicle to be Exported:	No
Intended De-registration Date:	30 Jan 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E250 AMG LINE AUTO
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	27492031117978
Chassis No.:	WDD2130452A297229
Maximum Power Output:	155.0 kW (207 bhp)
Open Market Value:	\$53,678.00
Original Registration Date:	27 Dec 2017
First Registration Date:	27 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$68,621.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Dec 2027
PARF Rebate Amount:	\$51,465.00
Intended COE Rebate Details	
COE Expiry Date:	26 Dec 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$48,011.00
COE Rebate Amount:	\$46,547.00
Total Rebate Amount:	\$98,012.00

The information contained herein is correct as at 30 Jan 2018

OK

QBE Insurance (Singapore) Pte Ltd

A member of the worldwide QBE Insurance Group - Unique Entity No. 199401363C

1 Raffles Quay, #29-10 South Tower, Singapore 048583
Tel: 65-6224 6633 Fax: 65-6533 3270
GST Registration No.: M200544018
www.qbe.com.sg

**Certificate of Insurance**

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULE, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate No. 8-V0016896-MVA

Account Name INSURANCE SG AGENCY

MCI Type MX1

- 1 Index Mark and Registration Number of Vehicle or Chassis No: SLV2994K
2 Name of Policyholder GUO MENGXIANG
3 Effective date of Commencement of Insurance for the purpose of the Regulations 27/12/2017
4 Date of Expiry 26/12/2018
5 Person or Classes of Person entitled to drive*

(a) The Policyholder

The Policyholder may also drive a motor car not belonging to him/her and not hired to him/her under a hire purchase agreement.

(b) Any person who is driving on the Policyholder's order or with his/her permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from the driving the Motor Vehicle

And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage

6 Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover use for hire or reward, racing, pace-making, reliability trial, speed-testing or the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

- 7 Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risk and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act 1987 (Malaysia) are not to be included under these headings

I/WE HEREBY CERTIFY that the Policy to which this certificate relates is issued in accordance with the provisions of the Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Hire Purchase : GENIE FINANCIAL SERVICES PTE LTD

QBE Insurance (Singapore) Pte Ltd

Date of Issue: 28/12/2017

Authorized Signature

REPUBLIC OF SINGAPORE DRIVING LICENCE

Identity Card No. S9171664Z

GUO MENGXIANG

17 Mar 1991

26 Aug 2011

0019930270




REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S9171664Z**



Name

GUO MENGXIANG

郭 梦 翔

Race

CHINESE

Date of birth

17-03-1991

Country of birth

CHINA

Sex

M

S9171664Z

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:


EFFECTIVE DATE

Class 3A Motor cars without clutch pedals (Auto) <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles without clutch pedals <= 2500kg **26 Aug 2011**

NP 428A



Identity Card No. **S9171664Z**



15-08-2005

15-08-2005

APT. BLK 730 WOODLANDS CIRCLE 607-373 SINGAPORE 730738

NRIC No: **S9171664Z**

Date: **26/05/2014**

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Fax: 62564315

Date : 26 January 2018

TO MOTOR CLAIM DEPT

QBE INSURANCE (INTL) LTD

60 Anson Road

Mapletree Anson #11-01

Singapore 079914

Vehicle No: SLV2994K

Model: MERCEDEZ BENZ E250 AMG

Chassis: WDD2130452A297229

Policy No: 8-V0016896-MVA

Date of Accident: 26/01/2018

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER		Bu \$948.00
1	FRONT BUMPER SIDE GARNISH RH		Del \$55.00
1	FRONT BUMPER TOW HOOK COVER		SW \$41.00
1	FRONT BUMPER PARKING SENSOR	shot \$108.00	\$216.00
1	FRONT BUMPER PARKING SENSOR RUBBER SEAL		NPL \$8.00
2	FRONT BUMPER PARKING SENSOR HOLDER	\$35.00	Re \$210.00
1	FRONT BUMPER INNER SPONGE		CR \$105.00
1	FRONT BUMPER SIDE RETAINER RH		Dis \$14.00
1	FRONT BUMPER INNER SUPPORT FRAME RH		LPA \$36.00
10	FRONT BUMPER CLIP	\$6.00	Re \$60.00
10	FRONT BUMPER RIVET	\$6.00	Re \$60.00
1	FRONT BUMPER REINFORCEMENT		R \$303.00
1	FRONT BUMPER TOP RUBBER SEAL		Re \$19.00
1	FRONT BUMPER TOP BEAM		Dis \$122.00
1	FRONT GRILLE		SP \$100.00
1	FRONT GRILLE CHROME MOULDING		CR \$162.00
1	FRONT GRILLE TOP BRACKET		Re \$107.00
1	FRONT HEADLAMP RH	my car	\$1,960.00
1	FRONT HEADLAMP CONTROL MODULE		SP \$375.00
1	FRONT FENDER RH		Bu \$588.00
1	FRONT FENDER INNER SHIELD FRONT		STO \$70.00
10	FRONT FENDER INNER SHIELD CLIP	\$6.00	Re \$60.00
SUB TOTAL			\$5,619.00
COST +15%			\$842.85
PARTS TOTAL			\$6,461.85

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date : 26 January 2018

TO MOTOR CLAIM DEPT
QBE INSURANCE (INTL) LTD
60 Anson Road
Mapletree Anson #11-01
Singapore 079914

Vehicle No: SLV2994K
Model: MERCEDEZ BENZ E250 AMG
Chassis: WDD2130452A297229
Policy No: 8-V0016896-MVA
Date of Accident: 26/01/2018

ESTIMATE

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	\$1,000.00	600
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	\$1,000.00	500
TO TUFF KOTE / ANTI-RUST	\$40.00	nn x
TO CHECK WIRING, REPLACED WITH FOCUS HEADLAMP & WATER LEAKAGE TEST	\$80.00	200
TO DIAGNOSTIC CHECK & RESET MEMORY TO IDENTIFICATION STANDARD	\$350.00	7 200
TO DISMANTLE & REPLACED FRONT BUMPER PARKING SENSOR	\$80.00	600

LABOUR TOTAL \$2,550.00

WINSON Total \$9,011.85

9683.15

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date : 31 January 2018

TO MOTOR CLAIM DEPT
QBE INSURANCE (INTL) LTD

Vehicle No: SLV2994K

60 Anson Road

Model: MERCEDEZ BENZ E250 AMG

Mapletree Anson #11-01

Chassis: WDD2130452A297229

Singapore 079914

Policy No: 8-V0016896-MVA

Date of Accident: 26/01/2018

SUPPLEMENTARY

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER LOWER BRACKET		<i>CM</i> \$62.00 ✓
		SUB TOTAL	\$62.00
		COST +15%	\$9.30
		SUB TOTAL	\$71.30

WINSON	Total	\$71.30
--------	-------	---------

P - 5636.15
L - 1530
S - 21.50
7237.45

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date : 26 January 2018

Vehicle No: SLV2994K

Model: MERCEDEZ BENZ E250 AMG

Chassis: WDD2130452A297229

Policy No: 8-V0016896-MVA

Date of Accident: 26/01/2018

TO MOTOR CLAIM DEPT

QBE INSURANCE (INTL) LTD

60 Anson Road

Mapletree Anson #11-01

Singapore 079914

ESTIMATE

QTY	DESCRIPTION	UNIT	SS	AMOUNT	SS
1	FRONT BUMPER			Bu	\$948.00
1	FRONT BUMPER SIDE GARNISH RH			Bu	\$55.00
1	FRONT BUMPER TOW HOOK COVER			Sm	\$41.00
1	FRONT BUMPER PARKING SENSOR	shot	\$108.00		\$216.00
1	FRONT BUMPER PARKING SENSOR RUBBER SEAL			me	\$8.00
2	FRONT BUMPER PARKING SENSOR HOLDER		\$35.00	me	\$210.00
1	FRONT BUMPER INNER SPONGE			CM	\$105.00
1	FRONT BUMPER SIDE RETAINER RH			Di	\$14.00
1	FRONT BUMPER INNER SUPPORT FRAME RH			CM	\$36.00
10	FRONT BUMPER CLIP		\$6.00	me	\$60.00
10	FRONT BUMPER RIVET		\$6.00	me	\$60.00
1	FRONT BUMPER REINFORCEMENT			R	\$303.00
1	FRONT BUMPER TOP RUBBER SEAL			R	\$19.00
1	FRONT BUMPER TOP BEAM			Di	\$122.00
1	FRONT GRILLE			CM	\$100.00
1	FRONT GRILLE CHROME MOULDING			CM	\$162.00
1	FRONT GRILLE TOP BRACKET			R	\$107.00
1	FRONT HEADLAMP RH			me CM	\$1,960.00
1	FRONT HEADLAMP CONTROL MODULE			CM	\$375.00
1	FRONT FENDER RH			Bu	\$588.00
1	FRONT FENDER INNER SHIELD FRONT			CM	\$70.00
10	FRONT FENDER INNER SHIELD CLIP		\$6.00	me	\$60.00
SUB TOTAL					\$5,619.00
COST +15%					\$842.85
PARTS TOTAL					\$6,461.85

4 days
01/1/18

10/1

Not Authorized
Resurvey B4 paint

Ex \$600

\$708.73

\$7.45

Fax: 62564315

4901.00
735.15
5636.15

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143 Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date : 26 January 2018

TO MOTOR CLAIM DEPT
QBE INSURANCE (INTL) LTD

60 Anson Road
Mapletree Anson #11-01
Singapore 079914

Vehicle No: SLV2994K
Model: MERCEDEZ BENZ E250 AMG
Chassis: WDD2130452A297229
Policy No: 8-V0016896-MVA
Date of Accident: 26/01/2018

ESTIMATE

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	\$1,000.00	600
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	\$1,000.00	500
TO TUFF KOTE / ANTI-RUST	nn \$40.00	X
TO CHECK WIRING, REPLACED WITH FOCUS HEADLAMP & WATER LEAKAGE TEST	\$80.00	200
TO DIAGNOSTIC CHECK & RESET MEMORY TO IDENTIFICATION STANDARD	\$350.00	7-200
TO DISMANTLE & REPLACED FRONT BUMPER PARKING SENSOR	\$80.00	600

LABOUR TOTAL \$2,550.00 1530.00

WAGON	Total	\$9,011.85
-------	-------	------------



Head Office : 8, Jalan Lembah Kallang, #01-01 Min Ghee Building
Singapore 339564.
Tel: 6298 3888 Fax: 6297 0863 (Accounts)
E-mail : info@minghee.com
Website : <http://www.minghee.com>

E-mail : info@minghee.com
Website : <http://www.minghee.com>

GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E

ACCOUNT NUMBER: OPTIMAW1 TIME:09:33

OPTIMA WERKZ PTE LTD
6, KUNG CHONG ROAD,
SINGAPORE 159143

2005

© 2013 Pearson Education, Inc. All rights reserved.

CO REG NO. 168905613E

ROUTE
SMO

DELIVER TO:
OPTIMA WERKS PTE LTD
~~6, JUNG CHONG ROAD,~~
SINGAPORE 159143

PA, Serapion North



INV NO : 8096278

DATE	31/01/2018	PAGE	1
TERM	30 Days Net	SALESMAN	Onig Hai Choon
CUSTOMER REF.	SLV2994K	OUR REF.	19148

DELIVER TO:

OPTIMA WEEKS INC. LTD.

4, ~~TUNG CHONG ROAD,~~
SINGAPORE 159143

PA, Serapion North

LOC	QUANTITY	UNIT PRICE	AMOUNT
1111	1 PC	62.00	62.00

OD# 184

SIN	62.00
78	4.34
SIN	66.34

Exclusive Distributor

HOK

NIGHT

Starbuck

GOODS SOLD ARE NOT RETURNABLE.

OVERDUE ACCOUNTS SHALL

MEAN INTEREST AT JOB'S PREVALENCY
LENDING RATE

***CASH INVOICE MUST BE
MAILED WITHIN 7 DAYS**

2

NOTES

ALL CHECKS MUST BE MADE PAYABLE TO
MINI GHEE AUTO PTE. LTD.



bisSAFE₃

For MIN GHEE AUTO PTE. LTD.



明義汽車私人有限公司
MIN GHEE AUTO PTE. LTD. TAX INVOICE

Head Office : 8, Jalan Lembah Kallang, #01-01 Min Ghee Building
Singapore 339564.

Tel: 6296 3888 Fax: 6297 0863 (Accounts)

E-mail : info@minghee.com

Website : http://www.minghee.com

INV NO : 8096312

DATE	31/01/2016	PAGE	1
TERM	30 Days Net	SALESMAN	Ong Mai Choon
CUSTOMER REF.	SLV2994K	OUR REF.	19204

GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E

ACCOUNT NUMBER: OPTIMAW1 TIME: 10:43

OPTIMA WERKE PTE LTD
6, KUNG CHONG ROAD,
SINGAPORE 159143

Telephone No : 64721313

159143

ROUTE
SMJ

DELIVER TO:
OPTIMA WERKE PTE LTD
9A SERANGOON NORTH AVE 5



PART NO.	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
1 M8A222 900 30 13	CONTROL UNIT	1E-10F	1 PC	375.00	375.00
2 M8A124 990 04 92	CLIPS	1E-12C	10 PCS	6.00	60.00
3 M8A003 990 94 97 64	BLIND RIVET	1D-3B	10 PCS	6.00	60.00
4 M8A124 990 04 92	RIVET	1E-12C	10 PCS	6.00	60.00
5 M8A000 542 12 51	RECOGNISING HOLDER	1A-01F	2 PCS	35.00	70.00

OD # 184

GOODS RECEIVED IN GOOD ORDER
AND CONDITION

*GOODS SOLD ARE NOT RETURNABLE
*OVERDUE ACCOUNTS SHALL
BEAR INTEREST AT LBS'S PREVAILING
LENDING RATE

*CASH INVOICE MUST BE
PRESENTED WITHIN 7 DAYS
FROM DATE OF INVOICE

Exclusive Distributor

HDK
CITY JOINT
MADE IN JAPAN

Stockists

SIGN & COMPANY'S STAMP

DATE

ALL CHECKS MUST BE MADE PAYABLE TO
MIN GHEE AUTO PTE. LTD.



For MIN GHEE AUTO PTE. LTD.



明義汽車私人有限公司
MIN GHEE AUTO PTE. LTD.

Head Office : 8, Jalan Lembah Kallang, 801-01 Min Ghee Building

Singapore 339564.

Tel: 6298 3888 Fax: 6297 0863 (Accounts)

E-mail : info@minghee.com

Website : http://www.minghee.com

TAX INVOICE

INV NO : 8096136

DATE	30/01/2016	PAGE	1
TERM	30 Days Net	SALESMAN	Ong Hai Choon
CUSTOMER REF	SLV2994K	OUR REF	18627

GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E CO REG NO. 198905613E

ACCOUNT NUMBER : OPTIMA WERKZ PTE LTD
6, KUNG CHONG ROAD,
SINGAPORE 159143

159143

Telephone No : 64721313

ROUTE
SHJ

DELIVER TO:
OPTIMA WERKZ PTE LTD
9A SERANGOON NORTH AVE 5



PART NO.	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
1 M8A213 885 27 00 9999	TRIM BUMPER	61-2A	1 PC	948.00	948.00
2 M8A213 885 68 00	SIDE GARNISH	1B-6K	1 PC	55.00	55.00
3 M8A213 885 06 21	RETAINER	1B-1G	1 PC	14.00	14.00
4 M8A213 885 54 01	IMPACT ABSORBER	61-00	1 PC	105.00	105.00
5 M8A213 620 17 01	CONSOLE	3B-1D	1 PC	122.00	122.00
6 M8A213 885 24 00	FRAME RH	1A-51	1 PC	36.00	36.00
7 M8A213 880 00 18	FRONT FENDER	3A-1A	1 PC	588.00	588.00
8 M8A238 690 16 03	WHEEL HOUSE COVERING	3A-3A	1 PC	70.00	70.00
9 M8A213 906 68 01	HEADLAMP UNIT	6B-4B	1 PC	1,960.00	1,960.00

OD # 184

GOODS RECEIVED IN GOOD ORDER AND CONDITION

GOODS SOLD ARE NOT RETURNABLE

*OVERDUE ACCOUNTS SHALL BEAR INTEREST AT 10% PREVAILING LENDING RATE

*CASH INVOICE MUST BE PAID WITHIN 15 DAYS FROM DATE OF INVOICE

Exclusive Distributor

HDK
C.F. JAPAN
MADE IN JAPAN

Stockists



DATE

ALL CHEQUES MUST BE MADE PAYABLE TO
MIN GHEE AUTO PTE. LTD.

TOTAL	SIN	3,898.00
ADD GST	7%	272.86
AMOUNT DUE	SIN	4,170.86

[Signature]

For MIN GHEE AUTO PTE. LTD.



MIN GHEE AUTO PTE. LTD.
Head Office : 0, Jalan Lembah Kallang, 001-01 Ghee Building
Singapore 330564.
Tel: 6290 3888 Fax: 6297 0803 (Accounts)
E-mail : info@minghee.com
Website : http://www.minghee.com

TAX INVOICE

INV NO : 8096451

OD# 184

GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E

CO REG NO. 196905613E

ACCOUNT NUMBER: OPTIMSW1 TIME: 09:39

OPTIMA WERKE PTE LTD
6, KUNO CHONG ROAD,
SINGAPORE 159112

DATE
ENI

Telephone No : 64721311

159112

DELIVER TO:
OPTIMA WERKE PTE LTD
9A SERANGOON NORTH AVE 5



PART NO.	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
1 M8A213 888 01 23	PROTECTIVE GRILLE	1B-11	1 PC	100.00	100.00
2 M8A213 885 02 00	ORNAMENTAL MOLDING	1B-12	1 PC	162.00	162.00

GOODS RECEIVED IN GOOD ORDER AND CONDITION

GOODS SOLD ARE NOT RETURNABLE
OVERDUE ACCOUNTS SHALL
BEAR INTEREST AT 10% PER ANNUM
LESSING RATE
CASH PAYMENTS MUST BE
PAID WITHIN 10 DAYS
FROM DATE OF INVOICE

SIGN & COMPANY'S STAMP

Exclusive Distributor

HDK
EX-3000
V6 2.0 16V
Stockists



TOTAL	SIN	262.00
ADD GST	7%	18.34
AMOUNT DUE	SIN	280.34

DATE
ALL CHECKS MUST BE MADE PAYABLE TO
MIN GHEE AUTO PTE. LTD.

FOR MIN GHEE AUTO PTE. LTD.

MERCEDES & BMW: Tel: 6298 3888 Fax: 6294 1450

Mitsubishi, Hyundai, Kia, Proton: Tel: 6298 3888 Fax: 6294 1450

Towata & Honda Tel: 6298 3888 Fax: 6294 1450



GOLDENLINK AUTO PTE LTD

TAX INVOICE



Invoice To

OPTIMA WERKZ PTE LTD
6 KUNG CHONG ROAD
SINGAPORE 159143

W0709

INVOICE NO: WL433824

DATE: 01-02-2018 09:33

PAGE: 1 / 1

SALESMAN: PCS

TERMS: 30 DAYS

PO REF :

SNO	ITEMCODE	DESCRIPTION	QUANTITY	UNITPRICE	AMOUNT
	Remark :	SLV28B4K SEND TO 9A SERANGOON NORTH AVE 5		(SGD)	(SGD)
1	000 905 5504 9999	PTS SENSOR FRT/RR	1	108.00	108.00
2	000 542 1251	PARKING SENSOR RING	1	8.00	8.00

OD#184

GOLDENLINK AUTO PTE LTD

Products received and checked to be
in good condition

SUB-TOTAL 116.00

ADD G.S.T 7% 8.12

TOTAL (SGD) 124.12

Authorised Signature

Customer's Signature / Company Stamp

Products purchased are to be installed in accordance to manufacturer's standards and procedures.

Cheques to be made payable to GOLDENLINK AUTO PTE LTD

Any overdue account shall be chargeable with interest at the prevailing prime rate from time to time of DBS Bank Limited
Request for the return of any unused product (in original and good condition) may be considered on a case by case basis
and subject to applicable terms and conditions. Such request must be accompanied by the original invoice and lodged
within 14 days of delivery of your order.



bizSAFE₃

Goldenlink Auto Pte Ltd

Head Office: 8 Changi South Lane #02-01 Singapore 486113

Tel: 6336 4903 (Accounts) 6326 2380 (Supply Chain) Fax: 6339 5618 Co Reg No: 199023171051 Reg No: 19-5461363-X

www.goldenlink.com.sg



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

QBE INSURANCE (SINGAPORE) PTE LTD

Ref : CS/QBE18001812/Krbe2

1 RAFFLES QUAY #29-10 SOUTH
TOWERSINGAPORE 048583

Date : 22-06-2018



Code : QBE

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SLV 2994K
Policy No.	8-V0016896-MVA	Coverage (\$)	0.00
Claim No.	VC011135	Excess (\$)	0.00
Assign From	SYAHEEDA OTHMAN	Assign Date	30/01/2018

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ E250 (A)	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WDD2130452A297229	Colour	METALLIC GREY
Odometer	3312	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/40 R19	PIRELLI	9 mm
L/H Front Tyre	245/40 R19	PIRELLI	9 mm
R/H Rear Tyre	275/35 R19	PIRELLI	9 mm
L/H Rear Tyre	275/35 R19	PIRELLI	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	26/01/2018	Inspection Date	29/01/2018
Survey held at	OPTIMA WERKZ PTE LTD 9A SERANGOON NORTH AVE 5 SINGAPORE 554500		

5a. Remarks

A)THE MARKET VALUE IS S\$250,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 2994K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER (WCP)	BUCKLED	948.00	948.00
1	FRONT BUMPER SIDE GARNISH RH (WCP)	DENTED	55.00	55.00
1	FRONT BUMPER TOW HOOK COVER (WCP)	SERVICEABLE	41.00	-
2	FRONT BUMPER PARKING SENSOR @\$108.00 (WCP)	SHORTED-ONLY 1PC	216.00	108.00
1	FRONT BUMPER PARKING SENSOR RUBBER SEAL (WCP)	NECESSARY	8.00	8.00
6	FRONT BUMPER PARKING SENSOR HOLDER @\$35.00 (WCP)	NECESSARY-ONLY 2PCS	210.00	70.00
1	FRONT BUMPER INNER SPONGE (WCP)	CRACKED	105.00	105.00
1	FRONT BUMPER SIDE RETAINER RH (WCP)	DISTORTED	14.00	14.00
1	FRONT BUMPER INNER SUPPORT FRAME RH (WCP)	CRACKED	36.00	36.00
10	FRONT BUMPER CLIP @\$6.00 (WCP)	NECESSARY	60.00	60.00
10	FRONT BUMPER RIVET @\$6.00 (WCP)	NECESSARY	60.00	60.00
1	FRONT BUMPER REINFORCEMENT (WCP)	TO REPAIR SEE LABOUR	303.00	-
1	FRONT BUMPER TOP RUBBER SEAL (WCP)	SERVICEABLE	19.00	-
1	FRONT BUMPER TOP BEAM (WCP)	DISTORTED	122.00	122.00
1	FRONT GRILLE (WCP)	CRACKED	100.00	100.00
1	FRONT GRILLE CHROME MOULDING (WCP)	CRACKED	162.00	162.00
1	FRONT GRILLE TOP BRACKET (WCP)	TO REPAIR SEE LABOUR	107.00	-
1	FRONT HEADLAMP RH (WCP)	MTG CRACKED	1,960.00	1,960.00
1	FRONT HEADLAMP CONTROL MODULE (WCP)	CRACKED	375.00	375.00
1	FRONT FENDER RH (WCP)	BUCKLED	588.00	588.00
1	FRONT FENDER INNER SHIELD FRONT (WCP)	CRACKED	70.00	70.00
10	FRONT FENDER INNER SHIELD CLIP @\$6.00 (WCP)	NECESSARY	60.00	60.00
1	FRONT BUMPER LOWER BRACKET (ADDITIONAL) (WCP)	CRACKED	62.00	62.00
	COST PLUS 15%		852.15	744.45
			6,533.15	5,707.45

Report Ref No. CS/QBE18001812/Krbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT AND FRONT GRILLE TOP BRACKET.		1,000.00	600.00
	TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION.		1,000.00	500.00
	TO TUFF KOTE / ANTI-RUST.	NOT NECESSARY	40.00	-
	TO CHECK WIRING, REPLACED WITH FOCUS HEADLAMP & WATER LEAKAGE TEST.		80.00	20.00
	TO DIAGNOSTIC CHECK & RESET MEMORY TO IDENTIFICATION STANDARD.		350.00	200.00
	TO DISMANTLE & REPLACED FRONT BUMPER PARKING SENSOR.		80.00	60.00
			2,550.00	1,380.00
	GRAND TOTAL		9,083.15	7,087.45
RECOMMENDED COST OF REPAIRS				7,087.45

Report Ref No. CS/QBE18001812/Krbe2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.