

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 8920A

DATE 1/27/2018 10:46

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper ✓			\$ 603.60	
	Rear Bumper Reinforcement ✓			\$ 504.35	
	Rear Bumper Reinforcement Bracket (LH/RH) ✓		\$ 180.00	\$ 360.00	
	Rear Bumper Sponge ✓			\$ 143.40	
	Rear Bumper Under Cover ✓			\$ 225.00	
	Rear Bumper Clips 10 pcs ✓			\$ 22.00	
	SUB TOTAL			\$ 1,858.35	
	LESS 20%			\$ 371.67	
	DISCOUNTED TOTAL			\$ 1,486.68	
	Rear Bumper Reverse Sensor X			\$ 135.70	Nett
	Rear Bumper Advertisement Logo X			\$ 50.00	Nett
	Rear Bumper Rubber Mat ✓			\$ 50.00	Nett
				\$ 235.70	
	Labour Charge			200	
	Panel Beating			\$ 350.00	
	Spray Painting Charge			\$ 200.00	180
	Wiring Charge			\$ 30.00	X
	Remove/Refix Reverse Sensor			\$ 120.00	20
	TOTAL LABOUR			\$ 700.00	
	ESTIMATE TOTAL			\$ 2,422.38	

Kaluz 11/1/18
 29/1/18 10:10
 2 Days
 PIP
 Before Paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be submitted and is subject to approval from Insurance Company

Acknowledge: _____
 Signature: _____
 Date: _____

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.