WHOLE	REF: Ct3 ALINSO			1	
	<u>ASS</u> .	IGNMENT			100
om:	Date:	Veh No:	SLK6558T	Yr Regn: 2017	
timated Cost:		Type (M.Car)	M.Cycle / Bus / Va	n / Lorry / Taxi / Prime Mover /	
TP/WS/TP RES/OD	RES / EVA / INV / MV	Truck	/ Trailer or	sedan . cc 99	9
Inspect Vehicle No:		Make:	Audi A3 S		THE THE PARTY OF THE
Workshop m/s		Colour	white.	A/C: Insured / Std	
		Sp.Reading	11090.	T/Radio: Insured / Std	INIINA
sured		Eng/No:		01/41.04/094	
olicy No. 21004	F <f8p< td=""><td>C/No:</td><td></td><td>8VXH 1046584</td><td></td></f8p<>	C/No:		8VXH 1046584	
aims No.	W12 - 10		Fair / Poor /		
um Insured:	Excess: 600		rde / Jammed / Le		
(Client's Record)			order / Jammed / Le		
lake of Veh:		-	/ S/Rim / STD A/F		
	,	Tyre Size:		05/55R16.	
(Policy Condition)				05/55R16	IMI /
emark: The veh had com		\dashv		LIZA / MIC / OHTSU / PIR / SU	1901 /
repair at the time		TOYOTY	OKO ar	_	
Bal. or Market Value:	115K	Front	N	Rear	200 000
DAC Accident Rport:	Consistent? : Yes or No	R/Bal.	of mm	R/Bal. 06	mm
GIA / PR Seen:	Consistent? : Yes or No	L/Bal.	1.1	property size Property	18
Est. Repairs: 3	days Res.: Yes or No		00/1/18	D.O.I. 30/01	10
Lum Sum:	% 3 Val.: Yes or No	Survey hel			0.00
CA / REV / REP. /	24 HRS		mages: FR / Kear	I O/S N/3 / U/C / Rooftop	
2	Vehicle: IN / Ol rson Contacted:	JTThe II/	C / Chassis frame	/ Body Structure affected due	e to collisio
Dato.	Instruction	1116 07	o / onaccioname	. Total	
	> Alg.				
30/1/18 Adria	in has applaint to 1	victor c	AIG)		
31/1/18 Email	vehicle ex \$600		1 10-1	14.346 84%)	
10/4/18 Final	fig \$ 2650 confirme	d by ex	mail (Red	14,346, 8470)	
	_				
	The state of the s	7 APR 20	ld		
	RECEIVED 1				
	RECEIVED 1		months and the second		
Date/Time, File Pass to?	: Preli. Report	Days Of	Repair: 3	Survey Fee:	200
1)		Days Of	months and the second	Survey Fee:	200
1) Date/Time, File Return to?	: Preli. Report	Days Of I	Repair: 3		
1)	: Preli. Report	Days Of I	Repair: 3 y No. of Trip:	Transportation	
1) Date/Time. File Return to?	: Preli. Report	Days Of I	Repair: 3 y No. of Trip:	Transportation:)S+RSSI	

Reference No.: CC3 | ANG | 800 | 866 | AVD
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

dmin Office	e Assign Form	<u>Y-Date</u>	N-Date	Y-Date	N-Date
С	Reference No.	~			
C	Customer Code				
N	Assign From				
C	Assign Date	~			
С	Veh No (Inspected)	~			
С	Veh No (Insured)				
C	D.O.A	~			
C	Policy No	~			
С	Claim No				
	Insurance Authorisation (CA /REV/REP)	~			
c					E
С	Report Type	~			
С	Weekend Charges	~		-	
N	Survey held at/Repairer	7			
С	Excess				2000
urvey	or (): Case handler to make s	ure the surveryor c	ompleted a	II required	informa
) Assig	gnment Form				_
С	Vehicle No	~			
С	Regn Month/Year	~			
N	Vehicle Type	~			
N	Make & Model	~			
C	Engine Capacity. (C.C)	_			
N	Colour	~			
C	Odometer. (Sp.Reading)	~			
C	Chassis No	~			
N	General Condition				
N	Steering	~	+	1	1
N	Brake		-		
N	Modification (Modi)	/	_		+
С	Tyre Size	~			1
Ν	Tyre Make	~			
С	Tyre Balance			-	+
С	Date of Inspection			-	-
N	Survey held		-	-	+
N	Des.of Damages			l	- 1
2) Svs	tem - (Views/Merimen)				
C	Damaged Vehicle Photographs Uploaded	~			
	rkshop Estimate/Assignment Form ALL Parts condition	~			
N					
C	Market Value for OD cases				
10040	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
c		V	-	1	
С	Days of repair			1 1	
c c	Finalised Amount				
c c c					

10418 VERON Check By: Date Case Handler



5a.

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Inter	rnationale Des Experts En Autor	mobile
AIG	ASIA PACIFIC INS	SURANCE PTE LTD	Ref : CC3/AIG1800	1866/Avb
CHA	SHENTON WAY #0 ARTIS BUILDING GAPORE 079120	8-16	Date: 31-01-2018 Code: AIG	
1.		Policy Part	iculars :- OWN DAMAGE	
	Insured Veh.		Veh. Inspected	SLK 6558T
	Policy No.	2100498727	Coverage (\$)	0.00
- 17	Claim No.		Excess (\$)	0.00
	Assign From		Assign Date	30/01/2018
2.		Vehicle F	Particulars & Condition	
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	29	Steering	
	Brakes		Modification	
	General			
3.		Co	nditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4.		Desc	ription of Damages	
5.	- Rugine No	Ge	neral Information	
	Accident Date	20/01/2018	Inspection Date	30/01/2018
	Survey held at	PREMIUM AUTOMOBILES 55 UBI ROAD 1 . SINGAPORE 408699	S PTE LTD	

Remarks

A)THE MARKET VALUE IS S\$-----(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Veron Chen (LKKAuto)

From:

Claims Dept <claims@premiumauto.com.sg>

Sent:

Tuesday, 20 February 2018 4:32 PM

To:

Veron Chen (LKKAuto); SUR

Cc:

claims@premiumauto.com.sg

Subject:

RE: SLK 6558 T Own Damage Claim

Attachments:

Vehicle Registration Details SLK6558T-Navin.pdf

Dear Veron,

We tried getting the LTA rebate and was not able to retrieve it.

This is the closest thing we have from the owner for your kind reference.

Many thanks!

Best regards, Jeffery Tan

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

Sent: Wednesday, 31 January, 2018 5:08 PM

To: Claims Dept <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: SLK 6558 T Own Damage Claim

Dear Jeffery,

Vehicle excess \$600/-

Kindly forward us a copy of LTA rebate.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Wednesday, 31 January 2018 2:42 PM

To: 'Claims Dept' < claims@premiumauto.com.sg>; SUR < sur@lkkauto.com>

Subject: RE: SLK 6558 T Own Damage Claim

Dear Jeffery,

Enclosed herewith marked estimate.

Kindly forward us a copy of LTA rebate.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept [mailto:claims@premiumauto.com.sg]

Sent: Tuesday, 30 January 2018 8:13 PM

To: SUR < sur@lkkauto.com> Cc: claims@premiumauto.com.sg Subject: SLK 6558 T Own Damage Claim

Dear all,

Kindly assist in providing a copy of the marked estimate by Adrian who surveyed the vehicle this morning.

Many thanks!

Best regards, Jeffery Tan

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you



Enquire Vehicle Registration Details

Owner Particulars

NRIC/Passport/Company Cert No.:

G5441960R

Owner ID Type:

Foreign Identification Number

Owner Name:

VERMA NAVIN KUMAR

Registered Address:

248 WESTWOOD AVENUE SINGAPORE 648353

Mailing Address:

Birth Date:

19 Sep 1973

Vehicle Particulars

Vehicle No.:

SLK6558T

Previous Vehicle No.:

Effective Date of Ownership:

23 Jan 2017

Original Regn Date:

23 Jan 2017

Registration Date:

23 Jan 2017

Year of Manufacture:

2016

Vehicle Type:

Passenger Motor Car

Vehicle Scheme:	
Vehicle Attachment 1:	No Attachment
Vehicle Attachment 2:	
Vehicle Attachment 3:	
Vehicle Make:	AUDI
Vehicle Model:	A3 SEDAN 1.0 TFSI S TRONIC (LED)
Primary Colour:	White
Secondary Colour:	
Passenger Capacity:	.4
Chassis No.:	WAUZZZ8VXH1046584
Engine No.:	CHZ184936
Engine Capacity / Power Rating:	999 cc/-
Maximum Power Output:	85.0 kW (113 bhp)
Propellant:	Petrol
Max Unladen Weight:	1280 kg
Maximum Laden Weight:	1755 kg
Open Market Value:	\$24,611.00
PARF Eligibility:	Yes

*	
PARF Eligibility Expiry Date:	22 Jan 2027
Minimum PARF Benefit:	\$8,228.00
No. of Transfers:	0
IU Label No.:	1127247905
COE No.:	2017020101002841D
COE Expiry Date:	22 Jan 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Registration Category:	A - Car up to 1600cc & 97kW (130bhp)
Quota Premium (QP) / Prevailing Quota Premium:	\$50,889.00 / -
Actual QP Paid:	\$50,889.00
QP (Regn Cat):	\$50,889.00
OPC Cash Rebate Eligibility:	No
QP during COE Bidding Exercise:	\$50,889.00
Additional Registration Fee Rate:	First \$20,000.00 (100%), next \$4,611.00 (140%)
Actual ARF Paid:	\$16,456.00
Vehicle Lifespan Expiry Date:	No Lifespan
CO2 Emission:	110.00 (g/km)

CEV/VES Rebate Utilised Amount:	\$10,000.00
CO Emission:	
HC Emission:	Alfait
NOx Emission:	
PM Emission:	**
Message:	
To renew the COE, the Prevailing 0	Quota Premium payable is that of Category A.

Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Wednesday, 31 January 2018 5:08 PM

To:

'Claims Dept'; SUR

Subject:

RE: SLK 6558 T Own Damage Claim

Dear Jeffery,

Vehicle excess \$600/-

Kindly forward us a copy of LTA rebate.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Wednesday, 31 January 2018 2:42 PM

To: 'Claims Dept' <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: SLK 6558 T Own Damage Claim

Dear Jeffery,

Enclosed herewith marked estimate.

Kindly forward us a copy of LTA rebate.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept [mailto:claims@premiumauto.com.sg]

Sent: Tuesday, 30 January 2018 8:13 PM

To: SUR <<u>sur@lkkauto.com</u>>
Cc: <u>claims@premiumauto.com.sg</u>
Subject: SLK 6558 T Own Damage Claim

Dear all,

Kindly assist in providing a copy of the marked estimate by Adrian who surveyed the vehicle this morning.

Many thanks!

Best regards, Jeffery Tan

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you



CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT(CHAPTER 189) MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA) MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

MX1

AUDI AUTO PROTECTOR

OWN DAMAGE EXCESS SS600.00 WINDSCREEN EXCESS

(I) S\$100.00

CERTIFICATE NO. 2100498727-00000

(for policies with effect from 1st November 2002)

SUM INSURED Market Value

INSURING WITH COE/PARF

1) VEHICLE REGISTRATION NO.

NAME OF INSURED

VERMA NAVIN KUMAR

3) EFFECTIVE DATE OF THE COMMENCEMENT OF INSURANCE FOR THE PURPOSES OF THE ACT 23 Jan 2017

SLK6558T

4) DATE OF EXPIRY OF INSURANCE

22 Jan 2018

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE * SUBJECT TO AGE CONDITION : All Age Condition

a) The Insured.

b) Any other person who is driving on the Insured's order or with his permission.

This policy will indemnify the insured or any authorised driver only if he/she meets the age conditions. A Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00, in additional to the

Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said

Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE *

Use only for social, domestic and pleasure purposes and for the Insured's business.

The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / AUDI AUTHORISED REPAIRERS

1. Audi Customer Service Center - 55 Ubi Road 1 (Tel: 63662323)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501)
4. Ethoz - 30 Bukit Batok Cres(Tel:66547777) 5. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only
6. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560) 7. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)
8. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)

10. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

Loss Of Use 15 days Replacement Car only for repairs at Audi Customer Service Centre LOSS OF USE

NAMED DRIVER NA

HIRE PURCHASE COMPANY HONG LEONG FINANCE LTD / EMPLOYER'S LOAN

Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore

25 Jan 2017

AIG Asia Pacific Insurance Pte. Ltd.

PREMIUM LEASING-CYS 281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE SINGAPORE 159938

AUTHORISED REPRESENTATIVE

Co. Reg. No. 201009404M





EMPLOYMENT PASS

Employment of Foreign Manpower Act (Chapter 91A) Republic of Singapore

NANYANG TECHNOLOGICAL UNIVERSITY



VERMA NAVIN KUMAR LECTURER, UNIVERSITY

G5441960R

30-05-2013 01-08-2013 Date of Expiry 01-08-2018



L3606603

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Motor Cars=< 3000kg with =<7 passengers, exclusive 14 May 2014 of the driver; and other motor vehicles =< 2500kg

NP 428A

Licence No: G5441960R

VISIT PASS Immigration Regulations

VERMA NAVIN KUMAR



Date of Birth Sex

19-09-1973 M

INDIAN

G5441960R 01-08-2013 01-08-2018

Date of Issue Date of Explry

MULTIPLE JOURNEY VISA ISSUED



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder

: VERMA NAVIN KUMAR : 23 Jan 2018 To 22 Jan 2019

Period of Insurance

: CHZ184936

Engine No. Chassis No.

: WAUZZZ8VXH1046584

Vehicle No.

: SLK6558T

Policy No.

: 2100498727-01

Endorsement No. Issued Date

: 20 Jan 2018

ABOUT THE COVER

Driver Restriction

Make/Model

: AUDI A3 Sedan 1.0 TFSI S tronic

Engine Capacity/Tonnage : 999.00 CC

Sum Insured : Market Value

Off Peak Car : No

First Year of Registration : 2017

Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

: NA

a) the Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition

: 40 years old and above

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving fultion, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)

VERMA NAVIN KUMAR - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: HONG LEONG FINANCE LTD

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125261

ARG

PREMIUM LEASING -CYS

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd. AUTHORISED REPRESENTATIVE

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

 Estimate
 : Accident Repairs

 Workshop
 : Ubi Road 1

 Contact No
 : 6366 2323

 Fax No
 : 6841 1183

Reference : PA/OD/0099/2018/PH

Date : 24-Jan-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Verma Navin Kumar

Address : BLK 248 Westwood Avenue

#07 - 62

Singapore 648353 elephone : HP +65 85058527

 Telephone
 : HP +65 85058527

 Type of Claim
 : Own Damage Claims

 Policy No.
 : 2100498727-00000

Vehicle No : SLK 6558 T

Model Code : Audi A3 Sedan 1.0 TFSI (A)

Model / Year : Jan-17 Engine No : CHZ 184936

Chassis No : WAUZZZ8VXH1046584

Mileage : Date In :

Liability : :

Estimated By : Allan Wu
Accident Date : 20-Jan-18

Place of Accident : Jurong Central Carpark Macdonald

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLK 6558 T.

S/n	Nature of Jobs			Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid . Check function .	S/N	\$	280.00 🖈	
2	To renew lhs $1/4~\mbox{glass}$ and rear windscreen to facilitate fender renewal .	S/N	\$	600.00 🗶	
3	To dislodge and reinstall rear wire harness for lights , battery manager , fuse and relay trays , electrical and audio equipment .	5/N	\$	1,400.00 ×	
4	To remove and reinstall rear seat, back rest , hat tray , abcd pillar trims , luggage compartment trims , seat belts . Dislodge roof liner and disengage curtain airbag etc .	S/N	\$	1,400.00 +	
5	To dismantle rear bumper and rear lid . Cut out and weld lhs rear fender . Repair lhs rear outer wheel house . Reinstall all parts removed .		\$	4,800.00	1520
6	To respray lhs rear fender , lhs sill panel , door entrance , drain panel , roof channel and end panelling . To carry out stone chip treatment and joint sealer works .		S	3,200.00	1400 /
7	To carry out wheel alignment	5/N	\$	240.00	
8	To carry out diagnostic checks.	5/N	\$	192.00	<.
	TOTAL LABOUR CHARGES	:	\$	12,112.00	

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLK 6558 T

S/N	Parts Description		Damaged F S/Nett	Parts & Prices Remark
1	REAR FENDER SECTIONAL PART - LE	EFT Pyis	\$ 2,006.00	X
2	REAR WHEEL HOUSING LINER - LEF	T ten	\$ 215.00	×
3	1 SET ATTACHMENT PARTS FOR WH	IEEL HOUSING	\$ 77.00	X
4	1/4 GLASS WINDOW - LH		\$ 502.00	+
5	REAR WINDSCREEN		\$ 704.00	x
6	PRIMER	2	\$ 37.00	X
7	GROMMET	6	\$ 47.00	+
8	SOUND ABSORBER	< <i>₩</i> 2	\$ 216.00	x
9	1/4 GLASS SEALANT	∽ S/N	\$ 100.00	x
10	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	×
11	AYCLIC SEALER	S/N	\$ 180.00	×
12	CAVITY WAX	S/N	\$ 140.00	x
13	STONE CHIP	S/N	\$ 180.00	×
14	METAL FILLER POWDER	S/N	\$ 280.00	×
	TOTAL SPARE PARTS CHARGES	:	\$ 4,884.00	_
	TOTAL LABOUR CHARGES		\$ 12,112.00	
	GRAND TOTAL		\$ 16,996.00	-
				<u></u>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

: Authorsed Riss, O4 Days.

Please Note

This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate

Accident Repairs Ubi Road 1 6366 2323

Workshop Contact No Fax No

6841 1183

Reference

PA/OD/0099/2018/PH

Date

24-Jan-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name

Mr. Verma Navin Kumar BLK 248 Westwood Avenue

Address

#07 - 62

Singapore 648353 HP +65 85058527

Telephone Type of Claim

Own Damage Claims 2100498727-00000

Policy No. Vehicle No

SLK 6558 T

Model Code

Audi A3 Sedan 1.0 TFSI (A)

Model / Year

Jan-17 CHZ 184936

Engine No Chassis No

WAUZZZ8VXH1046584

Mileage

Date In

Liability

Excess Cost

Allan Wu

Estimated By **Accident Date**

20-Jan-18

Place of Accident

Jurong Central Carpark Macdonald

Hi Adrian

3 days - ok - jb - 10 Apr 18

Premium Automobiles 55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLK 6558 T.

S/n	Nature of Jobs			Estimated Charges	Surveyor's Recommendati	
1	To remove and reinstall rear parking aid . Check function .	S/N	\$	280.00		
2	To renew lhs 1/4 glass and rear windscreen to facilitate fender renewal .	S/N	\$	600.00		
3	To dislodge and reinstall rear wire harness for lights , battery manager , fuse and relay trays , electrical and audio equipment .	S/N	\$	1,400.00		
4	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims, seat belts. Dislodge roof liner and disengage curtain airbag etc.	S/N	\$	1,400.00		
5	To dismantle rear bumper and rear lid . Cut out and weld lhs rear fender . Repair lhs rear outer wheel house . Reinstall all parts removed .		\$	4,800.00	\$	1,250.00
6	To respray lhs rear fender, lhs sill panel, door entrance, drain panel, roof channel and end panelling. To carry out stone chip treatment and joint sealer works.		\$	3,200.00	\$	1,400.00
7	To carry out wheel alignment	S/N	\$	240.00		
8	- t diaatia chacks	S/N	\$	192.00	3 475-	
	TOTAL LABOUR CHARGES	:	\$	12,112.00	\$	2,650.00

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLK 6558 T

		Damaged Parts & Prices				
S/N	Parts Description			S/Nett	F	Remark
Ont	Turio December					
1	REAR FENDER SECTIONAL PART - LEFT		\$	2,006.00		
2	REAR WHEEL HOUSING LINER - LEFT		\$	215.00		
3	1 SET ATTACHMENT PARTS FOR WHEEL H	IOUSIN	\$	77.00		28
4	1/4 GLASS WINDOW - LH		\$	502.00		
5	REAR WINDSCREEN		\$	704.00		
6	PRIMER	2	\$	37.00		
7	GROMMET	6	\$	47.00		
8	SOUND ABSORBER	2	\$	216.00		
9	1/4 GLASS SEALANT	S/N	\$	100.00		
10	REAR WINDSCREEN SEALANT	S/N	\$	200.00		
11	AYCLIC SEALER	S/N	\$	180.00		
12	CAVITY WAX	S/N	\$	140.00		
13	STONE CHIP	S/N	\$	180.00		
14	METAL FILLER POWDER	S/N	\$	280.00		
	TOTAL SPARE PARTS CHARGES	:	\$	4,884.00	\$	
	TOTAL LABOUR CHARGES		\$	12,112.00	\$	2,650.00
	GRAND TOTAL		\$	16,996.00	\$	2,650.00

All charges are not inclusive of GST.

Legend:

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost :

Liability :

Remarks :

Please Note

This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant

Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Tuesday, 10 April 2018 4:30 PM

To:

'Boo seng yak'; Carrine Leong; Nora Khai; SUR

Subject:

RE: FINAL REVISION SLK6558T - OD AIG - SURVEYED 30 JAN 18

Dear Mr Boo,

Confirm repair cost of \$2,650.00 before excess \$600 and GST @ 3 days of repairs.

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak [mailto:boojohnny@gmail.com]

Sent: Tuesday, 10 April 2018 4:17 PM

To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong

<carrine.leong@premiumauto.com.sg>; Nora Khai <nora.khai@premiumauto.com.sg>

Subject: FINAL REVISION SLK6558T - OD AIG - SURVEYED 30 JAN 18

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$2650.00 @ 3 days of repairs.

Your early closure is appreciated.

best regards - jb

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Motor Claims Dept Yr Ref: SLK 6558 T Norah Khai 6768 9911 6841 1183 Nora.khai@premiumauto.com.sg Body & Paint Dept PA/OD/0099/2018/MAS

14 April 2018

from

Telephone +65-Telefax +65-

EMail

Date

Our department

Our Ref Your Ref

total pages

Dear Sir.

RE: INSURANCE CLAIM FOR SLK 6558 T, Audi A3 Sedan 1.0 TFSI

With reference to the above-mentioned vehicle, no. SLK 6558 T, claimant, Mr. Verma Navin Kumar, please find the related document per attached.

- A copy of the Original invoice no. 85012347 S\$2,193.50
- A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai Claims Dept

Encls

AIG - SLK 6558 T

total pages

Premium Automobiles Pte Ltc Showroom 9 Leng Kee Road Singapore 159090 Telephone (65) 6566 1111

Telefax (65) 6471 3733

Service & Parts Centres 55 Ubi Rd 1 Singapore 408699 Telephone (65) 6336 2323 Telefax (65) 684 11183

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Ad1 Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status		
Main	27 Jan 2018		31 Jan 2018 11:27 Edit Adj Rpt	S\$2,650.00 Edit Estimates	5\$2,650.00 View Rpt		Pending for Survey Report Cancel Case		
	Main	Refe	erence	Claim De	tails	Documents	_ Show All		
CLAIM S	SUBFOLDER DE						d by insurer] (VERMA@GMAIL.COM		
Insured: Vehicle R	eg. No.:	SLK65	NAVIN KUMAR, 58T	ID: G5441960R, Date of	Tel: +6585058527	20/01/20 [11 Mont	018 18:00 - :59 ths and 28 Days From Date (Man Yr)]		
Claim Typ	pe:	OD / 8	OD / 8905052191SG Policy/Cover Note No.: 2100498727-00000 (Comprehensive)			727-00000			
				Excess:					
Repairer:		Premiu	m Automobiles I	Pte Ltd (UBI) 55 L	lbi Road 1, 408699	Ubi - Tel: 676898	28/9827/9911		
	Insurer:	TongSh	no.Loo@aig.com				Loo, Tong Shing]		
Adjuster:		due 09	to Consultants P 0/02/2018]	C2015-004			LING] [Final Rpt		
Driver/Ci	ustodian:	VERMA	NAVIN KUMAR (44	/ Male), NRIC: (35441960R, Tel: -	6585058527			
ASSOCI	ATED MAIL RE	CEIVED				View All	Compose Case Mail		
AIG_5	SG (31/01/2018):	SLK6558T / OD	/ 20/01/2018 /	Coverage & Exce	ss update				
E ALL AS	SOCIATED TAS	KS		Vie	w All Search Ta	sks Create	New Task Complet		
Due D		Type Task G	roup Subject	Handler A	ssigned By C	ompleted On	Created On Don		

Claim Documents

*SLK6558T (8905052191SG) OD Jan 20 2018 6:00PM [VERMA NAVIN KUMAR] Premium Automobiles Pte Ltd

12	To a few manufacture of the control	Upload Photos Compose New Letter Upload Video U	pload Audio View	Use Viewer	•
	Ipload Documents	Opioso riocos	3 per p	page •	V
no	tos/Images	S. Martin Bro Ltd (MO)		Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	0	Load JPG	V
1	31/01/18 14:28	General View	0	Load JPG	V
2	31/01/18 14:28	General View			V
3	31/01/18 14:28	General View	0	Load JPG	-
4	31/01/18 14:28	General View	0	Load JPG	0
371		General View	0	Load JPG	V
5	31/01/18 14:28	A STANDARD CONTROL	0	Load JPG	V
6	31/01/18 14:28	General View	0	Load JPG	7
7	31/01/18 14:28	General View	0	Load JPG	V
8	31/01/18 14:28	General View			-
9	31/01/18 14:28	General View	0	Load JPG	V
			1 per	page 🕶	V
Doc	cumentation			Thumbnail	Prin
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	0	Load PDF	
1	31/01/18 14:35	Singapore Accident Statement	0	Load PDF	
2	31/01/18 14:36	Police Report	0	Load PDF	
3	31/01/18 14:36	Certificate of Insurance	0	Load PDF	
4	31/01/18 14:36	Insured's Driving License	0		
5	31/01/18 14:36	ESTIMATE	Ö		
6	19/04/18 10:26	WORKSHOP INVOICE	ő		
7	19/04/18 10:26	DISCHARGE VOUCHER		2130	

Linked Accident Report Documents

		View	Use Viewer	•
		1 per p	age 🕶	V
	n / Automobiles Pto Ltd (URT)		Thumbnail	Print
		0	Load HTM	
22/01/18 20:18	Accident statement			
tos/Images		3 per (V
Finalized On	Premium Automobiles Pte Ltd (UBI)			
22/01/18 20:13	Police Report			7
22/01/18 20:13	Police Report		Load JPG	V
	Police Report	0	Load JPG	V
		0	Load JPG	7
		0	Load JPG	V
		0	Load JPG	V
		0	Load JPG	V
22/01/18 20:16	MANAGORIAN SANCER CONTROL CONT	0	Load JPG	V
22/01/18 20:16	MANAGEMENT CONTROL OF THE CONTROL OF	1.1	Load JPG	7
22/01/18 20:16	Accident Photo		Load IPG	7
22/01/18 20:16	Accident Photo	-		Lane .
		1 per	page -	7
The state of the s	Descrive Automobiles Pte Ltd (URT)		Thumbnai	Print
1102		0	Load JPG	V
		0	Load JPG	V
	22/01/18 20:13 22/01/18 20:13 22/01/18 20:13 22/01/18 20:16 22/01/18 20:16 22/01/18 20:16 22/01/18 20:16 22/01/18 20:16 22/01/18 20:16 22/01/18 20:16	Finalized On Premium Automobiles Pte Ltd (UBI) 22/01/18 20:18 Accident Statement 22/01/18 20:13 Police Report 22/01/18 20:13 Police Report 22/01/18 20:13 Police Report 22/01/18 20:13 Police Report 22/01/18 20:16 Accident Photo 22/01/18 20:16 Secident Photo 22/01/18 20:16 Secident Photo 32/01/18 20:16 Accident Photo Sumentation Finalized On Premium Automobiles Pte Ltd (UBI) 22/01/18 20:13 Sketch Plan	Sement Reports 1 per process Finalized On	Sesment Reports Sesment Reports Sesment Reports Thumbnail Thumbnail Second HTM Sec

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	•
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way #07-16

CC3/AIG18001866/AVBN2

Date:

Our File No:

19/04/2018

REFERENCE

Date of Loss:

Insured/Claimant:

Singapore 079120

VERMA NAVIN KUMAR

Policy No:

2100498727-00000

Nature of Claim:

Claim No: 8905052191SG

WAUZZZ8VXH1046584

DESCRIPTION & IDENTIFICATION OF VEHICLE

20/01/2018

Reg No:

SLK6558T

Make & Model:

AUDI A3, 999cc TFSI (A) 23/01/2017 (Man. Year: 2016) Engine No: Chassis No: CHZ184936

11090 km

Reg. Date: Colour:

White 999 cc

Engine Capacity: Market Value/New Car

Price: Sum Insured (S\$): \$\$115,000.00

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Odometer:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size:

205/55R16

Rear Tyre Size:

205/55R16

Front Left Side:

Bridgestone 6 mm Bridgestone 6 mm Rear Left Side: Rear Right Side: Bridgestone 6 mm Bridgestone 6 mm

Front Right Side: The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts Miscellaneous Items		Repairer's 4,884.00 0.00	Adjuster's 0.00 0.00	Difference 4,884.00 0.00	Diff % 100.00
Labour Paintwork Labour		12,112.00 0.00	2,650.00 0.00	9,462.00 0.00	78.12
Towing		0.00	0.00	0.00	
Calculated Gro	oss Total (S\$) - Excess (S\$)	16,996.00 600.00	2,650.00 600.00	14,346.00 0.00	84.41 0.00
	(S\$)	16,396.00	2,050.00 143.50	14,346.00 1,004.22	87.50 87.50
	00/7.00% (S\$) : Amount (S\$)	1,147.72 17,543.72	2,193.50	15,350.22	87.50

INSPECTION

Date of Assignment:

31/01/2018

Date Inspected:

30/01/2018 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair:

3.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

*REAR FENDER SECTIONAL PART-LEFT *REAR WHEEL HOUSING LINER-LEFT *SET ATTACHMENT PARTS FOR WHEEL HOUSING *1/4 GLASS WINDOW-LH *REAR WINDSCREEN	Repair Not Necessary Not Necessary Not Necessary	2,006.00 FS 215.00 FS 77.00 FS	6 30,000,00
*REAR WHEEL HOUSING LINER-LEFT *SET ATTACHMENT PARTS FOR WHEEL HOUSING *1/4 GLASS WINDOW-LH	Not Necessary		*-FS
*SET ATTACHMENT PARTS FOR WHEEL HOUSING *1/4 GLASS WINDOW-LH		77 00 FS	Y
*1/4 GLASS WINDOW-LH		11.0010	*-FS
	140t 1400033dily	502.00 FS	*-FS
	Not Necessary	704.00 FS	*-FS
*PRIMER	Not Necessary	37.00 FS	
*GROMMET	Not Necessary	47.00 FS	
*SOUND ABSORBER	Not Necessary	216.00 FS	4
*1/4 GLASS SEALANT	Not Necessary	100.00 FS	*-FS
*REAR WINDSCREEN SEALANT	Not Necessary	200.00 FS	*-FS
*AYCLIC SEALER	Not Necessary	180.00 FS	*-FS
*CAVITY WAX	Not Necessary	140.00 FS	*-FS
*STONE CHIP	Not Necessary	180.00 FS	*-FS
*METAL FILLER POWDER	Not Necessary	280.00 FS	*-FS
Nett.			
	Total Parts (S\$	4,884.00	0.00
	*METAL FILLER POWDER Jett.	*METAL FILLER POWDER Not Necessary lett. Total Parts (S\$	*METAL FILLER POWDER Not Necessary 280.00 FS

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

		· · · · · · · · · · · · · · · · · · ·
Recommended	2	hour
Recommended	$_{La}$	DOUL

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO REMOVE AND REINSTALL REAR PARKING AID.CHECK FUNCTION	New	280.00	-
2	TO RENEW LHS 1/4 GLASS AND REAR WINDSCREEN TO FACILITATE FENDER RENEWAL	New	600.00	•
3	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT	New	1,400.00	
4	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS, SEAT BELTS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	
5	TO DISMANTLE REAR BUMPER AND REAR LID.CUT OUT AND WELD LHS REAR FENDER.REPAIR LHS REAR OUTER WHEEL HOUSE.REINSTALL ALL PARTS REMOVED	New	4,800.00	1,250.00
6	TO RESPRAY LHS REAR FENDER, LHS SILL PANEL, DOOR ENTRANCE, DRAIN PANEL, ROOF CHANNEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS	New	3,200.00	1,400.00
7	TO CARRY OUT WHEEL ALIGNMENT	New	240.00	-
8	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	
	Gross Labou	r Cost (S\$)	12,112.00	2,650.00
	Report was unsubmitted duri	ng this print-out		

< END OF ESTIMATES >