

Surveyor:

ADP108

DOI:

30-1-18

Date / Time:

30-1-18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SDM 33635

Name of Insured:

CHONG CHUN HING

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

26-01-18

Is driver the owner?

(YES / ☒ NO)

Nature of Accident:

If NO, Driver Name / Age:

ZHANG GUANG

Driver Tel No.:

97565901

(V/L: ☒ YES / NO)

Claim No.:

SNM180 00572004/21 LKK03

Policy No.:

OMPUSN 3113681701

Make / Model:

Y. Corolla

Place of Accident:

Yick Rd > TPE

OI GIA REPORT: ☒ YES / NO ; TP GIA REPORT: ☒ YES / NO

Insured Liability: % Final ? Yes / No

SKG 5620



INSRS:

WSP:

Tel:

Liability:

RMKS:

My Solution



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time:

5/2/18 + 12.10pm

SKG 5620 X; SDM 33635 X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

Email 8/2/18

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time: 20.1.18

Sent By: Ash.

FINALIZATION

Date/Time:

Confirm with:

Confirm by: LWP

Repair Cost:

45 SS 12,000

(8 days) Reduction:

54 %

Email ☒Call ☐

FINAL SETTLEMENT

Date/Time: 30-10-18

Confirm with: Su Wong

Email ☒Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

36

If NO or B 28, Ass. Lia:

Repair Cost:

w/HSI

SS 12,840.00

OID LOST CONTROL HIT TP.

Loss of Rental (LOR):

SS -

(days)

Loss of Use (LOU):

SS 960.00

(\$ 80 x 12 days)

Loss of Income (LOI):

SS -

(\$ x days)

LOR only ☐LOU only ☒LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS 29.00

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

Total:

SS 13,829.00

Global Sum SS:

FINAL PAYMENT

Date/Time: 30-10-18

Confirm with: Su Wong

Email ☒Call ☐

Payee 1:

SS 13,829.00

Name 1:

MG SOLUTION PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

CONFIRM

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

7400

Survivor

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ g days Res.: Yes or No

Lum Sum: _____ \$o % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKG 562 C. Yr Regn: 2007 / Dec

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: Mercedes Benz E200 C.C. 1796

Colour: Black A/G: Insured / Std / NI / NA

Sp. Reading: 245750. T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDB2110412B220918.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/55R16
R: 225/55R16.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 30/01/18

Survey held at MG Solution.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / • Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP Churn.
	CQE Expiry : 30/11/2027
	MV : 88K 4/5 : + 12,000 (RED : + 14,207.68 54%)
	PV : 49.3K
	NHt : 38.7K ,

Date/Time, File Pass to?

☐ : Prelim. Report
☐ : Final Report

12

Date/Time: File Return to?

2

Report Format :

Lump Sum / I.B.I: (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee: : Site Insp (\$

□ Interview	(\$
-------------	-----

Tech. Invs (\$)

☐ Weekend (\$

Survey Fee:

Transportation:

$$) \quad S + RS \rightarrow SI$$

) Photos

Others

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI18001932/Aea3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 31-01-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SDM 3363S	Veh. Inspected	SKG 562C	
Policy No.	DMPCSN3113681701	Coverage (\$)	0.00	
Claim No.	SNM18D00512C02/3/LKKDS	Excess (\$)	0.00	
Assign From		Assign Date	31/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	26/01/2018	Inspection Date	30/01/2018	
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Mei Kwan (LKKAUTO)

From: Angie Foo <angie.foo@sg.cntaiping.com>
Sent: Friday, 2 February, 2018 1:15 PM
To: Mei Kwan (LKKAUTO)
Cc: Zaini (LKK Auto); Hsiao Tong (LKKAUTO); Admin A; Jowyn Tay; Asher Sng (LKKAUTO)
Subject: OUR REF: SNM18D00512C02/3/LKKDS & YR REF: (TP : LKK REF - CC6/CTI18001932/Aea3) on 26.01.2018
Attachments: MSM118013336-SDM3363S.pdf; SNM18D00512C01 20180202 TO INSURED - SDM3363S-LKKDirectSettlementAccidentLtr.pdf
Follow Up Flag: Follow up
Flag Status: Flagged
Categories: HMK

Dear Mei Kwan,

We refer to your email of 1st February 2018.

We attached our Insured's SAS Report and Assignment Letter for your necessary action.

Please take note, the claim handler on this case is Jowyn Tay 63896174.

Thank you.

Regards,
Angie Foo
Executive
Motor Division
Claims Department
China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road #16-00
Springleaf Tower
Singapore 079909
Co.Reg.No.200208384E
DID: 6389 6186
Fax: 6224 7478 /6224 7175
Email: angie.foo@sg.cntaiping.com
Email: claimsdept@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer:

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Thursday, 1 February, 2018 6:18 PM
To: Claims Dept of CTI
Cc: Irene Tay; Zaini (LKK Auto); Hsiao Tong (LKKAUTO); Admin A
Subject: Direct Settlement - Accident Involving SDM3363S (OI : CAI - TBA) AND SKG562C (TP : LKK REF - CC6/CTI18001932/Aea3) on 26.01.2018



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
Tel: 6389 6111 Fax: 6222 1033
Website: www.sg.cntaiping.com
Co. Reg. No. 200208384E

Our Reference: **SNM18D00512/C01/3**

Date : **02 FEBRUARY 2018**

via Ordinary & Registered Mail

**CHONG CHIN HING
BLK 183 BEDOK NORTH ROAD
#19-56
SINGAPORE 460183**

Dear Sir / Madam

**ACCIDENT INVOLVING SDM3363S AND SKG562G ON 26 JANUARY 2018
ALONG YIO CHU KANG ROAD TOWARDS TPE/CHANGI TUNNEL**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SKG562C** , is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd

Attn : ASHER


Ref : TP : LKK REF - CC6/CTI18001932/Aea3

Contact No : 6841 6051

via Email : AsherSng@lkkauto.com

CC : Agent - (AN0509A) - NITA PTE LTD

F01/LKKDS-2013



Mercedes-Benz E-Class E200
(COE till 04/2027)

\$68,000

\$7,350 /yr

02-Jun-1997

1,998 cc

-

Luxury

Available

DIRECT OWNER

Posted: 28-Jan-2018 Tags: 1997 Mercedes-Benz E200, Mercedes-Benz E200, Mercedes-Benz, E200, Used Mercedes-Benz



Mercedes-Benz E-Class E200
(COE till 11/2027)

\$65,838

\$6,700 /yr

28-Nov-1997

1,998 cc

-

Luxury

Available

20 Years Old Car Kept Well Preserved, Easy To Maintain. Call Us Now To View Vehicle, In House Loan Available, Low Interest.

Posted: 27-Jan-2018 Tags: 1997 Mercedes-Benz E200, Mercedes-Benz E200, Mercedes-Benz, E200, Used Mercedes-Benz



Mercedes-Benz E-Class E200
(COE till 09/2018)

\$10,800

\$16,920 /yr

22-Sep-1998

1,998 cc

-

Luxury

Available

Posted: 14-Dec-2017 Tags: 1998 Mercedes-Benz E200, Mercedes-Benz E200, Mercedes-Benz, E200, Used Mercedes-Benz



Mercedes-Benz E-Class E200
(COE till 11/2027)

\$68,000

\$6,910 /yr

24-Dec-1998

1,998 cc

-

Luxury

Available

DIRECT OWNER

Posted: 04-Jan-2018 Tags: 1998 Mercedes-Benz E200, Mercedes-Benz E200, Mercedes-Benz, E200, Used Mercedes-Benz



Mercedes-Benz E-Class E200
(COE till 03/2019)

\$11,888

\$10,230 /yr

26-Apr-1999

1,998 cc

-

Luxury

Available

100% Genuine Mileage! Can Renew COE For Another 10yrs! Well Maintained With Regular Servicing, STA Evaluation Welcome! Viewing By Appointment, Call Now!

PREMIUM AD

Posted: 30-Jan-2018 Tags: 1999 Mercedes-Benz E200, Mercedes-Benz E200, Mercedes-Benz, E200, Used Mercedes-Benz



Mercedes-Benz E-Class E200K
(COE till 04/2026)

\$69,888

\$8,500 /yr

22-Apr-2006

1,796 cc

221,000 km

Luxury

Available

Most Part Spare Replaced Car Selling As Is For More Detail For Viewing. Please Kindly Sms Or Whatsapp Only Will Not Entertain To Call.no Major Repair Required As Most Of Them Being Replaced.

DIRECT OWNER

Posted: 14-Jan-2018 Tags: 2006 Mercedes-Benz E200K, Mercedes-Benz E200K, Mercedes-Benz, E200K, Used Mercedes-Benz



Mercedes-Benz E-Class E200 NGT
(COE till 05/2026)

\$76,500

\$9,200 /yr

24-May-2006

1,796 cc

-

Luxury

Available

Front Bumper/Grille And Tail Lights Converted To New Facelift Avantgarde Model. New Paintwork. Nano Coated Sealant. Bluetooth Phone System. Wear And Tear Parts Fully Replaced Such As AC Compressor, En...

DIRECT OWNER

Posted: 27-Nov-2017 Tags: 2006 Mercedes-Benz E200, Mercedes-Benz E200, Mercedes-Benz, E200, Used Mercedes-Benz



Mercedes-Benz E-Class E200K
(COE till 07/2026)

\$78,888

\$9,280 /yr

22-Nov-2006

1,796 cc

80,000 km

Luxury

Available

Guaranteed Accident-Free, Keyless Start, Genuine Low Mileage, 90% Loan At 3.98%, Guaranteed Loan For Bad Credit/Ex-Bankruptcy.

Monster Motors Pte Ltd

PREMIUM AD

Posted: 18-Dec-2017 Tags: 2006 Mercedes-Benz E200K, Mercedes-Benz E200K, Mercedes-Benz, E200K, Used Mercedes-Benz

Mercedes-Benz E-Class E200K
(COE till 12/2026)

\$83,000

\$9,340 /yr

20-Dec-2006

1,796 cc

136,000 km

Luxury

Available

DIRECT OWNER

Used mercedes-benz e200 Car & Used Cars & Vehicles Singapore - sgCarMart



Original Condition, Accident Free, 2 Owners, Other Info: COE Dec 202 6 (Extended 10 Yrs) Extremely Well Maintained, Excellent And Original Conditions, No Repairs If You Are Interested, Please Make An ...

Posted: 15-Jan-2018 Tags: 2006 Mercedes-Benz E200K, Mercedes-Benz E200K, Mercedes-Benz, E200K, Used Mercedes-Benz



Mercedes-Benz E-Class E200K \$75,800 \$8,320 /yr 12-Mar-2007 1,796 cc - Luxury Available
(COE till 03/2027)

Well Maintained With Regular Servicing And Wear And Tear Parts Done, Brake Pads And Disc Changed, Excellent Engine Condition! Must View To Appreciate. Bank/In House Loan Available, Trade In Are Welcom...

Posted: 23-Dec-2017 Tags: 2007 Mercedes-Benz E200K, Mercedes-Benz E200K, Mercedes-Benz, E200K, Used Mercedes-Benz



Mercedes-Benz E-Class E200K \$85,500 \$9,330 /yr 28-May-2007 1,796 cc 170,000 km Luxury Available
(COE till 03/2027)

Only 2 Owner With An Average Of 16000km Per Year, Well Maintained With Regular Servicing And Wear And Tear Parts Replaced (With Receipt) And 4 New Tires. Excellent Condition! Must View To Appreciate.

Posted: 14-Jan-2018 Tags: 2007 Mercedes-Benz E200K, Mercedes-Benz E200K, Mercedes-Benz, E200K, Used Mercedes-Benz

DIRECT OWNER

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view Expired ads

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or station wagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used mercedes-benz e200, mercedes-benz e200 Singapore, used mercedes-benz e200 Singapore, used mercedes-benz e200, used vehicles Singapore or even buy used mercedes-benz e200 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

© 2004-2018 sgCarMart. All rights reserved.

- Terms of Service
- Privacy Policy
- Personal Data Protection Statement

Compare

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0791E
Vehicle Details	
Vehicle No.:	SKG562C
Vehicle to be Exported:	Yes
Intended De-registration Date:	31 Jan 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E200K
Primary Colour:	Black
Manufacturing Year:	2007
Engine No.:	27195630958796
Chassis No.:	WDB2110412B220918
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$49,490.00
Original Registration Date:	17 Dec 2007
First Registration Date:	17 Dec 2007
Transfer Count:	3
Actual ARF Paid:	\$54,439.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Nov 2027
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$50,168.00
COE Rebate Amount:	\$49,331.00
Total Rebate Amount:	\$49,331.00

The information contained herein is correct as at 31 Jan 2018

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : mg3solution@gmail.com

TO	: CHINA TAIPING INSURANCE	DATE	: 30/01/2018
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT :			
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SKG562C	Asher.	
MODEL	: MERCEDES BENZ E250	WDB211042B220918.	
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 26-Jan-18
		TIME	: 18:35HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT SIDE MIRROR FRAME ASSY <i>Repld.</i>	1	\$ 2,100.00	\$ 2,100.00
2	FRONT DOOR RH <i>Disturbed</i>	1	\$ 1,980.00	\$ 1,980.00
3	FRONT DOOR HINGE <i>Best</i>	2	\$ 126.00	\$ 252.00
4	FRONT DOOR CHECKER <i>Best</i>	1	\$ 250.00	\$ 250.00
5	FRONT DOOR LOCK <i>Repld</i>	1	\$ 320.00	\$ 320.00
6	FRONT DOOR CATCH <i>New</i>	1	\$ 96.00	\$ 96.00
7	FRONT DOOR WEATHERSTRIP <i>New</i>	1	\$ 310.00	\$ 310.00
8	FRONT DOOR OUTER CHROME PROTECTOR <i>Kit</i>	1	\$ 103.00	\$ 103.00
9	FRONT DOOR OUTER CHROME <i>Repld</i>	1	\$ 155.30	\$ 155.30
10	FRONT DOOR INNER BOARD <i>Repld</i>	1	\$ 1,030.00	\$ 1,030.00
11	FRONT DOOR INNER SIDE BOARD <i>Missing</i>	1	\$ 290.00	\$ 290.00
12	FRONT DOOR INNER SPEAKER <i>Repld</i>	1	\$ 188.30	\$ 188.30
13	FRONT DOOR GLASS REGULATOR <i>Repld</i>	1	\$ 530.00	\$ 530.00
14	FRONT DOOR POWER WINDOW MOTOR <i>New</i>	1	\$ 655.90	\$ 655.90
15	SIDE SKIRT RH <i>Repld</i>	1	\$ 855.00	\$ 855.00
16	FRONT FENDER <i>Disturbed</i>	1	\$ 920.00	\$ 920.00
17	FRONT FENDER OUTER PROTECTOR <i>Missing</i>	1	\$ 150.00	\$ 150.00
18	FRONT FENDER OUTER PROTECTOR CHROME	1	\$ 196.00	\$ 196.00

Missing

Missing.

1238.

55

532

45

19	FRONT FENDER INNER COWLING <i>Neu</i>	1	\$ 198.00	\$ 198.00	*
20	FRONT WHEEL HOUSE PANEL <i>Neu</i>	1	\$ 760.00	\$ 760.00	*
21	FRONT KNUCKLE ARM <i>Beit</i>	1	\$ 1,200.00	\$ 1,200.00	✓ 1036
22	FRONT WHEEL HUP WITH BEARING <i>Byd</i>	1	\$ 630.00	\$ 630.00	✓
23	FRONT LOWER ARM(STRAIGHT) <i>Beit</i>	1	\$ 520.00	\$ 520.00	✓
24	FRONT LOWER ARM(BENT) <i>Beit</i>	1	\$ 490.00	\$ 490.00	✓
25	FRONT SHOCK ABSORBER <i>Neu</i>	1	\$ 820.00	\$ 820.00	*
26	REAR FENDER RH <i>Byis</i>	1	\$ 1,900.00	\$ 1,900.00	*
27	REAR BUMPER <i>Beit</i>	1	\$ 1,593.00	\$ 1,593.00	✓ 1358
28	REAR BUMPER SIDE MOULDING RH <i>lit</i>	1	\$ 172.00	\$ 172.00	-
29	REAR BUMPER SIDE RETAINER RH <i>Byd</i>	1	\$ 96.00	\$ 96.00	-
30	REAR BUMPER CENTER MOULDING <i>Neu</i>	1	\$ 196.00	\$ 196.00	*
31	TAIL LAMP <i>lit</i>	1	\$ 663.00	\$ 663.00	✓

TOTAL PRICE \$ 19,619.50

LESS 10% \$ 1,961.95

SUB TOTAL PRICE \$ 17,657.55

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT FENDER INNER COWLING CLIPS(SET) <i>Neu</i>	1	\$ 20.00	\$ 20.00	*
2	FRONT DOOR INNER BOARD CLIPS(SET) <i>Neu</i>	1	\$ 20.00	\$ 20.00	✓
3	SIDE SKIRT CLIPS(SET) <i>Neu</i>	1	\$ 20.00	\$ 20.00	✓
4	REAR BUMPER CLIP(SET) <i>Neu</i>	1	\$ 20.00	\$ 20.00	✓
5	WHEEL TYRE <i>Neu</i>	1	\$ 800.00	\$ 800.00	*
6	WHEEL RIM <i>lit</i>	1	\$ 2,500.00	\$ 2,500.00	✓ 800 800

TOTAL \$ 3,380.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	TO PANEL BEAT, WELD, CUT, KNOCK STRAIGHTEN, ADJUST GRAZE, JOIN	\$ 2,000.00	1000.	
2	TO PUTTY, SPRAY PAINT, POLISH, WAX AFFECTED PARTS AND PANELS	\$ 1,800.00	1000	
3	TUFF COAT	\$ 250.00	50	
4	WIRING CHECK	\$ 120.00	30	
3	TO REMOVE AND REFIX FRONT DOOR <i>Pittings</i>	\$ 250.00	80	
4	TO REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 350.00	220	
5	WHEEL ALIGHMENT	\$ 100.00	80	
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50	

6	RESET REVERSE SENSOR WIRE HARNESS	\$ 280.00	X	
---	-----------------------------------	-----------	---	--

TOTAL

\$5,230.00

2510

ESTIMATE REPORT

TOTAL PARTS COST : \$ 20,977.55

TOTAL LABOUR COS : \$ 5,230.00

TOTAL REPAIR COS : \$ 26,207.55

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

Adrian Lj
L/S 30/01/18.
08 Days.

total: 15291.24
L/S: 12K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Monday, 5 February 2018 12:16 PM
To: 'MG Solution'
Cc: Vic (LKKAuto)
Subject: Accident Involving SKG 562C & SDM 3363S on 26/01/2018

WITHOUT PREJUDICE

Your Ref: SKG 562C
Our Ref: CC6/CTI18001932/Aea3

Dear Sir/Madam,

Accident Involving SKG 562C & SDM 3363S on 26/01/2018

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Thursday, 8 February 2018 2:21 PM
To: 'GUIRONG@GMAIL.COM'
Subject: ACCIDENT INVOLVING SDM 3363S AND SKG 562C ON 26/01/2018



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC6/CTH18001932/Aea3

08 FEB 2018

CHONG CHIN HING

Dear Sir/Madam,

ACCIDENT INVOLVING SDM 3363S AND SKG 562C ON 26/01/2018

We refer to the above accident where we are acting for China Taiping Insurance (Singapore) Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Yours faithfully,

Asher
Case Handler
DID: 6841 6051
FAX: 6741 4108
Email: ashersng@lkkauto.com

c.c. China Taiping Insurance (Singapore) Pte Ltd
(Motor Claims Dept)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CT118001932/Aea3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 20-11-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SDM 3363S	Veh. Inspected	SKG 562C
Policy No.	DMPCSN3113681701	Coverage (\$)	0.00
Claim No.	SNM18D00512/C02/3/LKKDS	Excess (\$)	0.00
Assign From		Assign Date	30/01/2018

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ E200	c.c	1796
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	WDB2110412B220918	Colour	BLACK
Odometer	245750	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55 R16	MICHELIN	6 mm
L/H Front Tyre	225/55 R16	MICHELIN	6 mm
R/H Rear Tyre	225/55 R16	MICHELIN	6 mm
L/H Rear Tyre	225/55 R16	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND UNDERCARRIAGE.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	26/01/2018	Inspection Date	30/01/2018
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKG 562C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT SIDE MIRROR FRAME ASSY	DAMAGED	2,100.00	1,238.00
1	FRONT DOOR RH	DISTORTED	1,980.00	1,980.00
2	FRONT DOOR HINGE @\$126.00	BENT	252.00	252.00
1	FRONT DOOR CHECKER	BENT	250.00	250.00
1	FRONT DOOR LOCK	DAMAGED	320.00	320.00
1	FRONT DOOR CATCH	NOT NECESSARY	96.00	-
1	FRONT DOOR WEATHERSTRIP	NECESSARY	310.00	310.00
1	FRONT DOOR OUTER CHROME PROTECTOR	CUT	103.00	103.00
1	FRONT DOOR OUTER CHROME	DEFORMED	155.30	155.30
1	FRONT DOOR INNER BOARD	CRACKED	1,030.00	1,030.00
1	FRONT DOOR INNER SIDE BOARD	MISSING	290.00	55.00
1	FRONT DOOR INNER SPEAKER	DAMAGED	188.30	188.30
1	FRONT DOOR GLASS REGULATOR	DAMAGED	530.00	530.00
1	FRONT DOOR POWER WINDOW MOTOR	NOT NECESSARY	655.90	-
1	SIDE SKIRT RH	DEFORMED	855.00	532.00
1	FRONT FENDER	DISTORTED	920.00	920.00
1	FRONT FENDER OUTER PROTECTOR	MISSING	150.00	150.00
1	FRONT FENDER OUTER PROTECTOR CHROME	MISSING	196.00	45.00
1	FRONT FENDER INNER COWLING	NOT NECESSARY	198.00	-
1	FRONT WHEEL HOUSE PANEL	NOT NECESSARY	760.00	-
1	FRONT KNUCKLE ARM	BENT	1,200.00	1,036.00
1	FRONT WHEEL HUP WITH BEARING	DAMAGED	630.00	630.00
1	FRONT LOWER ARM (STRAIGHT)	BENT	520.00	520.00
1	FRONT LOWER ARM (BENT)	BENT	490.00	490.00
1	FRONT SHOCK ABSORBER	NOT NECESSARY	820.00	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	1,900.00	-
1	REAR BUMPER	DEFORMED	1,593.00	1,358.00
1	REAR BUMPER SIDE MOULDING RH	CUT	172.00	172.00
1	REAR BUMPER SIDE RETAINER RH	DAMAGED	96.00	96.00
1	REAR BUMPER CENTER MOULDING	NOT NECESSARY	196.00	-

Report Ref No. CC6/CTI18001932/Aea3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAIL LAMP	CUT	663.00	663.00
	LESS 10% DISCOUNT		-1,961.95	-1,302.36
			17,657.55	11,721.24
	SPECIAL NETT ITEMS			
1	SET FRONT FENDER INNER COWLING CLIPS (SN)	NOT NECESSARY	20.00	-
1	SET FRONT DOOR INNER BOARD CLIPS (SN)	NECESSARY	20.00	20.00
1	SET SIDE SKIRT CLIPS (SN)	NECESSARY	20.00	20.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	20.00	20.00
1	WHEEL TYRE (SN)	NOT NECESSARY	800.00	-
1	WHEEL RIM (SN)	CUT	2,500.00	800.00
			3,380.00	860.00
	LABOUR			
	TO PANEL BEAT,WELD,CUT,KNOCK STRAIGHTEN,ADJUST GRAZE,JOIN.INCLUSIVE OF THE REPAIR OF REAR FENDER RH.		2,000.00	1,000.00
	TO PUTTY,SPRAY PAINT,POLISH,WAX AFFECTED PARTS AND PANELS.		1,800.00	1,000.00
	TUFF COAT.		250.00	50.00
	WIRING CHECK.		120.00	30.00
	TO REMOVE AND REFIX FRONT DOOR FITTINGS.		250.00	80.00
	TO REMOVE AND REFIX FRONT UNDERCARRIAGE.		350.00	220.00
	WHEEL ALIGHMENT.		100.00	80.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		80.00	50.00
	RESET REVERSE SENSOR WIRE HARNESS.	NOT NECESSARY	280.00	-
			5,230.00	2,510.00
	GRAND TOTAL		26,267.55	15,091.24
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			12,000.00

Report Ref No. CC6/CTI18001932/Aea3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.