

JHK

JOO HAK KEE AUTO PTE LTD
裕合记汽车私人有限公司
SINCE 1986

ATTN: MOTOR CLAIMS DEPARTMENT
OWNER : WEE PANG BOON
INSURER : NTUC INCOME INSURANCE CO-OPERATIVE LTD
REFERENCE: AXA DIRECT SETTLE
DATE OF ACCIDENT: 27/01/2018

REPAIR ESTIMATE

Est. No. : E18010011
Date : 30/01/2018
Vehicle Num. : SGZ6146D
Make/Model : Honda Civic 18B A
Chassis/Eng# : FD11103397
Yr. of Manu : 2007

No	Description	Qty	U/P	Amt
Section: LIST ITEMS				
1	REAR BUMPER <i>dent</i>	1.00	638.00	638.00 ✓
2	REAR BUMPER CLIPS <i>n</i>	10.00	5.71	57.10 30
3	REAR BUMPER SIDE RETAINER LH <i>n</i>	1.00	16.90	16.90 ✓
4	REAR BUMPER SIDE RETAINER RH <i>n</i>	1.00	16.90	16.90 ✓
5	BOOT LID <i>Dented</i>	1.00	610.70	610.70 ✓
6	BOOT LID LOGO EMBLEM <i>2 pc</i>	1.00	28.90	28.90 ✓
7	BOOT LID 'CIVIC' EMBLEM	1.00	31.40	31.40 ✓
8	BOOT LID RUBBER <i>n</i>	1.00	99.30	99.30 ✓
9	BOOT LID INNER LOCK <i>Dented</i>	1.00	86.50	86.50 ✓
10	BOOT LID CATCH <i>n</i>	1.00	17.60	17.60 +
11	BOOT LID HINGE LH <i>2 pc</i>	1.00	50.90	50.90 +
12	BOOT LID HINGE RH	1.00	50.90	50.90 +
13	BOOT LID LAMP LH <i>2 pc</i>	1.00	152.70	152.70 +
14	BOOT LID LAMP RH	1.00	152.70	152.70 +
15	END PANEL <i>Dented</i>	1.00	314.70	314.70 ✓
16	END PANEL TOP GARNISH <i>Dented</i>	1.00	61.80	61.80 ✓
17	END PANEL TOP GARNISH CLIPS <i>n</i>	6.00	5.71	34.26 10
18	SPARE TYRE PANEL <i>2 pc</i>	1.00	899.00	899.00 +
19	REAR FENDER LH <i>2 pc</i>	1.00	776.30	776.30 +
20	REAR FENDER RH <i>2 pc</i>	1.00	776.30	776.30 +
21	REAR FENDER INNER SHIELD LH <i>2 pc</i>	1.00	45.90	45.90 +
22	REAR FENDER INNER SHIELD RH <i>2 pc</i>	1.00	45.90	45.90 +

Continue on next page...



JHK

JOO HAK KEE AUTO PTE LTD
裕合记汽车私人有限公司
SINCE 1986

ATTN: MOTOR CLAIMS DEPARTMENT
OWNER : WEE PANG BOON
INSURER : NTUC INCOME INSURANCE CO-OPERATIVE LTD
REFERENCE: AXA DIRECT SETTLE
DATE OF ACCIDENT: 27/01/2018

REPAIR ESTIMATE

Est. No. : E18010011
Date : 30/01/2018
Vehicle Num. : SGZ6146D
Make/Model : Honda Civic 18B A
Chassis/Eng# : FD11103397
Yr. of Manu : 2007

No	Description	Qty	U/P	Amt
23	REAR FENDER INNER SHIELD CLIPS LH <i>2 per</i>	6.00	5.71	34.26 +
24	REAR FENDER INNER SHIELD CLIPS RH	6.00	5.71	34.26 +
25	TAIL LAMP LH <i>Att</i>	1.00	236.70	236.70 +
26	TAIL LAMP RH <i>Att</i>	1.00	236.70	236.70 +
27	TAIL LAMP PANEL LH <i>2 Pys</i>	1.00	68.70	68.70 +
28	TAIL LAMP PANEL RH	1.00	68.70	68.70 +
29	TAIL LAMP BRACKET LH <i>2</i>	1.00	26.90	26.90 +
30	TAIL LAMP BRACKET RH	1.00	26.90	26.90 +
31	REAR NUMBER PLATE LAMP LH	1.00	16.90	16.90 +
32	REAR NUMBER PLATE LAMP RH	1.00	16.90	16.90 +

Amt S\$ 5,731.58

Discount (20.00%) S\$ 999.99

Subtotal S\$ 4,585.26

Section: SPECIAL NETT ITEMS

33	REAR NUMBER PLATE W/COVER <i>2 per</i>	1.00	50.00	50.00 +
34	REVERSE CAMERA Sensor <i>2 per</i>	1.00	300.00	300.00 + 2.00
35	REAR BUMPER LOWER SPOILER <i>Deland</i>	1.00	280.00	280.00
36	WINDSCREEN SEALANT <i>per</i>	1.00	60.00	60.00 +

Amt S\$ 690.00


Discount (0.00%) S\$ 0.00

Subtotal S\$ 690.00

Section: LABOUR

37	TO PANEL BEAT AND RENEWAL OF ALL DAMAGED PARTS	1.00	780.00	780.00 7.00
----	--	------	--------	-------------

Continue on next page...



BLK 3007 UBI ROAD 1 #01-406, SINGAPORE 408701
BLK 3014 UBI ROAD 1 #01-324, SINGAPORE 408702

TEL: 6743 1913 FAX: 6743 5234
EMAIL: admin@jhk.com.sg

CO/GST REG NO: 201300082W
WEBSITE: www.jhk.com.sg

bizSAFE₃



ATTN: MOTOR CLAIMS DEPARTMENT
 OWNER : WEE PANG BOON
 INSURER : NTUC INCOME INSURANCE CO-OPERATIVE LTD
 REFERENCE: AXA DIRECT SETTLE
 DATE OF ACCIDENT: 27/01/2018


REPAIR ESTIMATE

Est. No. : E18010011
 Date : 30/01/2018
 Vehicle Num. : SGZ6146D
 Make/Model : Honda Civic 18B A
 Chassis/Eng# : FD11103397
 Yr. of Manu : 2007

No	Description	Qty	U/P	Amt
38	TO PUTTY & SPRAY PAINTING ON ACCIDENT DAMAGED PORTION	1.00	1,280.00	1,280.00 600
39	TO REMOVE AND REINSTALL BOOTLID COMPARTMENTS	1.00	100.00	100.00 50
40	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	1.00	100.00	100.00 x
41	TO CHECK WIRING FUNCTION AND REFIT WIRING	1.00	60.00	60.00 30
42	TO ANTI-RUST	1.00	50.00	50.00 40

Amt S\$ 2,370.00
 Discount (0.00%) S\$ 0.00
 Subtotal S\$ 2,370.00

Admin Lj
 L/S 31/01/18.
 O/S Rys.
 total: 3376.6x
 L/S 2.71c.



Joo Hak Kee Auto Pte. Ltd.

LIST ITEMS Subtotal S\$ 4,585.26
 SPECIAL NETT ITEMS Subtotal S\$ 690.00
 LABOUR Subtotal S\$ 2,370.00
 Total S\$ 7,645.26

BLK 3007 UBI ROAD 1 #01-408, SINGAPORE 408701
 BLK 3014 UBI ROAD 1 #01-324, SINGAPORE 408702

TEL: 6743 1013 FAX: 6743 5234
 EMAIL: admin@jhk.com.sg

CO/GST REG NO: 201300082W
 WEBSITE: www.jhk.com.sg

bizSAFE₃