

輝陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add: SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

29/01/2018

Owner: ALLIANCE LEASING PTE LTD

ESTIMATE TO REPAIR MAZDA 6 2.0L - SKH469J

spray painting
labour charges
Total

\$	600.00	400
\$	400.00	200
\$	1,000.00	

Not Authorised
\$600
Resurvey ASPA Paint
2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

