

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 30 January 2018

Third Party Insurer: AIG

Vehicle No: SKS9689Z

Third Party Veh No: SJS9220D

Model: MERCEDES BENZ C200

Date of Accident: 27/01/18

Chassis: WDD2050422R047956

Not Authorized
1.B.1
Resurvey B & paint
2 days

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	Bu 1Mc	\$1,535.00
1	REAR BUMPER LOWER DIFFUSER	nd 1 cm	\$200.00
1	REAR BUMPER CHROME MOULDING		\$225.00
10	REAR BUMPER CLIP	\$6.00	mc \$60.00
8	REAR BUMPER RIVET	\$6.00	mc \$48.00
1	REAR BUMPER REINFORCEMENT		\$580.00
1	REAR BUMPER TOP RETAINER		\$140.00
2	REAR BUMPER SIDE RETAINER L+R	\$54.00	ln \$108.00
2	REAR BUMPER LOWER BRACKET L+R	\$35.00	ln \$70.00
1	REAR BUMPER LOWER UNDER COVER		ha \$120.00
SUB TOTAL			\$3,086.00
Less 10%			-\$308.60
PARTS TOTAL			\$2,777.40

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	\$500.00	2501
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	\$500.00	2801
TO DIAGNOSTIC CHECK & RESET MEMORY TO IDENTIFICATION STANDARD	\$280.00	801
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR	\$80.00	601
TO CHECK WIRING WITH TEST	\$80.00	201

LABOUR TOTAL \$1,440.00

WINSON

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL \$4,217.40