

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

41 G

Name : Muhammad Fadzly Bin Zainal

Accident Date : 27-Jan-18

Vehicle No : FW 8239 J

Vehicle Model : Honda NF100

Estimated Repair Costs

Qty	Description	Amount S(\$)
<u>List Items</u>		
1	Front fender	\$ 65.00
1	Front cowling	\$ 75.00
2	Fork inner tubes	\$ 180.00
2	Fork outer tubes	\$ 190.00
1	Fork under bracket	\$ 170.00
1	Front rim shaft	\$ 42.00
1	Front rim bearing	\$ 38.00
1	Front brake disc	\$ 145.00
1	Headlamp	\$ 80.00
2	Side mirrors	\$ 96.00
1	Handle bar	\$ 78.00
2	Handle bar ends	\$ 44.00
1	Hand grip (1 set)	\$ 50.00
1	Brake lever	\$ 32.00
2	Side cowlings	\$ 190.00
2	Side inner cowlings	\$ 156.00
1	Front footrest bracket	\$ 48.00
1	Front footrest rubber -R/H	\$ 22.00
1	Brake pedal	\$ 42.00
2	Rear footrests	\$ 76.00
2	Rear footrest brackets	\$ 130.00
1	Exhaust assy	\$ 380.00
1	Rear tailboard	\$ 95.00
1	Rear centre cowling	\$ 48.00
1	Rear taillamp	\$ 88.00
1	Rear fender	\$ 68.00
1	Rear signal	\$ 45.00
1	Basket	\$ 32.00
		\$ 2,705.00
		\$ 270.50
		\$ 2,434.50

Not Allowed

2/1/18

2/5 \$1

of day.

take photo after repair

1/2/18

48

78

38

65

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Less 10%

1170
1050

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Name : Muhammad Fadzly Bin Zainal

Accident Date : 27-Jan-18

Vehicle No : FW 8239 J

Vehicle Model : Honda NF100

Estimated Repair Costs

Special Nett Items

1	Number plate (1 set)	\$ 54	28.00	10
2	Fork oils	\$ 11	30.00	9
2	Fork oil seals	\$ 11	56.00	2
1	Steering cone bearing (1 set)	\$ 11	75.00	2
1	Rear box	\$ 11	180.00	1
1	Rear box bracket	\$ 11	100.00	2
1	ERP IU	\$ 11	160.00	2
		\$	629.00	

S/No.


Labour

1	To provide towing service.	\$	50.00	35
2	To check wiring and reset headlamp focusing.	\$ 11	80.00	2
3	To provide labour.	\$	380.00	250
		\$	510.00	

Grand Total

\$ 3,573.50

Dollars: Three Thousand Five Hundred Seventy-Three And Fifty Cents Only.



EROFIA MOTOR TRADING PTE LTD