

22/03/2002

ASS. REC. BY:

REF:

CS/MSC18002010 / Avbnz

Special Instructions:

Surveyor:

Adnan.

ASSIGNMENT (Office)

From (Person):

Catherine Thia

of

MST/1

Date/Time:

01/02/2018 2:14pm

Estimated Cost:

Bill to:

OD / HW / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SCJ 8R

Insured:

SLS 4176H

at Workshop m/s

Premium Automobile

Tel:

6768 9828

of

55 Ubi Rd 1

Policy No:

A29011816AYW

Claim No:

547898

Sum Insured:

Excess:

Make of Veh:

D.O.A.

27/01/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS wpi

H.O.D. Endorsement:

Date/Time:

01/02/2018 2:48pm

Person Contacted:

Tony

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SCJ 8R - X

SLS 4176H - X

2/2/18

Send preli revised by merimen

31/5/18

Final fig \$18,657.20 (Red 4864.80, 2670) confirmed by email

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6 8/5 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SCJ8 R. Yr Regn: 2011 August
Type: (M.Ca) / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A8C.C. 2995

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

181594

T/Radio: Insured / Std / NI / NA

Eng/No:

WAU222H4BN014830

C/No:

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / SPD A/Rim or

Tyre Size:

F:

255/45R19.

R:

255/45R19.BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

06

mm

Rear

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

01/02/18

Survey held at:

PremiumDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP M816.MV: 105KPV: 77KNett: 28K

RECEIVED 31 MAY 2010

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1)

Date/Time, File Return to?

2) 31/5- typist

Report Format:

merimenLump Sum / I.B.I. (\$) 18,657.20Days Of Repair: 6Resurvey No. of Trip: -

Survey Fee:

Transportation:

) S = RS.) SI

) Photos

) Others

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

TOTAL

300
10310



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18002010/Avb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 01-02-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLS 4176H	Veh. Inspected	SCJ 8R
Policy No.	A29011816AVW	Coverage (\$)	0.00
Claim No.	547898	Excess (\$)	0.00
Assign From	MERIMEN (CATHERINE THIA)	Assign Date	01/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	27/01/2018	Inspection Date	01/02/2018
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1. SINGAPORE 408699		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia Shi Yi

Date: 02 Feb 2018

Preliminary Advice

Insured Vehicle No	: SLS4176H	Accident Date	: 27/01/2018
TP Vehicle No	: SCJ8R	Assignment Date	: 01/02/2018
Make	: AUDI A8 L	Est. Duration of Repair	: 6.00
Date of Inspection	: 01/02/2018		
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,522.00
Revised Amount	:S\$	18,876.00
Check Items (Estimated)	:S\$	1,424.00
Total	:S\$	20,300.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

Survey Department Check List (Case Handler)

Reference No.: CS/MSG/8002010/Avb
Policy Type: OD/TP/TP RES/TL/EVA

Case Handler

Typist

Admin (

): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA/REV/REP)	✓			
C	Report Type				
C	Weekend Charges	✓			
N	Survey held at/Repairer				
C	Excess				

Surveyor (

): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages				

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)	✓			
C	Days of repair	✓			
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: VERON 31/5/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/20

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Jan 2018		01 Feb 2018 14:44 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	CHAN WEI SHAN, MELISSA, ID: S9348733H, Tel: +6591691363, Email: NOEMAIL								
Main Claimant:	LIM TIONG JOO, ID: S1605445C								
Vehicle Reg. No.:	SCJ8R	Date of Loss:	27/01/2018 16:00 - :59						
Claim Type:	TP / 547898	Policy/Cover Note No.:	A29011816AVW (Comprehensive) Coverage: 24/08/2017 - 23/08/2018						
Vehicle Reg. No. (Insured):	SLS4176H	Policy No. (Claimant):							
		Excess:	S\$2,000.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 02/02/2018]								
Driver/Custodian (Insured):	CHAN WEI SHAN, MELISSA (24 / Female), NRIC: S9348733H, Tel: +6591691363								
Adj Asg. Remarks:	ON WP								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
<div> <input type="checkbox"/> </div> ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 31 May 2018 9:46 AM
To: Mei Kwan (LKKAUTO); Nora Khai; Carrine Leong; (boojohnny@gmail.com)
Cc: SUR
Subject: RE: FINAL REVISION - SCJ8R - TP NSIG - SURVEYED 1 FEB 18

Dear Mr Boo,

Confirm repair cost of \$18,657.20 before GST @ 6 days of repairs .

Final invoice and all supporting documents sent over to MSIG

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAUTO)
Sent: Tuesday, 22 May 2018 6:32 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: FINAL REVISION - SCJ8R - TP NSIG - SURVEYED 1 FEB 18

Hi,

Fyna. [CS/MSG18002010/Avb](#).

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak [<mailto:boojohnny@gmail.com>]
Sent: Tuesday, 22 May, 2018 4:39 PM
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; Nora Khai <nora.khai@premiumauto.com.sg>
Subject: FINAL REVISION - SCJ8R - TP NSIG - SURVEYED 1 FEB 18

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$18,657.20 @ 6 days of repairs exclude 1 Sunday and 1 Public Holiday.

Your early closure is well appreciated.

Best regards - jb

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5445C
Vehicle Details	
Vehicle No.:	SCJ8R
Vehicle to be Exported:	No
Intended De-registration Date:	02 Feb 2018
Vehicle Make:	AUDI
Vehicle Model:	A8L 3.0 TFSI QU (SR+HID)
Primary Colour:	Grey
Manufacturing Year:	2011
Engine No.:	CGW005561
Chassis No.:	WAUZZZ4H4BN014830
Maximum Power Output:	213.0 kW (285 bhp)
Open Market Value:	\$82,593.00
Original Registration Date:	26 Aug 2011
First Registration Date:	26 Aug 2011
Transfer Count:	0
Actual ARF Paid:	\$82,593.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Aug 2021
PARF Rebate Amount:	\$53,685.00
Intended COE Rebate Details	
COE Expiry Date:	25 Aug 2021
COE Category:	B - Car (1601cc & above)

COE Period(Years):	10
QP Paid:	\$65,521.00
COE Rebate Amount:	\$23,337.00
Total Rebate Amount:	\$77,022.00

The information contained herein is correct as at 02 Feb 2018

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5445C
Vehicle Details	
Vehicle No.:	SCJ8R
Vehicle to be Exported:	Yes
Intended De-registration Date:	01 Feb 2018
Vehicle Make:	AUDI
Vehicle Model:	A8L 3.0 TFSI QU (SR+HID)
Primary Colour:	Grey
Manufacturing Year:	2011
Engine No.:	CGW005561
Chassis No.:	WAUZZZ4H4BN014830
Maximum Power Output:	213.0 kW (285 bhp)
Open Market Value:	\$82,593.00
Original Registration Date:	26 Aug 2011
First Registration Date:	26 Aug 2011
Transfer Count:	0
Actual ARF Paid:	\$82,593.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Aug 2021
PARF Rebate Amount:	\$53,685.00
Intended COE Rebate Details	
COE Expiry Date:	25 Aug 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$65,521.00
COE Rebate Amount:	\$23,355.00
Total Rebate Amount:	\$77,040.00

The information contained herein is correct as at 01 Feb 2018



Audi A8

Price Range

Depreciation

2011

Vehicle Type

Advanced Search

Used Car Comparison

--- Comparing 2 Vehicles ---

Audi A8 4.2A FSI Quattro

Audi A8L 3.0A TFSI Quattro



Clear All

Add all to Shortlist

Back to search result

Add to Shortlist

Add to Shortlist

Use search bar above to select another car to compare.

Use search bar above to select another car to compare.

CAR DETAILS

Price	\$101,800	\$118,000	-	-
Instalment	\$1,759	\$1,822	-	-
Registration Date	16-Apr-2011	19-Sep-2011	-	-
Manufactured	2011	2011	-	-
Mileage	117,000 km	37,000 km	-	-
Transmission	Auto	Auto	-	-
Engine Cap	4,163 cc	2,995 cc	-	-
Road Tax	\$4,206 /yr	\$2,380 /yr	-	-
Power	273.0 kW (366 bhp)	213.0 kW (285 bhp)	-	-
Curb Weight	1,835 kg	1,880 kg	-	-
Features	Powerful 4.2L V8 Engine, 8 Speeds Automatic Transmission, Audi Quattro All-Wheel Drive System, Space Frame Aluminium Construction, Keyless System.	Audi's V6 TFSI Engine Producing 290B, Churning A Torque Of 420Nm Coupled With 8-Speed Automatic Tiptronic With Paddle Shifting.	-	-
Accessories	20" Original Sport Rims, Audi MMI, Bluetooth Connectivity For Phone And Music, GPS Navigation, Audi Park Assist, Cruise Control, Auto Headlight.	Full Cocoa Leather Interior With SElectronic Seats, Electronic Sunroof, Reverse Camera, GPS, Bluetooth, Rear Aircon, Rear Window Blind, Keyless Start/Stop.	-	-
Description	Fully Serviced And Maintained By Agent, Reasonable Mileage Done, Loan And Insurance Can Be Arranged, Check With Our Friendly Consultant For More Information.	Stunning Black Exterior Paintwork Agent Unit Unit Maintained In Excellent Condition! Extremely Low Mileage Considered For Its Age! Brand New Air Suspension Pumps. Call Now To Enquire Or To Arrange For A Viewing!	-	-
COE	\$72,001	\$63,002	-	-
OMV	\$92,156	\$81,318	-	-
ARF	\$92,156	\$81,318	-	-
Depreciation	\$17,400 /yr	\$21,310 /yr	-	-
No. of Owners	6	2	-	-
Type of Vehicle	Luxury	Luxury	-	-
Category	PARF Car	PARF Car, Low Mileage Car	-	-
Availability	Available	Available	-	-

SELLER INFORMATION

Seller	SKL Automobile Pte Ltd	AutoInc Eurosports	-	-
--------	------------------------	--------------------	---	---

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Lim Tiong Joo
 Period of Insurance : 26 Aug 2017 To 25 Aug 2018
 Engine No. : CGW005561
 Chassis No. : WAUZZZ4H4BN014830

Vehicle No. : SCJ8R
 Policy No. : 2100271592-06
 Endorsement No. :
 Issued Date : 17 Aug 2017

ABOUT THE COVER

Make/Model : AUDI A8L 3.0 TFSI QU
 Engine Capacity/Tonnage : 2,995.00 CC
 Driver Restriction : NA

Sum Insured : Market Value
 Off Peak Car : No

First Year of Registration : 2011
 Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDER") if You are or Your Authorised Driver (named or unnamed) is under the age of 25 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$1400 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Lim Tiong Joo - \$1400 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1956 (Malaysia).

0504125200

PREMIUM LEASING - AP

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
 SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

M. J. Tan

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

SSC00H

IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries, or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Vins/Summons/Correspondences from third party(ies) to AIG immediately.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number (65) 6419-3000 for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within 3 working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the original insurance policy and schedule issued by AIG, a copy of the Accident Report from Audi Customer Service Centre must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.
8. **The rental car will be delivered (within Singapore), and MUST BE RETURNED BACK TO Audi Customer Service Centre upon collection of your accident car.**

Rental Car Company: Premium Automobiles Pte. Ltd.

Activation Hotline: 64741223

55 Ubi Road 1 Singapore 408699

Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 1pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc).

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is **IMPORTANT** and **MUST** be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: **S9516177D**

Name:

WESLEY LIM YONG JIN

Birth Date: **21 Apr 1995**

Issue Date: **26 May 2016**



002571501A

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor cars with unladen weight $\leq 3000\text{kg}$ with ≤ 7 passengers, exclusive of driver; and other motor vehicles with unladen weight $\leq 2500\text{kg}$ 26 May 2016



Licence No: S9516177D

NP 428A

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/130/2018/GW
Date	:	30-Jan-18

Vehicle IN workshop. Kindly arrange for survey.

MSIG Insurance (Singapore) Pte Ltd

No 4 Shenton Way

#23-01 SGX Centre 2

Singapore 068896

Attn: Motor Claims Dept

Tel: 6827 27692 - Fax: 6225 7402

Owner's Name	:	Mr. Lim Tiong Joo
Address	:	50 Canberra Drive #08-19 Singapore 768438
Telephone	:	HP +65 96700294
Type of Claim	:	Third Party Claim
Policy No.	:	2100271592-06
Vehicle No	:	SCJ 8 R
Model Code	:	Audi A8L 3.0 TFSI Qu
Model / Year	:	Aug-11
Engine No	:	CGW 005561
Chassis No	:	WAUZZZ4H4BN014830
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	27-Jan-18
Place of Accident	:	Bukit Batok East Ave 3

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SCJ 8 R

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rhs front and rear door's multi-lock system, window devices with audio equipments.	S/N \$ 760.00 ✓	✓
2	To remove and renew rhs front and rear door, transfer old fittings to new doors. Reshape rhs rear fender, dismantle and renew rhs side member trim. Align to position and reinstall all parts removed.	\$ 2,800.00	2000 ✓
3	To remove paint on rhs front door, rear door, rear fender, side member trim.	\$ 3,400.00	2800 ✓
4	To remove and renew rhs rear wheel rim, check tyre and alignment.	S/N \$ 320.00 ✓	✓
5	To carry out diagnostic check.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		\$ 7,472.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCJ 8 R.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT DOOR-RH <i>Dented</i>	\$ 4,709.00	✓ 4709
2	FRONT DOOR ATTACHEMENT PARTS-RH <i>Not Nec</i>	\$ 188.00	? X
3	FRONT OUTER DOOR SEAL-RH <i>Ren</i>	2 \$ 488.00	✓ 244
4	BONDING AGENT <i>Not Nec</i>	\$ 43.00	? X
5	CLEANING SOLUTION <i>Not Nec</i>	\$ 64.00	? X
6	FRONT DOOR SOUND ABSORBER-RH <i>Not Nec</i>	2 \$ 216.00	? X
7	FRONT DOOR SEAL- RH <i>Ren</i>	\$ 202.00	+
8	REAR DOOR-RH <i>Dented</i>	\$ 5,578.00	✓ 5578
9	REAR DOOR ATTACHMENT PARTS-RH <i>Not Nec</i>	\$ 98.00	? X
10	REAR OUTER DOOR SEAL -RH <i>Ren</i>	\$ 244.00	✓ 244
11	BONDING AGENT <i>Not Nec</i>	\$ 43.00	? X
12	CLEANING SOLUTION <i>Not Nec</i>	\$ 64.00	? X
13	REAR DOOR SOUND ABSORBER-RH <i>Not Nec</i>	\$ 108.00	? X
14	REAR DOOR SEAL-RH <i>Ren</i>	\$ 200.00	+
15	SIDE MEMBER TRIM-RH <i>Repair</i>	\$ 988.00	+
16	SIDE MEMBER TRIM ATTACHEMENT PARTS <i>Ren</i>	\$ 432.00	X.
17	SIDE MEMBER TRIM COVER STRIP-RH <i>Ren</i>	\$ 961.00	✓ 961
18	REAR ALUMINIUM RIM-RH <i>Ren</i>	\$ 824.00	✓ 824
19	SUNDRIES <i>Nec</i>	\$ 600.00	? 125.20
TOTAL SPARE PARTS CHARGES		\$ 16,050.00	
TOTAL LABOUR CHARGES		\$ 7,472.00	
GRAND TOTAL		\$ 23,522.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lij
Surveyed Date : 01/02/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 06 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[Signature]
2/2/18

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/130/2018/GW
Date : 30-Jan-18

Vehicle IN workshop. Kindly arrange for survey.

MSIG Insurance (Singapore) Pte Ltd

No 4 Shenton Way

#23-01 SGX Centre 2

Singapore 068896

Hi Adrian

6 days exclude 1 Sunday 1 PH

jb 22 May 18

Attn: Motor Claims Dept

Tel: 6827 27692 - Fax: 6225 7402

Owner's Name : Mr. Lim Tiong Joo
Address : 50 Canberra Drive
#08-19
Singapore 768438
Telephone : HP +65 96700294
Type of Claim : Third Party Claim
Policy No. : 2100271592-06
Vehicle No : **SCJ 8 R**
Model Code : Audi A8L 3.0 TFSI Qu
Model / Year : Aug-11
Engine No : CGW 005561
Chassis No : WAUZZZ4H4BN014830
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 27-Jan-18
Place of Accident : Bukit Batok East Ave 3

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SCJ 8 R

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rhs front and rear door's multi-lock system, window devices with audio equipments.	S/N \$	760.00	\$ 760.00
2	To remove and renew rhs front and rear door, transfe old fittings to new doors. Reshape rhs rear fender, dismantle and renew rhs side member trim. Align to position and reinstall all parts removed.	\$	2,800.00	\$ 2,000.00
3	To remove paint on rhs front door, rear door, rear fender, side member trim.	\$	3,400.00	\$ 2,800.00
4	To remove and renew rhs rear wheel rim, check trye and alignment.	S/N \$	320.00	\$ 320.00
5	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 7,472.00</u>	<u>\$ 6,072.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCJ 8 R.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT DOOR-RH	\$ 4,709.00	\$ 4,709.00
2	FRONT DOOR ATTACHEMENT PARTS-RH	\$ 188.00	
3	FRONT OUTER DOOR SEAL-RH	2 \$ 488.00	\$ 244.00
4	BONDING AGENT	\$ 43.00	
5	CLEANING SOLUTION	\$ 64.00	
6	FRONT DOOR SOUND ABSORBER-RH	2 \$ 216.00	
7	FRONT DOOR SEAL- RH	\$ 202.00	
8	REAR DOOR-RH	\$ 5,578.00	\$ 5,578.00
9	REAR DOOR ATTACHMENT PARTS-RH	\$ 98.00	
10	REAR OUTER DOOR SEAL -RH	\$ 244.00	\$ 244.00
11	BONDING AGENT	\$ 43.00	
12	CLEANING SOLUTION	\$ 64.00	
13	REAR DOOR SOUND ABSORBER-RH	\$ 108.00	
14	REAR DOOR SEAL-RH	\$ 200.00	
15	SIDE MEMBER TRIM-RH	\$ 988.00	
16	SIDE MEMBER TRIM ATTACHEMENT PARTS	\$ 432.00	
17	SIDE MEMBER TRIM COVER STRIP-RH	\$ 961.00	\$ 961.00
18	REAR ALUMINIUM RIM-RH	\$ 824.00	\$ 824.00
19	SUNDRIES	\$ 600.00	\$ 25.20
	TOTAL SPARE PARTS CHARGES	\$ 16,050.00	\$ 12,585.20
	TOTAL LABOUR CHARGES	\$ 7,472.00	\$ 6,072.00
	GRAND TOTAL	\$ 23,522.00	\$ 18,657.20

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18002010/AVBN2

Date: 01/06/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A29011816AVW
Claimant Vehicle No :	SCJ8R	Insured Vehicle No :	SLS4176H
Date of Loss:	27/01/2018	Nature of Claim:	TP
		Claim No:	547898

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCJ8R	Engine No:	CGW005561
Make & Model:	AUDI A8 L, 4.0 TFSI Quattro (D4) (A)	Chassis No:	WAUZZZ4H4BN014830
Reg. Date:	26/08/2011 (Man. Year: 2011)	Odometer:	181594 km
Colour:	Silver		
Engine Capacity:	2995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/45R19	Rear Tyre Size:	255/45R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,050.00	12,585.20	3,464.80	21.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,472.00	6,072.00	1,400.00	18.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	23,522.00	18,657.20	4,864.80	20.68
+ GST 7.00/7.00% (S\$)	1,646.54	1,306.00	340.54	20.68
Nett Amount (S\$)	25,168.54	19,963.20	5,205.34	20.68

INSPECTION

Date of Assignment:	01/02/2018	
Date Inspected:	01/02/2018	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 01 Jun 2018)
Parts: 143	AUDI A8 L 4.0 TFSI Quattro (D4) (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SCJ8R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR-RH	Dented	4,709.00 FS	*4,709.00 FS
2	1		*FRONT DOOR ATTACHMENT PARTS-RH	Not Necessary	188.00 FS	*- FS
3	2		*FRONT OUTER DOOR SEAL-RH	Necessary	488.00 FS	*244.00 FS
4	1		*BONDING AGENT	Not Necessary	43.00 FS	*- FS
5	1		*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS
6	2		*FRONT DOOR SOUND ABSORBER-RH	Not Necessary	216.00 FS	*- FS
7	1		*FRONT DOOR SEAL-RH	Not Necessary	202.00 FS	*- FS
8	1		*REAR DOOR-RH	Dented	5,578.00 FS	*5,578.00 FS
9	1		*REAR DOOR ATTACHMENT PARTS-RH	Not Necessary	98.00 FS	*- FS
10	1		*REAR OUTER DOOR SEAL-RH	Necessary	244.00 FS	*244.00 FS
11	1		*BONDING AGENT	Not Necessary	43.00 FS	*- FS
12	1		*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS
13	1		*REAR DOOR SOUND ABSORBER-RH	Not Necessary	108.00 FS	*- FS
14	1		*REAR DOOR SEAL-RH	Not Necessary	200.00 FS	*- FS
15	1		*SIDE MEMBER TRIM-RH	Repair	988.00 FS	*- FS
16	1		*SIDE MEMBER TRIM ATTACHMENT PARTS	Not Necessary	432.00 FS	*- FS
17	1		*SIDE MEMBER TRIM COVER STRIP-RH	Cut	961.00 FS	*961.00 FS
18	1		*REAR ALUMINIUM RIM-RH	Cut	824.00 FS	*824.00 FS
19	1		*SUNDRIES	Necessary	600.00 FS	*25.20 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	16,050.00	12,585.20
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER RHS FRONT AND REAR DOORS MULTI-LOCK SYSTEM,WINDOW DEVICES WITH AUDIO EQUIPMENTS	New	760.00	760.00
2	TO REMOVE AND RENEW RHS FRONT AND REAR DOOR,TRANSFER OLD FITTINGS TO NEW DOORS,RESHAPE RHS REAR FENDER,DISMANTLE AND RENEW RHS SIDE MEMBER TRIM.ALIGN TO POSITION AND REINSTALL ALL PARTS REMOVED	New	2,800.00	2,000.00
3	TO REMOVE PAINT ON RHS FRONT DOOR,REAR DOOR,REAR FENDER,SIDE MEMBER TRIM	New	3,400.00	2,800.00
4	TO REMOVE AND RENEW RHS REAR WHEEL RIM,CHECK TYRE AND ALIGNMENT	New	320.00	320.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			7,472.00	6,072.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >