

LKK AUTO CONSULTANTS PTE LTD

51 Ubi Ave1, #01-25 Paya Ubi Industrial Park, Singapore 408933.

TEL : 6256 3561

FAX : 6256 4315

Reg. No: 199607198R

GST Reg. No. 19-9607198-R

MINISTRY OF DEFENCE
HQ-TRANSPORT COMMAND
KRANJI CAMP 3
151 CHUA CHU KANG WAY
SINGAPORE 688248

REF No. CC2/MIDA18002055/Ujq2
REF Date 16/5/2019
Code MIDA

DISBURSEMENT FEE

Vehicle No. MID 35229
Insured
Claim No FY17/18/0054
Policy No
Accident Date 31/1/2018
Inspection Date 2/2/2018

LKK Cost of Claim paid to claimant on behalf of MINDEF	Amount	GST	Total
Repair Cost of SJM 1789P	\$ 5,400.00	\$ 378.00	\$5,778.00
Loss of Revenue (6 days x \$60.00)	\$ 360.00	\$ -	\$ 360.00
Total Fee	\$ 5,760.00	\$ 378.00	\$ 6,138.00
Total Fee (Paid Global Sum)	\$ 5,622.00	\$ 378.00	\$ 6,000.00

We shall be glad if you could forward us the payment at your early convenience.

Cheque should be crossed and made payable to "LKK AUTO CONSULTANTS PTE LTD".

LKK AUTO CONSULTANTS PTE LTD

CHEW LIAN