

## LKK AUTO CONSULTANTS PTE LTD

51 Ubi Ave1, #01-25 Paya Ubi Industrial Park, Singapore 408933.

TEL : 6256 3561

FAX : 6256 4315

Reg. No: 199607198R

GST Reg. No. 19-9607198-R

MINISTRY OF DEFENCE  
HQ-TRANSPORT COMMAND  
KRANJI CAMP 3  
151 CHUA CHU KANG WAY  
SINGAPORE 688248

REF No. CC2/MIDA18002055/Ujq2  
REF Date 16/5/2019  
Code MIDA

### DISBURSEMENT FEE

Vehicle No. MID 35229  
Insured  
Claim No FY17/18/0054  
Policy No  
Accident Date 31/1/2018  
Inspection Date 2/2/2018

| <u>LKK Cost of Claim paid to claimant on behalf of MINDEF</u> |           |                 |
|---------------------------------------------------------------|-----------|-----------------|
| Repair Cost of SJM 1789P                                      | \$        | 5,400.00        |
| GST paid to claimant on behalf of MINDEF                      | \$        | 378.00          |
| Loss of Revenue (6 days x \$60.00)                            | \$        | 360.00          |
| <b>Total Fee</b>                                              | <b>\$</b> | <b>6,138.00</b> |
| <b>Total Fee (Paid Global Sum)</b>                            | <b>\$</b> | <b>6,000.00</b> |

We shall be glad if you could forward us the payment at your early convenience.

Cheque should be crossed and made payable to "LKK AUTO CONSULTANTS PTE LTD".

LKK AUTO CONSULTANTS PTE LTD

CHEW LIAN