1950m			a (1. lux	
INS. CASE OV	THERE Flanc	CC# / EQI1800	2057 /TI 883 W IDAC	
	my	ASSIGN	MENT	
Surveyor	44266	DOI:	Date / Tiple 31/01/12	
Pre-assign /	CU/ETE		Registered in Menmen:	
	1000	2120 V	v.	
Insured Vehic	le No. YV	32725	Claim No. : 0m18/296 - EC	
Name of Innu	ed APPLIED	LOATETICS PTE LTD	Policy No. : PMCFHQ17-000/41	
Insured Tel N		HP:	Make / Model : MITSUBISHI FE8 1866	SE NEA - 20
Excess Sec II	:55	D.O.A: 25/01/18	Place of Accident: SLE (BKE) BEFORE B	
Is driver the o	Amer? (YES / 60		actions of actions of	RE CILI
	Name / Age: BONT &		OF GIA REPORT: YES / NO : TP GIA REPORT: YES / NO	
Driver	Tel No. : 8287 14	OH (VALTES/NO)	Insured Liability: % Final? Yes/No	
634	2725		7.	
01		SITG Z4E	650 45518 - UNKNOWN	-> UNKNOW!
INSRS: WSP:		NSP: Ethoz Gray	INSRS: INSRS:	
H Tet:	HH	el U U	WSP: Tel: WSP: Tel:	
Liability : RMKS:	100 -477	inbility:	Liability:	
Date/Time		OIAS:	RMKS: RMKS:	
Time Time	STT 9346 - X	C. C. Win Francisco	Processing and the second	
02/02/8 (Ach	7)	1 YN 31925 -V	STAGE DATE / PIC Non-Reporting by (1st)	
			Non-Reporting ltr (2nd)	
च्यांशह € 3.44 इ.स. ६ के खादादद	M CHURD OUD CONFIRM	DED ACLIDERY DID PRICUED IT	Non-Reporting lit (Final):	
200	TOTAL STATE LAND	ST VEN. Juffsons TO Coders Acres	N SWITE C Nittification for (if non-pickup) O To Satus Call Of: Employ 27 2 2 18	- 1
	AND AWARE ARD	of these locates.	After sall lir to Ot	-
	EMAIN WAS LIMBURT	. wase	Documentation Check List: Handler Typist	_
	EURIC RIPL CHICITAL	CLERC.	Notification lit (if non-pickup)	
2/1/1	8 FILE PAGE TO T	YAND TO PREPARE REPORT.	After call its to OI Authorisation To Act:	
			Release Voucher: (No. NEED)	-
11/0	extend 1	12	Final Repair Bill:	-
	CVIENO I	lo	Car Rental Invoice:	
			Towing Invoice	
			LTA / GIA : Medical Bill	
			PIR:	
	DECE	IVED 0 3 OCT 2018	Mandate/Reject Instruction:	
	KECE	TAED 0 2 001 5010	LOD	
PRELIMINARY ADVICE	F. Dute/Time: 0:5 s 5		Payment Breakdown Form:	
	2 system 15-10	Sent By: HMF	Post-Repair Photos.	
FINALIZATION	Date/Time:	Confirm with:	Others:	
Repair Cost: 1/5	\$\$ 10,000	to days) Reduction: 60	Confirm by:	
FINAL SETTLEMENT	Date/Time: 03 volv8	Confirm with Names	Email Call	-
Final Linbility	% 100 (Agree	ed / Assessed) BOLA S/N No. : 38	# NO or B 28. Ass. Lin : 100%	-
Repair Cost: #Fest Loss of Rental (LOB)	55 lb 700 .00	3 VEN C.C	Oth Jest.	-
Loss of Use (LOU):	SS CAN ID AS EN	days.)		
Loss of Income (LOI):	SS (200-00 1550	s (L days)	L France	
LOR only LOU on	The second secon	x days) LOR + LO	2010	
GIA/LTA Search	5534.45	LOR + LO [Tick only one]	5 10 0	OBL
Medical:	28 -			1
Disbursement:	SS -	(e.g. Tow/ Independent)	Claim status: Nemsal/Reject/Private Senie Researt University	Bu
Legal Cost	SS -	A. A. (See, mange policia)	2) Report Format: TP 3) Survey fee: \$400	9
Lotal:	\$\$ 11.336.45	Global Sum S\$:	(3) Survey fee: +100	-
				11
FINAL PAYMENT	Date/Time: 02.10-18	Confirm with: Pething	Email Call	-1
PINAL PAYMENT Payee 1:	58 11, 334-45	Name I Emoz PROSECT PR		7
	Date/Time: 02.10-18			

taught EQI	Ref: 18002057	171055
any		GE 2019 Sey.
01/02/18	S5T9346	a mod Sex.
	6	
11 A 12 12 11 11 12 11 11 11 11 11 11 11 11	their terminal of	
SJT 934G	flouda lik	1497
5/1 4544	Miss	el mana in n ne
E-hoz	15 = 12 = 1 D D	Figure Hauses Brown No.
30, Bkf Batok crescent		
21242	m R H G	m 26 709 Po 20209.
*** TE		
See S	(.7	
Sommers Edeli		KES EUROP
Diam's Reput	\$1904 1200 Lat	
N'818 ET 87	No HI (8) STO AR	1
	X FREE X	55/57K16
Esta farassa	2	7'-
Ramen. The web red commenced ha	THE DAY BOOK OF THE L	LIA WG CHTE, PR ELV
receives the time of inspection	TOYOU YOKO ::	
\$24,500 D	× ===	2010
Dut Appen Parm Donastent Yealor No.	F 5 8 0	F E 6
30 st deer Comment YearNi	.81	.34 4
Em Pacara 40 cays Pas Yes or No	20)-	1/2/188/13
20 No 3/11 Yes or No	5/14/14/19 D	1/63 6K
24 85, 855 24 85 Wp	Can of Carragas (FT)	dis NS Ud Raetas H
F.54	N OUT	
		Body Browning of the product of the
,	to K, end to lee	
- 1	15: 410,000 (EED: +14.808.96 60%)	
MARKET YALLE: = 34,500		
(TA REBOTE: +14,84		
MT1 WILLE: = 10.316.		
Smitha Lating Preli Report	Days Of Recein	
Final Report	Resumes No of This	LVX RB
Country Sudices	United by United Bills	
	dd Fee See 3	
	Tara N	
2 ± 1 + 1 = 1 (c)		
		port of the second



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

EO	INSURANCE COM		Ref : CC4/EQI1800	
EQ	INSURANCE CON	IPANT LID	Rei : CG4/EQITOUG	2057/11655
#17	AXWELL ROAD -00 TOWER BLOC D COMPLEXSING		Date: 01-02-2018	
			Code: EQI	
1.			ulars :- THIRD PARTY CLA	
	Insured Veh.	YN 3272S	Veh. Inspected	SJT 934G
	Policy No.	DMCFHQ17-000141	Coverage (\$)	0.00
	Claim No.	DM18/296-EC	Excess (\$)	0.00
	Assign From		Assign Date	01/02/2018
2.		Vehicle	Particulars & Condition	
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	2	Steering	
	Brakes		Modification	
	General			
3.		C	onditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4.		Des	cription of Damages	
5.		G	eneral Information	
-	Accident Date	25/01/2018	Inspection Date	01/02/2018
_	Survey held at	ETHOZ GROUP LTD	mapection Date	O I TO E Z E O TO
	Survey new at	30 BUKIT BATOK CRESC SINGAPORE 658075	ENT	
5a.			Remarks	
	A)THE INSPECTIO	N WAS CONDUCTED ON	A"WITHOUT PREJUDICE" BAS	iis



Company Registration No. 199607198R

51 UBI AVE 1, 802-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 400933 TEL: (005) 62563561 FAX: (005) 62564315

Your ref:

DM18/296-EC

Our ref:

CC4/EQI18002057/T1es3

Date:

09.02.2018

The Motor Claims Department

M/s EQ INSURANCE COMPANY LTD

PRELIMINARY ADVICE OF VEHICLE NO.

SJT 934G

We refer to the above matter.


Please be informed that we had conducted the inspection of the above mentioned vehicle on 01.02.2018 at the premises of M/s Ethoz Protect Pte Ltd (Bukit Batok) and have the following to report:-

: S\$	24,805.96
: S\$	13,135.88
: S\$	5,817.60
: S\$	(*)
: SS	541
: S\$	-
	: S\$: S\$: S\$

Description of Damage:

The vehicle sustained damages at the

Front & Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 10.0 days

Remarks: Parts price incomplete, supplementary will be impose.

Yours faithfully,

MOHD, TAUFIKH

Licensed Appraiser



PLEASE ARRANGE TO SURVEY VEHICLE AT 30 BUKIT BATOK CRESCENT (S 658075)

Lee Chen Sin

CLAIM DEPARTMENT

DID: 66547520

Date

30/01/2018

0.00

FAX:

To

EQ INSURANCE COMPANY LIMITED

ESTIMATION

Attn

Motor Claim Department

FAX:

Owner

IRAWAN ADI PRASETYO

AIG ASIA PACIFIC INSURANCE PTE, LTD.

Certificate No

2100508560

Accident Date

25/01/2018

Vehicle No

SJT-934-G

Make & Model

HONDA CITY 1.5L I-VTEC AUTO

1497 cc

ESTIMATED REPAIR COST DETAILS

Excess

0.00

Add Excess : 0.00

2.00

QTY	DESCRIPTION	REPAIRER AMT (S) SURVEYOR APP.
List	<u>Item</u>	
1	FRONT BONNET	615.20 61-
1	FRONT BONNET HINGE LH	84.80 61-
1	FRONT BONNET HINGE RH	84.80 At -
1	FRONT BONNET INSULATOR	75.60 de
10	FRONT BONNET INSULATOR CLIPS	35.00 401
1	FRONT BONNET AIR VENT LH	68.90 Krafts
1	FRONT BONNET SEAL LH	9.10 \$ 1910
1	FRONT BONNET SEAL RH	9.10 \$ 12/12
1	FRONT BONNET LOCK	235.40 × 10 1

ETHOŹ

Date

30/01/2018

To

EQ INSURANCE COMPANY LIMITED

ESTIMATION

Attn

Motor Claim Department

FAX:

Owner

IRAWAN ADI PRASETYO

AIG ASIA PACIFIC INSURANCE PTE. LTD.

Certificate No

2100508560

Accident Date : 25/01/2018

Vehicle No

SJT- 934-G

Make & Model

: HONDA CITY 1.5L I-VTEC AUTO

ESTIMATED REPAIR COST DETAILS

Excess

: 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$) SURVEYOR APP.
1	FRONT BONNET CLIPS	7.00 W KW/m
1	FRONT FENDER LH	RESTORE JAN
1	FRONT FENDER RH	326.70 Jue
1	FRONT FENDER INNER SHIELD RH	96.40 de
10	FRONT FENDER INNER SHIELD CLIPS	96.20 her
1	FRONT FENDER OUTER GARNISH RH	112.30 📯 🚧
1	"A" PILLAR RH	RESTORE (NN
1	FRONT DOOR RH	RESTORE J'
1	HEADLAMP LH	451.70 🖟 🕪
1	HEADLAMP RH	451.70 Ona



30/01/2018

To

EQ INSURANCE COMPANY LIMITED

ESTIMATION

Attn

Motor Claim Department

FAX:

Owner

IRAWAN ADI PRASETYO

AIG ASIA PACIFIC INSURANCE PTE. LTD.

Certificate No

2100508560

Accident Date : 25/01/2018

Vehicle No

SJT-934-G

Make & Model : HONDA CITY 1.5L I-VTEC AUTO

ESTIMATED REPAIR COST DETAILS

Excess

: 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (S) SURVEYOR APP.
1	HEADLAMP LOWER BRACKET LH	95.50 × Wp
1	HEADLAMP LOWER BRACKET RH	95.50 APC
1	FRONT GRILLE BASE	246.30 0~
1	FRONT GRILLE MOULDING	255.40 AMAC
1	FRONT GRILLE LOGO	45.70 ner
10	FRONT GRILLE CLIPS	35.00
1	FRONT BUMPER	610.40 de
10	FRONT BUMPER CLIPS	35.00
1	FOG LAMP COVER RH	45.60 \$ 7 NA
1	FOG LAMP RH	386.40 ★) ***



30/01/2018

To

EQ INSURANCE COMPANY LIMITED

ESTIMATION

Attn

Motor Claim Department

FAX:

Owner

IRAWAN ADI PRASETYO

AIG ASIA PACIFIC INSURANCE PTE. LTD.

Certificate No

2100508560

Accident Date :

25/01/2018

Vehicle No

SJT-934-G

Make & Model : HONDA CITY 1.5L I-VTEC AUTO 1497 cc

ESTIMATED REPAIR COST DETAILS

Excess

0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (S) SURVEYOR APP.
1	FRONT BUMPER REINFORCEMENT	334.50 × +443
1	SUPPORT PANEL	596.40 bu
1	CONDENSER	753.10 7
1	RADIATOR	1,582.40 7
1	AIR COND FAN COWLING	141.60 🛴
1	AIR COND FAN MOTOR	396.40
1	AIR COND FAN BLADE	85.90
1	RADIATOR FAN COWLING	121.60 R
1	RADIATOR FAN MOTOR	405.30
1	RADIATOR FAN BLADE	95.30 7



30/01/2018

To

EQ INSURANCE COMPANY LIMITED

ESTIMATION

Attn

Motor Claim Department

FAX:

Owner

IRAWAN ADI PRASETYO

AIG ASIA PACIFIC INSURANCE PTE. LTD.

Certificate No

2100508560

Accident Date : 25/01/2018

Vehicle No

SJT-934-G

Make & Model : HONDA CITY 1.5L I-VTEC AUTO 1497 cc

ESTIMATED REPAIR COST DETAILS

Excess

: 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$) SURVEYOR APP.
1	AIR COND HOSE (DISCHARGE)	181.60
1	AIR COND HOSE (SUCTION)	242.30 7
1	AIR COND HOSE (LIQUID)	275.40 7
1	WIPER TANK	134.50] , 🖟
1	WIPER TANK MOTOR	95.40 7
1	ENGINE MOUNTING RH	262.90 €
1	ABS PUMP	2,954.30 ⊀
1	ABS PUMP BRACKET	75.40 7
1	FRONT WHEEL HOUSE EXTENSION RH	275.60 Ry
1	FRONT SIDE FRAME BRACKET RH	69.90 Ky

ETHOŹ

Date

30/01/2018

To

EQ INSURANCE COMPANY LIMITED

ESTIMATION

Attn

Motor Claim Department

FAX:

Owner

IRAWAN ADI PRASETYO

AIG ASIA PACIFIC INSURANCE PTE. LTD.

Certificate No

2100508560

Accident Date :

25/01/2018

Vehicle No

SJT-934-G

Make & Model : HONDA CITY 1.5L I-VTEC AUTO

1497 cc

ESTIMATED REPAIR COST DETAILS

Excess

0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (S) SURVEYOR APP.
1	FRONT SIDE FRAME PLATE RH	95.60 Bx 44
1	FRONT SIDE FRAME GUSSET RH	85.70
1	SIDE MIRROR RH	495.20 👭
1	REAR FENDER LH	RESTORE MY
1	REAR FENDER RH	962.40 bucc
1	REAR FENDER INNER SHIELD RH	42.10 Kroke
10	REAR FENDER INNER SHIELD CLIPS	35.00 × +3/4
1	REAR BOOTLID	755.90
1	REAR BOOTLID HINGE LH	95.50 H
1	REAR BOOTLID HINGE RH	95.50 H



30/01/2018

To

EQ INSURANCE COMPANY LIMITED

ESTIMATION

Attn

Motor Claim Department

FAX:

Owner

IRAWAN ADI PRASETYO

AIG ASIA PACIFIC INSURANCE PTE. LTD.

Certificate No

2100508560

Accident Date : 25/01/2018

Vehicle No

SJT-934-G

Make & Model : HONDA CITY 1.5L I-VTEC AUTO

ESTIMATED REPAIR COST DETAILS

Excess

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (S) SURVEYOR APP.
1	REAR BOOTLID EMBLEM CENTRE	57.60 ACI
1	REAR BOOTLID EMBLEM CITY	47.70 Kei
1	REAR BOOTLID EMBLEM I-VTEC	45.60 10
1	REAR BOOTLID CHROME GARNISH	191.50 CM
2	REAR NUMBER PLATE LAMPS	42.00 R 1343
1	REAR BOOTLID LOCK	141.30 67
1	REAR BOOTLID INNER TRIM	171.80 de
1	REAR BOOTLID RUBBER	165.50 two
1	REAR LAMP LH	388.70 Co
1	REAR LAMP RH	388.70 009



30/01/2018

To

EQ INSURANCE COMPANY LIMITED

ESTIMATION

Attn

Motor Claim Department

FAX:

Owner

IRAWAN ADI PRASETYO

AIG ASIA PACIFIC INSURANCE PTE. LTD.

Certificate No

2100508560

Accident Date : 25/01/2018

Vehicle No

SJT- 934-G

Make & Model : HONDA CITY 1.5L I-VTEC AUTO

1497 cc

ESTIMATED REPAIR COST DETAILS

Excess

: 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
6	REAR LAMP CLIPS	30.00	KEC
1	REAR LAMP PANEL RH	272.60	halv
1	REAR BUMPER	657.20	ner-
10	REAR BUMPER CLIPS	35.00	ner-
1	REAR BUMPER SIDE RETAINER LH		A Tuly
1	REAR BUMPER SIDE RETAINER RH	35.60	w
1	REAR BUMPER INNER BRACKET LH	24.50	× Mes
1	REAR BUMPER INNER BRACKET RH	24.50	ner
1	REAR END PANEL	755.90	bt-
1	REAR END PANEL TOP GARNISH	185.40	der

ETHOŹ

Date

30/01/2018

To

EQ INSURANCE COMPANY LIMITED

ESTIMATION

Attn

Motor Claim Department

FAX:

Owner

IRAWAN ADI PRASETYO

AIG ASIA PACIFIC INSURANCE PTE. LTD.

Certificate No

2100508560

Accident Date :

25/01/2018

Vehicle No

SJT- 934-G

Make & Model

: HONDA CITY 1.5L I-VTEC AUTO

1497 cc

ESTIMATED REPAIR COST DETAILS

Excess

0.00

Add Excess : 0.00

.

QTY	DESCRIPTION	REPAIRER AMT (S) SURVEYOR APP.		
1	REAR BOOTSIDE TRIM LH	196.40₺)		
1	REAR BOOTSIDE TRIM RH	196.40 100/10		

1 SPARE TYRE BOARD

RESTORE AN

SPARE TYRE PANEL
REAR WINDSCREEN

REAR WINDSCREEN MOULDING

1 REAR EXHAUST BOX

3 REAR EXHAUST MOUNTING

983.60 an

41.30 4

153 30

00 8



30/01/2018

To

EQ INSURANCE COMPANY LIMITED

ESTIMATION

Attn

Motor Claim Department

FAX:

Owner

IRAWAN ADI PRASETYO

AIG ASIA PACIFIC INSURANCE PTE. LTD.

Certificate No

2100508560

Accident Date

25/01/2018

Vehicle No

SJT-934-G

Make & Model

HONDA CITY 1.5L I-VTEC AUTO 1497 cc

ESTIMATED REPAIR COST DETAILS

Excess.

0.00 Add Excess : 0.00

QTY DESCRIPTION	REPAIRER AMT (S) SURVEYOR APP.
Sub Total	22576.20
Discount 20% On Parts	(4515.24)
Special Nett Item	500 T A-C-500 T A
1 FRONT NUMBER PLATE	35.00 × ~ 1/2
1 RADIATOR COOLANT	30.00
1 HEADLAMP BULB	10.00
1 PARKING LIGHT BULB	10.00 \$ 226
1 SIGNAL LAMP BULB	10.00
1 WINDSCREEN SEALANT	60.00 reg
1 END PANEL SEALANT	50.00 nec

ETHŌŹ

Date

30/01/2018

To

EQ INSURANCE COMPANY LIMITED

ESTIMATION

Attn

Motor Claim Department

FAX:

Owner

IRAWAN ADI PRASETYO

AIG ASIA PACIFIC INSURANCE PTE. LTD.

Certificate No

2100508560

Accident Date

25/01/2018

Vehicle No

SJT-934-G

Make & Model

: HONDA CITY 1.5L I-VTEC AUTO


1497 cc

ESTIMATED REPAIR COST DETAILS

Excess

: 0.00 Add Excess : 0.00

QTY DESCRIPTION	REPAIRER AMT (S)	SURVEYOR APP.
1 REVERSE SENSOR	200.00	~
1 REAR NUMBER PLATE	35.00 6	tu
1 TOWING FEE	50.00	
Sub Total	490.00	
abour & Misc		
LABOUR TO CARRY OUT FRONT RE	PAIR 1,200.00	900
LABOUR TO CARRY OUT REAR REP	AIR 1,400.00	000
TO CHECK AND RECONNECT ALL N	La Company of the Com	,0
TO SPRAY PAINTING ON FRONT AF	FECTED AREA 1,200.00 /	000





30/01/2018

To

EQ INSURANCE COMPANY LIMITED

ESTIMATION

Attn

Motor Claim Department

FAX:

Owner

IRAWAN ADI PRASETYO

AIG ASIA PACIFIC INSURANCE PTE. LTD.

Certificate No

2100508560

Accident Date : 25/01/2018

Vehicle No

SJT-934-G

Make & Model : HONDA CITY 1.5L I-VTEC AUTO

ESTIMATED REPAIR COST DETAILS

Excess

0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
7 2	TO SPRAY PAINTING ON REAR AFFECTED AREA	1,200.00	1000
	SPRAY RUST PROOF ON AFFECTED AREA	60.00	40
	TO REMOVE & FIX AIRCON CONDENSER INCLUDING TOP UP AIRCON GAS	150.00	100
	TO REMOVE & INSTALL ALL REAR BOOT LID COMPONENT TO FACILITATE REPAIRS	100.00	50.
	TO REMOVE & INSTALL REAR WINDSCREEN GLASS	150.00	120.
	TO REMOVE & REFIT ALL NECCESSARY TRIM BOARDS, GARNISH, CARPET, FLOOR MATS & SEAT	100.00	60
	TO DETACH & RENEW REVERSE SENSOR	60.00	30
	TO PULL OFF STRAIGHTENING FRONT CHASSIS MEMBER LH RH	300.00	200 / ptoto



30/01/2018 Date 4 EO INSURANCE COMPANY LIMITED To ESTIMATION FAX: Motor Claim Department Attn Owner IRAWAN ADI PRASETYO AIG ASIA PACIFIC INSURANCE PTE. LTD. Certificate No 2100508560 Accident Date 25/01/2018 Vehicle No SJT-934-G Make & Model HONDA CITY 1.5L I-VTEC AUTO 1497 cc ESTIMATED REPAIR COST DETAILS Excess 0.00 Add Excess : 0.00 OTY DESCRIPTION REPAIRER AMT (S) SURVEYOR APP. TO PULL OFF STRAIGHTENING REAR CHASSIS MEMBER 300.00 LH RH Sub Total 6255.00 LKK Auto Consultants hence notify the "a arer of the following: beforelafter spray painting Estimated part(s) during resurvey * First proces are subject to confirmation. party survey is on a "Without Prejudice" basis < "As alegal modification(s) is allowed · Commentary dem(s) must be resurveyed and a subject to final approval from Insurance Company 20 nowledged by Repairer Synàtures 24,805.96 Date: Remarks: SUB TOTAL GST 7.0 % 1,736.42 26,542.38 TOTAL Surveyor's name: IRAWAN ADI PRASETYO Principal's name: Survey Date & Time:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Singapore NRIC	
Owner ID:	80731	
Vehicle Details		
Vehicle No.:	SJT934G	
Vehicle to be Exported:	No	
Intended De-registration Date:	29 Jan 2018	
Vehicle Make:	HONDA	
Vehicle Model:	HONDA CITY LX 1.5 I-VTEC AUTO	
Primary Colour:	Blue	
Manufacturing Year:	2008	
Engine No.:	L15A71800784	
Chassis No.:	MRHGM26709P020209	
Maximum Power Output:	88.0 kW (118 bhp)	
Open Market Value:	\$20,387.00	
Original Registration Date:	23 Sep 2009	
First Registration Date:	23 Sep 2009	
Transfer Count:	1	
Actual ARF Paid:	\$20,387.00	
Intended PARF Rebate D	etails	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	22 Sep 2019	
PARF Rebate Amount:	\$11,212.00	
Intended COE Rebate De	etails	
COE Expiry Date:	22 Sep 2019	
COE Category:	A - Car (1600cc & below)	
COE Period(Years):	10	
QP Paid:	\$18,020.00	
COE Rebate Amount:	\$2,972.00	
Total Rebate Amount:	\$14,184.00	

The information contained herein is correct as at 29 Jan 2018



1	A.	加	T	∆a
41			C	
(24)	нот	LINE	9182	8217

Cash Sales/ Work Order

M/S:	それ	oz.			
ehicle No: STT	9344 Mo	del :_		5755 c	ity .
om: 99 3 But		e Start: _			
to the	DE STATE	e End:_			
emarks:	Tidue No :	nus	602		
Change Tyres /Jump Start	Accident		Use Car Car	rior	
Basement / Multi Carpark	☐ Crane Up / Winch Out		Open Door	1101	
Using King Dolley	Dismantle Shaft / Brake		Loaded	AMOUNT S\$	50
Seo LCA				GST S\$	350
1	45			TOTAL S\$	53.50
Lee Chen Sir	bizs	AFE,			m

Vehicle is transported at owner's risk. The company accepts no responsibility for damaged or other misdemeanour to your vehicle whilst being transported.

Asher Sng (LKKAuto)

From:

Ashley Nguyen <Ashley.Nguyen@ethozgroup.com>

Sent:

Tuesday, 2 October 2018 9:48 AM

To:

Asher Sng (LKKAuto)

Cc:

Admin A

Subject:

RE: Your ref: YN32725 - Our ref: SJT934G

Dear Asher,

Accident Involving SJT934G & YN3272S on 25/01/2018.

We refer to your email below, our client accepts your offer to close case at \$11,336.49 all in.

Kindly proceed DV.

Warmest Regards, Ashley Nguyen Claims Settlement



22 Tampines St 92 S(528876)

DID: 6654 7920 | Fax: 6654 7699 Website: www.ethozgroup.com









From: Asher Sng (LKKAuto) [mailto:AsherSng@lkkauto.com]

Sent: Monday, October 01, 2018 2:34 PM

To: Ashley Nguyen <Ashley.Nguyen@ethozgroup.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Your ref: YN3272S - Our ref: SJT934G

Without Prejudice

Hi Sir,

We refer to the above matter.

We propose settlement as follows: -

Cost of Repair(w/GST)
 Loss of Use (12 days x \$5

\$ 10,700.00

2. Loss of Use (12 days x \$50)

\$ 600.00 \$ 36.49

3. LTA/GIA search fee

TOTAL \$ 11,336.49

Kindly let us have your acceptance.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: <u>ashersng@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | \$(408933)

From: Asher Sng (LKKAuto)

Sent: Monday, 10 September 2018 2:12 PM

To: 'Ashley Nguyen' < Ashley. Nguyen@ethozgroup.com >

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Your ref: YN3272S - Our ref: SJT934G

Without Prejudice

Hi Ashley,

We refer to the email below.

We in the midst of preparing the report to seek approval from our principal.

Thank You.

Best Regards.

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: <u>ashersng@lkkauto.com</u> | tax: 6741-4108 8lk 51, Paya Ubi Industrial Park. Ubi Avenue 1, #02-25 | 5(408933)

From: Ashley Nguyen <Ashley.Nguyen@ethozgroup.com>

Sent: Monday, 10 September 2018 2:01 PM

To: Asher Sng (LKKAuto) < Asher Sng@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Your ref: YN3272S - Our ref: SJT934G

Importance: High

Dear Asher,

Accident Involving SJT934G & YN3272S on 25/01/2018.

We refer to your email dated on 07 August 2018, is there any outcome for this case?

Kindly revert back to us as soon as possible.

We await for your favorable reply.

Warmest Regards, Ashley Nguyen Claims Settlement



22 Tampines St 92 S(528876)

DID: 6654 7920 | Fax: 6654 7699 Website: www.ethozgroup.com









From: Asher Sng (LKKAuto) [mailto:AsherSng@lkkauto.com]

Sent: Tuesday, August 07, 2018 11:08 AM

To: Ashley Nguyen < Ashley. Nguyen@ethozgroup.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Your ref: YN3272S - Our ref: SJT934G

Without Prejudice

Hi Ashley,

We refer to the email below.

We in the midst of preparing the report to seek approval from our principal.

Thank You.

Best Regards.

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: <u>ashersng@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park. Ubi Avenue 1, #02-25 | \$(408933)

From: Ashley Nguyen < Ashley.Nguyen@ethozgroup.com>

Sent: Tuesday, 7 August 2018 9:44 AM

To: Asher Sng (LKKAuto) <Asher Sng@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Your ref: YN3272S - Our ref: SJT934G

Importance: High

Dear Asher,

Accident Involving SJT934G & YN3272S on 25/01/2018.

Please refer to the above matter, is there any outcome for this case?

Kindly revert back to us as soon as possible.

We await for your favorable reply.

Thanks and Best Regards

Ashlov Aguyon



ETHOZ Group Ltd

22 Tampines St 92 5(528876) DID: 6654 7920 | Fax: 6654 7699 Website: www.ethozgroup.com









From: Asher Sng (LKKAuto) [mailto:AsherSng@lkkauto.com]

Sent: Monday, July 02, 2018 1:57 PM

To: Ashley Nguyen <Ashley.Nguyen@ethozgroup.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Your ref: YN3272S - Our ref: SJT934G

Without Prejudice

Hi Ashley,

We acknowledge your email below.

We will seek approval from our principal and revert to you once is approve.

Thank You.

Best Regards.

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersna@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | \$(408933)

From: Ashley Nguyen [mailto:Ashley.Nguyen@ethozgroup.com]

Sent: Monday, 2 July 2018 10:52 AM

To: Vic (LKKAuto) < vicalpeh@lkkauto.com>; Asher Sng (LKKAuto) < Asher Sng@lkkauto.com>; CS A Team < csa@lkkauto.com>; Taufikh (LKKAuto) < Taufikh@lkkauto.com>; Vivian Lau (LKKAuto) < vivianlau@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; Rasul (LKKAuto) <Rasul@lkkauto.com>

Subject: RE: Your ref: YN3272S - Our ref: SJT934G

Importance: High

Dear Sir / Madam,

Accident Involving SJT934G & YN3272S on 25/01/2018.

Please refer to the above matter, is there any outcome for this case?

Kindly revert back to us as soon as possible.

We await for your favorable reply.

Thanks and Best Regards

Ashloy Nguyon



ETHOZ Group Ltd

22 Tampines St 92 5(528876) DID: 6654 7920 | Fax: 6654 7699

Website: www.ethozgroup.com









From: Ashley Nguyen

Sent: Thursday, May 31, 2018 5:04 PM

To: Vic (LKKAuto) < vicalpeh@lkkauto.com >; Asher Sng (LKKAuto) < Asher Sng@lkkauto.com >; CS A Team < cs-

a@lkkauto.com>; Taufikh@lkkauto.com; Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; Rasul (LKKAuto) <Rasul@lkkauto.com>

Subject: Your ref: YN3272S - Our ref: SJT934G

Importance: High

Dear All,

Accident Involving SJT934G & YN3272S on 25/01/2018.

We attach Letter of Demand for your necessary action.

Kindly let us hear from you as soon as possible.

Thanks and Best Regards

Ashlov Aguyon



ETHOZ Group Ltd

22 Tampines St 92 5(528876) DID: 6654 7920 | Fax: 6654 7699

Website: www.ethozgroup.com



Disclaimer: This message may contain confidential information intended only for the use of the addressee named above. If you are not the intended recipient of this message you are hereby notified that any use, dissemination, distribution or reproduction of this message is prohibited. If you received this message by mistake, please notify the sender by reply email immediately. Please conduct your own virus checks before opening any attachment as ETHOZ Group does not guarantee the integrity of this email or attached files has been maintained nor this communication is free of viruses, interceptions or interference. Any views expressed in this message are those of the individual sender and may not necessarily reflect the views of ETHOZ Group. ETHOZ Group shall not be responsible nor liable for the improper and incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system.

Disclaimer: This message may contain confidential information intended only for the use of the addressee named above. If you are not the intended recipient of this message you are hereby notified that any use, dissemination, distribution or reproduction of this message is prohibited. If you received this message by mistake, please notify the sender by reply email immediately. Please conduct your own virus checks before opening any attachment as ETHOZ Group does not guarantee the integrity of this email or attached files has been maintained nor this communication is free of viruses, interceptions or interference. Any views expressed in this message are those of the individual sender and may not necessarily reflect the views of ETHOZ Group. ETHOZ Group shall not be responsible nor liable for the improper and incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system.

Disclaimer: This message may contain confidential information intended only for the use of the addressee named above. If you are not the intended recipient of this message you are hereby notified that any use, dissemination, distribution or reproduction of this message is prohibited. If you received this message by mistake, please notify the sender by reply email immediately. Please conduct your own virus checks before opening any attachment as ETHOZ Group does not guarantee the integrity of this email or attached files has been maintained nor this communication is free of viruses, interceptions or interference. Any views expressed in this message are those of the individual sender and may not necessarily reflect the views of ETHOZ Group. ETHOZ Group shall not be responsible nor liable for the improper and incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system.

Disclaimer: This message may contain confidential information intended only for the use of the addressee named above. If you are not the intended recipient of this message you are hereby notified that any use, dissemination, distribution or reproduction of this message is prohibited. If you received this message by mistake, please notify the sender by reply email immediately. Please conduct your own virus checks before opening any attachment as ETHOZ Group does not guarantee the integrity of this email or attached files has been maintained nor this communication is free of viruses, interceptions or interference. Any views expressed in this message are those of the individual sender and may not necessarily reflect the views of ETHOZ Group. ETHOZ Group shall not be responsible nor liable for the improper and incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system.

Catherine Chong (LKK Auto)

From:

Elaine Cheong <elaine.cheong@eqinsurance.com.sg>

Sent:

Wednesday, 31 January, 2018 3:47 PM

To:

assignments

Subject:

FW: Accident Involving SJT934G & YN3272S (EQ) at 25/01/2018 06:50HRS - CLAIM

REF: DM18/296-EC (PART 1)

Attachments:

OI - YN3272S.PDF; SURVEY VEHICLE NO : SJT934G (4.11 MB)

Our ref

YN3272S

TP ref

SJT934G

Policy No.

DMCFHQ17-000141

Dear All,

Please refer to the email below.

Kindly proceed to survey the third party vehicle.

We enclosed the following documents for your perusal:

- Insured, YN32725 GIA report
- PRS request, SJT934G GIA report

Please acknowledge receipt. Thank you.

31.01.2018 @ 352pm

Lee veh in ununge 01.02 xule
Thullish

Regards,

Elaine Cheong

Senior Executive | Claims

EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 did 65 6500 6772 | tel 65 6223 9433 ext. 772 | fax 65 62234190 WANTE TO STREET WATER BY STREET, WATER STREE



you've got a friend

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all capies c

From: Lee Chen Sin [mailto:ChenSin.Lee@ethozgroup.com]

Sent: Wednesday, January 31, 2018 11:03 AM

To: Elaine Cheong

Cc: Stanley Lim; Selamatshahh Zainal; Leon Lim; Toh Khar Kian

Subject: RE: Accident Involving SJT934G & YN3272S (EQ) at 25/01/2018 06:50HRS

Hi Elaine,

Kindly arrange LKK Auto Consultants to survey above mention vehicle.

Thanks you.

Best Regards, Chen Sin

From: Elaine Cheong [mailto:elaine.cheong@eqinsurance.com.sg]

Sent: Wednesday, January 31, 2018 10:36 AM

To: Toh Khar Kian < KharKian. Toh@ethozgroup.com>

Cc: Stanley Lim <Stanley.Lim@ethozgroup.com>; Selamatshahh Zainal <Selamatshahh.Zainal@ethozgroup.com>;

Lee Chen Sin < ChenSin.Lee@ethozgroup.com>; Leon Lim < Leon.Lim@ethozgroup.com>
Subject: RE: Accident Involving SJT934G & YN3272S (EQ) at 25/01/2018 06:50HRS

WITHOUT PREJUDICE

Dear Toh.

We refer to your email of 27.01.2018.

we shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please <u>revert within 2 working days</u> if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

1)	AJAX Inspection Services Pte Ltd Tel: 6255 0808 Fax: 6849 9155	2)	Automobile Inspection Services Pte Ltd Tel: 6286 0155 Fax: 6284 1539
			Contact Person: Sophia
3)	LBS Automotive Appraisal Pte Ltd	4)	Priority Services
	L.B.S. Auto Consultants Pte Ltd		Tel: 62934822
	Tel: 6281 6690 / 62832866		Fax: 62963283
	Fax: 6281 8748		Contact Person: Hui Lian
	Contact Person: Amy/ Grace		
5)	RT Appraisal Pte Ltd	6)	LKK Auto Consultants Pte Ltd
	Tel: 67486076		Tel: 6256-3561
	Fax: 67480361		Fax: 6741-4108
	Contact Person: Ricky Teng		
7)	Kelvin Automotive Appraising Services	8)	Automotive Appraiser & Surveying
	Tel: 81825263		Services
	Fax: 67461148		Tel: 96623655
	Contact Person: Kelvin		Fax: 67655662
			Contact Person: Mr Chee
9)	JP Knights Pte Ltd		
	Tel: 63450068		
	Fax: 63445328		

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Regards,

Elaine Cheong

Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 62234190 www.eqinsurance.com.sg



you've got a friend

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of

From: Toh Khar Kian [mailto:KharKian.Toh@ethozgroup.com]

Sent: Saturday, January 27, 2018 2:54 PM

To: Janet Tan; Elaine Cheong

Cc: Toh Khar Kian; Stanley Lim; Selamatshahh Zainal; Lee Chen Sin; Leon Lim Subject: Accident Involving SJT934G & YN3272S (EQ) at 25/01/2018 06:50HRS

Dear All,

Please be at advised that we will be submitting a claim against your insured.

We would like to propose direct settlement for this case.

Attached herewith is the GIA Report for your perusal.

SJT934G	
YN3272S	
25/01/2018 06:50	

Best Regards, Toh Khar Kian Service Engineer



30 Bukit Batok Crescent Singapore 658075

DID: 6654 7505 | Mobile: (65) 83987469 | Fax: 6654 7543

Email: kharkian.toh@ethozgroup.com

Disclaimer: This message may contain confidential information intended only for the use of the addressee named above. If you are not the intended recipient of this message you are hereby notified that any use, dissemination, distribution or reproduction of this message is prohibited. If you received this message by mistake, please notify the sender by reply email immediately. Please conduct your own virus checks before opening any attachment as ETHOZ Group does not guarantee the integrity of this email or attached files has been maintained nor this communication is free of viruses, interceptions or interference. Any views expressed in this message are those of the individual sender and may not necessarily reflect the views of ETHOZ Group. ETHOZ Group shall not be responsible nor liable for the improper and incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system.

Disclaimer: This message may contain confidential information intended only for the use of the addressee named above. If you are not the intended recipient of this message you are hereby notified that any use, dissemination, distribution or reproduction of this message is prohibited. If you received this message by mistake, please notify the sender by reply email immediately. Please conduct your own virus checks before opening any attachment as ETHOZ Group does not guarantee the integrity of this email or attached files has been maintained nor this communication is free of viruses, interceptions or interference. Any views expressed in this message are those of the individual sender and may not necessarily reflect the views of ETHOZ Group. ETHOZ Group shall not be responsible nor liable for the improper and incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system.



TAX INVOICE

EQ INSURANCE COMPANY LIMITED

22 GEMMILL LANE SINGAPORE - 069257 Tax Invoice

: WS 1810/OPR0158

Invoice Date

: 02-Oct-2018

Ref. No.

: 18011339

GST No.

: M2-0057587-3

VEHICLE NO.: SJT- 934-G

MAKE & MODEL: HONDA CITY 1.5L I-VTEC AUTO

1497 cc

ACCIDENT DATE: 25/01/2018

Qty

Unit Price(S\$)

Amount (S\$)

Page 1

BEING 100 % SUCCESSFUL CLAIM FOR VEH NO. SJT- 934-G

ACCIDENT ON 25/01/2018 AS FOLLOWS :-

REPAIR COSTS

10,000.00

LOSS OF USE

Description

600.00

LTA SEARCH FEE

7.00

GIA FEE

27,10

7 % GST

702.39

Total (S\$)

11,336.49

ESOE

CHEQUE SHOULD BE CROSSED AND MADE PAYABLE TO ETHOZ PROTECT PTE LTD

No receipt will be issued

CONTACT

ASHLEY NGUYEN

Main

80547920 63198000

Customer's Copy

Please do not staple. Please write your invoice No. on the back of your cheque

Customer Name

: EQ INSURANCE COMPANY LIMITED

Reference, No.

: 18011339

Computer generated document no signature required.

Tax Invoice Invoice Date : WS 1810/OPR0158 : 02-Oct-2018

Invoice Amount Payment Due Date : S\$ 11,336.49 : 02-Oct-2018

Cheque No.

PLEASE DETACH AND ENCLOSED WITH PAYMENT



ETHOZ PROTECT PTE LTD

SINGAPORE 658075

30 BUKIT BATOK CRESCENT



WITHOUT PREJUDICE

Letter of Demand

Your Ref

YN - 3272 - S

Our Ref

OPR/25012018/TP-9830

Date

31/05/2018

EQ INSURANCE COMPANY LIMITED

22 GEMMILL LANE Singapore - 069257

Attn

Motor Claim Department

Subject

ACCIDENT INVOLVING VEHICLE NUM: SJT- 934-G, YN3272S, GBD4551E,

UNKNOWN, UNKNOWN ON 25/01/2018 AT ALONG SLE 11 1/2 KM (BEFORE

EXIT TO MANDAI RD)

Dear Sir / Madam,

We would like to append our losses as follows :-

AMOUNT (S)

1. Repair Cost	10,700.00
2. Loss Of Use (12 days) _ two weekend	960.00
3. LTA Search Fees	7.49
4. Miscellaneous = GIA /ee	29.00

TOTAL

11,696,49

Enclosed:

Copies of Repair Cost Invoice ,LTA Search Invoice, GIA search invoice & GIA Report

for your perusal and kind attention.

Kindly look into the matter and revert to us as soon as possible.

Thank you,

Yours faithfully.

Ashley Nguyen

CLAIM DEPARTMENT

DID: 66547920

FAX: 66547540

EMAIL ashley.nguyen@ethozgroup.com

Asher Sng (LKKAuto)

From:

Asher Sng (LKKAuto)

Sent:

Tuesday, 27 February 2018 2:40 PM

To:

'BONIBOY23@HOTMAIL.COM'

Subject:

ACCIDENT INVOLVING YN 3272S / SJT 934G / OTHERS ON 25/01/2018



Auto. Consultants Fie Ud

51 UBI AVE 1, #01-25 1000 UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 67414108

Our Ref: CC4/EQ118002057/T1es3

27 FEB 2018

APPLIED LOGISTICS PTE LTD

Dear Sir/Madam,

ACCIDENT INVOLVING YN 3272S / SJT 934G / OTHERS ON 25/01/2018

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an aminable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days to make date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal EQ INSURANCE COMPANY LIMITED.

Please call us if you have further queries.

Yours faithfully,

Asher

Case Handler DID: 6841 6051 FAX: 6741 4108

Email: ashersng@ll.kemto.com

c.c. EQ INSURANCE COMPANY LIMITED
(Motor Claims Dept)

Date : 14/2/2018
To : ETHOZ PROTECT PTE LTD () 30, Bukit Batok Crescent, Singapore 658075 () 50, Gul Crescent, Singapore 629543 () 22, Tampines Street 92, Singapore 528876
From : TRAWAH ADJ PRASETYO (Name of Owner & Policyholder/Authorising Party**)
CLAIM VEHICLE NO.: SJT -934-G
ACCIDENT DATE: 25118
OTHER VEHICLE (S): Along SCE 11 1/2 KM (Before exit to Mandai)
(IF ANY)
I hereby authorise ETHOZ PROTECT PTE LTD ("ETHOZ") to : -
 proceed with the repairs (the "Repair") to the above accident (the "Accident") damaged vehicle (the "Vehicle"); and
b: act as sole and principal agent to claim (the "Claim") on my behalf for the damage to the Vehicle (the "Damage") from my insurer in question (the "Insurer") until the Claim is wholly completed, settled and/or resolved. [Claim against own insurer(s)].
•
 b. act as sole and principal agent to claim (the "Claim") on my behalf for the damage to the Vehicle and/or ** bodily injury sustained as a result of the Accident (collectively known hereinafter as the "Damage") from the Third Party and/or Third Party Insurer in question (collectively known as the "Third Party") until the Claim is wholly completed, settled and/or resolved. [Claim against Third Party].
 I confirm that ETHOZ's authorisation shall include without limitation paying for all relevant reports/documents, corresponding and negotiating with the Insurer/Third Party** and any other relevant parties, correspondence of any nature with solicitors, appointing solicitors to act in connection with the Claim and any or all such other tasks concerning the settlement, resolution and/or completion of the Claim;
Where authorising party is not vehicle owner and poliryholder.

I am duly authorised by the owner and policyholder of the Vehicle to enter into this Agreement with ETHOZ on his behalf. Unless the context otherwise requires, any references to "me", "my", "I" and the like in this Afreement shall be taken to mean the vehicle owner and policyholder.

Page 1 of 3

*Tick where applicable.

** Delete us appropriate.

EXCEPT: -

- such matters or tasks that the Insurer/Third Party** and/or the law requires me to personally attend to; and
- b. the due submission of the Claim to the Insurer (where applicable)
- I understand if I submit a claim of whatever nature to my own insurer(s) FOURTEEN (14) days
 after the Accident (or such other time stipulated by my own insurer(s) and/or the law),
 such claim will not or may not be accepted by my own insurer.
- I further confirm and accept that :
 - a. To the extent permitted by law: -
 - I will indemnify and keep ETHOZ indemnified in connection with or arising from the Claim; and
 - That notwithstanding this Agreement or otherwise, under no circumstances will I (jointly or severally) in any manner hold ETHOZ liable for losses/damages of whatever nature arising from or in connection with the Claim.
- b. ETHOZ does not guarantee and never represented that the Insurer/Third Party** will fully indemnify me for the Damage and/or the Repair's costs AND, that I shall be and continue to be liable to ETHOZ for the whole of the Repair's costs.
- I agree and accept "ETHOZ's Deposit refund policy". If the final successful percentage of indemnity/contribution/liability from or of the Insurer/Third Party** in respect of the Repair's costs to me is: -

a. 50% and below

NO REFUND

b. 100%

FULL REFUND

- I shall inform and forward to ETHOZ all correspondence and letters received by me from the Insurer/Third Party**, any other insurer, solicitors, governmental authorities and/or, any other relevant party.
- I shall fully co-operate with and act expeditiously on any requests by ETHOZ, particularly
 the signing/endorsement/execution of any "Discharge Voucher", failing which I shall be liable to
 ETHOZ for the full repair costs and the expenses incurred (directly or indirectly) by ETHOZ in
 connection with the Claim.

I shall not: -

9.

respond to correspondence and letters; and

 negotiate agree or accept any offer from the Insurer/Third Party** or any other relevant party; without consultation of and expressed approval from ETHOZ

Page 2 of 3
*Tick where applicable.
** Delete as appropriate.

Mus

- In consideration hereof (including without limitation ETHOZ's agreeing to repair the Vehicle and defer demanding payment of the Repair's cost), I wholly assign to ETHOZ all proceeds of the Claim for: -
 - a the Repair's costs; and
 - damage, compensation, interest, costs (including party-to-party legal costs on a full indemnity basis) and expenses in connection with the Accident, Repair and/or Claim;

which ETHOZ shall be further entitled to apportion in its absolute with any excess being paid by ETHOZ to me as it deems fit in its absolute discretion.

11. I further confirm that payment to ETHOZ or to any person (which shall include a body corporate) authorised by you to receive payment in lieu shall constitute a good and effective discharge of the payment obligations by any party of the aforesaid proceeds of my Claim And that I shall not be authorised in law to receive payment.

Owner & Policyholder's Signature/Company Stamp (if applicable); or **
Authorising Party's Signature/Company Stamp (if applicable)

Name:

18AWAN ADD 86968073I

PRASETYO

NRIC No.: Designation:

Designation: Address:

Witness' Signature Tan KHA

Name:

622142180

NRIC No.:

Designation: MOTOR CLAIMS SALES EXECUTIVE

Address: C/O 30 BT BATOK CRESCENT SINGAPORE 658075

*** This Discharge Voucher applies only to be the claimant's Claim for his property damage and will not affect his personal injuries claim and/or uninsured losses claim in a later date. Further, the settlement terms herein about not be used as an evidence to prejudice to the claimant's personal injuries claim and/or other uninsured losses claim arising of the subject matter in this action.

Page 3 of 3
*Tick where applicable.
** Delete as appropriate.



TAX INVOICE

IRAWAN ADI PRASETYO BLK 880 WOODLANDS ST82

#07-16

SINGAPORE - 730880

Tax Invoice

: WS 1805/OPR0295

Invoice Date : 31-May-2018

Ref. No.

: 18011339

: M2-0057587-3

GST No.

VEHICLE NO.: SJT- 934-G

MAKE & MODEL : HONDA CITY 1.5L I-VTEC AUTO

Page 1

ACCIDENT DATE: 25/01/2018

Description

Qty

Unit Price(S\$)

Amount (S\$)

BEING REPAIR COST FOR THE ABOVE VEHICLE

10,000.00

7 % GST

700.00

10,700.00 Total (S\$)

EAGE

CHEQUE SHOULD BE CROSSED AND MADE PAYABLE TO ETHOZ PROTECT PTE LTD.

Computer generated document no signature required:

CONTACT DID Main

ASHLEY NGUYEN 66547970 63198000

PLEASE DETACH AND ENCLOSED WITH PAYMENT

Customer's Copy

Please do not steple. Please write your invoice No. on the back of your cheque.

Customer Name Reference. No.

: IRAWAN ADI PRASETYO

Tax Invoice Invoice Date Invoice Amount

Payment Due Date

: 18011339

: WS 1805/OPR0295 : 31-May-2018

: \$\$ 10,700.00 : 31-May-2018

Cheque No.

ETHOZ PROTECT PTE LTD 30 BUKIT BATOK CRESCENT SINGAPORE 658075





Land Transport Authority 10 Sin Ming Drive Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time :

27 Jan 2018 / 14:41:27

Receipt Date/Time: 27 Jan 2018 / 14:41:27

Tax Invoice/Receipt

Receipt No.: ITNET-00000-180127-000715

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.		Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
	ult of Insurance Enquiry - YN3272S t 25 Jan 2018/06:50:00		2 6	359 8	0.00
Insu	rance Co: EQ INSURANCE COMPANY	LTD			
1	Insurance Enquiry - YN3272S Enquiry Fee 20180127144030181923		7.00	0.49	7.49
		Sub-Total	7.00	0.49	7.49
		Total Before Rounding	7.00	0.49	7.49
		Rounding Difference			0.04
		Total Amount Payable			7.45
		Paid By			
		xxxxxxxxxxxx5754	Credit Card: Visa/MasterCard		7.45
		Total			7.45
		Cash Change			0.00
		Tendered Amount			7.45
		Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Our Ref No:

GR-18-015363

Date of Request

29/01/2018

Your Ref No:

TOH KHAR KIAN(BT BATOK)

ETHOZ Protect Pte Ltd 30 Bukit Batok Crescent Singapore 658075

Dear Sir/Madam,

Date of Accident

25/01/2018

Vehicle No:

SJT934G

Place of Accident:

ALONG SLE 11 1/2 KM (BEFORE EXIT TO MANDAI RD)

Involving Vehicle No: YN3272S

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)	
YN3272S	ALONG SLE 11 1/2 KM (BEFORE EXIT TO MANDAI RD)	14.00	1	13.08	
GST Amount					
Total Amount D	lue (GST Inclusive)			14.00	

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

[X] GIRO [] Cash [] Cheque



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm GST Registration No: M400017735

TAX INVOICE

Our Ref No:

GR-18-013549

Date of Request:

25/01/2018

Your Ref No:

TOH KHAR KIAN(BT BATOK)

ETHOZ Protect Pte Ltd 30 Bukit Batok Crescent Singapore 658075

Dear Sir/Madam.

Your Search Criteria:

Date of Accident:

25/01/2018

Place of Accident:

ALONG SLE 11 1/2 KM (BEFORE EX

Client Vehicle No:

SJT934G

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

[X] GIRO [] Cash [] Cheque

Asher Sng (LKKAuto)

From:

Joel Goh <joel.goh@eqinsurance.com.sg>

Sent:

Wednesday, 19 September 2018 1:29 PM

To:

Asher Sng (LKKAuto)

Cc:

Admin A

Subject:

RE: [MANDATE REQUEST] RE: Accident Involving SJT934G & YN3272S (EQ) at 25/01/2018 06:50HRS - CLAIM REF: DM18HO00296-JG (PART 1) *** LKK REF -

CC4/EQI18002057/T1es3

Follow Up Flag:

Follow up

Flag Status:

Flagged

Dear Asher

Please proceed to resolve this matter up to \$\$11,336.49.

Best Regards,

Joel Goh

Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190 www.eginsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the



Sent: Saturday, September 15, 2018 2:57 PM

To: Joel Goh; Janet Tan

Cc: Admin A

Subject: [MANDATE REQUEST] RE: Accident Involving SJT934G & YN3272S (EQ) at 25/01/2018 06:50HRS - CLAIM REF:

DM18/296-EC (PART 1) *** LKK REF - CC4/EQI18002057/T1es3

Your ref: DM18/296-EC

Our ref: CC4/EQI18002057/T1ea3q2

Dear Sirs,

We refer to the above matter.

The said chain collision involved 3 vehicles whereby our insured was the last vehicle.

In accordance to the MCF guideline for chain collision, we have to settle the front vehicle's claim at 100%.

We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer repairer " ETHOZ GROUP LTD" at \$11,336.49 (all-in).

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repairs (with GST)	\$ 26,542.38	\$ 10,700.00
2. Loss of Use (12days x \$80)	\$ 960.00	\$ 600.00 (12days x \$50)
3. LTA Search Fee	\$ 36.49	\$ 36.49
Total	\$ 27,538.88	\$ 11,336.49

Enclosed here with all the relevant documents for your perusal.

For your approval please.

Thank You.

Best Regards.

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: <u>ashersng@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | \$(408933)

From: Shirley Hiew (LKK Auto)

Sent: Friday, 9 February 2018 10:35 AM

To: Elaine Cheong <elaine.cheong@eqinsurance.com.sg>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>

Subject: RE: Accident Involving SJT934G & YN3272S (EQ) at 25/01/2018 06:50HRS - CLAIM REF: DM18/296-EC (PART 1)

*** LKK REF - CC4/EQI18002057/T1es3

Your ref: DM18/296-EC

LKK ref: CC4/EQI18002057/T1es3

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

This is a TP direct settlement case.

We have inspected TP vehicle SJT 934G at M/s Ethoz Protect Pte Ltd - Bukit Batok.

Enclosed for your perusal is:

TP estimated cost of repair

Preliminary advice

Kindly take note that the case handler in-charge is Asher and he can be contacted at DID: 6841 6051.

To check availability of the case handler , you may contact the undersigned.

Thank you.

Best Regards,

Shirley Hiew | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: <u>ShirleyHiew@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Wednesday, 31 January 2018 3:53 PM

To: 'Elaine Cheong' <elaine.cheong@eqinsurance.com.sg>; assignments <assignments@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Accident Involving SJT934G & YN3272S (EQ) at 25/01/2018 06:50HRS - CLAIM REF: DM18/296-EC (PART 1)

Dear Elaine,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Elaine Cheong [mailto:elaine.cheong@eginsurance.com.sg]

Sent: Wednesday, 31 January, 2018 3:47 PM To: assignments <assignments@lkkauto.com>

Subject: FW: Accident Involving SJT934G & YN3272S (EQ) at 25/01/2018 06:50HRS - CLAIM REF: DM18/296-EC (PART 1)

Our ref

YN3272S

TP ref

2

SJT934G

Policy No.

.

*

DMCFHQ17-000141

Dear All,

Please refer to the email below.

Kindly proceed to survey the third party vehicle.

We enclosed the following documents for your perusal:

- Insured, YN3272S GIA report
- PRS request, SJT934G GIA report

Please acknowledge receipt. Thank you.

Regards,

Elaine Cheong

Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 did 65 6500 6777 | tel 65 6223 9433 ext 772 | fax 65 62234190 www.eginsurance.com.sg





Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of it.

From: Lee Chen Sin [mailto:ChenSin.Lee@ethozgroup.com]

Sent: Wednesday, January 31, 2018 11:03 AM

To: Elaine Cheong

Cc: Stanley Lim; Selamatshahh Zainal; Leon Lim; Toh Khar Kian

Subject: RE: Accident Involving SJT934G & YN3272S (EQ) at 25/01/2018 06:50HRS

Hi Elaine.

Kindly arrange LKK Auto Consultants to survey above mention vehicle.

Thanks you.

Best Regards, Chen Sin

From: Elaine Cheong [mailto:elaine.cheong@eqinsurance.com.sg]

Sent: Wednesday, January 31, 2018 10:36 AM

To: Toh Khar Kian < KharKian. Toh@ethozgroup.com>

Cc: Stanley Lim <Stanley.Lim@ethozgroup.com>; Selamatshahh Zainal <Selamatshahh.Zainal@ethozgroup.com>; Lee

Chen Sin < Chen Sin Chen Sin

WITHOUT PREJUDICE

Dear Toh,

We refer to your email of 27.01.2018.

we shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please <u>revert within 2 working days</u> if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the

appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

1)	AJAX Inspection Services Pte Ltd Tel: 6255 0808	2)	Automobile Inspection Services Pte Ltd Tel: 6286 0155
	Fax: 6849 9155		Fax: 6284 1539
	101. 0043 3133		Contact Person: Sophia
3)	LBS Automotive Appraisal Pte Ltd	4)	Priority Services
	L.B.S. Auto Consultants Pte Ltd		Tel: 62934822
	Tel: 6281 6690 / 62832866		Fax: 62963283
	Fax: 6281 8748		Contact Person: Hui Lian
	Contact Person: Amy/ Grace		
5)	RT Appraisal Pte Ltd	6)	LKK Auto Consultants Pte Ltd
	Tel: 67486076		Tel: 6256-3561
	Fax: 67480361		Fax: 6741-4108
	Contact Person: Ricky Teng		
7)	Kelvin Automotive Appraising Services	8)	Automotive Appraiser & Surveying
	Tel: 81825263		Services
	Fax: 67461148		Tel: 96623655
	Contact Person: Kelvin		Fax: 67655662
			Contact Person: Mr Chee
9)	JP Knights Pte Ltd		
	Tel: 63450068		
	Fax: 63445328		
	Contact Person: Edna Lee		

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Regards,

Elaine Cheong

Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Bond #17-00 Tower Block MND Complex Singapore 069110





Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of it.

From: Toh Khar Kian [mailto:KharKian, Toh@ethozgroup.com]

Sent: Saturday, January 27, 2018 2:54 PM

To: Janet Tan; Elaine Cheong

Cc: Toh Khar Kian; Stanley Lim; Selamatshahh Zainal; Lee Chen Sin; Leon Lim Subject: Accident Involving SJT934G & YN3272S (EQ) at 25/01/2018 06:50HRS

Dear All,

Please be at advised that we will be submitting a claim against your insured.

We would like to propose direct settlement for this case.

Attached herewith is the GIA Report for your perusal.

Our Client's Vehicle Number:	SJT934G
EQ Vehicle Number:	YN3272S
Date/Time of Loss:	25/01/2018 06:50

Best Regards, Toh Khar Kian Service Engineer



30 Bukit Batok Crescent Singapore 658075

DID: 6654 7505 | Mobile: (65) 83987469 | Fax: 6654 7543

Email: kharkian.toh@ethozgroup.com

Disclaimer: This message may contain confidential information intended only for the use of the addressee named above. If you are not the intended recipient of this message you are hereby notified that any use, dissemination, distribution or reproduction of this message is prohibited. If you received this message by mistake, please notify the sender by reply email immediately. Please conduct your own virus checks before opening any attachment as ETHOZ Group does not guarantee the integrity of this email or attached files has been maintained nor this communication is free of viruses, interceptions or interference. Any views expressed in this message are those of the individual sender and may not necessarily reflect the views of ETHOZ Group. ETHOZ Group shall not be responsible nor liable for the improper and incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. Disclaimer: This message may contain confidential information intended only for the use of the addressee named above. If you are not the intended recipient of this message you are hereby notified that any use, dissemination, distribution or reproduction of this message is prohibited. If you received this message by mistake, please notify the sender by reply email immediately. Please conduct your own virus checks before opening any attachment as ETHOZ Group does not guarantee the integrity of this email or attached files has been maintained nor this communication is free of viruses, interceptions or interference. Any views expressed in this message are those of the individual sender and may not necessarily reflect the views of ETHOZ Group. ETHOZ Group shall not be responsible nor liable for the improper and incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system.



51 UBLAVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To: M/s EQ INSURANCE COMPANY LTD

Date: 15/10/2018

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	YN 3272S	(Insd Veh)	Your Ref. No. : DM18/296-EC
verlicie No.	SJT 934G	(TP Veh)	Our Ref. No.: CC4/EQI18002057/T1ea3q2
Date of Accident	25/1/2018		

Liability		100%		
Final Repair Cost	: \$	10,700.00		
Loss of Use	: \$	600.00	12 days	
Rental (If any)	: \$		days	
Others:	: \$	36.45		
	: \$			
		11,336.45		
Final Settlement Sum	: \$	11,336.45		
Remarks	:			

1)	ETHOZ PROTECT PTE LTD	: \$	11,336.45
		: \$	

JOANNE LEE LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Intern	nationale Des Experts En Auto	mobile	
EQ	NSURANCE CON	PANY LTD	Ref : CC4/EQI18002	2057/T1ea3q2	
#17-	AXWELL ROAD 00 TOWER BLOC COMPLEXSING		Date: 15-10-2018		
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YN 3272S	Veh. Inspected	SJT 934G	
	Policy No.	DMCFHQ17-000141	Coverage (\$)	0.00	
	Claim No.	DM18/296-EC	Excess (\$)	0.00	
	Assign From	ELAINE	Assign Date	31/01/2018	
2.		Vehicle Pa	articulars & Condition		
	Make & Model	HONDA CITY	c.c	1497	
	Engine No.	HIDDEN	Year of Reg.	2009	
	Chassis No.	MRHGM26709P020209	Colour	BLUE	
	Odometer	a	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.		Con	ditions of Tyres		
		Size	Make	Balance	
	R/H Front Tyre	185/55 R16	BRIDGESTONE	6 mm	
	L/H Front Tyre	185/55 R16	BRIDGESTONE	6 mm	
	R/H Rear Tyre	185/55 R16	BRIDGESTONE	6 mm	
	L/H Rear Tyre	185/55 R16	BRIDGESTONE	6 mm	
4.	Description of Damages				
	DAMAGES SEE D	STAINED DAMAGES AT THE ETAILS.	FRONT AND REAR PORTIO	ON.	
5.		Gen	eral Information		
	Accident Date	25/01/2018	Inspection Date	01/02/2018	
	Survey held at	ETHOZ GROUP LTD			
		30 BUKIT BATOK CRESCEN SINGAPORE 658075	П		
5a.			Remarks	Martin Man J. To.	
	ANTHE INSPECTIO	ON WAS CONDUCTED ON A"	ANTHOUT DDE HIDIOET DAG	ne.	

Estimate Days of Repair

10 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR:



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 934G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			7/
1	FRONT BONNET	BENT	615.20	615.20
1	FRONT BONNET HINGE LH	BENT	84.80	84.80
1	FRONT BONNET HINGE RH	BENT	84.80	84.80
1	FRONT BONNET INSULATOR	DEFORMED	75.60	75.60
10	FRONT BONNET INSULATOR CLIPS	NECESSARY	35.00	35.00
1	FRONT BONNET AIR VENT LH	NOT NECESSARY	68.90	9.000000
1	FRONT BONNET SEAL LH	NOT NECESSARY	9.10	
1	FRONT BONNET SEAL RH	NOT NECESSARY	9.10	
1	FRONT BONNET LOCK	NOT NECESSARY	235.40	1
1	FRONT BONNET CLIPS	NOT NECESSARY	7.00	
1	FRONT FENDER LH (NPA)	NOT NECESSARY		
1	FRONT FENDER RH	BUCKLED	326.70	326.70
1	FRONT FENDER INNER SHIELD RH	DEFORMED	96.40	96.40
10	FRONT FENDER INNER SHIELD CLIPS	NECESSARY	96.20	96.20
1	FRONT FENDER OUTER GARNISH RH	NOT NECESSARY	112.30	
1	'A' PILLAR RH (NPA)	NOT NECESSARY		
1	FRONT DOOR RH (NPA)	NOT NECESSARY		
1	HEADLAMP LH	NOT NECESSARY	451.70	
1	HEADLAMP RH	CRACKED	451.70	451.70
1	HEADLAMP LOWER BRACKET LH	NOT NECESSARY	95.50	-
1	HEADLAMP LOWER BRACKET RH	NECESSARY	95.50	95.50
1	FRONT GRILLE BASE	CRACKED	246.30	246.30
1	FRONT GRILLE MOULDING	NECESSARY	255.40	255.40
1	FRONT GRILLE LOGO	NECESSARY	45.70	45.70
10	FRONT GRILLE CLIPS	NECESSARY	35.00	35.00
1	FRONT BUMPER	DEFORMED	610.40	610.40
10	FRONT BUMPER CLIPS	NECESSARY	35.00	35.00
1	FOG LAMP COVER RH	NOT NECESSARY	45.60	
1	FOG LAMP RH	NOT NECESSARY	386.40	
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	334.50	
1	SUPPORT PANEL	BUCKLED	596.40	596.40



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
- 1	CONDENSER	NOT NECESSARY	753.10	1
1	RADIATOR	NOT NECESSARY	1,582.40	
1	AIR COND FAN COWLING	NOT NECESSARY	141.60	
1	AIR COND FAN MOTOR	NOT NECESSARY	396.40	
1	AIR COND FAN BLADE	NOT NECESSARY	85.90	9
1	RADIATOR FAN COWLING	NOT NECESSARY	121.60	9
1	RADIATOR FAN MOTOR	NOT NECESSARY	405.30	9
1	RADIATOR FAN BLADE	NOT NECESSARY	95.30	3
1	AIR COND HOSE (DISCHARGE)	NOT NECESSARY	181.60	
1	AIR COND HOSE (SUCTION)	NOT NECESSARY	242.30	
1	AIR COND HOSE (LIQUID)	NOT NECESSARY	275.40	
1	WIPER TANK	NOT NECESSARY	134.50	9
1	WIPER TANK MOTOR	NOT NECESSARY	95.40	
1	ENGINE MOUNTING RH	NOT NECESSARY	262.90	
1	ABS PUMP	NOT NECESSARY	2,954.30	
1	ABS PUMP BRACKET	NOT NECESSARY	75.40	9
1	FRONT WHEEL HOUSE EXTENSION RH	TO REPAIR SEE LABOUR	275.60	2
1	FRONT SIDE FRAME BRACKET RH	TO REPAIR SEE LABOUR	69.90	3
1	FRONT SIDE FRAME PLATE RH	NOT NECESSARY	95.60	
1	FRONT SIDE FRAME GUSSET RH	NOT NECESSARY	85.70	ā
1	SIDE MIRROR RH	TO REPAIR SEE LABOUR	495.20	
1	REAR FENDER LH (NPA)	NOT NECESSARY		9
1	REAR FENDER RH	BUCKLED	962.40	962.40
1	REAR FEDER INNER SHIELD RH	NOT NECESSARY	42.10	9
10	REAR FEDER INNER SHIELD CLIPS	NOT NECESSARY	35.00	
1	REAR BOOTLID	BENT	755.90	755.90
1	REAR BOOTLID HINGE LH	BENT	95.50	95.50
1	REAR BOOTLID HINGE RH	BENT	95.50	95.50
1	REAR BOOTLID EMBLEM CENTRE	NECESSARY	57.60	57.60
1	REAR BOOTLID EMBLEM CITY	NECESSARY	47.70	47.70
1	REAR BOOTLID EMBLEM I-VTEC	NECESSARY	45.60	45.60



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	REAR BOOTLID CHROME GARNISH	CRACKED	191.50	191.50
2	REAR NUMBER PLATE LAMPS	NOT NECESSARY	42.00	3
1	REAR BOOTLID LOCK	BENT	141.30	141.30
1	REAR BOOTLID INNER TRIM	DEFORMED	171.80	171.80
1	REAR BOOTLID RUBBER	TWISTED	165.50	165.50
1	REAR LAMP LH	CRACKED	388.70	388,70
-1	REAR LAMP RH	CRACKED	388.70	388.70
6	REAR LAMP CLIPS	NECESSARY	30.00	30.00
. 1	REAR LAMP PANEL RH	BUCKLED	272.60	272.60
1	REAR BUMPER	NECESSARY	657.20	657.20
10	REAR BUMPER CLIPS	NECESSARY	35.00	35.00
1	REAR BUMPER SIDE RETAINER LH	NOT NECESSARY	35.60	
1	REAR BUMPER SIDE RETAINER RH	NECESSARY	35.60	35.60
1	REAR BUMPER INNER BRACKET LH	NOT NECESSARY	24.50	
1	REAR BUMPER INNER BRACKET RH	NECESSARY	24.50	24.50
1	REAR END PANEL	BENT	755.90	755.90
1	REAR END PANEL TOP GARNISH	DEFORMED	185.40	185.40
1	REAR BOOTSIDE TRIM LH	NOT NECESSARY	196.40	9
1	REAR BOOTSIDE TRIM RH	NOT NECESSARY	196.40	
1	SPARE TYRE BOARD	CRACKED	186.20	186.20
1	SPARE TYRE PANEL (NPA)	NOT NECESSARY	-	
1	REAR WINDSCREEN	CRACKED	983.60	983.60
1	REAR WINDSCREEN MOULDING	NECESSARY	141.30	141.30
1	REAR EXHAUST BOX	NOT NECESSARY	753.30	
3	REAR EXHAUST MOUNTING	NOT NECESSARY	68.90	
	LESS 20% DISCOUNT		-4,515.24	-2,120.22
			18,060.96	8,480.88
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	35.00	
1	RADIATOR COOLANT (SN)	NECESSARY	30.00	30.00
	HEADLAMP BULB (SN)	NOT AVAILABLE	10.00	===0
1	PARKING LIGHT BULB (SN)	NOT NECESSARY	10.00	
1	SIGNAL LAMP BULB (SN)	NOT NECESSARY	10.00	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	WINDSCREEN SEALANT (SN)	NECESSARY	60.00	60.00
1	END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	REVERSE SENSOR (SN)	NOT WORKING	200.00	200.00
1	REAR NUMBER PLATE (SN)	BENT	35.00	35.00
			440.00	375.00
	LABOUR			
	TOWING FEE.		50.00	50.00
	LABOUR TO CARRY OUT FRONT REPAIR INCLUSIVE OF THE REPAIR OF FRONT WHEEL HOUSE EXTENSION RH,FRONT SIDE FRAME BRACKET RH AND SIDE MIRROR RH.		1,200.00	800.00
	LABOUR TO CARRY OUT REAR REPAIR.		1,400.00	1,000.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS.		35.00	30.00
	TO SPRAY PAINTING ON FRONT AFFECTED AREA.		1,200.00	1,000.00
	TO SPRAY PAINTING ON REAR AFFECTED AREA.		1,200.00	1,000.00
	SPRAY RUST PROOF ON AFFECTED AREA.		60.00	40.00
	TO REMOVE & FIX AIRCON CONDENSER INCLUDING TOP UP AIRCON GAS.		150.00	100.00
	TO REMOVE & INSTALL ALL REAR BOOT LID COMPONENT TO FACILITATE REPAIRS.		100.00	50.00
	TO REMOVE & INSTALL REAR WINDSCREEN GLASS.		150.00	120.00
	TO REMOVE & REFIT ALL NECESSARY TRIM BOARDS ,GARNISH ,CARPET ,FLOOR MATS & SEAT.		100.00	60.00
	TO DETACH & RENEW REVERSE SENSOR.		60:00	30.00
	TO PULL OFF STRAIGHTEN FRONT CHASSIS MEMBER LH RH	NOT NECESSARY	300.00	
	TO PULL OFF STRAIGHTENING REAR CHASSIS MEMBER LH RH .	NOT NECESSARY	300.00	
			6,305.00	4,280.00
	GRAND TOTAL		24,805.96	13,135.88



Page No.:5 of 5

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)	10,000.00
--	-----------

Report Ref No. CC4/EQI18002057/T1ea3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

Jimon T

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES: This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report. In whole or in part, does so at his or her own risk,