



320 UBI ROAD 3 SINGAPORE 408649

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TPVehicle No. : SKH2123TMake & Model : MERCEDES BENZ C 180Year of Manufacture : 2012Chassis No. : WDD2040312A776581Engine No. : 27491030019086

Policy No. : _____

Time of Accident : _____

Ins Company : SOMPO vs AIG

Excess : _____

Date of Accident : 30/01/2018

Suggested Days of Repair : _____

In-house Vehicle AssessorCase Owner : ANIKKA

Signature : _____

Contact No

68485725 – ANIKKA

68485726 – JASMINE CHNG

Repair Estimates

Parts (a) Cost / List Price Items	<u>\$8,944.00</u>
Plus/Less <u>-20%</u>	<u>\$(1,788.80)</u>
Total of Cost / List	<u>\$7,155.20</u>
(b) Nett Price Items	<u>\$45.00</u>
Less _____	_____
Total of Nett Item	_____
(c) Special Nett Items	<u>\$-</u>
Total Parts Cost (Appendix A)	<u>\$7,155.20</u>
Labour (Appendix B)	<u>\$2,650.00</u>
Total Repair Cost	<u>\$9,805.20</u>

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Adrian Lj
 Company : W.L.C.
 Survey conducted on : 08/02/18 at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : 888

Date:

08/02/18

Spark Car Care

ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
TEL :68438723/68438736 Fax:67436072

Spare Parts

Vehicle No : SKH2123T Case Owner : ANIKKA
Make & Model : MERCEDES BENZ C 180
BLUEEFFICIENCY Year Manufacture : 2012
Chassis No : WDD2040312A776581 Engine No : 27491030019086
Sales Order : _____ Supplier : _____
Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Dispositi Surveyo
1	FRONT NUMBER PLATE <i>Best</i>	1			\$45.00	✓	
2	FRONT NUMBER PLATE GARNISH <i>men</i>	10		\$115.00	✓		
3	FRONT BUMPER <i>Best</i>	1		\$1,315.00	✓		
4	FRONT BUMPER INNER BRACKET LH <i>3/4</i>	2		\$48.00	✓		
5	FRONT BUMPER INNER BRACKET RH	1		\$48.00	✓		
6	FRONT BUMPER SPONGE <i>Best</i>	1		\$115.00	✓		
7	FRONT BUMPER REINFORCEMENT <i>?</i>	1		\$295.00	?		
8	FRONT BUMPER SIDE BRACKET LH <i>?</i>	1		\$82.00	?		
9	FRONT BUMPER SIDE BRACKET RH <i>?</i>	1		\$82.00	?		
10	FRONT BUMPER CLIPS <i>men</i>	10		\$80.00	✓		
11	FRONT SUPPORT PANEL <i>?</i>	1		\$125.00	✓		
12	FRONT SUPPORT PANEL LH <i>men</i>	1		\$117.00	✓		
13	FRONT SUPPORT PANEL RH	1		\$117.00	✓		
14	SUPPORT PANEL TOP GARNISH	1		\$65.00	✓		
15	HEAD LAMP ASSY LH <i>men</i>	1		\$1,050.00	✓		
16	HEAD LAMP ASSY RH <i>men</i>	1		\$1,050.00	✓		
17	HEAD LAMP BRACKET LH <i>3/4</i>	1		\$240.00	✓		
18	HEAD LAMP BRACKET RH	1		\$240.00	✓		
19	FRONT BUMPER LOWER GRILLE (CTR) <i>?</i>	1		\$150.00	✓		
20	FRONT BUMPER LOWER GRILLE (LH) <i>?</i>	1		\$62.00	✓		
21	FRONT BUMPER LOWER GRILLE (RH)	1		\$62.00	✓		
22	FOG LAMP - CHROME (LH) <i>3/4</i>	1		\$118.00	✓		
23	FOG LAMP - CHROME (RH)	1		\$118.00	✓		
24	CONDENSOR <i>3/4</i>	1		\$1,250.00	✓		
25	RADIATOR <i>3/4</i>	1		\$1,280.00	✓		
26	RADIATOR GRILLE <i>embled</i>	1		\$720.00	✓		
27							
28		0					
29		0					
30		0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
Tel: 68438723/68438736 FAX : 67436072

Vehicle No. :	SKH2123T	Case Owner :	ANIKKA
Make & Model :	MERCEDES BENZ C 180 BLUEEFFICIENCY	Year of Manufacture :	2012

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.