



Customer Code: 3000066

SMRT BUSES LTD

Block Unit  
STREET 62  
6 ANG MO KIO  
SINGAPORE 569140



SMRT Automotive Services Pte Ltd  
251 North Bridge Road Singapore 179102  
Tel: 65 63311000 Fax: 65 63340247

## Tax Invoice

GST Reg No. : MR-8500001-7  
CRN : 199004280Z  
Invoice No. : IV180800137  
Date : 11.08.2018  
Vehicle No. : SG5516J  
Your Ref No. : BUS/01/18/7042  
Our Ref No. : 24094494  
Terms : 30 Days

Description	Qty	Unit Cost	Add %	/ (Discount) Amount	Amount
<b>Parts</b>					
LIGHT, REVERSE:LED, FOR ADL E500 DD BUS	1.00	\$ 861.86	(10.00 )	\$ 86.19	\$ 775.67
LAMP:LED, STOP-TAIL-FLASHER, ADL E500 DD	1.00	\$ 362.39	(10.00 )	\$ 36.24	\$ 326.15
EXT REAR N/S CORNER	1.00	\$1648.08	(10.00 )	\$ 164.81	\$ 1483.27
FLYSCREEN ASSEMBLY	1.00	\$ 900.80	(10.00 )	\$ 90.08	\$ 810.72
COOLER DOOR ASSEMBLY	1.00	\$2872.05	(10.00 )	\$ 287.20	\$ 2584.85
Sub-Total					\$ 5980.66
<b>Labour</b>					
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	1.00	\$1060.00	0.00	\$ 0.00	\$ 1060.00
<b>Others</b>					
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	1.00	\$ 300.00	0.00	\$ 0.00	\$ 300.00
GRAND TOTAL					\$ 7,340.66

Remark :

Make/Model : Volvo B9TL DD  
Accident Date : 19.01.2018

N.B. Payment by cheque should be crossed and made payable to 'SMRT Automotive Services Pte Ltd'.  
No receipt will be issued unless requested.

Authorised Signature  
for SMRT Automotive Services Pte Ltd

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	26/01/2018 16:13
Date Of Accident	19/01/2018 09:25
Exact Location Of Accident	YISHUN RING RD AFT BS:59561 BLK 798
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SG5516J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	198202292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64823888

### Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	BUS

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category BUS

### Insurance Company

Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD

Type Of Coverage THIRD PARTY

Fleet Policy YES

Policy Number D-17087563MFBP

Cover Note Number

### Driver

Name of Driver SHAHRIZAM BIN ZAINAL ABIDIN

NRIC No G6930255L

Date Of Birth 21/05/1986

Occupation OUTDOOR

Date Of Driving Pass 02/03/2015

Driving Experience 2 YEARS AND 10 MONTHS

Gender MALE

Mobile Number

Fax Number

Contact Number

EMail Address NOEMAIL

Address	NOADDRESS
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	16

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

Bus was travelling along Yishun Ring Road, after BS: 59561 (Blk 798), suddenly heard a sound from the rear right side of the bus. View from the right view mirror found that the bus right rear was hit by the left front of a lorry XB8440R. For the alleged accident nobody was injured.

#### Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XB8440R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	MOHD ISKANDAR BIN MOHKREH
NRIC/Passport Number	
Contact Number	81527748
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**IMPORTANT NOTE:** Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

## ADDENDUM

### (A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MSR118013072 Vehicle Registration No: SG5516L  
Name(as shown in NRIC) : SMRT BUSES LTD NRIC/FIN/Passport No : 198202292D  
(\*Vehicle Driver / Vehicle Owner) (\*) Please delete as appropriate  
Address : — Singapore( )  
Contact (Tel) : — Mobile No.: —  
Email Address : —  
Date of Accident : 19/01/2018 Time of Accident : 09:23  
Place of Accident : YISHUN RING ROAD AFTER BS:59561 - 798  
Insurance Company: MS FIRST CAPITAL INSURANCE LTD

### (B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

The insured's vehicle no. should correctly read as SG5516J instead of SG5516L.




Policyholder / Driver's Signature  
Date:



BALQISH

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:  
Date:

SKETCH PLAN



Fishun Rig Rd.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pls refer to R14 report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Enquire Transaction History

### Transaction History Details

Log Date/Time:	30 Jan 2018 / 12:31:15		
Asset Type:	Vehicle	Transaction Amount:	\$7.49
Asset ID:	XB8440R		
Transaction Type:	18.32 Insurance Enquiry (GIRO Payment)	Channel:	External Agency
User ID:	ESASBAH0 - BALQISH BINTE ABDUL HALIL	Business Transaction Reference No.:	20180130123115090217

Search Date / Time: 19 Jan 2018 09:23:00

Insurance Company: AXA INSURANCE PTE LTD

Information displayed is correct as at the log date and time.

[Enquire Related Logs](#)[Back to List](#)



OFFSIDEFR0  
3G5516J

19/01/2018 19:20:54



