

INS. CASE OWNER:

CC 4 / AIG1800

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE

Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SJE 9602J

INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PTR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

3103.00

Loss of Rental (LOR):

S\$

240.00

(

2 days) x 120

Loss of Use (LOU):

S\$

(S

x

days)

Loss of Income (LOI):

S\$

(S

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

2.00

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost:

S\$

Total:

S\$

3345.00

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

3345.00

Name 1:

TORQUE 5 PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

COPY SENT

ASSIGNMENT

From: _____ Date: 05/02/2018
 Estimated Cost: _____
 QD / TP / WS / TP RES / QD RES / EVA / INV / MV
 To Inspect Vehicle No: SJE 9602J
 at Workshop no: Torque 5
 of: 8 Kaki Bukit Ave 4 #01-50
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition) after 1030am
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAO Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res: Yes or No
 Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle IN / OUT

Veh No: SJE9602J Yr Regn: 2008 May
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or: _____

Make: Mit Lanes cc: 1998
 Colour: Black A/C: Insured / Std / Nil / NA
 Sp. Reading: 205468 T/Radio: Insured / Std / Nil / NA

Eng No: _____
 Cr No: JMYSTCY4A84002939

Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R17
 R: 215/60R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Achilles

Front Rear
 R/Bal: 06 mm R/Bal: 06 mm
 L/Bal: 06 mm L/Bal: 06 mm
 D.O.A: _____ D.O.I: 05/02/18

Survey held at: Torque 5
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction
TP ALG

MV : 12K L/S - \$ 2900K Red: 7085.83 (73 %)
 PV : 9.3K
 Net : 2.7K

Date/Time File Pass to: ☐ Prel. Report
☐ Final Report
 Date/Time File Return to: _____
 Report Format: _____
 Lump Sum / I.B./ I/S: _____

Days Of Repair: _____
 Resurvey No. of Trip: _____
 Add Fee: ☐ Site Insp: \$
☐ Inter. Exp: \$
☐ Tech. Insp: \$
☐ Weekend: \$

Survey Fee: _____
 Transportation: _____
☐ S + P + B
 Photo: _____
 Other: _____
 TOTAL: _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC4/AIG18002120/Aua3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 02-02-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKW 9699Z	Veh. Inspected	SJE 9602J	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	02/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	01/02/2018	Inspection Date	05/02/2018	
Survey held at	TORQUE 5 PTE LTD 8 KAKI BUKIT AVENUE 4 #01-50 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

T.P.A.H.
This Item

ESTIMATION REPORT

Vehicle No : SJE9602J
Make & Model : MITSUBISHI, LANCER 2.0L MIVEC GLS 6-
CVT, JMYSTCY4A8U002939
Year of Manufacture : 2007

Estimation No. : E18020008
DOA : 01/02/2018

No	Description	Qty	U/P	Amt
<u>Section: List Items</u>				
1	Rear bootlid <i>new</i>	1.00	0.00	0.00 <i>1389.00</i>
2	Rear bootlid logo	1.00	0.00	0.00 <i>67.00</i>
3	Rear bootlid weather strip	1.00	0.00	0.00 <i>84.50</i>
4	Rear bootlid lock	1.00	0.00	0.00 <i>167.00</i>
5	Rear bootlid lamp (RH)	1.00	0.00	0.00 <i>144.00</i>
6	Rear bumper <i>replaced</i>	1.00	0.00	0.00 <i>1205.00</i>
7	Rear bumper clip <i>new</i>	1.00 <i>10</i>	0.00 <i>5.00</i>	0.00 <i>50.00</i> <i>30</i>
8	Rear bumper retainer (RH) <i>new</i>	1.00	0.00	0.00 <i>92.00</i>
9	Rear bumper bracket (RH) <i>new</i>	1.00	0.00	0.00 <i>82.00</i>
10	Rear bumper reinforcement <i>Bent</i>	1.00	0.00	0.00 <i>211.30</i>
11	Rear bumper reflector (RH) <i>new</i>	1.00	0.00	0.00 <i>68.00</i>
12	Rear bumper towing cap <i>replaced</i>	1.00 <i>10</i>	0.00 <i>5.00</i>	0.00 <i>50.00</i> <i>28</i>
13	Tail lamp (RH)	1.00	0.00	0.00 <i>352.00</i>
14	Tail lamp clip (RH)	1.00 <i>2</i>	0.00 <i>5.00</i>	0.00 <i>10.00</i>
15	Rear fender (RH) - repair	1.00	0.00	0.00 <i>850.00</i>
16	Rear fender inner trim (RH)	1.00	0.00	0.00 <i>267.00</i>
17	Rear fender inner trim clip (RH)	1.00 <i>10</i>	0.00 <i>5.00</i>	0.00 <i>50.00</i> <i>441</i>
18	Rear end panel <i>Dented</i>	1.00	0.00	0.00 <i>806.00</i>
19	Rear end panel top garnish <i>replaced</i>	1.00	0.00	0.00 <i>322.00</i> <i>175</i>
20	Rear end panel top garnish clip <i>new</i>	1.00	0.00	0.00 <i>50.00</i> <i>10</i>
21	Exhaust pipe <i>Bent</i>	1.00	0.00	0.00 <i>963.00</i> <i>642</i>
22	Exhaust pipe mounting <i>new</i>	1.00	0.00	0.00 <i>70.00</i>
23	Exhaust pipe gasket <i>new</i>	1.00	0.00	0.00 <i>68.00</i>

Continue on next page...



Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJE9602J
Make & Model : MITSUBISHI, LANCER 2.0L MIVEC GLS 6-
CVT, JMYSTCY4A8U002939
Year of Manufacture : 2007

Estimation No. : E18020008
DOA : 01/02/2018

No	Description	Qty	U/P	Amt
			Amt	S\$ 0.00 7328.70
			Discount (10.00%)	S\$ 0.00 732.87
			Subtotal	S\$ 0.00 6595.83

Section: Special Nett Items

24	Rear bumper reverse sensor <i>2nd</i>	1.00	400.00	400.00 <i>2w</i>
25	Rear number plate <i>310</i>	1.00	50.00	50.00 ✓
26	Rear fender sealant <i>2w</i>	1.00	80.00	80.00 +
27	Rear end panel sealant <i>2w</i>	1.00	80.00	80.00 <i>60</i>

Amt S\$ 610.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 610.00

Section: Labour Items

28	To R&R accident affected areas	1.00	1,000.00	1,000.00 <i>150</i>
29	To putty & respray accident affected areas	1.00	1,000.00	1,000.00 <i>500</i>
30	To rust proof accident affected areas	1.00	60.00	60.00 <i>40</i>
31	To R&R rear boot mechanism <i>1310</i>	1.00	80.00	80.00 +
32	To R&R rear luggage compartment	1.00	200.00	200.00 <i>40</i>
33	To R&R rear bumper reverse sensor & check function	1.00	80.00	80.00 <i>50</i>
34	To check wiring layout of tail lamp	1.00	80.00	80.00 +
35	To R&R exhaust pipe assy	1.00	180.00	180.00 <i>80</i>
36	To check for water seepage	1.00	100.00	100.00 +

Amt S\$ 2,780.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 2,780.00

P: 3710-20-10%

3239-18

SN: 310-00

Adrian Lj
L/S 05/02/18.
os ap.

total 3732.48
L/S: 2.9K

LUX Auto 2.5 1410-00
The Repairer shall be responsible for the following:
1. To provide a written estimate of the cost of the repair.

- To provide a written estimate of the cost of the repair.
- To provide a written estimate of the cost of the repair.
- To provide a written estimate of the cost of the repair.
- To provide a written estimate of the cost of the repair.
- To provide a written estimate of the cost of the repair.

Acknowledged by Repairer

Signature:

Date:

List Items Subtotal S\$ 0.00
Special Nett Items S\$ 610.00
Subtotal S\$ 610.00
Labour Items Subtotal S\$ 2,780.00
Total S\$ 3,390.00

PAGE 2 OF 2

Total 9985.83

TAX INVOICE

Our Ref No: GR-18-018928
Date of Request: 05/02/2018

Your Ref No: Online Purchase

Torque 5 Pte Ltd
No. 8 Kaki Bukit Ave 4,
#01-50
Singapore 415875

Dear Sir/Madam,

Date of Accident: 01/02/2018
Vehicle No: SJE9602J
Place of Accident: MOULMEIN U-TURN
Involving Vehicle No: SKW9699Z

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SKW9699Z	MOULMEIN U-TURN	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-018928
Date of Request: 05/02/2018

Your Ref No: Online Purchase

Torque 5 Pte Ltd
No. 8 Kaki Bukit Ave 4,
#01-50
Singapore 415875

Dear Sir/Madam,

Date of Accident: 01/02/2018
Vehicle No: SJE9602J
Place of Accident: MOULMEIN U-TURN
Involving Vehicle No: SKW9699Z

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SKW9699Z	MOULMEIN U-TURN	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

**GENERAL
INSURANCE
ASSOCIATION**

RECORDS MANAGEMENT CENTRE

GENERAL INSURANCE ASSOCIATION OF SINGAPORE**RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

SEARCH RESULTS

Our Ref No: GR-18-018917

Date of Request: 05/02/2018

Your Ref No:

Online Purchase

Torque 5 Pte Ltd
No. 8 Kaki Bukit Ave 4,
#01-50
Singapore 415875

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 01/02/2018

Place of Accident: MOULMEIN U-TURN

Client Vehicle No: SJE9602J

With reference to your search criteria for the accident report, the following documents were found to closely match your search criteria:

REQ. VEHICLE	ACCIDENT LOCATION	ACCIDENT DATE
SKW9699Z	EXIT 7C CTE	01/02/2018 11:00

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-018917
Date of Request: 05/02/2018

Your Ref No: Online Purchase

Torque 5 Pte Ltd
No. 8 Kaki Bukit Ave 4,
#01-50
Singapore 415875

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 01/02/2018
Place of Accident: MOULMEIN U-TURN
Client Vehicle No: SJE9602J

DESCRIPTION	AMOUNT (\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

Thin Thin (LKKAUTO)

From: Thin Thin (LKKAUTO)
Sent: Wednesday, 28 March 2018 7:03 PM
To: 'cvbharadwaj@gmail.com'
Subject: ACCIDENT INVOLVING SKW 9699Z & SJE 9602J ON 01/02/2018



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/AIG18002120/Aua3

28 MARCH 2018

CHIVUKULA BHARADWAJ
3 RHU CROSS
#03-03
SINGAPORE 437433

Dear Sir/Madam,

ACCIDENT INVOLVING SKW 9699Z & SJE 9602J ON 01/02/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

THIN THIN HLAING
Case Handler
DID: 6841 2360
FAX: 6741 4108
Email: thinthin@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd

(Motor Claims Dept)



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. Reg. No.: 201313221G

LETTER OF AUTHORISATION

Accident on 01/02/2018 along Moulmein U turn
Involving vehicles SJE 9602J, SKW 9699Z

In consideration of **Torque 5 Pte Ltd, 8 Kaki Bukit Ave 4, Premier @ Kaki Bukit #01-50 Singapore 415875**, repairing my/our motor vehicle no SJE 9602J at my request, I/We, Torque 5 Leasing Pte Ltd ("the claimant") of 8 Kaki Bukit Ave 4 #01-50 Premier @ Kaki Bukit (415875) bearing NRIC No 201530768C the owner of motor vehicle no SJE 9602J, hereby authorize them to demand claim, settle and receive whatever amount settle payable by the insurance company or third party or commence legal proceeding for cost of repairs, loss of use and etc to any of their appointed solicitors to act for me/us in respect of the said accident/claim and all the amount claimed or settled shall belong and make payable to them absolutely by the insurance company of the third party. I/We further authorized them to give an absolute discharge on my/our behalf and to sign discharge voucher(s) and any other documents necessary or incidentals to the conduct and disposal of my/our above claims.

I/We further agree to fully co-operate and attend all court hearings that are necessary to prosecute the claims maintained by **Torque 5 Pte Ltd**.

I/We further agree and undertake to indemnify them against my/our claim for costs which arise therewith.

In the event that my/our claim is unsuccessful, I/we undertake to pay to **Torque 5 Pte Ltd** the cost of repairs to my/our vehicle.

In the event that the settlement/payment cheque is being made in my/our favour, I/we hereby undertake to return the full amount to **Torque 5 Pte Ltd** account, within 7 days from receiving and clearance of the said settlement/payment cheque. Failing which, **Torque 5 Pte Ltd** will have the legal rights to take legal proceedings against me/us to recover the said sum, with further costs and disbursements to be incurred by me/us.

I/We further authorize **Torque 5 Pte Ltd** to settle the aforesaid claim in a manner that you deem fit and to utilize the monies to pay your charges without further reference to me/us. The payment to **Torque 5 Pte Ltd** shall amount to a good discharge of **Torque 5 Pte Ltd** obligation to me/us in respect of the settlement monies.

Dated this 05 day of February (month) 20 18 (year)


Signed by "the claimant"

Name: Torque 5 Leasing Pte Ltd

NRIC No: 201530768C


Signed by Torque 5 Pte Ltd

Name: Michelle

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, TORQUE 5 PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$ 3,103.00 (Repair Cost), S\$ 240.00 (Loss of Rental/Use), S\$ 2.00 (Disbursement) for vehicle no. SJE 9602J that was damaged pursuant to the accident which occurred on 01/02/2018 (date) along EXIT 7C CTE (location) involving vehicle no/s SKW 9699Z. This is pursuant to the inspection conducted on 05/02/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner TORQUE 5 LEASING PTE LTD ("the third party claimant") of vehicle no. SJE 9602J make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SJE 9602J (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 12 (day) of April (month) 20 18 (year)



WJP

Signed by appointed surveyor

WJP



Signed by "the workshop" (with chop)

my execution of this Discharge Voucher is only
for my claim for property damage and not prejudicial
to any other claims arising from the same accident.

**Torque 5 Pte Ltd**

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

Tax Invoice**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way
#07-16 AIG Building
Singapore 079120
Tel: 6419 1000

Inv. No. : T51804179
Inv. Date : 12 Apr 2018
Ref : 01/02/2018
Terms : 30 Days
Veh. No. : SJE9602J
Make & Model : MITSUBISHI LANCER
2.0L MIVEC GLS 6-CVT

#	Description	Qty	UOM	Unit Price	Disc	Amt
1	TO SUPPLY SPARE PARTS AND LABOUR FOR ACCIDENT REPAIR PARTS LUMP SUM AMOUNT	1.00		2,900.00	0.00	2,900.00

Subtotal : S\$ 2,900.00
GST 7.0% : S\$ 203.00
Total : S\$ 3,103.00

*I agree to the price as listed above and
affirm that the goods are received in good
condition.*

For **TORQUE 5 PTE. LTD.**

(Authorised Signature)



(Customer's Signature and Company Stamp)



No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit
#01-50 Singapore 415875
Tel: +65 6452 4457 Fax: +65 6452 4584
Email: leasing@torque5.com
Company Reg. No: 201530768C

Lim Chain Chuen
8 Kaki Bukit Ave 4 Premier @ Kaki Bukit #01-50 S(415875)
C/O
Torque 5 Pte Ltd
8 Kaki Bukit Avenue 4, #01-50
Premier @ KB, Singapore 415875
Tel: 6452 4457 Fax: 6452 4584

Rental Invoice

Inv No. : L51802007
Date : 07 Feb 2018
Ref : SJE9602J
Currency : SGD
Terms : COD
RA No. : R18020006
Veh No. : SGN4191Z

#	Rental Period	Rate	Disc	Amt
1	Rental (05/02/2018 10:00 to 07/02/2018 17:00)	400.00	0.0000	400.00

I agree to the price as listed above and
affirm that the goods are received in good
condition.

(Customer's Signature and Company Stamp)

Subtotal : S\$ 400.00
GST 7.0% : S\$ 0.00
Total : S\$ 400.00

For TORQUE 5 LEASING PTE LTD


TORQUE 5 LEASING PTE LTD
REG NO: 201530768C
(Authorised Signature)

RENTAL AGREEMENT

T 001924

HIRER'S PARTICULAR		Veh. No/Model: <u>SJE 9602J M-Lan car</u>															
Name: <u>Lim Choin Chuen / Torque 5 Leasing Pte Ltd</u>		Rental Veh. No/Model: <u>SGN 4191Z V-Golf</u>															
NRIC/Passport No: <u>F1480651L / 201530768C</u>		Date/Time Out: <u>5/2/2018 10am</u>															
Address: <u>8 Kaki Bukit Ave 4 Premier @ Kaki Bukit #01-50 S(415875)</u>		Date/Time In: <u>7/2/2018 5pm</u>															
Tel: <u>8608 6539</u>		OUT 1/2 E F IN 1/2 E F															
Driving license No: _____ Exp: _____		Milage: <u>18095</u> Milage: <u>190200</u>															
ADDITIONAL DRIVER'S PARTICULAR		Rental Charges															
Name: _____		<table border="1"> <thead> <tr> <th>Hours @</th> <th>per hour</th> </tr> </thead> <tbody> <tr> <td>2</td> <td>200</td> </tr> <tr> <td>Days @</td> <td>per day</td> </tr> <tr> <td>Weeks @</td> <td>per week</td> </tr> <tr> <td>Months @</td> <td>per month</td> </tr> <tr> <td colspan="2">Subtotal <u>400</u></td> </tr> <tr> <td colspan="2">GST @ 7%</td> </tr> </tbody> </table>		Hours @	per hour	2	200	Days @	per day	Weeks @	per week	Months @	per month	Subtotal <u>400</u>		GST @ 7%	
Hours @	per hour																
2	200																
Days @	per day																
Weeks @	per week																
Months @	per month																
Subtotal <u>400</u>																	
GST @ 7%																	
NRIC/Passport No: _____		Others															
Address: _____		TOTAL CHARGES <u>400</u>															
Tel: _____		Mode of Payment:															
Driving license No: _____ Exp: _____		Cash/Nets/Cheque/Credit Card: _____															
(A) - ACCIDENTS (D) - DENTS (S) - SCRATCHES		<table border="1"> <thead> <tr> <th>Deposit</th> <th>Refunded</th> </tr> </thead> <tbody> <tr> <td>Amount</td> <td></td> </tr> </tbody> </table>		Deposit	Refunded	Amount											
Deposit	Refunded																
Amount																	
		Remarks: _____ Received by _____															
Physical Damage Excess <table border="1"> <tbody> <tr> <td>Singapore - Own Damage</td> <td>S\$2,000</td> </tr> <tr> <td>Singapore - 3rd Party Damage</td> <td>S\$2,000</td> </tr> <tr> <td>Malaysia (if applicable)</td> <td>S\$8,000</td> </tr> <tr> <td>For Driver aged < 27 or above 65 and/or less than 2 yrs driving experience regardless of age</td> <td>S\$3,000 (Additional)</td> </tr> </tbody> </table>		Singapore - Own Damage	S\$2,000	Singapore - 3rd Party Damage	S\$2,000	Malaysia (if applicable)	S\$8,000	For Driver aged < 27 or above 65 and/or less than 2 yrs driving experience regardless of age	S\$3,000 (Additional)	Acknowledgement 							
Singapore - Own Damage	S\$2,000																
Singapore - 3rd Party Damage	S\$2,000																
Malaysia (if applicable)	S\$8,000																
For Driver aged < 27 or above 65 and/or less than 2 yrs driving experience regardless of age	S\$3,000 (Additional)																
IMPORTANT NOTE: 1. ONLY PERSONS ABOVE 22 YEARS OF AGE, HOLDING A VALID SINGAPORE LICENCE FOR MORE THAN 2 YEARS, AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE. 2. Vehicle is strictly for use in Singapore only and may not be driven out of Singapore without the prior written consent of Torque 5 Leasing Pte Ltd. 3. Use of vehicle for illegal purposes (e.g. In connection with theft, drug peddling or trafficking, smuggling) is strictly prohibited. 4. In case of accident, the hirer shall report to Torque 5 Leasing Pte Ltd immediately.		Hirer Signature/Date _____ for Torque 5 Leasing Pte Ltd Owner Signature/Date _____ 															

2/1/2018

Invoice



GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-017658
Date of Request: 01/02/2018

Your Ref No: Online Purchase

Torque 5 Pte Ltd
No. 8 Kaki Bukit Ave 4,
#01-50
Singapore 415875

Dear Sir/Madam,

Enquiry Date: 01/02/2018
Enquiry By: Stephanie Tao Wan Ting
TP Vehicle No: SKW9699Z
Accident Date: 01/02/2018

SJE 9602J

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKW9699Z	AIG Asia Pacific Insurance Pte. Ltd.	22/10/2017-21/10/2018	65-6419-3000

Thank You,

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

2/1/2018

Invoice



GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-017858
Date of Request: 01/02/2018

Your Ref No: Online Purchase

Torque 5 Pte Ltd
No. 8 Kaki Bukit Ave 4,
#01-50
Singapore 415875

Dear Sir/Madam,

Enquiry Date: 01/02/2018
Enquiry By: Stephanie Teo Wan Ting
TP Vehicle No: SKW9999Z
Accident Date: 01/02/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Feb 2018 Edit Reg		02 Feb 2018 00:00 Edit Adj Rpt	\$2,900.00 Edit Estimates	\$2,900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS [Created by adjuster] Insured: CHIVUKULA BHARADWAJ, ID: 57687683E Main Claimant: Torque 5 Leasing Pte Ltd, Co. Reg. No.: 201530768C Vehicle Reg. No.: SJE9602J Date of Loss: 01/02/2018 11:00 - :59 [116 Months and 18 Days From LTA Reg Date (Man Yr)] Claim Type: TP / 7576475306SG Policy/Cover Note No.: 2100434738 (Comprehensive) Vehicle Reg. No. (Insured): SKW9699Z Policy No. (Claimant): - Excess: Repairer: Torque 5 Pte Ltd (Kaki Bukit) No. 8 Kaki Bukit Ave 4, #01-50, 415875 Kaki Bukit - Tel: 64524457 Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel: Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 13/02/2018]					ASSOCIATED MAIL RECEIVED View All Compose Case Mail - AIG_SG (05/02/2018): No OI GIA Report - AIG_SG (05/02/2018): Request To Upload TP GIA Report																			
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

Claim Documents

***SJE9602J (7576475306SG)**
[SKW9699Z]

TP

Torque 5 Leasing Pte Ltd
Feb 1 2018 11:00AM
[CHIVUKULA BHARADWAJ]
Torque 5 Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser Print		
Letters/Correspondences												1 per page		☒			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	(Draft)	Third Party Express Settlement – Payment Breakdown										1	Edit				
Assessment Reports												1 per page		☒			
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)										Thumbnail		Print			
1	05/02/18 15:28	Accident Statement From: SC – Reg. No: SKW9699Z, Claimant: CHIVUKULA BHARADWAJ										1	Load HTM				
Photos/Images												3 per page		☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	26/03/18 18:42	General View										1	Load JPG	☒			
2	26/03/18 18:42	Chassis Number										1	Load JPG	☒			
3	26/03/18 18:42	General View										1	Load JPG	☒			
4	26/03/18 18:42	General View										1	Load JPG	☒			
5	26/03/18 18:42	General View										1	Load JPG	☒			
6	26/03/18 18:42	General View										1	Load JPG	☒			
7	26/03/18 18:42	General View										1	Load JPG	☒			
8	26/03/18 18:42	General View										1	Load JPG	☒			
9	26/03/18 18:42	General View										1	Load JPG	☒			
10	26/03/18 18:42	General View										1	Load JPG	☒			
11	26/03/18 18:42	General View										1	Load JPG	☒			
12	26/03/18 18:42	General View										1	Load JPG	☒			
13	26/03/18 18:42	General View										1	Load JPG	☒			
14	26/03/18 18:42	General View										1	Load JPG	☒			
15	26/03/18 18:42	General View										1	Load JPG	☒			
16	26/03/18 18:42	General View										1	Load JPG	☒			
17	26/03/18 18:42	General View										1	Load JPG	☒			
18	26/03/18 18:42	General View										1	Load JPG	☒			
19	26/03/18 18:42	General View										1	Load JPG	☒			
20	26/03/18 18:42	General View										1	Load JPG	☒			
21	26/03/18 18:43	Reinspection Photo										1	Load JPG	☒			
22	26/03/18 18:43	Reinspection Photo										1	Load JPG	☒			
23	26/03/18 18:43	Reinspection Photo										1	Load JPG	☒			
24	26/03/18 18:43	Reinspection Photo										1	Load JPG	☒			
25	26/03/18 18:43	Reinspection Photo										1	Load JPG	☒			
26	26/03/18 18:43	Reinspection Photo										1	Load JPG	☒			
27	26/03/18 18:43	Reinspection Photo										1	Load JPG	☒			
28	26/03/18 18:43	Reinspection Photo										1	Load JPG	☒			
29	26/03/18 18:43	Reinspection Photo										1	Load JPG	☒			
30	26/03/18 18:43	Reinspection Photo										1	Load JPG	☒			

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	26/03/18 18:43	Reinspection Photo	 Load JPG	☒
32	26/03/18 18:43	Reinspection Photo	 Load JPG	☒
33	26/03/18 18:43	Reinspection Photo	 Load JPG	☒
34	26/03/18 18:43	Reinspection Photo	 Load JPG	☒
35	26/03/18 18:43	Reinspection Photo	 Load JPG	☒
36	26/03/18 18:43	Reinspection Photo	 Load JPG	☒
37	26/03/18 18:43	Reinspection Photo	 Load JPG	☒
38	26/03/18 18:43	Reinspection Photo	 Load JPG	☒
39	26/03/18 18:43	Reinspection Photo	 Load JPG	☒
40	26/03/18 18:43	Reinspection Photo	 Load JPG	☒
41	26/03/18 18:43	Reinspection Photo	 Load JPG	☒
42	26/03/18 18:43	Reinspection Photo	 Load JPG	☒
43	26/03/18 18:43	Reinspection Photo	 Load JPG	☒
44	26/03/18 18:43	Reinspection Photo	 Load JPG	☒
45	26/03/18 18:43	Reinspection Photo	 Load JPG	☒
46	26/03/18 18:43	Reinspection Photo	 Load JPG	☒
47	26/03/18 18:43	Reinspection Photo	 Load JPG	☒
48	26/03/18 18:43	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/02/18 15:42	EMAIL PRS	 Load PDF	
2	02/02/18 15:42	ACKNOWLEDGEMENT EMAIL TO AIG DD 02.02.2018	 Load PDF	
3	02/02/18 15:42	TP GIA REPORT	 Load PDF	
4	18/04/18 09:34	WORKSHOP INVOICE	 Load PDF	
5	18/04/18 09:34	AUTHORISATION TO ACT FORM	 Load PDF	
6	18/04/18 09:34	Release Voucher	 Load PDF	
7	18/04/18 09:34	RENTAL RECEIPT	 Load PDF	
8	18/04/18 09:34	GIA SEARCH	 Load PDF	
9	18/04/18 09:34	LETTER TO OI	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SKW9699Z (Insd veh)	Model:	MITSUBISHI LANCER 2.0 L
	SJE9602J (TP veh)		MIVEC GLS6-CVT (A)
Date of Accident:	01/02/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	10,684.84
Final Repair Cost	:	\$	3,103.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	240.00 2 days
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	3,345.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Torque 5 Pte Ltd	:	\$ 3,345.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

18 Apr
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18002120/AUA3Q2

Date: 18/04/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100434738
 Claimant Vehicle No: SJE9602J Insured Vehicle No: SKW9699Z
 Date of Loss: 01/02/2018 Nature of Claim: TP Claim No: 7576475306SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJE9602J
 Make & Model: MITSUBISHI LANCER, 2.0 L MIVEC GLS6-CVT (A) Engine No: 4B11BC5734
 Reg. Date: 14/05/2008 (Man. Year: 2007) Chassis No: JMYSTCY4A8U002939
 Colour: Black Odometer: 205468 km
 Engine Capacity: 1998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17
 Front Left Side: Achilles 6 mm Rear Left Side: Achilles 6 mm
 Front Right Side: Achilles 6 mm Rear Right Side: Achilles 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,205.83	2,422.48	4,783.35	66.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,780.00	1,310.00	1,470.00	52.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,985.83	3,732.48	6,253.35	62.62
Approved Total (Overridden) (S\$)		2,900.00		
(S\$)	9,985.83	2,900.00	7,085.83	70.96
+ GST 7.00/7.00% (S\$)	699.01	203.00	496.01	70.96
Nett Amount (S\$)	10,684.84	3,103.00	7,581.84	70.96
+ Car Rental (2.0 x S\$120.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,345.00		

INSPECTION

Date of Assignment: 02/02/2018
 Date Inspected: 05/02/2018 Inspected At: Torque 5 Pte Ltd (Kaki Bukit)
 No. 8 Kaki Bukit Ave 4., #01-50
 Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: THIN THIN HLAING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Not Necessary	1,339.00 FL	*- FL
2	1		*REAR BOOTLID LOGO	Not Necessary	67.00 FL	*- FL
3	1		*REAR BOOTLID WEATHERSTRIP	Not Necessary	84.50 FL	*- FL
4	1		*REAR BOOTLID LOCK	Not Necessary	167.00 FL	*- FL
5	1		*REAR BOOTLID LAMP (RH)	Not Necessary	144.00 FL	*- FL
6	1		*REAR BUMPER	Deformed	1,205.00 FL	*758.00 FL
7	10		*REAR BUMPER CLIP	Necessary	50.00 FL	*30.00 FL
8	1		*REAR BUMPER RETAINER (RH)	Necessary	52.00 FL	*52.00 FL
9	1		*REAR BUMPER BRACKET (RH)	Not Necessary	82.00 FL	*- FL
10	1		*REAR BUMPER REINFORCEMENT	Bent	211.20 FL	*211.20 FL
11	1		*REAR BUMPER REFLECTOR (RH)	Not Necessary	68.00 FL	*- FL
12	10		*REAR BUMPER TOWING CAP	Deformed	50.00 FL	*28.00 FL
13	1		*TAIL LAMP (RH)	Not Necessary	352.00 FL	*- FL
14	2		*TAIL LAMP CLIP (RH)	Not Necessary	10.00 FL	*- FL
15	1		*REAR FENDER (RH)	Not Necessary	850.00 FL	*- FL
16	1		*REAR FENDER INNER TRIM (RH)	Not Necessary	267.00 FL	*- FL
17	10		*REAR FENDER INNER TRIM CLIP (RH)	Not Necessary	50.00 FL	*- FL
18	1		*REAR END PANEL	Dented	806.00 FL	*441.00 FL
19	1		*REAR END PANEL TOP GARNISH	Deformed	323.00 FL	*175.00 FL
20	1		*REAR END PANEL TOP GARNISH CLIP	Necessary	50.00 FL	*10.00 FL
21	1		*EXHAUST PIPE	Bent	963.00 FL	*642.00 FL
22	1		*EXHAUST PIPE MOUNTING	Not Necessary	70.00 FL	*- FL
23	1		*EXHAUST PIPE GASKET	Not Necessary	68.00 FL	*- FL
24	1		*REAR BUMPER REVERSE SENSOR	Damaged	400.00 FS	*200.00 FS
25	1		*REAR NUMBER PLATE	Bent	50.00 FS	*50.00 FS
26	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
27	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,938.70	2,657.20
- List Item Discount on L Items 10.00/10.00% (S\$)	732.87	234.72
Total Parts (S\$)	7,205.83	2,422.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO R&R ACCIDENT AFFECTED AREAS	New	1,000.00	600.00
2	TO PUTTY & RESPRAY ACCIDENT AFFECTED AREAS	New	1,000.00	500.00
3	TO RUST PROOF ACCIDENT AFFECTED AREAS	New	60.00	40.00
4	TO R&R REAR BOOT MECHANISM	New	80.00	0.00
5	TO R&R REAR LUGGAGE COMPARTMENT	New	200.00	40.00
6	TO R&R REAR BUMPER REVERSE SENSOR & CHECK FUNCTION	New	80.00	50.00
7	TO CHECK WIRING LAYOUT OF TAIL LAMP	New	80.00	0.00
8	TO R&R EXHAUST PIPE ASSY	New	180.00	80.00
9	TO CHECK FOR WATER SEEPAGE	New	100.00	0.00
Gross Labour Cost (S\$)			2,780.00	1,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >