

M/s China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Attention: Motor Claim Department

RE : VEHICLE NO : XD9938E ISUZU

DESCRIPTION

- 1 1 FRONT GRILLE
- 2 1 FRONT LOWER GRILLE
- 3 2 CORNER PANEL RH+LH
- 4 1 FRONT BUMPER
- 5 1 HEADLAMP LH
- 6 1 SIGNAL LAMP LH
- 7 1 SIGNAL LAMP TOP BRACKET LH
- 8 1 HEADLAMP RIM *RH*
- 9 1 HEADLAMP BRACKET LH

1685

*Not Authorized
nkk
L/S H 5000
3 day
5/2/18
take photo After repair*

ESTIMATE

DATE : 02/02/2018
ACC DATE : 01/02/2018
REF NO : VFIX-TP20180411
POLICY NO :

AMOUNT S\$

<i>Cne</i>	1,322.00	<i>—</i>
<i>Cne</i>	422.00	<i>—</i>
<i>Cne</i>	2,240.00	<i>—</i>
<i>Used</i>	2,088.80	<i>—</i>
<i>17</i>	747.60	<i>✓</i>
<i>17</i>	503.60	<i>✓</i>
<i>17</i>	65.00	<i>✓</i>
<i>mis</i>	115.00	<i>✓</i>
<i>17</i>	285.00	<i>X</i>
\$	7,789.00	
LESS 20%	\$	1,557.80
\$	6,231.20	

*+ 764
4627.2*

DESCRIPTIONS (SPECAIL NETT)

AMOUNT S\$

1	1	FRONT NUMBER PLATE		<i>but</i>	35.00	SN	<i>1X</i>
2	1	AIR CON SUCTION HOSE		<i>17</i>	285.00	SN	<i>✓</i>
3	8	CORNER PANEL CLIP	7.00	<i>17</i>	56.00	SN	<i>✓</i>
4	8	FRONT GRILLE CLIP	7.00	<i>17</i>	56.00	SN	<i>—</i>
5	4	FRONT LOWER GRILLE CLIP	5.00	<i>17</i>	20.00	SN	<i>—</i>
6	4	HEADLAMP RUBBER MOUNTING	18.00	<i>17</i>	72.00	SN	<i>✓</i>
7	4	HEADLAMP RIM CLIP	8.00	<i>17</i>	32.00	SN	<i>✓</i>
				\$	556.00		

LABOUR & MISCELLANEOUS:

AMOUNT S\$

1	To remove damaged body panel with all necessary components/attachments apply hot-works where necessary straighten front panel, repair/reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components/attachments	880k	1,200.00
2	To spray paint replaced/repainted body panels inclusive of preparatory works and painting materials	650	1,000.00
3	To remove, replace suction hose vacuum system and recharge gas	11X	150.00
4	To conduct headlamp alignment	✓	30.00
		\$	2,380.00

GRAND TOTAL : \$ 9,167.20

SINGAPORE DOLLARS : NINE THOUSAND ONE HUNDRED SIXTY SEVEN & CENTS
TWENTY ONLY

Vfix Auto Service Pte Ltd



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: