

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18002196/Gvbn2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 21-02-2018	
			Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKD 6621S	Veh. Inspected	SHF 248B	
Policy No.	5088247237	Coverage (\$)	0.00	
Claim No.	MT/0980412-002	Excess (\$)	0.00	
Assign From		Assign Date	02/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS HYBRID	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FUX03576384	Colour	MAROON	
Odometer	8376	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	9 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	9 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA	9 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/01/2018	Inspection Date	02/02/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		