



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG18002207/hb3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 05-02-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKX 7265A	Veh. Inspected	SKP 2458K	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	05/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	03/02/2018	Inspection Date		
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 19740155PW GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

286, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

05 FEB 2018

Estimate No. : b1 45770
Date Estimated : 05/02/2018
Prepared By : Chua Kee Sin

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Choong Lai Heng
Apt Blk 143 Lorong 2 Toa Payoh
#11-184

Singapore 310143

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKP2458K	J722125	26/08/2014	316iA/4	0

DESCRIPTION

Remove right front side fender front bumper and remove attachment etc include knock on accident dent

VALUE
~~850~~ 2,580.00

Spray painting front bumper and front right side fender

~~1730~~ 1,923.00

To check steering geometry and conduct wheel alignment according to BMW specification (1X)

X 531.00

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

~~150~~ 177.00

Sundries. *N/A*

~~40~~ 150.00

Total Labour 1: 5,331.00

DESCRIPTION

FRT LH TOP SUPPORT SIDE PANEL
FRT RH TOP SUPPORT SIDE PANEL
RH SUPPORT FOGLAMP
FRT LH BOTTOM MOUNTING SIDE PANEL
FRT RH BOTTOM MOUNTING SIDE PANEL
GROMMET
PLAQUE 82MM

QTY	PRIC
1	18.00
1	18.00
1	37.60
1	18.00
1	18.00
2	0.75
1	69.50

VALUE
18.00
18.00
37.60
18.00
18.00
1.50
69.50

Total Parts : 180.60

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190526 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 45770
Date Estimated : 05/02/2018
Prepared By : Chua Kee Sin

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKP2458K	J722125	26/08/2014	316iA/4	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OO / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
Date&Time 12/03/18 @ 2/15 Excess S\$ _____
Surveyor's Name Rafael Sign _____
Surveyor's Tel 90010068 Authorised Yes / No _____
Authorised Date _____ Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PHL Yes / No _____
Surveyor's E-mail _____
No. of Working Days Recommend 3-4 days

Labour 1	:	5,331.00
Parts	:	180.60
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	385.81
Grand Total	:	<u>5,897.41</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

5,511.60

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 45770
Date Estimated : 05/02/2018
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Choong Lai Heng
Apt Blk 143 Lorong 2 Toa Payoh
#11-184

Singapore 310143

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SKP2458K	J722125	26/08/2014	316iA/4	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To make good the front bumper, front RH fender include replacment of damaged parts and knocking out dents caused by the accident	850.00		850.00
To spray paint front bumper and front RH fender	1730.00		1,730.00
* To check electrical wiring systems at the front section for proper function including adjustments of headlights,	150.00		150.00
Sundries.	40.00		40.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
GROMMET	0.75	2.00		1.50
PLAQUE 82MM	69.50	1.00		69.50

SUPPLEMENTARY ITEMS

Total Labour :	2,770.00
Total Parts :	71.00
Total Labour & Parts :	2,841.00
Deduction for Excess :	
Total Repair Costs less Excess:	2,841.00
GST @7%:	198.87
Grand Total :	3,039.87

Vic (LKKAuto)

From: PBSP <pml-pbsp@sime-darby.com.sg>
Sent: Monday, 2 April, 2018 4:58 PM
To: Rasul (LKKAuto); Vic (LKKAuto)
Cc: Asher Sng (LKKAuto)
Subject: FINAL REPORT / SKP2458K
Attachments: Final Report SKP2458K.pdf

Dear Rasul and Vic

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 2,770.00
Total Parts : 71.00
Total Labour & Parts : 2,841.00

Repair days: 3

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**AIG THIRD PARTY EXPRESS SETTLEMENT
FOR ACCIDENTS ON OR AFTER 1ST JUNE 2008
(PAYMENT BREAKDOWN)**

Vehicle No:	SKP 2458K	Model:	BMW 316i/4
Date of Accident:	3.2.18		

Global Sum Settlement	: <input type="checkbox"/> Yes	<input type="checkbox"/> No	
Repair Estimate	: \$	5,897.41	
Final Repair Cost	: \$	3,039.87	
Loss of Use	: \$	150.00	3 days at \$50 per day
Rental (if any)	: \$	-	days
LTA / GIA Search Fee	: \$	2.00	
Others:	: \$	/	
	: \$	/	
Final Settlement Sum	: \$	3,191.87	

Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/No BOLA Scenario No: _____
BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks	

Payment Instruction: Payee's Breakdown		
1)	Performance Motors Ltd	: \$ 3,039.87
2)	Performance Motors Ltd	: \$ 2.00
3)	Chang Lai Heng	: \$ 150.00

Signed by appointed surveyor _____

Date _____

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act;
Survey Report; Medical Report/ Bill (if any))



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

13 FEBRUARY 2018

**MA CHUNG MENG
BLOCK 97 LORONG 3 TOA PAYOH
#07-58
SINGAPORE 310097**

BY POST & BY EMAIL

Dear Sir/Madam,

**OUR REF : CC3/AIG18002207/hb3
YOUR REF : SKX 7265A
ACCIDENT INVOLVING SKX 7265A AND SKP 2458K ALONG BISHAN MSCP ON
03.02.2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of SKP 2458K against your motor insurance policy.

Based on the accident report, accident scenario and all available evidence and information at hand, it was reported that your vehicle had collided to the stationary Third-Party vehicle SKP 2458K. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@ikkauto.com within 10 days from the date of this letter **if not provided at AIG's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Vic Alpeh
Case Handler
DID: 6841 2096
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

c.c. machungmeng@singnet.com.sg
(email)

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Tuesday, 13 February, 2018 5:04 PM
To: machungmeng@singnet.com.sg
Cc: Admin A; Vic (LKKAUTO)
Subject: YOUR REF: SKX 7265A_ACCIDENT INVOLVING SKX 7265A AND SKP 2458K ALONG BISHAN MSCP ON 03.02.2018



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

13 FEBRUARY 2018

MA CHUNG MENG
BLOCK 97 LORONG 3 TOA PAYOH
#07-58
SINGAPORE 310097

BY POST & BY EMAIL

Dear Sir/Madam,

OUR REF : CC3/AIG18002207/hb3
YOUR REF : SKX 7265A
ACCIDENT INVOLVING SKX 7265A AND SKP 2458K ALONG BISHAN MSCP ON 03.02.2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of SKP 2458K against your motor insurance policy.

Based on the accident report, accident scenario and all available evidence and information at hand, it was reported that your vehicle had collided to the stationary Third-Party vehicle SKP 2458K. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 10 days from the date of this letter **if not provided at AIG's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)

- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

AUTHORISATION TO ACT
(AIG Express Third Party Claim)


I, Chong Lai Heng (the third party claimant) of Blk 143 Loring 2
Tan Kah #11-184 S(310143) (address), owner of SKP2458 K (vehicle no.)
hereby authorize Performance Motors Ltd ("the workshop") to act for me
with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle
no. SKP2458 K that was damaged pursuant to the accident which occurred on 03.02.18 ✓
(date) along Bishan Munte Street Carpark (location) involving vehicle no/s
SKX 7265 A ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit
and the workshop is further authorized to receive payment further to settlement of my claim with
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 14 (day) of 03 (month) 2018 (year)

Chong Lai Heng
Signed by "the third party claimant"
(with chop if applicable)


Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG Express Third Party Claim)

"We/I, Performance Motors Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$3,031.87 (Repair Cost), S\$ 150.00 (Loss of ~~rental~~ use), S\$ 2.00 (Disbursement), for vehicle no. SKP 2458K, that was damaged pursuant to the accident which occurred on 3-2-18 (date) along Bishan Multi Storey Carpark (location) involving vehicle no/s SK*7265A. This is pursuant to the inspection conducted on 12-3-18 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Chuang Lai Heng ("the third party claimant") of vehicle no. SKP2458K make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SKP 2458K (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 07 (day) of 06 (month) 2018 (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770288, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)**SERVICE TAX INVOICE**

Repair Order No. : B1 1250216

Date IN : 12/03/2018

Cust. Svc. Advisor: Chua Kee Sin

Page No. : 1 of 2

Invoice Number : 1972423 / WSB

Invoice Date : 05/06/2018

Payment Terms : 30 Days From Invoice

Invoice By : Toh Jing Xuan

- CUSTOMER INFORMATION -Mdm Choong Lai Heng
Apt Blk 143 Lorong 2 Toa Payoh
#11-184

Singapore 310143

- INVOICE TO - 121AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKP2458K /	J722125	26/08/2014	316IA/4	22973

- - - - LABOUR 1 - - - -To make good the front bumper, front right fender including
replacement of damage parts and knock out dented area
caused by the accident.NETT

850.00

To respray front bumper and front right fender.

1,730.00

To check electrical wiring systems at the front section
for proper function including adjustments of headlights.

150.00

Sundries.

40.00

INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.

0.00

DATE OF ACCIDENT : 03.02.2018. 3RD PARTY CAR : SKX7265A.

YOUR REF NO : NIL.

VEHICLE WAS SURVEYED BY MR RASUL FROM LKK AUTO ON
12.03.2018 AT 12:15PM. AUTHORISED REPAIR BY MS VIC ALPEH
FROM LKK AUTO ON 13.02.2018 VIA EMAIL.PROPOSE LOSS OF USE = \$50x3. THE AMOUNT IS SUBJECTED
TO INSURANCE COMPANY CONFIRMATION.

0.00

GIA SEARCH FEE = \$2.00.

0.00

Total Labour 1: 2,770.00**- - - - PARTS - - - -**

PLAQUE 82MM

Qty	Retail Price
1	69.50

NETT

69.50

GROMMET

2 0.75

1.50

Total Parts : 71.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kemping Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64795601 (AfterSales)
64795624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1250216	Page No. : 2 of 2
Date IN : 12/03/2018	Invoice Number : 1972423 / WSB
Cust. Svc. Advisor: Chua Kee Sin	Invoice Date : 05/06/2018
	Payment Terms : 30 Days From Invoice
	Invoice By : Toh Jing Xuan

Labour Charges : 2,730.00	Total Labour & Parts Charges : S\$ 2,841.00
Parts Charges : 71.00	Less Insurance Excess : S\$ 0.00
Lubricant/Misc : 40.00	Invoice Total Amount Exclude GST : S\$ 2,841.00
	GST @ 7% : S\$ 198.87
	Invoice Total Amount Include GST : S\$ 3,039.87

Computer generated invoice. No signature is required.

Amount Payable Include GST : **S\$ 3,039.87**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-018995

Date of Request: 05/02/2018

Your Ref No: Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date 05/02/2018

Enquiry By Vivi

TP Vehicle No. SKX7265A

Accident Date 03/02/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKX7265A	AIG Asia Pacific Insurance Pte. Ltd.	28/12/2017-27/12/2018	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-018995
Date of Request: 05/02/2018

Your Ref No: Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date 05/02/2018
Enquiry By Vivi
TP Vehicle No. SKX7265A
Accident Date 03/02/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING






Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Feb 2018 Edit Reg		12 Mar 2018 00:00 Edit Adj Rpt	S\$2,841.00 Edit Estimates	S\$2,841.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Ma Chung Meng , ID: S1771034F								
Main Claimant:	CHOONG LAI HENG , ID: S7473910E								
Vehicle Reg. No.:	SKP2458K	Date of Loss:	03/02/2018 15:00 - :59 [41 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 4234198367SG	Policy/Cover Note No.:	2100444386 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKX7265A	Policy No. (Claimant):	B27766185SMP						
		Excess:							
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wul, Shawn-KJ] Shawnkaijie.Wul@aig.com								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 14/02/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (05/02/2018): No OI GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKP2458K (4234198367SG)
[SKX7265A]
TP
CHOONG LAI HENG
Feb 3 2018 3:30PM
[Ma Chung Meng]
Performance Motors Limited

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser		
Video														1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)											Thumbnail		Print		
1	13/02/18 16:42	Video - Accident											1	Load MP4			
Letters/Correspondences														1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail		Print		
1	(Draft)	Third Party Express Settlement – Payment Breakdown											1	Edit			
Assessment Reports														1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)											Thumbnail		Print		
1	13/02/18 16:39	Accident Statement From: SC - Reg. No: SKX7265A, Claimant: MA CHUNG MENG											1	Load HTM			
Photos/Images														3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail		Print		
1	24/05/18 14:44	Odometer Reading											1	Load JPG	<input checked="" type="checkbox"/>		
2	24/05/18 14:44	Chassis Number											1	Load JPG	<input checked="" type="checkbox"/>		
3	24/05/18 14:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
4	24/05/18 14:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
5	24/05/18 14:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
6	24/05/18 14:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
7	24/05/18 14:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
8	24/05/18 14:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
9	24/05/18 14:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
10	24/05/18 14:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
11	24/05/18 14:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
12	24/05/18 14:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
13	24/05/18 14:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
14	24/05/18 14:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
15	24/05/18 14:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
16	24/05/18 14:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
17	24/05/18 14:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
18	24/05/18 14:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
19	24/05/18 14:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
Documentation														1 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail		Print		
1	05/02/18 14:47	TP GIA REPORT											1	Load PDF			
2	05/02/18 14:47	TP ESTIMATE											1	Load TIF			
3	06/02/18 11:24	Non reporting letter											1	Load PDF			
4	13/02/18 16:50	EMAIL FROM AIG											1	Load PDF			
5	13/02/18 17:06	EMAIL TO OI											1	Load PDF			
6	13/02/18 17:06	LETTER TO OI											1	Load PDF			

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
7	13/03/18 18:54	TP ESTIMATE- MARKED	 Load PDF	
8	11/06/18 09:23	WORKSHOP INVOICE	 Load PDF	
9	11/06/18 09:23	AUTHORISATION TO ACT FORM	 Load PDF	
10	11/06/18 09:23	Release Voucher	 Load PDF	
11	11/06/18 09:23	GIA SEARCH	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKX7265A (Insd veh)	Model:	BMW 316i 1.6 (A)
	SKP2458K (TP veh)		
Date of Accident:	03/02/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	5,897.41
Final Repair Cost	:	\$	3,039.87
Loss of Use	:	\$	150.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	3,191.87

3.00 days at \$50.00 per day
days

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop**: Agreed Liability _____(%)

B) For **GIA Registered Workshop**: BOLA Applicable: ~~Yes~~/ No BOLA Scenario No: _____

NIL

BOLA Liability: _____100_____(%) Assessed Liability (*): _____(%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 3,041.87
2)	Choong Lai Heng	:	\$ 150.00
3)		:	\$

JOANNE LEE KHANG MIN

11 Jun
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18002207/R1HB3Q2

Date: 11/06/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 2100444386

Claimant Vehicle No: SKP2458K

Insured Vehicle No: SKX7265A

Date of Loss: 03/02/2018

Nature of Claim: TP

Claim No: 4234198367SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKP2458K

Make & Model: BMW 316I, 1.6 (A)

Reg. Date: 26/08/2014 (Man. Year: 2014)

Colour: Blue

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: A580J780N13B16A

Chassis No: WBA3A12060J722125

Odometer: 22973 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	330.60	111.00	219.60	66.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,181.00	2,730.00	2,451.00	47.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,511.60	2,841.00	2,670.60	48.45
+ GST 7.00/7.00% (S\$)	385.81	198.87	186.94	48.45
Nett Amount (S\$)	5,897.41	3,039.87	2,857.54	48.45
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,191.87		

INSPECTION

Date of Assignment: 12/03/2018

Date Inspected: 12/03/2018 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*40.00 FS
2	1		*FRT LH TOP SUPPORT SIDE PANEL	Not Necessary	18.00 FS	*- FS
3	1		*FRT RH TOP SUPPORT SIDE PANEL	Not Necessary	18.00 FS	*- FS
4	1		*RH SUPPORT FOGLAMP	Not Necessary	37.60 FS	*- FS
5	1		*FRT LH BOTTOM MOUNTING SIDE PANEL	Not Necessary	18.00 FS	*- FS
6	1		*FRT RH BOTTOM MOUNTING SIDE PANEL	Not Necessary	18.00 FS	*- FS
7	2		*GROMMET	Necessary	1.50 FS	*1.50 FS
8	1		*PLAQUE 82MM	Necessary	69.50 FS	*69.50 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	330.60	111.00
---------------------------	---------------	---------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE RIGHT FRONT SIDE FENDER FRONT BUMPER AND REMOVE ATTACHMENT ETC INCLUDE KNOCK ON ACCIDENT DENT	New	2,550.00	850.00
2	SPRAY PAINTING FRONT BUMPER AND FRONT RIGHT SIDE FENDER	New	1,923.00	1,730.00
3	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION	New	531.00	0.00
4	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS	New	177.00	150.00
Gross Labour Cost (\$\$)			5,181.00	2,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >