

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

05 FEB 2018

Estimate No.	: b1 45770	Page No. : 1 of 2
Date Estimated	: 05/02/2018	
Prepared By	: Chua Kee Sin	

- ESTIMATE REPAIR FOR - Choong Lai Heng Apt Blk 143 Lorong 2 Toa Payoh #11-184 Singapore 310143	- ACCOUNT - 40000 Cash Sales - Service Singapore
--	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKP2458K	J722125	26/08/2014	316iA/4	0

DESCRIPTION	VALUE
Remove right front side fender front bumper and remove attachment etc include knock on accident dent	850 2,550.00
Spray painting front bumper and front right side fender	1730 1,923.00
To check steering geometry and conduct wheel alignment according to BMW specification (1X)	X 531.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150? 177.00
Sundries.	? 150.00

Total Labour 1: 5,331.00

DESCRIPTION	QTY	PRIC	VALUE
FRT LH TOP SUPPORT SIDE PANEL	1	18.00	? 18.00
FRT RH TOP SUPPORT SIDE PANEL	1	18.00	? 18.00
RH SUPPORT FOGLAMP	1	37.60	? 37.60
FRT LH BOTTOM MOUNTING SIDE PANEL	1	18.00	? 18.00
FRT RH BOTTOM MOUNTING SIDE PANEL	1	18.00	? 18.00
GROMMET	2	0.75	W 1.50
PLAQUE 82MM	1	69.50	W 69.50

Total Parts : 180.60

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 45770
Date Estimated : 05/02/2018
Prepared By : Chua Kee Sin

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKP2458K	J722125	26/08/2014	316iA/4	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
Date & Time 12/03/18 @ 1215 Excess S\$ _____
Surveyor's Name Rafael Sign _____
Surveyor's Tel 90010568 Authorised Yes / No _____
Authorised Date _____ Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No
Surveyor's E-mail _____
No. of Working Days Recommend 3-4 days

Labour 1	:	5,331.00
Parts	:	180.60
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	385.81
Grand Total	:	<u>5,897.41</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **