



ESTIMATE BILL

DATE : 05-02-18

JHMR#684085204266

OUR REF NO : SJG 4709H
MODEL : HONDA STRAM

NAME : JY ELETRICAL PTE LTD
ADDRESS : 7, YISHUN, INDUSTRIAL ST 1,
#05-46, NORTH SPRINT BIZHUB
SINGAPORE 768162

ESTIMATE ITEM

1) REAR WINDSCREEN MOULDING <i>Nec</i>	2 PCS @ \$ 84.10	168.20 ✓
2) BOOT LID <i>Dented</i>		1520.00 903
3) BOOT LID WEATHERSTRIPE <i>Cut</i>		238.00 122.10
4) BOOT LID STOPPER <i>Nec Nec</i>	2 PCS @ \$ 10.20	20.40 X.
5) TAIL LAMP (RH) <i>Cracked</i>		427.00 338.80
6) REAR BUMPER <i>Delam</i>		1431.10 684
7) REAR BUMPER CLIP <i>Nec</i>	6 PCS @ \$ 4.00	24.00 ✓
8) REAR BUMPER SIDE ATTACHMENT <i>Nec</i>	2 PCS @ \$ 49.00	98.00 48
9) REAR BUMPER TOW COVER <i>Delam</i>		74.00 36.
10) REAR EXHAUST SILENCER <i>2 Nec</i>		567.00 X
11) REAR EXHAUST MOUNTING <i>2 Nec</i>	2 PCS @ \$ 26.00	52.00 X
12) REAR END PANEL <i>Dented</i>		480.80 ✓
13) REAR PANEL INNER GARNISH <i>Nec</i>		185.10 X.
14) SPARE TYRE BRACKET <i>2 Nec</i>		340.00 X
15) SPARE TYRE ADJUSTING HOOK AND NUT <i>2 Nec</i>		45.00 X
		5662.60
	LESS DISCOUNT - 20%	1132.52
		4530.08

SPECIAL NETT ITEM

1) REAR WINDSCREEN INNERSEAL <i>2 Nec</i>		60.00 40
2) REAR WINDSCREEN GUM <i>2 Nec</i>		60.00 40
3) REVERSE SNSOR WITH CONTROL UNIT <i>Damaged</i>		380.00 200
4) REAR EXHAUST CHROME <i>Nec Nec</i>		120.00 X.
		620.00

LABOUR CHARGE

1) TO CHECK WIRING SYSTEM		50.00 30
2) TO APPLY UNDER SEALING ON AFFECTED AREAS		120.00 50
3) TO REMOVE AND REFIX BOOT LID FIXING AND REALIGNMENT		240.00 80
4) TO REMOVE AND REFIX SPARE TYRE BRACKET		120.00 X
5) TO REMOVE AND REFIX REAR EXHAUST SILENCER		150.00 X.

- 6) TO REMOVE AND REFIX REVERSE SENSOR WITH CONTROL UNIT
- 7) TO REMOVE AND REFIX TRIM, GARNISH, UPHOLSTERY AND ETC
- 8) TO REPLACE NEW PARTS, CUT, WELD, KNOCK ETC
- 9) TO RESPRAY ON THE AFFECTED AREAS

1770

120.00	50
150.00	60
1000.00	800
880.00	700
	2830.00
	<u>7980.08</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

H/s Admining
05/02/18.
06 Days.

total: 425712
L/s 3 HK ✓