

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/GAI18002246/R1d3e2 GREAT AMERICAN INSURANCE COMPANY Ref: 3 TEMASEK AVENUE #16-01 CENTENNIAL Date: 17-05-2018 **TOWER SINGAPORE 039190** Code: GAI 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SKU 3471M Veh. Inspected SFR 3390M Policy No. Coverage (\$) 0.00 SKU3471M 0.00 Claim No. Excess (\$) **RACHEL TAN** 05/02/2018 **Assign From Assign Date** 2. **Vehicle Particulars & Condition** MITSUBISHI LANCER Make & Model 1499 c.c **Engine No. HIDDEN** Year of Reg. 2009 JMYSRCY2AAU000425 Chassis No. Colour RED 129467 KM Odometer **IN ORDER** Steering **IN ORDER** Brakes Modification SPORTS RIM FAIR General **Conditions of Tyres** 3. Size Make **Balance** 5 mm 205/60 R16 **PIRELLI** R/H Front Tyre **PIRELLI** 5 mm L/H Front Tyre 205/60 R16 R/H Rear Tyre 205/60 R16 **PIRELLI** 5 mm 205/60 R16 **PIRELLI** 5 mm L/H Rear Tyre 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. **General Information** 5. 01/02/2018 Inspect Date / Time 06/02/2018 (05:28 PM) **Accident Date** HOE MENG SPRAY PAINTING SERVICE PTE LTD Survey held at BLK 3023A #01-55 UBI RD 1 SINGAPORE 408717 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000-\$8,000

Report Ref No. CS3/GAI18002246/R1d3e2

Estimate Days of Repair

Inspected By

5b.

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

ESTIMATED NORMAL PERIOD FOR REPAIR:

REGD Auto Consultant-SAE, Licensed Appraiser

4 Working Days

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.