# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. From: LKK Auto Consultants Pte Ltd

AIG Building 51 Ubi Ave 1 #01-25 78 Shenton Way #07-16 Paya Ubi Industrial Park Singapore 079120 Singapore 408933

Dally Amri, Mimi Zarina Date: 06 Feb 2018 Attn:

## **Preliminary Advice**

Vehicle No : SJW2218L Accident Date : 31/01/2018 Make : AUDI A3 Policy No. : 1800003093 : 05/02/2018 Excess Assignment Date : S\$0.00 Est. Duration of Repair Date of Inspection : 05/02/2018 : 4.00

Inspection At : PREMIUM AUTOMOBILES PTE LTD (UBI)

> 55 UBI ROAD 1 SINGAPORE 408699

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,478.00
Revised Amount	:S\$	8,903.00
Check Items (Estimated)	:S\$	433.00
Total	:S\$	9,336.00

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value :S\$

Pre-Accident Value :S\$ 120,000.00 COE / PARF Rebate :S\$ 60.511.00

Salvage Value :S\$

Margin for Repair :S\$ 59,489.00

#### Remarks

(	Х	)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
(		)	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
(		)	Other comments :