

SMRT Accident Vehicle Repair Estimates

A x 9

(717)

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5717C
 Ref. No : TAX/02/18/2024
 Reg. Date : 12/10/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : LEOW LOONG CHONG (LIAO LONGZHANG)
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 03/02/2018 02:30:00 PM
 Accident Reported Date / Time : 05/02/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 03/02/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094476
 Special Instruction to ARC, if any :
 TOWED \$40 / SLU3433L
 Prepared Date : 05/02/2018 12:11:18 PM



Sebastian.
 6/2/18.
 - Part by part repair.
 - Question mark Item
 Photo
 - Photo before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU303572967

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	338.00	0.00
Total Spray Painting Charges :	558.00	0.00
Total Material Charges :	1,303.04	1,303.04
Other Charges :	340.00	0.00
TOTAL :	2,539.04	0.00
Lum Sum Total :	0.00	0.00
No. of Repair Days :	3.00	0.00
Prepared / Adjusted By :		2 days
Arc / Surveyor Sing Off Date :	05/02/2018 04:56:06 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 05/02/2018 04:53:28 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount : 0.00	Prepared Date : 2/5/2018 4:57:19 PM

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope		Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION		338.00	0.00 200
Total Labour		338.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope		Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER		378.00	0.00 200
TO RESPRAY BUMPER BEAM		180.00	0.00 ?
Total Spray Painting & Panel Beating		558.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope		Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE		80.00	0.00 ✓
TO CHECK WIRING AND SYSTEM FUNCTION		80.00	0.00 ✗
TO TEST AND REFIX REVERSE SENSOR SYSTEM		120.00	0.00 30
TO WASH AND VACUUM		60.00	0.00 ✗
Total Other Costs		340.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159479 13			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace <i>R</i>	No
52161160 10			CLIPS PIECE, FRT & RR BUMPER	10	1.50	25.00	11.25	Replace	Replace <i>✓ N/C</i>	No
52453470 10			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.72	Replace	Replace <i>✓ CRK</i>	No
52169470 20			COVER, GUARD RR BUMPER LOWER	1	14.80	25.00	11.10	Replace	Replace <i>✓ MS</i>	No
52461470 10			PAD, RR BUMPER, CTR	3	2.20	25.00	4.95	Replace	Replace <i>?</i>	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace <i>?</i>	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace <i>✓ N/C</i>	No
52023470 30			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Replace <i>?</i>	No
TOTAL MATERIALS								1,303.05	1,303.04	
TOTAL MATERIALS(Discounted)							1,303.04	1,303.04		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									