

Supplementary or Omitted List



VEHICLE NUMBER: SLS2227H

MODEL JETTA TSI (DSG) TRENDLINE

CLAIMS DETAILS

	LABOUR DESCRIPTION	AMOUNT		
		Qty	Unit	Amount
	LABOUR TO REPAIR END PANEL	1	\$ 840.00	\$ 840.00 ✓
	SPRAY PAINTING END PANEL & LHS RR FENDER	2	\$ 800.00	\$ 1,600.00 ✓
Total				\$2,440.00

No.	Item No.	Description	Qty	Unit Pricing	Discount	Amount
1	5C6807863B	BUMPER CENTRE BRACKET	1	\$96.99		\$96.99 ✓
2	WHT007341	NUT	2	\$2.18		\$4.36 ✓
3	8D0853419D	RR NUMBER PLATE PACKING	1	\$12.66		\$12.66 ✓
	5C6919491E	SENSOR BRACKET	2	\$23.79	(A)	\$47.58 ✓
	5C6919492D	SENSOR BRACKET	1	\$23.79		\$23.79 ✓
	5C6919491D	SENSOR BRACKET	1	\$23.79		\$23.79 ✓
	D 180KU2A1	2KADHESIVE	1	\$89.84		\$89.84 ✓
	D 822150A1	BONDAGENT	1	\$64.27		\$64.27 ✓
	5CU971104	SENSOR WIRE HARNESS	1	\$161.14		\$161.14 ✓
TOTAL:						\$524.42

Total Labour & Parts

\$2,964.42

Survey By