



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

General Details

Involving	TPVD TOYOTA ESTIMA AERAS 2.4 A (SDT8998R)
Date of Loss	1 February 2018
Time of Loss	23.05
Loss Description	SJV8440B (INSD) C/W SDT8998R (TP) - VF IN MERIMEN
Comment	

Workshop Details

Total Rebate Amount	13847
Nett Loss Amount	\$3,153.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)
Days of work completion *	251



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#	SDT8998R	Purchase Date	dd/mm/yyyy
Registration State	SINGAPORE	Registration Date *	04/04/2008
Mileage	234318	Age of Vehicle	9

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year		2007
Make	TPVD TOYOTA	TOYOTA
Model	ESTIMA AERAS 2.4 A	ESTIMA AERAS 2.4 A

Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	CHEE AIK THUAN	
Date of Birth	3 May 1958	dd/mm/
Age	60	

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		
Type of Paint		
Chassis No		ACR500059845
Engine No		2AZF116503
Engine Capacity		2362
Sum Insured		0
Market Value		17000

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	
Education Qualification	Other	
Driving Experience	41	
Driver License #		
License Type		
License Issue Date	3 May 1977	dd/mm/
License Expiration Date		dd/mm/
Address	BLK 601 CHOA CHU KANG, ST. 62 #04-07, 680601, Singapore	
Address type	Personal Correspondence	

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Male	
Marital status	Unknown	
Identification #	S1322334C	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

06/02/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Fair ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

215/55R17

Rear Tyre Size

215/55R17

Front left side

BRIDGESTONE6mm

Rear left side

BRIDGESTONE6mm

Front right side

BRIDGESTONE6mm

Rear right side

BRIDGESTONE6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary
- Parts

Add

Approve

Deny

Submit All

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		1	1		REAR LH TAILLAMP			Damaged	706.68		25		530.01	Reviewing	

Labour

Add

Approve

Deny

Submit All

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1	TO REMOVE DAMAGED PARTS AND ATTACHMENTS, TO REPAIR REAR LH FENDER }	800	0	0	Reviewing		
		2	TO RESPRAY PAINT ON REAR LH FENDER, FENDER PROTECTOR, LH SLIDING DOOR PROTECTOR AND REAR BUMPER }	0	0	0	Reviewing		

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	DAYS OF REPAIR : 2 DAYS	Reviewing			

Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
----------------------------	--------------------------	-------------------	---------------	----------------	---------------	---------

Claim Amount

\$1,330.01

Claim Amount

\$1,330.01

CATEGORY	ESTIMATE	REVISED AMOUNT
Spare Parts	\$530.01	\$530.01
Labour	\$800.00	\$800.00

Submit for Review

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR
NO

NAME

ACTION

AMOUNT

COMMENT

REMOVE



1

FINAL
LUMP
SUM

Reviewing

1050



Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
----------------------------	--------------------------	-------------------	---------------	----------------	---------------	---------

Claim Amount

\$1,050.00

Claim Amount

\$1,050.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Miscellaneous	\$1,050.00	\$1,050.00

Submit for Review