



# NGEE SENG AUTO WORKS 誼盛摩哆

REGISTRATION NO: 52791500M

Bik. 3022A, Ubi Road 1, #01-50, Singapore 408716. Tel: 6841 2276 Fax: 6743 9006

ALL TYPES OF MOTOR REPAIRS SERVICES, SPRAY PAINTING & INSURANCE CLAIMS.

**AIG ASIA PANCIFIC INSURANCE PTE LTD**  
 78, Shenton Way #07-16  
 Chartis Building  
 Singapore 079120

*Not about  
 note  
 01/2/18  
 to the shop  
 4 day.*

**ESTIMATE : TP18002**  
 Date : :05/02/2018  
 Ref No : :SLL3236L  
 Policy No.: :  
 Page : :01

**RE : VEHICLE NO. SLL3236L MINI COOPERS**

Qty	Description	Unit Price	Amount	
1	REAR BOOTLID RH <i>n</i>		\$1,740.00	X
1	BOOTLID COOPERS EMBLEM <i>nee</i>		\$146.00	✓
1	BOOTLID MINI EMBLEM <i>nee</i>		\$135.00	✓
1	BOOTLID CLUBMAN EMBLEM <i>nee</i>		\$125.00	✓
1	BOOTLID CHROME MOULDING <i>17</i>		\$273.00	X
1	BOOTLID RUBBER		\$326.00	?
1	REAR BUMPER <i>DO/A</i>		\$945.00	✓
1	REAR BUMPER REINFORCEMENT		\$680.00	?
2	REAR BUMPER NUMBER PLATE LAMP	\$165.00	\$330.00	?
2	REAR BUMPER REVERSE SENSOR <i>check</i>	\$295.00	\$590.00	✓
1	REAR BUMPER LOWER BRACKET		\$242.00	?
1	REAR BUMPER SPOILER <i>ground</i>		\$474.00	✓
2	REAR BUMPER LAMP	\$347.00	\$694.00	?
1	REAR BUMPER CLIPS (SET) <i>nee</i>		\$75.00	✓
1	EXHAUST HEAT SHIELD <i>n</i>		\$198.00	✓
1	REAR NUMBER PLATE <i>nee</i>		\$100.00	✓
<b>TOTAL (1)</b>			<b>\$7,073.00</b>	

**LABOUR**

TO CHECKS WIRING ,CAMERA & REVERSE SENSOR	\$200.00	50
TO REMOVE & REFIX BOOTLID COMPONENT	17	\$200.00 X
TO REMOVE & REFIX WINDSCREEN	17	\$250.00 X
TO REMOVE & REFIX EXHAUST		\$150.00 60
TO PANEL BEATING		\$1,250.00 ?
TO SPRAY PAINTING		\$1,600.00 ?
		<b>\$3,650.00</b>

**TOTAL SPARE PARTS & LABOUR CHARGES**

**\$10,723.00**

**LABOUR CHARGES**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: