

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

Date : 9/2/2018

M/S AIG

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR SLJ605K

LIST PRICE

List Items

1 1 PC FRONT BUMPER

2 1 PC FRONT CORNER RH SIDE

3 1 PC FRONT CORNER LH SIDE

4 1 PC FRONT GRILLE

LESE 20%

5

6 LABOUR CHARGE (FRONT)

7 SPRAY PAINTING (FRONT)

8 WIRING

\$	833.00	✓
\$	343.00	x
\$	142.00	✓
\$	142.00	x
\$	1,460.00	975
\$	(292.00)	
\$	1,168.00	
\$	600.00	250
\$	400.00	280
\$	30.00	20
\$	2,198.00	

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: