

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 8527D

MAKE :

MODEL : HYUNDAI i40

AIG

DATE 6/2/2018 10:12

DOA: 05.02.18

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover		R X	\$ 1,052.20
	Front Bumper Bracket (LH)		LH X	\$ 24.60
	Front Door Mirror (LH)		R X	\$ 980.50
	Front Pillar Upper Cover, LH		R X	\$ 190.00
	SUB TOTAL			\$ 2,247.30
	LESS 20%			\$ 449.46
	DISCOUNTED TOTAL			\$ 1,797.84
	Labour Charge			400
	Panel Beating			\$ 600.00
	Spray Painting Charge		SCU	\$ 700.00
	Wiring Charge			\$ 50.00 X
	TOTAL LABOUR			\$ 1,350.00
	ESTIMATE TOTAL			\$ 3,147.84
<div style="border: 1px solid black; padding: 5px;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div> <div style="margin-top: 10px;"> <p>LABOUR ONLY</p> <p>2w/7days</p> <p>6/2/2018 @ 14.20</p> <p>LKK Auto with</p> <p>After paint photo</p> </div>				
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				

Larry Ng