



09/11  
Survivor

REF:

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SKC54017 Yr Regn: 2011 / Sept

Type: M.Co / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Camry. CC 2362

Colour: Silver. A/C: Insured / Std / NI / NA

Sp. Reading: 161085 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MRO53BK4007046832

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: 215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 06 mm R/Bal: 06 mm

L/Bal: 06 mm L/Bal: 06 mm

D.O.A. \_\_\_\_\_ D.O.I. 06/02/18

Survey held at: Success United

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Rtg.

LIS - \$ 37001 - CRed: \$ 3819.68 / 49%.

Date/Time. File Pass to?

☐ : Prel. Report

1) \_\_\_\_\_

☐ : Final Report

Date/Time. File Return to?

2) \_\_\_\_\_

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS \$

Photos

Other

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18002445/Aua3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 07-02-2018		
		Code : AIG		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SKK 4389P	Veh. Inspected	SKC 5401Y	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	07/02/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	02/02/2018	Inspection Date	06/02/2018	
Survey held at	SUCCESS UNITED PTE LTD 2 KAKI BUKIT AVE 2 #01-33 KAKI BUKIT AUTOHUB SINGAPORE 417921			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Estimate : TP/18-021

M/s AIG Asia Pacific Insurance Pte Ltd

Date : 6th February 2018

AIG Building

78 Shenton Way, #07-16

Singapore 079120

Vehicle No : SKC 5401Y

Make/ Model : Toyota Camry

Chassis No : MR053BK4007046832

Acc. Date : 02.02.18

Policy No :

Attn : Motor Claims

Tel: 64191053

Your Ref : SKK 4389P

Fax: 68357416

S/n.	Qty	Particulars	Unit Price	Amount
<u>Materials</u>				
1	1	Rear Boot Lid Buckled.		\$ 984.70 ✓
2	1	Rear Boot Weatherstrip Cut		\$ 273.10 ✓
3	1	Rear Boot Mechanism Lock Damaged		\$ 382.20 ✓
4	1	Rear Boot Lid Camry Emblem		\$ 65.80 ✓
5	1	Rear Boot Lid 2.4 Emblem		\$ 65.80 ✓
6	1	Rear Boot Lid Toyota Logo		\$ 59.90 ✓
7	2	Rear Boot Lid Hinge L/R not new	\$ 139.90	\$ 279.80 X
8	1	Rear End Panel Dented.		\$ 768.30 ✓
9	1	Rear End Panel Inner Top Garnish Deformed		\$ 368.90 ✓
10	2	Rear Lamp Panel L/R	\$ 400.80	\$ 801.60 X
11	1	Rear Lamp Lower Bracket LH		\$ 98.90 X
12	1	Rear Bumper Deformed		\$ 654.70 ✓
13	1	Rear Bumper Bracket LH not new		\$ 89.90 X
14	1	Rear Bumper Side Holder LH new		\$ 79.90 ✓
15	1	Rear Bumper Reflector Lamp LH cracked		\$ 93.80 ✓
16	1	Rear Bumper Screw Cover LH not new		\$ 79.90 ✓
17	1	Rear Bumper Reinforcement Bent		\$ 483.10 ✓
18	1	Rear Fender Inner Upholstry Trim LH not new		\$ 382.60 X
				\$ 6,012.90
				Less 25%
				\$ 1,503.23
				\$ 4,509.68
19	1 set	Reverse Sensor Damaged 200	S/Nett	\$ 380.00 - 200
				Parts Total : \$ 4,889.68

Labour

- To remove, rearrange electrical wirings, check lightings
- To remove, instal upholstery, inner trim garnishes.
- To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident.
- To putty and respray painting on rear boot lid, rear bumper, end panel, rear fender LH.

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Success United Pte Ltd

1510 \$ 80.00 30  
\$ 350.00 20  
\$ 1,200.00 80  
\$ 1,200.00 600  
Labour Total : \$ 2,830.00

Total Parts & Labour : \$ 7,719.68

Adrian Ling total 4820.15  
H/S 06/02/18 r/s 3.9K.



聯成汽車維修

**SUCCESS UNITED PTE LTD**

2 Kaki Bukit Ave 2, #01-33 / #02-29 Kaki Bukit AutoHub Singapore 417921

Tel: 6746 1515 / 6747 1787 Fax: 6748 5015

www.successunited.com.sg Co. / GST Reg: 200402570G

Your Ref: SKK 4389P

23/4/2018

M/s. AIG Asia Pacific Insurance Pte Ltd  
AIG Building  
78 Shenton Way, #07-16  
Singapore 079120

Attn: Motor Claims

Dear Sir

**Re: Acc Invg SKC 5401Y & SKK 4389P On 02.02.18**

We refer to the above accident which was caused due to the negligence of your insured driver of Veh No. SKK 4389P

We are claiming for the following costs and losses incurred:

1)	Cost of Repairs (Inc. 7% GST)	\$ 4,173.00
2)	Car Rental	\$ 770.40
3)	Search Fees	\$ 2.00
<b>Total:</b>		<b>\$ 4,945.40</b>

Enclosed herein the following documents for your perusal.

- 1) Tax Invoice No. SU18-0111
- 2) Car Rental Invoice/Agreement
- 3) GIA Search Fee
- 4) Letter of Authorisation

We appreciate your prompt attention and response.

Yours faithfully



## Thin Thin (LKKAuto)

---

**From:** Thin Thin (LKKAuto)  
**Sent:** Wednesday, 14 March 2018 4:19 PM  
**To:** 'chintamwan@gmail.com'  
**Subject:** ACCIDENT INVOLVING SKK 4389P & SKC 5401Y ON 02/02/2018



Auto  
Consultants  
Pte Ltd

---

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG18002445/Aua3

14 MARCH 2018

**CHIN TAM WAN @ CHEN THAM VOON**

Dear Sir/Madam,

**ACCIDENT INVOLVING SKK 4389P & SKC 5401Y ON 02/02/2018**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

THIN THIN HLAING

Case Handler

DID: 6841 2360

FAX: 6741 4108

Email: [thinthin@lkkauto.com](mailto:thinthin@lkkauto.com)

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)

## LETTER OF AUTHORISATION

To: **Success United Pte Ltd**  
**Singapore**

RE: ACCIDENT INVOLVING VEHICLE NOS: **SKC 5401Y & SKK 4389P**  
ALONG **PIE slip rd to Jalan Eunus** ON **02.02.18**

I/We, **Sanz Pte Ltd** Co's Rgn/NRIC No. **199901602C**  
of **Blk 20 Woodlands Link, #07-30, Woodland East Ind Est. Singapore 738733**  
the owner of vehicle no. **SKC 5401Y** hereby authorise you to commence repair to the said  
vehicle forthwith. In consideration of you repairing my/our vehicle at my/our request:

- a) I/We hereby irrevocably authorise you to demand claim settle receive whatever amount settled/payable by the insurance and/or third party or to commence legal proceeding, if necessary, in my name, for the costs of repair and loss of use, etc and to you appointing any Solicitor to act for me in respect of the accident claim and all and any amount claimed, received and/or settled shall belong absolutely to you. I/We agree to assign the whole proceeds of my/our third party claim to you and my/our Solicitors (to be appointed by you on my/our behalf) shall accept this as my/our irrevocable authorisation to pay the amount compensated direct to you after deduction of their costs on a Solicitor & Client basis. I/We undertake to co-operate fully with you and my/our Solicitors to see the claim to a successful conclusion.
- b) If the third party claim is unsuccessful or in your discretion inappropriate for any reason, I/we hereby instruct and authorise you to claim direct from my/our insurance company on my/our behalf for all monies due to you. I undertake to pay you for the Excess applicable under my policy and to reimburse you all costs, fees and expenses incurred by you in pursuing the claim on my behalf.
- c) If the own insurers' claim is not applicable and/or the third party claim fails and/or either of the aforesaid is inadequate, I/we undertake to pay you for your expenses, costs and fees immediately.

I/We also irrevocably authorise you to sign all discharge vouchers/indemnity forms and all necessary papers in connection with the above claim in my/our absence. I/We irrevocably authorise you to appoint such a firm of Solicitors on my/our behalf as you shall deem fit for the purpose of the third party/own insurer's claim.

I/We undertake to inform you and/or the Solicitors appointed by you on my behalf in the event the third party's insurance company communicate with me/us directly, orally or in writing and I/we further undertake not to accept any monies or offer of settlement from the third party's insurers without first communicating with you and obtaining your consent.

Upon settlement of the third party claim and in case the settlement monies was sent to me/us by the third party's insurers, I/we undertake to pay you and my/our solicitor the cost of repairs settled and related expenses and disbursement incurred.

My/Our Insurer is/are **AXA Insurance Pte Ltd**  
Policy No. **GA05983/1**

Expiry Date: **06.09.18**

Date: **05.02.18**

Excess: **0**

**SANZ PTE LTD**  
**Blk 20, Woodlands Link #07-30**  
**Woodlands East Industrial Estate Singapore 738733**  
Tel: (65) 6269 8602 / 6269 1687 Fax: (65) 6269 5634  
Co. Reg. No. **199901602C** GST Reg. No.: **199901602C**  
Sanz Pte Ltd  
NRIC No: **199901602C**

Witness Signature/Name



**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, SUCCESS UNITED PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$ 4,173.00 (Repair Cost), S\$ 770.40 (Loss of Rental/Use), S\$ 2.00 (Disbursement) for vehicle no. SKC 5401Y that was damaged pursuant to the accident which occurred on 02/02/2018 (date) along PIE SLIP ROAD TO JALAN EUNOS (location) involving vehicle no/s SKK 4389P. This is pursuant to the inspection conducted on 06/02/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner SANZ PTE LTD ("the third party claimant") of vehicle no. SKC 5401Y make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SKC 5401Y (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 27th (day) of APRIL (month) 2018 (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)





聯成汽車維修

**SUCCESS UNITED PTE LTD**

2 Kaki Bukit Ave 2, #01-33 / #02-29 Kaki Bukit AutoHub Singapore 417921

Tel: 6746 1515 / 6747 1787 Fax: 6748 5015

www.successunited.com.sg Co. / GST Reg: 200402570G

**Tax Invoice : SU18-0111**

M/s. **AIG Asia Pacific Insurance Pte Ltd**

AIG Building

78 Shenton Way, #07-16

Singapore 079120

Date : 23rd April 2018

Vehicle No : **SKC 5401Y**

Make/ Model : **Toyota Camry**

Chassis No : **MR053BK4007046832**

Date of Acc. : 02.02.18

Tel : 64191053

Fax : 68357416

Your Ref : SKK 4389P

S/n.	Qty	Particulars	Unit Price	Amount
------	-----	-------------	------------	--------

To provide material, labour and  
respray painting.

LUMP SUM REPAIRS \$ 3,900.00



for Success United Pte Ltd

Sub Total : \$ 3,900.00  
Add GST 7% : \$ 273.00  
**TOTAL DUE : \$ 4,173.00**



**GOLDBELL**  
CAR RENTAL

10,000 Leasing Clients Served.  
And Counting.

**GOLDBELL CAR RENTAL PTE LTD**

Main Office: 10 Raeburn Park #02-01 Singapore 088702 Tel: 6828 6300 Fax: 6225 1029  
Finance: 18 Tjua Avenue 10 Singapore 639142 Tel: 6216 3000 Fax: 6862 3500  
Website: www.gbr.com.sg  
Co Reg No: 2007106510

Sales Order No :

Date :

05 Feb 2018

### Passenger Vehicle

AN AGREEMENT made on **05-Feb-2018** Between **GOLDBELL CAR RENTAL PTE LTD** ("the Owner") a company incorporated in Singapore and having its registered office at **10 RAEBURN PARK #02-01 BLK B SINGAPORE 088702** of the one part and **SUCCESS UNITED PTE LTD** ("the Hirer") carrying business at **2 KAKI BUKIT AVENUE 2 #01-33 SINGAPORE 417921** of the other part.

No.	Description	Transaction
1	<b>Description of Vehicle(s) / Equipment(s)</b> Description: TOYOTA CAMRY (A) 2.5 L Model: CAMRY (A) 2.5 L Services: Accessories: Value Add:  Vehicle Register No.: SKK9443H Engine No.: 2ARU064728 Chassis No.: MR053AK5004006162  <b>Remarks:</b> Excess in Singapore: \$2,000 No Travelling to Malaysia	<b>Agreement No</b> Agreement No.: CPVS1802038  <b>Contract Period</b> Lease Period: 3 Days Start Date: 05-Feb-2018 End Date: 08-Feb-2018  <b>Payment</b> Daily Rental: \$180.00  <b>Insurance</b> Third Party Property Damage (Limited To): \$500,000.00

### Interest On Overdue Payments

Interest on Overdue Payments: 1.5% Per Month

All payments are subjected to 7% GST (Excludes Deposit)

### Remarks:

EXTENDED TILL 09/02/2018.

This Lease Agreement is agreed by the following signatories. Unless expressly agreed in writing, all terms and conditions shall be as stipulated in the Standard Terms and Conditions (**TLC1406001**) to our Agreement dated **05-Feb-2018**

## SCHEDULE



**GOLDBELL**  
CAR RENTAL

10,000 Leasing Clients Served.  
And Counting.

**SIGNED for and on behalf of the  
Owner by**

Name: **WONG HIN CHOE**  
Designation: **ASST. GENERAL MANAGER**  
NRIC No: **S1700067E**

In the presence of:-  
Witness: **MARCUS NG SONG YU**  
NRIC No: **S9217380A**



**GOLDBELL CAR RENTAL PTE LTD**

Main Office: 10 Raffles Park #02-01 Singapore 088702 Tel: 6838 6300 Fax: 6225 1029  
Finance: 12 Tuas Avenue 10 Singapore 639142 Tel: 6316 3000 Fax: 6662 3500  
Website: [www.gbr.com.sg](http://www.gbr.com.sg)  
Co Reg No: 2007106510

**SIGNED for and on behalf of the  
Hirer by**

Name:  
Designation:  
NRIC No:

In the presence of:-  
Witness:  
NRIC No:

**SCHEDULE**



# GOLDBELL CAR RENTAL

10,000 Leasing Clients Served.  
And Counting.

## GOLDBELL CAR RENTAL PTE LTD

Main Office: 10 Raffles Park #02-01 Singapore 088702 Tel: 6828 8300 Fax: 6225 1023  
Finance: 18 Tines Avenue 10 Singapore 639142 Tel: 6316 3000 Fax: 6862 3900  
Website: [www.gbr.com.sg](http://www.gbr.com.sg)  
Co Reg No: 2507106810

Page 1 / 1

SUCCESS UNITED PTE LTD  
2 KAKI BUKIT AVENUE 2  
#01-33, KAKI BUKIT AUTOHUB  
SINGAPORE 417921  
SIRINA SOON

### TAX INVOICE

GST Reg No. : M9-0002514-E  
Invoice No. : CXI00029363  
Invoice Date. : 12-02-2018  
Account No. : C00005533  
Our Ref. : CPVS1802038  
Your Ref. :  
Credit Term. : CASH  
Salesman. : MARCUSNGSY

PARTICULARS		AMOUNT SGD
Asset Description	: TOYOTA CAMRY (A) 2.5 L	
Reg No/ID No	: SKK9443H	
Chassis No	: MR053AK5004006162	
Engine No	: 2ARU064728	
Agreement No	: CPVS1802038	
Contract Period	: 05-02-2018 To 09-02-2018	
Type Of Lease	: Short Term	
BEING RENTAL CHARGES FOR THE ABOVE		720.00
GST @7.00% for \$ 720.00		50.40
E.& O.E		
TOTAL		\$ 770.40

Please make all cheques payable to GOLDBELL CAR RENTAL PTE LTD

When making payment, please quote our invoice numbers.

No receipts will be issued for Cheque Payments.

This is a computer generated document. No signature is required.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**Third Party Insurer Enquiry**

Our Ref No: GR-18-018950

Date of Request: 05/02/2018

Your Ref No: Online Purchase

Success United Pte Ltd  
2 Kaki Bukit Ave 2 #01-33  
Kaki Bukit AutoHub  
Singapore 417921

Dear Sir/Madam,

Enquiry Date 05/02/2018

Enquiry By Sirina Soon

TP Vehicle No. SKK4389P

Accident Date 02/02/2018

**Enquiry Result**

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKK4389P	AIG Asia Pacific Insurance Pte. Ltd.	17/07/2017-16/07/2018	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-18-018950

Date of Request: 05/02/2018

Your Ref No: Online Purchase

Success United Pte Ltd  
2 Kaki Bukit Ave 2 #01-33  
Kaki Bukit AutoHub  
Singapore 417921

Dear Sir/Madam,

Enquiry Date 05/02/2018

Enquiry By Sirina Soon

TP Vehicle No. SKK4389P

Accident Date 02/02/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

---

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Feb 2018 <a href="#">Edit Reg</a>		06 Feb 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>\$53,900.00</b> <a href="#">Edit Estimates</a>	<b>\$53,900.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>































Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>Chin Tam Wan @ Chen Tham Voon</b> , ID: S2551810A								
Main Claimant:	<b>SANZ PTE LTD</b> , Co. Reg. No.: 199901602C								
Vehicle Reg. No.:	<b>SKC5401Y</b>	Date of Loss:	02/02/2018 19:00 - :59 [76 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 4398018718SG</b>	Policy/Cover Note No.:	2100346316 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SKK4389P</b>	Policy No. (Claimant):	GA059830/1						
		Excess:							
Repairer:	<b>Success United Pte Ltd (HQ)</b> 2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub, 417921 Kaki Bukit - Tel: 6746 1515								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>MdNoor, Norsiah</b> ] <a href="mailto:Norsiah.MdNoor@aig.com">Norsiah.MdNoor@aig.com</a>								
Claimant's Insurer:	<b>AXA Insurance Pte Ltd (HQ)</b> - Tel: 6338 7288								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ADRIAN LING</b> ] ... <b>[Final Rpt due 19/02/2018]</b>								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*SKC5401Y (4398018718SG)**  
**[SKK4389P]**  
**TP**  
**SANZ PTE LTD**  
**Feb 2 2018 7:00PM**  
**[Chin Tam Wan @ Chen Tham Voon]**  
**Success United Pte Ltd**

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	(Draft)	Third Party Express Settlement – Payment Breakdown														Edit				
Assessment Reports															1 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)													Thumbnail		Print			
1	08/02/18 14:42	Accident Statement From: SC - Reg. No: SKK4389P, Claimant: CHEN TAM WAN @ CHEN THAM VOON														Load HTM				
Photos/Images															3 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	20/04/18 12:35	General View														Load JPG	<input checked="" type="checkbox"/>			
2	20/04/18 12:35	General View														Load JPG	<input checked="" type="checkbox"/>			
3	20/04/18 12:35	General View														Load JPG	<input checked="" type="checkbox"/>			
4	20/04/18 12:35	General View														Load JPG	<input checked="" type="checkbox"/>			
5	20/04/18 12:35	General View														Load JPG	<input checked="" type="checkbox"/>			
6	20/04/18 12:35	General View														Load JPG	<input checked="" type="checkbox"/>			
7	20/04/18 12:35	General View														Load JPG	<input checked="" type="checkbox"/>			
8	20/04/18 12:35	General View														Load JPG	<input checked="" type="checkbox"/>			
9	20/04/18 12:35	General View														Load JPG	<input checked="" type="checkbox"/>			
10	20/04/18 12:35	General View														Load JPG	<input checked="" type="checkbox"/>			
11	20/04/18 12:35	General View														Load JPG	<input checked="" type="checkbox"/>			
12	20/04/18 12:35	General View														Load JPG	<input checked="" type="checkbox"/>			
13	20/04/18 12:35	General View														Load JPG	<input checked="" type="checkbox"/>			
14	20/04/18 12:35	General View														Load JPG	<input checked="" type="checkbox"/>			
15	20/04/18 12:35	General View														Load JPG	<input checked="" type="checkbox"/>			
16	20/04/18 12:35	General View														Load JPG	<input checked="" type="checkbox"/>			
17	20/04/18 12:35	General View														Load JPG	<input checked="" type="checkbox"/>			
18	20/04/18 12:35	General View														Load JPG	<input checked="" type="checkbox"/>			
19	20/04/18 12:35	General View														Load JPG	<input checked="" type="checkbox"/>			
20	20/04/18 12:35	General View														Load JPG	<input checked="" type="checkbox"/>			
21	20/04/18 12:35	General View														Load JPG	<input checked="" type="checkbox"/>			
22	20/04/18 12:35	General View														Load JPG	<input checked="" type="checkbox"/>			
23	20/04/18 12:35	General View														Load JPG	<input checked="" type="checkbox"/>			
24	20/04/18 12:35	General View														Load JPG	<input checked="" type="checkbox"/>			
25	20/04/18 12:35	General View														Load JPG	<input checked="" type="checkbox"/>			
26	20/04/18 12:35	General View														Load JPG	<input checked="" type="checkbox"/>			
27	20/04/18 12:35	General View														Load JPG	<input checked="" type="checkbox"/>			
28	20/04/18 12:35	General View														Load JPG	<input checked="" type="checkbox"/>			
29	20/04/18 12:35	General View														Load JPG	<input checked="" type="checkbox"/>			
30	20/04/18 12:35	General View														Load JPG	<input checked="" type="checkbox"/>			

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	20/04/18 12:35	General View	 Load JPG	<input checked="" type="checkbox"/>
32	20/04/18 12:36	General View	 Load JPG	<input checked="" type="checkbox"/>
33	20/04/18 12:36	General View	 Load JPG	<input checked="" type="checkbox"/>
34	20/04/18 12:36	General View	 Load JPG	<input checked="" type="checkbox"/>
35	20/04/18 12:36	General View	 Load JPG	<input checked="" type="checkbox"/>
36	20/04/18 12:36	General View	 Load JPG	<input checked="" type="checkbox"/>
37	20/04/18 12:36	General View	 Load JPG	<input checked="" type="checkbox"/>
38	20/04/18 12:36	General View	 Load JPG	<input checked="" type="checkbox"/>
39	20/04/18 12:36	General View	 Load JPG	<input checked="" type="checkbox"/>
40	20/04/18 12:36	General View	 Load JPG	<input checked="" type="checkbox"/>
41	20/04/18 12:36	General View	 Load JPG	<input checked="" type="checkbox"/>
42	20/04/18 12:36	General View	 Load JPG	<input checked="" type="checkbox"/>
43	20/04/18 12:36	General View	 Load JPG	<input checked="" type="checkbox"/>
44	20/04/18 12:36	General View	 Load JPG	<input checked="" type="checkbox"/>
45	20/04/18 12:36	General View	 Load JPG	<input checked="" type="checkbox"/>
46	20/04/18 12:36	General View	 Load JPG	<input checked="" type="checkbox"/>
47	20/04/18 12:36	General View	 Load JPG	<input checked="" type="checkbox"/>
48	20/04/18 12:36	General View	 Load JPG	<input checked="" type="checkbox"/>
49	20/04/18 12:36	General View	 Load JPG	<input checked="" type="checkbox"/>
50	20/04/18 12:36	General View	 Load JPG	<input checked="" type="checkbox"/>
51	20/04/18 12:36	General View	 Load JPG	<input checked="" type="checkbox"/>
52	20/04/18 12:36	General View	 Load JPG	<input checked="" type="checkbox"/>
53	20/04/18 12:36	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/02/18 13:33	TP GIA REPORT	 Load PDF	
2	04/05/18 14:57	WORKSHOP INVOICE	 Load PDF	
3	04/05/18 14:57	AUTHORISATION TO ACT FORM	 Load PDF	
4	04/05/18 14:57	Release Voucher	 Load PDF	
5	04/05/18 14:57	RENTAL RECEIPT	 Load PDF	
6	04/05/18 14:57	GIA SEARCH	 Load PDF	
7	04/05/18 14:57	LETTER TO OI	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKK4389P (Insd veh)	Model:	TOYOTA CAMRY 2.4 ABS
	SKC5401Y (TP veh)		AIRBAG (A)
Date of Accident:	02/02/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	8,260.05
Final Repair Cost	:	\$	4,173.00
Loss of Use	:	\$	_____ days at \$0.00 per day
Rental (if any)	:	\$	770.40 5 days
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	4,945.40

**Is Third Party Workshop GIA Registered?** ☐ YES ☒ NO (Kindly indicate below)

**A) For Non GIA Registered Workshop:** Agreed Liability \_\_\_\_\_ 100\_\_\_\_\_(%)

**B) For GIA Registered Workshop:** BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_\_

BOLA Liability: \_\_\_\_\_(%) Assessed Liability (\*): \_\_\_\_\_(%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Success United Pte Ltd	:	\$ 4,945.40
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

04 May  
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

# LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: [sun@lkkauto.com](mailto:sun@lkkauto.com); [assignments@lkkauto.com](mailto:assignments@lkkauto.com)

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18002445/AUA3Q2

Date: 04/05/2018

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100346316  
**Claimant Vehicle No :** SKC5401Y **Insured Vehicle No :** SKK4389P  
 Date of Loss: 02/02/2018 Nature of Claim: TP Claim No: 4398018718SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKC5401Y**  
 Make & Model: TOYOTA CAMRY, 2.4 ABS AIRBAG (A) Engine No: 2AZE226938  
 Reg. Date: 07/09/2011 (Man. Year: 2011) Chassis No: MR053BK4007046832  
 Colour: Silver Odometer: 161085 km  
 Engine Capacity: 2362 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16  
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,889.67	3,410.15	1,479.52	30.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,830.00	1,510.00	1,320.00	46.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,719.67</b>	<b>4,920.15</b>	<b>2,799.52</b>	<b>36.26</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,900.00</b>		
(S\$)	7,719.67	3,900.00	3,819.67	49.48
<b>+ GST 7.00/7.00% (S\$)</b>	540.38	273.00	267.38	49.48
<b>Nett Amount (S\$)</b>	<b>8,260.05</b>	<b>4,173.00</b>	<b>4,087.05</b>	<b>49.48</b>
<b>+ Car Rental (5.0 x S\$144.00/day + 7.00% GST) (S\$)</b>		770.40		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>4,945.40</b>		

### INSPECTION

Date of Assignment: 06/02/2018  
 Date Inspected: 06/02/2018 Inspected At: Success United Pte Ltd (HQ)  
 2 Kaki Bukit Ave 2 #01-33, Kaki Bukit

AutoHub  
Singapore 417921

Estimated Period of Repair: 6.0 days

---

**Adjuster:** ADRIAN LING

**Manager:** THIN THIN HLAING

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Buckled	984.70 FL	*984.70 FL
2	1		*REAR BOOT WEATHERSTRIP	Cut	273.10 FL	*273.10 FL
3	1		*REAR BOOT MECHANISM LOCK	Damaged	382.20 FL	*382.20 FL
4	1		*REAR BOOT LID CAMRY EMBLEM	Necessary	65.80 FL	*65.80 FL
5	1		*REAR BOOT LID 2.4 EMBLEM	Necessary	65.80 FL	*65.80 FL
6	1		*REAR BOOT LID TOYOTA LOGO	Necessary	59.90 FL	*59.90 FL
7	2		*REAR BOOT LID HINGE L/R	Not Necessary	279.80 FL	*- FL
8	1		*REAR END PANEL	Dented	768.30 FL	*768.30 FL
9	1		*REAR END PANEL INNER TOP GARNISH	Deformed	368.90 FL	*368.90 FL
10	2		*REAR LAMP PANEL L/R	Not Necessary	801.60 FL	*- FL
11	1		*REAR LAMP LOWER BRACKET LH	Not Necessary	98.90 FL	*- FL
12	1		*REAR BUMPER	Deformed	654.70 FL	*654.70 FL
13	1		*REAR BUMPER BRACKET LH	Not Necessary	89.90 FL	*- FL
14	1		*REAR BUMPER SIDE HOLDER LH	Necessary	79.90 FL	*79.90 FL
15	1		*REAR BUMPER REFLECTOR LAMP LH	Cracked	93.80 FL	*93.80 FL
16	1		*REAR BUMPER SCREW COVER LH	Not Necessary	79.90 FL	*- FL
17	1		*REAR BUMPER REINFORCEMENT	Bent	483.10 FL	*483.10 FL
18	1		*REAR FENDER INNER UPHOLSTERY TRIM LH	Not Necessary	382.60 FL	*- FL
19	1		*SET REVERSE SENSOR	Damaged	380.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,392.90</b>	<b>4,480.20</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>1,503.23</b>	<b>1,070.05</b>
<b>Total Parts (\$\$)</b>	<b>4,889.67</b>	<b>3,410.15</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE,REARRANGE ELECTRICAL WIRINGS ,CHECK LIGHTINGS	New	80.00	30.00
2	TO REMOVE,REINSTAL UPHOLSTERY ,INNER TRIM GARNISHES	New	350.00	80.00
3	TO REMOVE,REPAIR AND REPLACED DAMAGED BODYPARTS ,REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT	New	1,200.00	800.00
4	TO PUTTY AND RESPRAY PAINTING ON REAR BOOT LID ,REAR BUMPER,END PANEL,REAR FENDER LH	New	1,200.00	600.00
<b>Gross Labour Cost (S\$)</b>			<b>2,830.00</b>	<b>1,510.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >