

**HONDA****KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

Registration No : SFJ7988E

Chassis No : JHMRU1810GX203494

Model : HRV DX-SIN CVT YM 2016

Owner's Name : LOW NGET FONG

Ins Policy No. :

Date of Accident : 3/2/2018

Document No. : SQT18000556 Page 1

Date : 5. Feb 2018

Customer No. : WZ1007

Svc Advisor :

Engine No : L15B4533497

Date | Time : 5. Feb 2018 7:48:01 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:LOW NGET FONG OWNER INSURER:TOKIO MARINE ACC DATE:03/02/2018 SURVEYED BY: DATE: REF NO: TP INSURER:INDIA INTERNATIONAL INSURANCE PTE LTD TP VEH:SH7174T						
67550-T7A-300ZZ	PANEL COMPL.RR.DOOR	1	774.40	25	580.80	40.66	621.46
67865-T7A-003	TAPEL.RR.DOOR SASH	1	15.40	25	11.55	0.81	12.36
72866-T7A-J01	SEALL.DOOR LOWER	1	5.00	25	3.75	0.26	4.01
	Sum Item				596.10	41.73	637.83
BKDR21R	REMOVE & TRANSFER ITEMS TO NEW RR L DR. ADJUST	1	560.00		560.00	39.20	599.20
BP01R	SPRAY PAINTING ON RR L DOOR	1	900.00		900.00	63.00	963.00
BOSUN	SUNDRIES	1	100.00		100.00	7.00	107.00
BOMISC1	RESET SMART ENTRY FOR LHR DOOR	1	280.00		280.00	19.60	299.60
BKDR21K	REMOVE AND REPLACE, ALIGN RR L DOOR.	1	1120.00		1120.00	78.40	1198.40
	Sum Labor				2960.00	207.20	3,167.20

Survey By

Rasul

Date & Time

20/02/18 @ 1155

Excess

3 days

Status

Signature

Rasul

Hp 90010068

Reg 64 paint

Total Amount 3,556.10 248.93 3,805.03

Total (Inclusive of GST) 3,805.03

Printed on 6/2/2018 5:14:48 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: