

India Inter
07/02/18 wed
after 11am.

輝陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

03/02/2018

Owner: MKM CAR LEASING PTE LTD

Not Authorised
21Lr @ 10000
Running After Paint
2 day

ESTIMATE TO REPAIR TOYOTA PRIUS ALPHA 1.8S A - SLP5346T

1pc rear bumper
1pc rear bumper LH side retainer
1pc rear bumper LH side reflector
1pc rear bumper LH inner side garnish

Bul/nd
\$ 891.45 ✓
ne
\$ 141.45 ✓
sn
\$ 181.25 x
sn
\$ 258.85 x

less 25%

\$ 1,473.00
\$ 368.25
\$ 1,104.75

spray painting
labour charges
Total

\$ 500.00 *2200*
\$ 500.00 *200*
\$ 2,104.75

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

