

LKK-  
IDAC

Surveyor: Palvin

**ASSIGNMENT**  
DOI: 8/2/18

Date / Time : 7/2/18  
Registered in Merimen: —

Pre-assign / CCU / FTE



Pre-assign / CCU / FTE

Name of Insured : GLAS-TECHNIE VIC

Insured Tel No. \_\_\_\_\_ HP: \_\_\_\_\_

**Excess Sec II :SS**

Is driver the owner? ( YES / NO )

Nature of Accident :

If NO, Driver Name / Age : HEMM BOON PEN

Driver Tel No. :

(V/L: ~~YES~~ / NO)

Claim No. \_\_\_\_\_

Policy No.

Make / Model :

Place of Accident :

OI GIA REPORT: YES/ NO : TP GIA REPORT: YES/ NO

Insured Liability :	%	Final ? Yes / No
1. Automobile liability		
2. Boat liability		
3. Commercial liability		
4. Directors and officers liability		
5. Employment liability		
6. General liability		
7. Professional liability		
8. Products liability		
9. Real estate liability		
10. Umbrella liability		
11. Workers' compensation liability		



INSRS:  
WSP:  
Tel :  
Liability  
RMKS:



INSRS:  
WSP:  
Tel :  
Liability :  
RMKS:



INRS:  
WSP:  
Tel :  
Liability :  
RMKS:



INSRS:  
WSP:  
Tel :  
Liability :  
RMKS:

Date/Time	STAGE	DATE / PIC
1/1/18 VIC	Non-Reporting ltr (1st): Non-Reporting ltr (2nd): Non-Reporting ltr (Final): Notification ltr (if non-pickup): Call OE: After call ltr to OE:	
02/05/18	Documentation Check List: Handler Typist	
02/05/18	Notification ltr (if non-pickup): After call ltr to OE:	
08/05/18	Authorisation To Act: Release Voucher: Final Repair Bill: Car Rental Invoice: Towing Invoice: LTA/GIA: Medical Bill: PIR: Mandate/Reject Instruction: LOD: Payment Breakdown Form: Post-Repair Photos: Others:	
09/05/18 10/05/18		

<b>FINALIZATION</b>		Date/Time:		Confirm with:		Confirm by:	
Repair Cost:	L16	SS	1150.00 ( 2 days)	Reduction:	63 %	Email	<input type="checkbox"/> Call <input type="checkbox"/>
<b>FINAL SETTLEMENT</b>		Date/Time: 09/05/18		Confirm with: GARY		Email <input type="checkbox"/> Call <input type="checkbox"/>	
Final Liability:	%	100	(Agreed / Assessed)	BOLA S/N No.:	23	If NO or B 28, Ass. Lia :	
Repair Cost:	(w/GRS)	SS	1,230.50	COPY SENT 11/5/18			
Loss of Rental (LOR):	SS	556.48	( 3 days)	X 4	112.16		
Loss of Use (LOU):	SS	120.00	to x 3 days)				
Loss of Income (LOI):	SS	-	( \$ x days)				
LOR only <input type="checkbox"/>	LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/>	LOR + LOI <input checked="" type="checkbox"/>	[Tick only one]			
GIA/TA Search	SS	7.45					
Medical:	SS	-	1) Claim status: Normal/Reject/Private Settle				
Disbursement:	SS	-	(e.g. Tow/ Independent )				
Legal Cost	SS	-	2) Report Format:				
			3) Survey fee: 450.00				
<b>Total:</b>	SS	1,694.43	<b>Global Sum SS:</b>		1,690.00		
<b>FINAL PAYMENT</b>		Date/Time:		Confirm with:		Email <input type="checkbox"/> Call <input type="checkbox"/>	
Payee 1:	SS	1,690.00	Name 1:	PREMIER AUTOMOTIVE SERVICES PTE LTD			
Payee 2: (Strike if N.A.)	SS	-	Name 2:	-			
Payee 3: (Strike if N.A.)	SS	-	Name 3:	-			

## ASSIGNMENT

SHC 6327H

6 Jan 2015

100

Type: M.Car / M.Cycle / Bus / Van / Lorry / T: 6 Prime-Mover

Truck / Trailer: 0

8. 2000

Case

So Reading

Eng No.

CNe

Gen. Cond: Good / Fair / Poor / Burnt

Steering inoperative / Jammed / Leaked / Burnt or

Brake: inoper / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD ~~S/Rim~~ or

Type Size

FS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO cr

Front

233

LEB

D.O.A.

Survey held at:

Dep. of Outcomes: FA / Real / O/S / N/S / U/C / Referred

The UIC / Chassis frame / Body Structure affected due to collision.

Data File Path:

☐: Prelim. Report

☐: Final Report

... ..

Recent Format:

Lytic Sum / I.E. = 6

Days Of Repair:

Resurvey No. of Trip:

Environ Biol Fish (2015) 98:223–233

1998, 1999, 2000, 2001, 2002, 2003, 2004, 2005, 2006, 2007, 2008, 2009, 2010, 2011, 2012, 2013, 2014, 2015, 2016, 2017, 2018, 2019, 2020, 2021, 2022, 2023, 2024, 2025, 2026, 2027, 2028, 2029, 2030, 2031, 2032, 2033, 2034, 2035, 2036, 2037, 2038, 2039, 2040, 2041, 2042, 2043, 2044, 2045, 2046, 2047, 2048, 2049, 2050, 2051, 2052, 2053, 2054, 2055, 2056, 2057, 2058, 2059, 2060, 2061, 2062, 2063, 2064, 2065, 2066, 2067, 2068, 2069, 2070, 2071, 2072, 2073, 2074, 2075, 2076, 2077, 2078, 2079, 2080, 2081, 2082, 2083, 2084, 2085, 2086, 2087, 2088, 2089, 2090, 2091, 2092, 2093, 2094, 2095, 2096, 2097, 2098, 2099, 2100, 2101, 2102, 2103, 2104, 2105, 2106, 2107, 2108, 2109, 2110, 2111, 2112, 2113, 2114, 2115, 2116, 2117, 2118, 2119, 2120, 2121, 2122, 2123, 2124, 2125, 2126, 2127, 2128, 2129, 2130, 2131, 2132, 2133, 2134, 2135, 2136, 2137, 2138, 2139, 2140, 2141, 2142, 2143, 2144, 2145, 2146, 2147, 2148, 2149, 2150, 2151, 2152, 2153, 2154, 2155, 2156, 2157, 2158, 2159, 2160, 2161, 2162, 2163, 2164, 2165, 2166, 2167, 2168, 2169, 2170, 2171, 2172, 2173, 2174, 2175, 2176, 2177, 2178, 2179, 2180, 2181, 2182, 2183, 2184, 2185, 2186, 2187, 2188, 2189, 2190, 2191, 2192, 2193, 2194, 2195, 2196, 2197, 2198, 2199, 2200, 2201, 2202, 2203, 2204, 2205, 2206, 2207, 2208, 2209, 2210, 2211, 2212, 2213, 2214, 2215, 2216, 2217, 2218, 2219, 2220, 2221, 2222, 2223, 2224, 2225, 2226, 2227, 2228, 2229, 2230, 2231, 2232, 2233, 2234, 2235, 2236, 2237, 2238, 2239, 2240, 2241, 2242, 2243, 2244, 2245, 2246, 2247, 2248, 2249, 2250, 2251, 2252, 2253, 2254, 2255, 2256, 2257, 2258, 2259, 2260, 2261, 2262, 2263, 2264, 2265, 2266, 2267, 2268, 2269, 2270, 2271, 2272, 2273, 2274, 2275, 2276, 2277, 2278, 2279, 2280, 2281, 2282, 2283, 2284, 2285, 2286, 2287, 2288, 2289, 2290, 2291, 2292, 2293, 2294, 2295, 2296, 2297, 2298, 2299, 2300, 2301, 2302, 2303, 2304, 2305, 2306, 2307, 2308, 2309, 2310, 2311, 2312, 2313, 2314, 2315, 2316, 2317, 2318, 2319, 2320, 2321, 2322, 2323, 2324, 2325, 2326, 2327, 2328, 2329, 2330, 2331, 2332, 2333, 2334, 2335, 2336, 2337, 2338, 2339, 2340, 2341, 2342, 2343, 2344, 2345, 2346, 2347, 2348, 2349, 2350, 2351, 2352, 2353, 2354, 2355, 2356, 2357, 2358, 2359, 2360, 2361, 2362, 2363, 2364, 2365, 2366, 2367, 2368, 2369, 2370, 2371, 2372, 2373, 2374, 2375, 2376, 2377, 2378, 2379, 2380, 2381, 2382, 2383, 2384, 2385, 2386, 2387, 2388, 2389, 2390, 2391, 2392, 2393, 2394, 2395, 2396, 2397, 2398, 2399, 2400, 2401, 2402, 2403, 2404, 2405, 2406, 2407, 2408, 2409, 2410, 2411, 2412, 2413, 2414, 2415, 2416, 2417, 2418, 2419, 2420, 2421, 2422, 2423, 2424, 2425, 2426, 2427, 2428, 2429, 2430, 2431, 2432, 2433, 2434, 2435, 2436, 2437, 2438, 2439, 2440, 2441, 2442, 2443, 2444, 2445, 2446, 2447, 2448, 2449, 2450, 2451, 2452, 2453, 2454, 2455, 2456, 2457, 2458, 2459, 2460, 2461, 2462, 2463, 2464, 2465, 2466, 2467, 2468, 2469, 2470, 2471, 2472, 2473, 2474, 2475, 2476, 2477, 2478, 2479, 2480, 2481, 2482, 2483, 2484, 2485, 2486, 2487, 2488, 2489, 2490, 2491, 2492, 2493, 2494, 2495, 2496, 2497, 2498, 2499, 2500, 2501, 2502, 2503, 2504, 2505, 2506, 2507, 2508, 2509, 2510, 2511, 2512, 2513, 2514, 2515, 2516, 2517, 2518, 2519, 2520, 2521, 2522, 2523, 2524, 2525, 2526, 2527, 2528, 2529, 2530, 2531, 2532, 2533, 2534, 2535, 2536, 2537, 2538, 2539, 2540, 2541, 2542, 2543, 2544, 2545, 2546, 2547, 2548, 2549, 2550, 2551, 2552, 2553, 2554, 2555, 2556, 2557, 2558, 2559, 2560, 2561, 2562, 2563, 2564, 2565, 2566, 2567, 2568, 2569, 2570, 2571, 2572, 2573, 2574, 2575, 2576, 2577, 2578, 2579, 2580, 2581, 2582, 2583, 2584, 2585, 2586, 2587, 2588, 2589, 2590, 2591, 2592, 2593, 2594, 2595, 2596, 2597, 2598, 2599, 2600, 2601, 2602, 2603, 2604, 2605, 2606, 2607, 2608, 2609, 2610, 2611, 2612, 2613, 2614, 2615, 2616, 2617, 2618, 2619, 2620, 2621, 2622, 2623, 2624, 2625, 2626, 2627, 2628, 2629, 2630, 2631, 2632, 2633, 2634, 2635, 2636, 2637, 2638, 2639, 2640, 2641, 2642, 2643, 2644, 2645, 2646, 2647, 2648, 2649, 2650, 2651, 2652, 2653, 2654, 2655, 2656, 2657, 2658, 2659, 2660, 2661, 2662, 2663, 2664, 2665, 2666, 2667, 2668, 2669, 2670, 2671, 2672, 2673, 2674, 2675, 2676, 2677, 2678, 2679, 26

Add Fee:

100

— — — — — 50

— 100 —

**Abstract**




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CC4/LPC18002487/K1hb3	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 07-02-2018	
		Code : LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SJD 2443C	Veh. Inspected	SHC 6327H
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	07/02/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	06/02/2018	Inspection Date	07/02/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised  
Our ref: CC4/LPC18002487/K1hb3

Date: 08.02.2018

The Motor Claims Department  
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SHC6327H**

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 07.02.2018 at the premises of M/s Premier Automotive Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	3,127.30
Revised Estimate Amount	: S\$	1,459.80
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

**Description of Damage:**

The vehicle sustained damages at the  
Rear O/S Portion



**Comments/Present Status:**

Damages Consistent

Estimated normal period for repairs: 2 days

Yours faithfully,

KALVIN ANG  
Licensed Appraiser

**Catherine Chong (LKK Auto)**

---

**From:** ERIC WOO JUN KIAT <ericwoo@lonpac.com>  
**Sent:** Wednesday, 7 February, 2018 10:57 AM  
**To:** assignments@lkkauto.com  
**Cc:** MT\_Claim\_SG  
**Subject:** Our Ref: 17/18/18/VP05/020381 Accident involving SJD2443C & SHC6327H at Bishan Junction on 6/2/18  
**Attachments:** 07022018105104.pdf

Dear Catherine,

Kindly refer to our attachment.

Please proceed to conduct a survey of the vehicle SHC 6327H on without Prejudice Basis.

We look forward to receiving your report soon.

*Kalvin*

Thank you.

Best Regards,  
Eric Woo  
Claims Executive | Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse, Singapore 199555  
Tel: (65) 6279 9253 | Fax: (65) 6296 3767

**Shu Pei (LKKAUTO)**

---

**From:** GERALD POH WEE BIN <geraldpoh@lonpac.com>  
**Sent:** Wednesday, 28 February 2018 9:53 AM  
**To:** Shu Pei (LKKAUTO)  
**Cc:** MT\_Claim\_SG  
**Subject:** RE: Our Ref: 17/18/18/VP05/020381 Accident involving SJD2443C & SHC6327H at Bishan Junction on 6/2/18 \*\*\*LKK REF:CC4/LPC18002487/K1hb3  
**Attachments:** 28022018083520.pdf

Dear Shu Pei,

We attached a copy of insured's GIA report for your attention.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

---

**From:** Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]

**Sent:** Monday, 26 February, 2018 7:10 PM

**To:** GERALD POH WEE BIN

**Cc:** MT\_Claim\_SG

**Subject:** RE: Our Ref: 17/18/18/VP05/020381 Accident involving SJD2443C & SHC6327H at Bishan Junction on 6/2/18  
\*\*\*LKK REF:CC4/LPC18002487/K1hb3

**WITHOUT PREJUDICE**

Dear Sir / Madam,

We refer to the above matter.

Kindly advice whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** GERALD POH WEE BIN [mailto:geraldpoh@lonpac.com]

**Sent:** Friday, 9 February 2018 9:11 AM

**To:** Shu Pei (LKKAUTO) <[shupeil@lkkauto.com](mailto:shupeil@lkkauto.com)>

Cc: MT\_Claim\_SG <mt\_claim@lonpac.com>

**Subject:** RE: Our Ref: 17/18/18/VP05/020381 Accident involving SJD2443C & SHC6327H at Bishan Junction on 6/2/18

\*\*\*LKK REF:CC4/LPC18002487/K1hb3

Dear Shu Pei,

Our insured has yet to lodge a report and we are making enquiries.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

---

**From:** Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]

**Sent:** Thursday, 8 February, 2018 7:16 PM

**To:** ERIC WOO JUN KIAT; GERALD POH WEE BIN

**Cc:** MT\_Claim\_SG; Admin A; Vic (LKKAUTO); Asher Sng (LKKAUTO)

**Subject:** RE: Our Ref: 17/18/18/VP05/020381 Accident involving SJD2443C & SHC6327H at Bishan Junction on 6/2/18

\*\*\*LKK REF:CC4/LPC18002487/K1hb3

**WITHOUT PREJUDICE**

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHC 6327H at M/s Premier Automotive Services Pte Ltd.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice

Our case handler in-charge is Vic and he can be contacted at DID: 6841 2096.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Admin-D (LKKAuto)

**Sent:** Wednesday, 7 February 2018 10:59 AM

**To:** 'ERIC WOO JUN KIAT' <[ericwoo@lonpac.com](mailto:ericwoo@lonpac.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>

**Cc:** 'MT\_Claim\_SG' <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Subject:** RE: Our Ref: 17/18/18/VP05/020381 Accident involving SJD2443C & SHC6327H at Bishan Junction on 6/2/18

Dear Eric,

Thank you for the assignment.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** ERIC WOO JUN KIAT [<mailto:ericwoo@lonpac.com>]

**Sent:** Wednesday, 7 February, 2018 10:57 AM

**To:** [assignments@lkkauto.com](mailto:assignments@lkkauto.com)

**Cc:** MT\_Claim\_SG <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>

**Subject:** Our Ref: 17/18/18/VP05/020381 Accident involving SJD2443C & SHC6327H at Bishan Junction on 6/2/18

Dear Catherine,

Kindly refer to our attachment.

Please proceed to conduct a survey of the vehicle SHC 6327H on without Prejudice Basis.

We look forward to receiving your report soon.

Thank you.

Best Regards,

Eric Woo

Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6279 9253 | Fax: (65) 6296 3767



# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

7-Feb-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6327 H

1 pc	Rear bumper	\$ 696.00
1 pc	Rear bumper lower cover	\$ 206.00
1 pc	Rear bumper o/s side bracket @ \$29.00 ✕	\$ 29.00
1 pc	Rear bumper inner sponge ✕	\$ 114.00
1 pc	Rear bumper reinforcement ✕	\$ 607.00
1 pc	Rear bumper o/s stay @ \$53.00 ✕	\$ 53.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 ✕	\$ 36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 ✕	\$ 36.00
		<hr/>
		\$ 1,777.00
Less 10%		\$ 177.70
		<hr/>
		\$ 1,599.30

### S/NETT

1 set	Rear bumper clips	\$ 48.00
1 set	Reverse sensor	\$ <del>280.00</del> 200
Sundry		\$ <del>50.00</del> ✕
To dismantle / replace/test reverse sensor to new bumper and reset to the same		\$ <del>120.00</del> 20
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$ <del>180.00</del> ✕
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same		\$ <del>450.00</del> 200
To putty and spray painting on rear bumper		\$ <del>200.00</del> 180
To apply rustproofing on the repaired and replaced panels.		\$ <del>200.00</del> ✕
		<hr/>
		\$ 3,127.30

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Ka Loo (LKK)  
7/2/18 0950 hrs  
2 Rtn.  
L/s  
After Repair p/h

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

7-Feb-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6327 H

1 pc	Rear bumper	\$ 696.00
1 pc	Rear bumper lower cover	\$ 206.00
1 pc	Rear bumper o/s side bracket @ \$29.00	\$ 29.00
1 pc	Rear bumper inner sponge	\$ 114.00
1 pc	Rear bumper reinforcement	\$ 607.00
1 pc	Rear bumper o/s stay @ \$55.00	\$ 53.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$ 36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$ 36.00
		\$ 1,777.00
	Less 10%	\$ 177.70
		\$ 1,599.30

### S/NETT

1 set	Rear bumper clips	\$ 48.00
1 set	Reverse sensor	\$ 280.00
	Sundry	\$ 50.00
	To dismantle / replace/test reverse sensor to new bumper and reset to the same	\$ 120.00
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs	\$ 180.00
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same	\$ 450.00
	To putty and spray painting on rear bumper	\$ 200.00
	To apply rustproofing on the repaired and replaced panels	\$ 200.00
		\$ 3,127.30

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

12/2/18  
Kala (LKK)  
7/2/18 0950 hrs  
2 B-1  
4/5  
After Repair pls

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

## Vic (LKKAUTO)

---

**From:** Gary Shi <gary.shi@premiertaxi.com>  
**Sent:** Wednesday, 9 May, 2018 1:25 PM  
**To:** Vic (LKKAUTO)  
**Cc:** AccReport; Admin A; Asher Sng (LKKAUTO)  
**Subject:** RE: LOD / Accident involving SHC6327H & SJD2443C on 06.02.18 (Lonpac case) LKK REF CC4/LPC18002487/K1hb3  
**Attachments:** SHC6327H - DV.pdf

WITHOUT PREJUDICE

Dear Vic,

On a without prejudice basis and without admission of liability whatsoever on our client's part and driver of SHC6327H, our client agreed to direct settle the above claims at \$1690.00

We enclosed hereby Discharge voucher for & ATA your kind attention, original copies will pass to Mr Calvin.

Kindly let us have your settlement sum of S\$1690.00 in our favour – Premier Automotive Services Pte Ltd within 14days from the date hereof.

Please be informed that this settlement excludes any bodily injuries arising out of the above said accident and pertains to property damage only.

Regards

Gary Shi  
Senior Executive, Claims  
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443  
Tel: 6214 8880 Ext 069 | DID: 6544 6671 | Fax: 6214 1511  
Visit us at: [www.premiertaxi.com.sg](http://www.premiertaxi.com.sg)

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

 Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION

---

**From:** Vic (LKKAUTO) [mailto:vicalpeh@lkkauto.com]  
**Sent:** Tuesday, 8 May, 2018 5:32 PM  
**To:** Gary Shi  
**Cc:** AccReport; Admin A; Asher Sng (LKKAUTO); Vic (LKKAUTO)  
**Subject:** RE: LOD / Accident involving SHC6327H & SJD2443C on 06.02.18 (Lonpac case) LKK REF CC4/LPC18002487/K1hb3

Without Prejudice

Dear Gary,

We refer further to our below email.

Purely for an amicable settlement on a without prejudice basis and without admission of any liability to our Insured's part, we have our principal's mandate and we propose a global sum of **\$1,690.00** (all in) to settle your client's claim.

If agreeable, kindly chop and sign the enclosed **DV and ATA** then forward back to us the original signed copy together with the LOD and supporting documents for payment processing.

Thank you.

*"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters."*

Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



AUTO  
CONSULTANTS  
PTE LTD

*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

---

**From:** Vic (LKKAuto)

**Sent:** Tuesday, 13 February, 2018 4:40 PM

**To:** Gary Shi

**Cc:** AccReport; Admin A; Asher Sng (LKKAuto); Vic (LKKAuto)

**Subject:** RE: LOD / Accident involving SHC6327H & SJD2443C on 06.02.18 (Lonpac case) LKK REF CC4/LPC18002487/K1hb3

Without Prejudice

Dear Gary,

We refer to your below email and the contents were noted.

Please be informed that till date, we are still pending for our Insured's GIA report.

We will follow up and will get back to you for an update.

Thank you.

Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicapeh@lkkauto.com](mailto:vicapeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

---

**From:** Gary Shi [<mailto:gary.shi@premiertaxi.com>]

**Sent:** Tuesday, 13 February, 2018 4:10 PM

**To:** Asher Sng (LKKAuto); Vic (LKKAuto)

**Cc:** AccReport; CS A Team

**Subject:** LOD / Accident involving SHC6327H & SJD2443C on 06.02.18 (Lonpac case)

WITHOUT PREJUDICE

Dear Asher & Vic,

Your Ref: SJD2443C

Our Ref: SHC6327H/GS

Date of accident: 06/02/2018

We refer to the above mentioned accident.

Hereby we would like to append our losses from Lonpac Insurance Bhd, as insurers of vehicle number SJD2443C which their insured driver's negligence driving in the above accident.

Enclosed herewith our letter of demand and supporting documents for your kind perusal.

Kindly look into the matter and let us have your favourable reply as soon as possible.

To expedite this claim settlement, please reply to us by email.

Regards

Gary Shi

Senior Executive, Claims

Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443

Tel: 6214 8880 Ext 069 | DID: 6544 6671 | Fax: 6214 1511

Visit us at: [www.premiertaxi.com.sg](http://www.premiertaxi.com.sg)

---

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

 Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION



**Gary Shi**

---

**From:** Gary Shi  
**Sent:** Wednesday, 9 May, 2018 1:25 PM  
**To:** 'Vic (LKKAUTO)'  
**Cc:** AccReport; Admin A; Asher Sng (LKKAUTO)  
**Subject:** RE: LOD / Accident involving SHC6327H & SJD2443C on 06.02.18 (Lonpac case) LKK REF CC4/LPC18002487/K1hb3  
**Attachments:** SHC6327H - DV.pdf

WITHOUT PREJUDICE

Dear Vic,

On a without prejudice basis and without admission of liability whatsoever on our client's part and driver of SHC6327H, our client agreed to direct settle the above claims at \$1690.00

We enclosed hereby Discharge voucher for & ATA your kind attention, original copies will pass to Mr Kalvin.

Kindly let us have your settlement sum of S\$1690.00 in our favour – Premier Automotive Services Pte Ltd within 14days from the date hereof.

Please be informed that this settlement excludes any bodily injuries arising out of the above said accident and pertains to property damage only.

Regards

Gary Shi  
Senior Executive, Claims  
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443  
**Tel: 6214 8880 Ext 069 | DID: 6544 6671 | Fax: 6214 1511**  
Visit us at: [www.premiertaxi.com.sg](http://www.premiertaxi.com.sg)

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

 Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION

---

**From:** Vic (LKKAUTO) [mailto:[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)]  
**Sent:** Tuesday, 8 May, 2018 5:32 PM  
**To:** Gary Shi  
**Cc:** AccReport; Admin A; Asher Sng (LKKAUTO); Vic (LKKAUTO)  
**Subject:** RE: LOD / Accident involving SHC6327H & SJD2443C on 06.02.18 (Lonpac case) LKK REF CC4/LPC18002487/K1hb3

Without Prejudice

Dear Gary,

We refer further to our below email.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC18002487/K1hb3n2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 11-05-2018		
		Code : LPC2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJD 2443C	Veh. Inspected	SHC 6327H	
Policy No.	Z17VP05013462	Coverage (\$)	0.00	
Claim No.	17/18/18/VP05/020381	Excess (\$)	0.00	
Assign From	ERIC	Assign Date	07/02/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KNAGM414MF5561402	Colour	SILVER	
Odometer	260619	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	ACHILLES	7 mm	
L/H Front Tyre	205/65 R16	ACHILLES	7 mm	
R/H Rear Tyre	205/65 R16	ACHILLES	7 mm	
L/H Rear Tyre	205/65 R16	ACHILLES	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	06/02/2018	Inspection Date	07/02/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6327H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	DEFORMED	696.00	696.00
1	REAR BUMPER LOWER COVER	CRACKED	206.00	206.00
1	REAR BUMPER O/S SIDE BRACKET	SERVICEABLE	29.00	-
1	REAR BUMPER INNER SPONGE	SERVICEABLE	114.00	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	607.00	-
1	REAR BUMPER O/S STAY	SERVICEABLE	53.00	-
2	REAR BUMPER REINFORCEMENT LOWER BRACKET @\$18.00	SERVICEABLE	36.00	-
2	REAR BUMPER REINFORCEMENT UPPER BRACKET @\$18.00	SERVICEABLE	36.00	-
	LESS 10% DISCOUNT		-177.70	-90.20
			1,599.30	811.80
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	SUNDRY (SN)	NOT NECESSARY	50.00	-
			378.00	248.00
<b><u>LABOUR</u></b>				
	TO DISMANTLE/REPLACE/TEST REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.		120.00	20.00
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE SAME.		450.00	200.00
	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER.		200.00	180.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	200.00	-
			1,150.00	400.00
<b>GRAND TOTAL</b>			<b>3,127.30</b>	<b>1,459.80</b>



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,150.00
---	--	--	----------

Report Ref No. CC4/LPC18002487/K1hb3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.