

SGU945E

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

07 FEB 2018

Estimate No. : b1 45784	Page No. : 1 of 2
Date Estimated : 05/02/2018	
Prepared By : Han Kwan Yong	

- ESTIMATE REPAIR FOR - Chung Heejin 12 Belmont Road Singapore Singapore 269859	- ACCOUNT - 40000 Cash Sales - Service Singapore
--	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGU945E	C581196	14/07/2011	535iA	0

DESCRIPTION	VALUE
To replace rear bumper & attachments including to knock out dented area caused by the accident	850. 1,275.00
To respray rear bumper	934 1,038.00
To replace bootlid smart opener top and bottom sensor lines including program and conduct checks for proper function.	561? 661.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150. 177.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
Sundries.	? 80.00
Total Labour 1:	3,408.00

DESCRIPTION	QTY	PRIC	VALUE
RR BUMPER GUIDE BOTTOM CENTRE	1	58.95	? 58.95
RR BUMPER CTR GUIDE	1	67.35	? 67.35
RR BUMPER CARRIER	1	714.25	? 714.25
RR BUMPER PANEL PRIMED (PDC)	1	1,467.20	de-? 1,467.20
RR BUMPER TOW HOOK COVER PRIMED	1	46.45	? 46.45
RR BUMPER ADAPTER	1	48.00	? 48.00
PLUG	10	1.05	? 10.50
PLUG BLACK D=5MM	10	0.90	? 9.00
SENSOR WIRE FOR SMART OPENER TOP	1	42.10	? 42.10
SENSOR WIRE FOR SMART OPENER BOTTOM	1	40.50	? 40.50
EXPANDING NUT	10	0.55	? 5.50
REAR LH REFLECTOR	1	35.20	x 35.20
REAR RH REFLECTOR	1	35.20	x 35.20
DECOUPLING RING PDC TORQUE CONVERTE	2	5.05	nu- 10.10
BUMPER PDC SENSOR (A90 SOPHISTOGRAU	2	368.80	? 737.60

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 45784**
Date Estimated : **05/02/2018**
Prepared By : **Han Kwan Yong**

Page No. : **2 of 2**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGU945E	C581196	14/07/2011	535iA	0

Total Parts : **3,327.90**

14/2/18 @ 1405
Taufik
97449773
WP

RESURVEY PARTS

Surveyor's E-mail: taufik@lkkauto.com

No. of Working Days Recommended: 3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	3,408.00
Parts	:	3,327.90
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	471.51
Grand Total	:	7,207.41

**** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY****

**** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE ****