

12/05/2001

ASS. REC. BY:

REF: CS/MSG18002520/Urd3ⁿ² Special Instructions

Surveyor:

Marianne

ASSIGNMENT (Office)

From (Person):

Irene Tan

of

MSIG

Date/Time:

7/2/18 @ 10:57am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJD 8194G

Insured:

FY76422

at Workshop m/s

1up Motor Trading

Tel:

67840039/98154655

of

31K9004, Tampines street 93 #01-120

Policy No:

MSD/VM7/17-885913

Claim No:

MSC/V/18-000211

Sum Insured:

Excess:

Make of Veh:

D.O.A.

5/2/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time:

3:20pm @ 7/2/18

Person Contacted:

David

Vehicle:

IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

SJD 8194G-X

FY76422-X

sent preli thru marianne

(08/11/13) wef

ASS. REC. BY: *MARCUS*

REF:

MS16/

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: *SYD819461*
at Workshop m/s *my motor 3 per*
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: *£8300*
IDAC Accident Report: _____ Consistent? : Yes or No
GIA PR Seen: *e* Consistent? : Yes or No
Est. Repairs: *4* days Res.: Yes or No
Lum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: *SYD81946* Yr Regn: *4/408*
Type: *M.Cat* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or *VA*
Make: *mt haren* C.C. *1584*
Colour: *Red* A/C: Insured / Std / NI / NA
Sp. Reading: *238761* T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: *YMY/STC 53 AFU 006A2*
Gen. Cond: *Good* / Fair / Poor / Burnt
Steering: *In order* / Jammed / Leaked / Burnt or
Brake: *In order* / Jammed / Leaked / Burnt or
Modi: *Nil* / STD A/Rim or
Tyre Size: F: *195/65R15*
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or *Finanxe*

Front Rear
R/Bal. *5-* mm R/Bal. *5-* mm
L/Bal. *5-* mm L/Bal. *5-* mm
D.O.A. *5/2/18* D.O.I. *7/2/18*
Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27A 6767

base on estimate should be 4581800 but only allow 4581500

7/2/18 Confirmed 4581500 with Bond

Red: 1547.36, 50%

RECEIVED 08 FEB 2018

Date/Time, File Pass to? ☐ : Preli. Report

1) *typist* ☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: *4*

Resurvey No. of Trip: *-*

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

☐ S + RS. ☐ SI

Photos

Others

TOTAL

Report Format: *TP*

Lump Sum / L.B.I. (\$) *1500*

200

10

210

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Feb 2018		07 Feb 2018 10:57 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	AMIRUL HAKIM BIN AZLEE, ID: S9814442J		
Main Claimant:	KOH GIN THIAM, ID: S1309319I		
Vehicle Reg. No.:	SJD8194G	Date of Loss:	05/02/2018 17:00 - :59
Claim Type:	TP / MSC/V/18-000211	Policy/Cover Note No.:	MSD/VMT/17-985913 (Third Party Only) Coverage: 14/09/2017 - 13/09/2018
Vehicle Reg. No. (Insured):	FY7642Z	Policy No. (Claimant):	
		Excess:	
Repairer:	Hup Motor Trading & Service (HQ) Blk 9004 Tampines Street 93, #01-120, 528838 Tampines - Tel: 67840039/98154655		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Imm.Advice due 08/02/2018]		
Driver/Custodian (Insured):	AMIRUL HAKIM BIN AZLEE (), NRIC: S9814442J		
Adj Asg. Remarks:	SURVEY APPT 07/02/18 2-3PM OWNER WAITING		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS View All

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18002520/Urd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 07-02-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FY 7642Z	Veh. Inspected	SJD 8194G
Policy No.	MSD/VMT/17-985913	Coverage (\$)	0.00
Claim No.	MSC/V/18-000211	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAN)	Assign Date	07/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	05/02/2018	Inspection Date	07/02/2018
Survey held at	HUP MOTOR TRADING & SERVICE BLK 9004 TAMPINES ST 93 #01-120 SINGAPORE 528838		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 08 Feb 2018

Preliminary Advice

Insured Vehicle No	: FY7642Z	Accident Date	: 05/02/2018
TP Vehicle No	: SJD8194G	Assignment Date	: 07/02/2018
Make	: MITSUBISHI LANCER	Est. Duration of Repair	: 4.00
Date of Inspection	: 07/02/2018		
Inspection At	: HUP MOTOR TRADING & SERVICE (HQ) BLK 9004 TAMPINES STREET 93, #01-120 SINGAPORE 528838		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,047.36
Revised Amount	:S\$	2,275.86
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,275.86
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.



redefining / insurance

AXA Insurance Pte Ltd

1800 880 4888 (Within Singapore)

(65) 6880 4888 (International)

(65) 6880 4740

customer.care@axa.com.sg

www.axa.com.sg

account number

04066

Certificate of Insurance

-Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) - Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 - Road Transport Act, 1987 (Malaysia)
-Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Policy details

Policyholder name	KOH GIN THIAM	Certificate number	GA093981 / 1
Cover	Comprehensive	Chassis number	JMYSTCS3A8U006852
Plan name	Private APW	Engine number	4G18JQ1641
NCD applicable	50%		
Vehicle registration number	SJD8194G		
Period of Insurance	from 04/04/2017 to 03/04/2018 (both dates inclusive)		
Finance loan company	Nil		

Persons or classes of persons entitled to drive*

- (a) The Policyholder
(b) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS	Basic Own Damage Excess	SGD 0.00
	Windscreen Excess	SGD 100.00

An Additional Excess is applicable as follows:

1. S\$500 for unnamed *Authorised Driver*
2. S\$500 for declared *Young and Inexperienced Driver*
3. S\$5,000 for undeclared *Young and Inexperienced Drivers*. This additional excess is reduced to S\$2,500 if You have chosen AXA Premium Workshops.

Additional clauses & endorsements to your policy

Nil

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

Authorised signature

Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189). The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, endorsement etc.

sgCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Articles

Forum

Tools & Tips



JEWELLERY PUBLIC AUCTION

SEIZED ASSETS - OVER 900 ITEMS

Saturday, 10th February
 Preview: 11am - Auction: 1pm - 5pm
Mandarin Orchard Hotel
 333 Orchard Rd. Singapore



Mitsubishi Lancer

Price Range

Depreciation

2008

Vehicle Type

Submit

Advanced Search

Home » Used Cars » Breaking Point » Mitsubishi Lancer 1.6A GLX

Tools & Tips

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle

Car Tyres



SERVCORP



Mitsubishi Lancer 1.6A GLX

Overview Financial Accessories Similar Research Photos Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price	\$10,800
Depreciation	-
Reg Date	27-Jun-2008 (4mths 19days COE left)
Manufactured	2008
Mileage	-
Transmission	AUTO
Engine Cap	1,584 cc
Road Tax	\$734 /yr
Power	79.0 kW (105 bhp) View specs of the Mitsubishi Lancer (2006-2008)
Curb Weight	1,162 kg
Features	-
Accessories	-
COE	\$16,301
OMV	\$12,408
ARF	\$12,408
Dereg Value	\$6,825 as of today (change)
No. of Owners	4
Type of Veh	Mid-Sized Sedan
Category	PARF Car
Availability	Available

Add to Shortlist

Add to Compare

Add a Note

Posted on: 01-Feb-2018 | Last Updated on: 01-Feb-2018

Tags: Mitsubishi Lancer, 2008 Mitsubishi Lancer, Mitsubishi Lancer, Used Mitsubishi

Upfront Payment

» more Financial Info

Transfer Fee	\$25	
Down Payment	\$3,240 (change)	Maximum 70% Loan
1st Instalment	\$1,909	
Total Upfront Payment	\$5,174 (excluding insurance)	

Estimates based on 70% loan at 2.98% interest rate. Check with seller for exact figure.

Items for Mitsubishi Lancer

» View All

Car Pedals
\$108Door Visor
\$65Door Handle Bowl
\$65LED Dome Light 15 LEDs (LED Cabin L...)
\$30

SLG 9 Y



Seller Information

Company	Breaking Point
	• dealer's pricelist • 9 vehs sold 15 vehs available
Address	252 Jurong East Street 24 #03-127 Search cars nearby this location
Office No	65614858
Contact Person(s)	Peter 85476568 Benny 85890598

Useful Services



Make sure of this car condition with STA Evaluation.
Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.
Free Valuation

New Cars

Used Cars

Sell My Car

Directory

Products

Articles

Forum

Tools & Tips

- Suspended net playground at City Square Mall
- All about kueh lapis
- Celebrities & The Cars They Drive

Mitsubishi Lancer

Price Range

Depreciation

2008

Vehicle Type

Submit

Advanced Search

Home » Used Cars » Boeki Auto & Marine » Mitsubishi Lancer 1.6A GLX (OPC)

Tools & Tips

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle

Car Leasing



Mitsubishi Lancer 1.6A GLX (OPC)

Overview

Financial

Accessories

Similar

Research

Photos

Map



BOEKI AUTO & MARINE



Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price	\$8,188	
Depreciation	-	
OPC Scheme	Revised OPC scheme (use full day on Sat)	
Reg Date	22-May-2008 (3mths 14days COE left)	
Manufactured	2008	
Mileage	130,500 km (13.4k /yr)	
Transmission	Auto	
Engine Cap	1,584 cc	
Road Tax	\$234 /yr	
Power	79.0 kW (105 bhp) View specs of the Mitsubishi Lancer (2006-2008)	
Curb Weight	1,162 kg	
Features	-	
Accessories	-	
Description	Trade In All Available, Interested Please Call For Viewing, Viewing By Appointment Only	
COE	\$16,500	
OMV	\$12,536	
ARF	\$12,536	
Dereg Value	\$6,734 as of today (change)	
No. of Owners	2	
Type of Veh	Mid-Sized Sedan	
Category	OPC Car, PARF Car	
Availability	Available	

Add to Shortlist

Add to Compare

Add a Note

Posted on: 06-Dec-2017 | Last Updated on: 07-Feb-2018

Tags: Mitsubishi Lancer, 2008 Mitsubishi Lancer, Mitsubishi, Lancer, Used Mitsubishi



Seller Information

Company	Boeki Auto & Marine • dealer's pricelist • 74 vehs sold 74 vehs available
Address	176 Sin Ming Drive #02-15 Search cars nearby this location
Location	Sin Ming Auto Care
Office No	65549390
Contact Person(s)	Boeki 82180500

view used cars | read company profile

Upfront Payment

» more Financial Info

Transfer Fee	\$25	
Down Payment	\$2,456 (change)	Maximum 70% Loan
1st Instalment	\$1,925	
Total Upfront Payment	\$4,406 (excluding insurance)	

Estimates based on 70% loan at 2.98% interest rate. Check with seller for exact figure.



Make sure of this car condition with STA Evaluation

Items for Mitsubishi Lancer

» View All

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9319I
Vehicle Details	
Vehicle No.:	SJD8194G
Vehicle to be Exported:	No
Intended De-registration Date:	07 Feb 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.6 A
Primary Colour:	Red
Manufacturing Year:	2008
Engine No.:	4G18JQ1641
Chassis No.:	JMYSTCS3A8U006852
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$11,940.00
Original Registration Date:	04 Apr 2008
First Registration Date:	04 Apr 2008
Transfer Count:	1
Actual ARF Paid:	\$13,134.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Apr 2018
PARF Rebate Amount:	\$6,567.00
Intended COE Rebate Details	
COE Expiry Date:	03 Apr 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$12,856.00
COE Rebate Amount:	\$200.00
Total Rebate Amount:	\$6,767.00

The information contained herein is correct as at 07 Feb 2018

OK

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2885/02/18

Your Ref:

Date: 6th February 2018

MR KOH GIN THIAM
BLK 230J, #08-673
TAMPINES STREET 21
SINGAPORE 523230

1/5 @ 1500
4 day.

not Authorized
LKK
Tel: 62563581
7/2/18
To be repaid after repair

Estimate cost of repair to MITSUBISHI LANCER 1.6 (A) Saloon - SJD 8194 G

1 pc n/s tail lamp assy	BRU		\$ 421.00	Nett
2 pcs n/s tail lamp clips & stopper	17	@ \$ 5.00 N	10.00	"X"
1 pc rear bumper	no/de		689.00	"X"
8 pcs rear bumper clips	nu	@ \$ 3.80 N	30.40	"X"
1 pc rear bumper n/s side retainer	17		45.00	"X"
1 pc rear bumper n/s top retainer	17		43.00	"X"
10 pcs rear bumper rivets	nu	@ \$ 5.50 N	55.00	"X"
1 pc boot lid 'Lancer' emblem	17		44.00	"X"
1 pc boot lid 'GLX' emblem	17		43.00	"X"
			\$ 1,380.40	Nett
Less 10%			\$ 138.04	
			\$ 1,242.36	
To wiring check up			35.00	20
To remove & refix carpet, floor mat, garnish, floor board cover, wheel guard & necessary parts.			120.00	60
Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear n/s fender, boot lid, rear end panel & necessary parts, to weld, renew & align above parts.			650.00	520
To putty & respray painting on all affected accident parts.			1,000.00	600
			\$ 3,047.36	
			=====	

Dollars :Three Thousand Forty Seven And Cents Thirty Six Only.

1195.4
1075.86
2275.88

HUP MOTOR TRADING & SERVICE

.....

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18002520/URD3N2

Date: 09/02/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/17-985913
Claimant Vehicle No :	SJD8194G	Insured Vehicle No :	FY7642Z
Date of Loss:	05/02/2018	Nature of Claim:	TP
		Claim No:	MSC/V/18-000211

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJD8194G	Engine No:	4G18JQ1641
Make & Model:	MITSUBISHI LANCER, 1.6 (A)	Chassis No:	JMYSTCS3A8U006852
Reg. Date:	04/04/2008 (Man. Year: 2008)	Odometer:	238761 km
Colour:	Red		
Engine Capacity:	1584 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Firenza 5 mm	Rear Left Side:	Firenza 5 mm
Front Right Side:	Firenza 5 mm	Rear Right Side:	Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,242.36	1,075.86	166.50	13.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,805.00	1,200.00	605.00	33.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,047.36	2,275.86	771.50	25.32
Approved Total (Overridden) (S\$)		1,500.00		
Nett Amount (S\$)	3,047.36	1,500.00	1,547.36	50.78

INSPECTION

Date of Assignment:	07/02/2018	
Date Inspected:	07/02/2018	Inspected At: Hup Motor Trading & Service (HQ) Blk 9004 Tampines Street 93, #01-120 Singapore 528838
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 09 Feb 2018)
Parts: 143	mitsubishi LANCER 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJD8194G)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*N/S TAIL LAMP ASSY	Broken	421.00 FN	*421.00 FN
2	2		*N/S TAIL LAMP CLIPS & CTOPPER	Not Necessary	10.00 FN	*- FN
3	1		*REAR BUMPER	Dented/Deformed	689.00 FN	*689.00 FN
4	8		*REAR BUMPER CLIPS	Necessary	30.40 FN	*30.40 FN
5	1		*REAR BUMPER N/S SIDE RETAINER	Not Necessary	45.00 FN	*- FN
6	1		*REAR BUMPER N/S TOP RETAINER	Not Necessary	43.00 FN	*- FN
7	10		*REAR BUMPER RIVETS	Necessary	55.00 FN	*55.00 FN
8	1		*BOOT LID LANCER EMBLEM	Not Necessary	44.00 FN	*- FN
9	1		*BOOT LID GLX EMBLEM	Not Necessary	43.00 FN	*- FN

F=Franchise part. N=NetItemDisc.

Sub Total (\$\$)	1,380.40	1,195.40
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	138.04	119.54
Total Parts (\$\$)	1,242.36	1,075.86

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO WIRING CHECK UP	New	35.00	20.00
2	TO REMOVE & REFIX CARPET,FLOOR MAT,GARNISH,FLOOR BOARD COVER,WHEEL GUARD & NECESSARY PARTS	New	120.00	60.00
3	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS,TO JACK,STRAIGHTEN & KNOCKING OUT REAR N/S FENDER,BOOT LID,REAR END PANEL & NECESSARY PARTS,TO WELD,RENEW & ALIGN ABOVE PARTS	New	650.00	520.00
4	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS	New	1,000.00	600.00
Gross Labour Cost (S\$)			1,805.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >