

TRANS EUROKARS PTE LTD NO:5 UBI CLOSE, SINGAPORE 408605



ESTIMATE COST OF REPAIRS

AXA INSURANCE PTE LTD

NAME:

Mr Seow Khee Choon

61431

8 SHENTON WAY

ADDRESS: 8 Hindhede Place

WIP: **EXCESS:**

#24-01 AXA TOWER

Singapore 587858

DATE: 7-Feb-18

SINGAPORE 068811

ATTN.:

MOTOR CLAIMS

TEL :

FAX:

SBU92A VEH NO:

CONTACT PERSON: DATE IN: MILEAGE: TYPE OF CLAIM:

JESS 6395 7874

CHASSIS NO:

JM6BM4278G0300965

DATE REG.:

POLICY NO. :

THIRD PARTY CLAIM

MODEL:

MAZDA3 2.0L

10-Mar-15

NATURE OF WORKS

	T	Parts Description	<u> </u>		-	
NO		QTY		REVISED	P	RICES
1	FRONT BUMPER	1	MBHR3-50-031BBB		\$	1,031.70
2	RETAINER(LHS), FRONT BUMPER	1	MBHN1-50-0U1E		\$	18.70
3	RETAINER(RHS), FRONT BUMPER	1	MBHN1-50-0T1F		\$	18.70
4	BRACKET(LHS), FRONT BUMPER	1	MBHN1-50-162		\$	15.10
5	BRACKET(RHS), FRONT BUMPER	1	MBHN1-50-152		\$	15.10
6	COVER(RHS), FOGLAMP	1	MBJE1-50-C11A		\$	46.40
7	CHROME(RHS), FOGLAMP	1	MBJE1-50-C12		\$	106.70
8	FRONT REINFORCEMENT	1	MB45A-50-070A		\$	444.50
9	GROMMET, FRONT BUMPER	2	MGHP9-50-0Z5		\$	5.40
10	CLIP, FRONT BUMPER	14	MC274-50-133		\$	49.00
11	FASTENER, FRONT BUMPER	2	MB45A-56-146A		\$	5.60
12	GRILLE TOP	1	MBHN1-50-033 50		\$	335.00
13	RIVET, GRILLE TOP	6	MS51S-51-833		\$	22.80
14	RIVET, GRILLE TOP	4	MTK21-50-355		\$	34.80
15	BRACKET TOP, GRILLE	1	MBHN1-50-717D		\$	102.40
16	CHROME(LHS), FRONT BUMPER	1	MBHN1-50-7K1A		\$	176.70
17	CHROME(RHS), FRONT BUMPER	1	MBHN1-50-7J1A		\$	176.70
18	GRILLE:BLACK (GLOSS)	1	MBJE1-50-712B		\$	581.60
19	MASCOT, FRONT	1	MC235-51-731A		\$	44.20
20	BRACKET(LHS), FRONT BUMPER	1	MBHN1-50-163		\$	15.10
21	BRACKET(RHS), FRONT BUMPER	1	MBHN1-50-153		\$	15.10
22	PIN LOCATOR, GRILLE	2	MKD45-50-1K5A		\$	5.40
23	GROMMET, GRILLE	2	MKD45-50-ES1		\$	5.40
24	RIVET, GRILLE	2	MEA01-50-037		\$	15.20
25	FASTENER, GRILLE	8	MGD7A-50-EA1		\$	24.00
26	PLATE,SET (REINFORCEMENT)	1	MBHN1-50-1C0B		\$	158.40
27	FASTENER, PLATE SET	4	MGD7A-50-EA1		\$	12.00
28	GRILLE,UNDER	1	MBJD6-50-R10A		\$	693.60
29	PLATE,SET (CENTER)	1	MBHN9-50-1C0A		\$	32.40
30	COVER(RHS), HEADLAMP WASHER	1	MBHT4-51-8G1 50		\$	85.10

31	ACTUATOR(RHS), HEADLAMP WASHER	1	MBHT4-51-82X	\$ 242.40
32	CLAMP, ACTUATOR	1	MTK33-51-829	\$ 16.40
33	TANK,WASHER	1	MGHP9-67-481	\$ 104.00
34	HEADLAMP RHS	1	MBHT6-51-031A	\$ 2,245.00
35	CLIP, HEADLAMP	2	MFB01-50-133C	\$ 7.60
36	RIVET, HEADLAMP	1	MB092-51-833	\$ 3.30
37	REAR BUMPER	1	MBPD8-50-221ABB	\$ 1,074.80
38	RETAINER(LHS), REAR BUMPER	1	MBHN1-50-2J1A	\$ 36.10
39	RETAINER(RHS), REAR BUMPER	1	MBHN1-50-2H1A	\$ 36.10
40	BRACKET(LHS), REAR BUMPER	1	MBHN9-51-077B	\$ 45.60
41	BRACKET(RHS), REAR BUMPER	1	MBHN9-51-067B	\$ 45.60
42	BRACKET LOWER, REAR BUMPER	1	MBHR2-50-251A	\$ 23.70
43	BRACKET CENTER, REAR BUMPER	1	MKD53-50-251	\$ 5.10
44	SENSOR,ULTRASONIC	4	MKD47-67-UC1 50	\$ 775.60
45	RETAINER, SENSOR	4	MKD47-67-UC5A50	\$ 69.20
46	TAPE PROTECTOR, SENSOR	3	MGS1D-50-EM1A	\$ 24.30
47	CORD,SHORT (SENSOR)	1	MBHR1-67-290	\$ 153.00
48	REINFORCEMENT REAR	1	MB45A-50-260	\$ 537.30
49	FASTENER, REAR BUMPER	4	MB45A-56-146A	\$ 11.20
50	CLIP, REAR BUMPER	2	MGJ21-50-049	\$ 6.40
51	RIVET, REAR BUMPER	4	MBBM4-50-355	\$ 16.80
52	GROMMET, REAR BUMPER	1	M9991-00-501	\$ 2.80
53	GROMMET, REAR BUMPER	4	MBHN1-50-0Z1A	\$ 10.00
54	REFLECTOR LHS	1	MD350-51-5L0E	\$ 50.40
55	REFLECTOR RHS	1	MD350-51-5M0E	\$ 50.40
56	COVER(LHS), TOWING	1	MBHN1-50-EL1 BB	\$ 15.70
57	COVER(RHS), TOWING	1	MBHN1-50-EK1 BB	\$ 16.20
58	REAR END PANEL	1	MB4YA-70-75Z	\$ 505.10
59	BOOT LID	1	MBHY5-52-61XA	\$ 852.65
60	HINGE(LHS), BOOT LID	1	MB45A-52-720B	\$ 145.40
61	HINGE(RHS), BOOT LID	1	MB45A-52-710B	\$ 145.40
62	WEATHERSTRIP, BOOT LID	1	MBHN1-56-951A	\$ 107.70
63	LOCK, BOOT LID	1	MBHY1-56-82XA	\$ 177.30
64	MAZDA, EMBLEM	1	MBHN1-51-721	\$ 53.40
65	MASCOT, REAR	1	MBHN1-51-730	\$ 74.40
66	SKYACTIV, EMBLEM	1	MBHN1-51-771	\$ 63.60
67	ANTENNA, KEYLESS	1	MKD47-67-6NXA	\$ 105.80
68	CLIP, ANTENNA	1	MKD45-67-6NYA	\$ 2.50
69	GASKET(LHS), TAILLAMP	1	MBHN1-51-163	\$ 20.90
70	GASKET(RHS), TAILLAMP	1	MBHN1-51-153	\$ 20.90
71	FASTENER, TAILLAMP	2	MKD53-51-146B	\$ 7.80
72	GROMMET, TAILLAMP	2	MGJ6A-51-14Y	\$ 29.80
73	GASKET(LHS), BOOT LID LAMP	1	MB45A-51-3J8	\$ 20.90
74	GASKET(RHS), BOOT LID LAMP	1	MB45A-51-3H8	\$ 20.90
75	FASTENER, BOOT LID LAMP	2	MEG21-51-146	\$ 11.80
76	GROMMET, BOOT LID LAMP	2	MGA7B-51-146	\$ 6.20
77	GUARD(LHS), STONE	1	MBHS2-50-4P2	\$ 17.30

78	GUARD(RHS), STO	NE 1	MBHS2-50-4R2			\$	16.50
							40.004.05
			TOTAL PARTS			_	12,324.05
			LESS 10%			\$	1,232.41
			TOTAL PARTS COST			\$	11,091.65
		Labour Descriptio	1			_	
1	MZ-BR-FRONT3	TO REPLACE FRONT BUMPER, FRONT REINFORCEMENT A AREAS AFFECTED BY THE ACCIDENT.	ND GRILLE TOP. REPAIR ALL			\$	2,640.00
2	MZ-SP-SFRT03	TO RESPRAY FRONT BUMPER, FRONT REINFORCEMENT /	AND GRILLE TOP,			\$	2,520.00
3	MZ-BR-REAR05	TO REPLACE REAR BUMPER, REAR REINFORCEMENT, RE LID.REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	AR END PANEL AND BOOT			\$	3,960.00
4	MZ-SP-SREAR5	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, RE	AR END PANEL AND BOOT LID,			\$	3,150.00
5	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	3			\$	350.00
6	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.				\$	250.00
7	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SEC REPAIR ON THE REAR SECTION.	TION TO GIVE WAY TO THE			\$	660.00
8	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.				\$	660.00
9	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.				\$	660.00
10	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTION	ING.			\$	250.00
11	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORK	SS.			\$	350.00
12	MZ-BR-SUNDRI	SUNDRIES.		N	IETT	\$	100.00
	1	h:	TOTAL LABOUR	\$	ħ	\$	15,550.00
			TOTAL PARTS	\$	-	\$	11,091.65
			TOTAL	\$		\$	26,641.65
			LESS EXCESS	\$		\$	2
			TOTAL AFTER EXCESS	\$			
			GST 7%	\$	Ē	\$	ě
			GRAND TOTAL	\$		\$	

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED

TRANS EUROKARS PTE LTD

	Authorised Signature
PRICE AS WELL AS LABOUR CHARGES.	
ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS	
WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid.	
	ACCIDENT STATEMENT
Date Of Report	03/02/2018 19:55
Date Of Accident	03/02/2018 13:15
Exact Location Of Accident	ALONG PIE /CHANGI THOMSON RD
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SBU92A
Insured/Policyholder	
Name Of Registered Owner	SEOW KHEE CHOON
NRIC No	S1493952J
Email Address	SHAWNSJJ92@GMAIL.COM
Mobile Phone No	(LOCAL) +65-92950209
Alternative Phone No	OFFICE-92950209
Vehicle Particulars	
Manufacturer	MAZDA
Model	3 SEDAN 2.0 SPORTS A/T 2WD S/R
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D17MTPV01003017
Cover Note Number	N.A.
Driver	
Name of Driver	SHAWN SEOW JUN JIE
NDIC No.	\$0216772

NRIC No S9216772J
Date Of Birth 12/05/1992
Occupation INDOOR
Date Of Driving Pass 28/12/2012

Driving Experience 5 YEARS AND 1 MONTH

Gender MALE

Mobile Number (LOCAL) +65-92950209

Fax Number

Contact Number OFFICE-92950209

EMail Address SHAWNSJJ92@GMAIL.COM

Address

NII

Postcode

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

CHILDREN

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

NO

Was any body injured in the Accident? Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO 2

Number of Passengers (Including Driver)

Passenger 1

NAME:

: FONG YOKE WAN

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

BUKIT TIMAH NEIGHBOURHOOD POLICE POST

Police Station Address

ROAD: BLK 1 TOH YI DRIVE, POSTCODE: 590001, COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: 1800-4689999 - FAX NO: 64623782

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

ON THE ABOVE MENTIONED DATE, TIME AND LOCATION, I WAS DRIVING MY CAR BEARING REGISTRATION PLATE NUMBER: SBU92A, I WAS DRIVING ON THE 1ST LANE OF A 4 LANE ROAD AT PIE TOWARDS CHANGI. AS I WS DRIVING THE VEHICLE IN FRONT OF ME, BEARING REGISTRATION PLATE NUMBER SHD1G SUDDENLY MADE A BRAKE AS THE VEHICLE IN FRONT OF HIM SLOW DOWN. I FOLLOWED SUIT AND MANAGED TO BRAKE IN TIME. I THEN CHECK MY REAR VIEW MIRROR AND THE CAR BEHIND ME BEARING REGISTRATION PLATE: SCW8330M ALSO DID STOPPED IN TIME. ABOUT A FEW SECONDS LATER, I FELT AND IMPACT FROM THE REAR AND MY CAR MOVE FORWARD AND HIT ONTO THE REAR OF THE TAXI, TRAFFIC POLICE CAME TO MY ACCIDENT SCENE AND ADVISED ME TO LODGE A POLICE REPORT. THERE IS CCTV CAMERA IN THE CAR BUT I AM NOT SURE IF THE CAMERA IS SWITCH ON AT THE MATERIAL MOMENT OF TIME.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SCW8330M

Vehicle Make/Model/Colour

PORSCHE/ MACAN

Details Of Properties

NA

Vehicle Category

PRIVATE CAR

Name of Driver

MR NG

NRIC/Passport Number

Contact Number

96341663

Address

NA

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SLB3902A

Vehicle Make/Model/Colour

KIA/ FORTE K3

Details Of Properties

NA

Vehicle Category

PRIVATE CAR

Name of Driver

UNKNOWN

NRIC/Passport Number

Contact Number

NA

Address

NA

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SDJ8909B

Vehicle Make/Model/Colour

VOLKSWAGEN/ NEW GOLF

Details Of Properties

NA PRIVATE CAR

Vehicle Category Name of Driver

UNKNOWN

NRIC/Passport Number

Contact Number

NA

Address

NA

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number

SHD1G

Vehicle Make/Model/Colour

RENAULT/ LATITUDE

Details Of Properties Vehicle Category

NA TAXI

Name of Driver

MR ANG

NRIC/Passport Number

Contact Number


91012425

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)



POLICE REPORT



Police Station Of Origin: Bukit Timah NPP 1 Toh Yi Drive #01-139 SINGAPORE 591501 Tel No: 1800-4689999



1 013 Report No. T/20180203/2125

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: Vide Report No.: Station Diary No.: 03/02/2018 15:57 31

Informant's Particulars Name of Informant Address: 8 HINDHEDE PLACE SINGAPORE 587858 SHAWN SEOW JUN JIE ID Type / ID No. Contact No. NRIC NO / 89216772J Home/Office Mobile: 92950209 Nationality: Email SINGAPORE CITIZEN Sex Age: 25 Date of Birth; Type of Informant Male 12/05/1992 Driver Race Language: Institution / School Name: Chinese Overseas Occupation: Driving Licence Information Student Class: 3 Date of Expiry:

General Information of the Accident Non-Injury Date/Time of Drink Type of

Attended by Police Drive: Accident: Accident No 03/02/2018 13:15 Type of Location Straight Road

Location Along Road 1 PAN ISLAND EXPRESSWAY

Towards changi. Weather Road Speed Limit Road Surface: Dry Clear Traffic Volume Traffic Control Traffic Flow Moderate Not Controlled Dual Carriage Way Anyone conveyed by Type of Collision. Between Moving Vehicles - Head To Rear ambulance

etails of Vi	hicle Invalve	Make	Model	Color	Contation	No of Passers
ahicte No	133				Sale in	2
BU92A	Car				Damaged	
	Car				Stightly	2
CV/8330M		19190			Slightly	
			· 原原 · 原原		Damaged	
0.18909B		1			Slightly	2
	TAXI				Damaged Stightly	2
HOIG		THE VIEW			Damaged	
SLB3902A	C			See Walle	11 (4) 41	



Police Station Of Origin: **Bukit Timah NPP** 1 Toh Yi Drive #01-139 SINGAPORE 591501 Tel No: 1800-4689999

2013 Report No. T/20180203/2125

CONTINUATION OF REPORT

Brief Details.


Brief Details.

On the above mentioned date, time and location, I was driving my car bearing registration plate number SBU92A. I was driving on the 1st lane of a 4 lane road at PIE towards Changi. As I was driving the vehicle in front of me, bearing registration plate number SHD1G suddenly made a brake as the vehicle in front of him slow down, I followed suit and managed to brake in time. I then check my rear view mirror and the car behind me bearing registration plate SCW8330M also did stopped in time.

About a few parates later, I felt and impact from the rear and my car move forward and hit onto the rear of the taxt. Traffic police came to my accident scene and advised me to lodge a police report. There is CCTV camera in the car but I'm not sure if the camera is switch on at the material moment of time.

camera in the car but I'm not sure if the camera is switch on at the material moment of time.

POLICE REPORT





Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623 Tel: 6461 6555 | Fax: 6221 3302 | Website; www.sompo.com.sg Co. Reg. No.: 198905490E | GST Reg. No.: M200903196

Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER189) MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES,1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA) MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Cert No./Policy No.

D17MTPV01003017

1. Registration No.

SBU92A

2. Insured Name

SEOW KHEE CHOON

3. Commencement Date

10 MARCH 2017 00:00

4. Expiry Date

3 09 MARCH 2018 23:59

5. Coverage

Market value at time of loss - Comprehensive - ExcelDrive PRESTIGE

6. Excess

: \$600 - Section I

(Waived up to S\$1,000 Standard Excess each claim at ExcelDrive Workshops for first two claims

per policy year)

7. Voluntary Excess

· NA

8. Persons or Classes of Persons entitled to drive*

a) The Insured.

The Insured may also drive a motor car other than those belonging to or hired (under a hire purchase agreement or otherwise) to him or his employer or his partner.

b) Any other person who is driving on the Insured's order or with his permission.

c) In the event of the death of the insured

i) any member of the insured's family, or a paid driver who has been driving the car during the life of the insured and permission to drive had not been withdrawn prior to the death of the insured; and

ii) any other person who has been given permission to drive the vehicle prior to the death and such permission had not been withdrawn by the insured.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

9. Limitations as to use*

Use only for social, domestic and pleasure purposes and for the Insured's business.

The Policy does not cover

Use for hire or reward, racing, pace-making, speed testing, reliability trial, the carriage of goods other than samples in connection with any trade or business or use for any purposes in connection with the Motor Trade.

10. ExcelDrive Workshops & Accident Reporting

It is a condition precedent to liability that the Policyholder shall, together with the Motor Vehicle, call at the Company's Accident Reporting Center and report the accident within 24 hours of the accident or by the next working day thereof.

It is compulsory to have the accident repairs to the insured vehicle carried out at ExcelDrive Workshops, or at the manufacturer's or distributor's appointed workshop otherwise claim is not payable. In an emergency and for directions to the Company's Accident Reporting Centers, please contact our Emergency

Hotline: (65) 6226 3323

Visit www.sompo.com.sg for list of ExcelDrive Workshops and Accident Reporting Centers.

11. Loss of Use

As provided in policy wordings.

I/We HEREBY CERTIFY that the policy to which this Certificate relates is issued in accordance with (1) the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia); and (2) the Policy terms, conditions and exceptions of the Private Car Policy ref MTP.26

Sompo Insurance Singapore Pte. Ltd.

Date/Time of Issue: 14 FEBRUARY 2017 10:50

*Limitation rendered inoperative by section 8 of the Motor Vehicles(Third-Parly Risks and Compensation)Act (Chapter 189 and section 95 of the Road Transport Act,1987(Malaysia), are not to be included under these headings.

IMPORTANT NOTICE

1. Insureds are hereby warned that under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap.189), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicles without a valid policy of insurance under the Act.


2. Insureds are further warned that on the sale of a motor vehicle or if for any reason the Insurance is terminated during its currency, they must surrender the Certificate of Insurance and the Policy to the insurance company if the Certificate of Insurance has been lost or destroyed a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation)Act (Cap.189)

3. The Policy will cease to be valid once the motor vehicle has been sold to another person. It is not transferable to a new owner of the Vehicle, Please note that this insurance is subject to the premium being paid and received in full by the Company (a) before the inception date where the Policy is to be issued to an Individual; or (b) within the period specified in the Premium Payment Warranty applied to the Policy in all other instances.

5. Insurance coverage under this Policy is subject to the terms and conditions as stipulated in the Motor Insurance Policy











REPUBLIC OF SINGAPORE IDENTITY CARD NO. \$9216772J





Name

SHAWN SEOW JUN JIE

CHINESE Date of birth 12-05-1992

Country of birth SINGAPORE

S9216772J

4044803

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Motor Cars=< 3000kg with =<7 passengers, exclusive 28 Dec 2012 of the driver; and other motor vehicles =< 2500kg

NP 428A

Date of lesue 18-05-2007

8 HINDHEDE PLACE SINGAPORE 587858