

Kim Chwee Auto Ptd Ltd

1 Kaki Bukit Avenue 6 , #01-46/48/50 , Autobay , Singapore 417883

H/P : 9487 7074 Tel : 6741 7244 , 6746 5405 Fax : 6754 8520,6746 5786

Email : general@fastechauto.com.sg

Not Authorized
LKH
2/5/18 4500
28/2/18
take photo after repair
4 day.

VEHICLE NO:SLN 4854K

QTY	PARTICULAR	AMOUNT S\$
-----	------------	------------

N - ITEM:

1PCS	TAILGATE BOTTOM	994	1,400.00	
1PCS	REAR BUMPER	1478.80	1,680.00	
1PCS	REAR BUMPER REINFORCEMENT	785.65	785.65	
1PCS	REAR BUMPER INNER TOP RE TAINER	106.20	249.20	
1PCS	REAR BUMPER LOWER SKIRTING		650.00	X
1PCS	RAER BUMPER CHROME MOULDING	262.10	280.00	
1PCS	REAR BUMPER LOWER CENTRE GARNISH	352.10	345.00	
2PCS	REAR BUMPER SIDE HOLDERS @ \$115		230.00	X
1SET	REAR BUMPER CLIPS		58.00	
2PCS	REAR BUMPER PDC SENSORS @ \$225		450.00	
1PCS	REAR END PANEL		1,210.00	X
		Σ	TOTAL :	\$7,337.85

4286.85
4262.10

LABOUR CHARGES :

TO CHECK WIRING	\$80.00	20
TO DISMENTLE & REPLACING PDC SENSOR	\$80.00	50
TO SPRAY RUST PROOFING	\$50.00	40
TO DISMENTLE & REFIX SEAT , CUSHION UPHOLSTERY	\$150.00	60
LABOUR FOR PANEL BEATING & REPLACING PARTS	\$680.00	450
TO PUTTY & SPRAY PAINTING	\$1,080.00	800
TOTAL :		\$9,457.85

5682.50
4546

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: