

REF:

CC3 / 12618002536 / Alba

ASSIGNMENT

From _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No. _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

\$800

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

65K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

04/18

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

SKB2931J

Yr Regn: _____

2011 May

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: _____

Audi A5

cc 1798

Colour: _____

Grey.

A/C: Insured / Std / NI / NA

Sp. Reading: _____

200962

Ti Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

WAU2228 TABA015000

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size: _____

F: _____

245/40R18

R: _____

245/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Fullen.

Front

Rear

R/Bal. _____

06

mm

R/Bal. _____

06

mm

L/Bal. _____

06

mm

L/Bal. _____

06

mm

D.O.A. _____

D.O.I. _____

07/02/18

Survey held at _____

Premium

Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

00 AIG.

SKB 2931J - X

8/2- Inform premium authorise repair excess TBA
part by part \$5956.76 (Red: 2485.24, 29%)

RECEIVED 28 MAY 2018

Date/Time, File Pass to?



Preli. Report

1) 28/5 Typist



Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

4

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐

Site Insp (\$ _____)

) \$ + RS \$ _____



Interview (\$ _____)

) Photos _____



Tech. Invs (\$ _____)

) Others _____



Weekend (\$ _____)

)

Report Format: _____


00

Lump Sum / (B): (\$ 5956.76)

TOTAL: _____

200

10





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18002536/Atb

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 08-02-2018



Code : AIG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SKB 2931J
Policy No. 2100258891	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	07/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	19/01/2018	Inspection Date	07/02/2018
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 . SINGAPORE 408699		

5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199807198R GST Reg. No: 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLQ 4197H

INSPECTION



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/01/2018 16:11
Date Of Accident	19/01/2018 11:15
Exact Location Of Accident	50 DAIRY FARM ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKB2931J
Insured/Policyholder	
Name Of Registered Owner	CHEN MING LIEN
NRIC No	S1419949G
Email Address	MLCHEN1960@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-96353846
Alternative Phone No	OFFICE-96353846

Vehicle Particulars

Manufacturer	AUDI
Model	A5 SB 1.8 TFSI MU 8T
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100258891-06000
Cover Note Number	

Driver

Name of Driver	CHEN MING LIEN
NRIC No	S1419949G
Date Of Birth	07/02/1960
Occupation	INDOOR
Date Of Driving Pass	25/01/1983
Driving Experience	34 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96353846
Fax Number	
Contact Number	OFFICE-96353846
Email Address	MLCHEN1960@HOTMAIL.COM

Address	28B POH HUAT ROAD
Postcode	546739
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	SERANGOON GARDENS NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: 51 SERANGOON GARDEN WAY , POSTCODE: 555947 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2879999 - FAX NO: 62815969
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT NO: T20180129/2123

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	UNKNOWN
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to regulate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GI Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name: Liza K. S. Tan
NRIC/IN No.: 98555109M

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Police Report



**SINGAPORE
POLICE FORCE**



1-201801252123

Police Station Of Origin:
Serangoon Gardens NPP
51 Serangoon Garden Way SINGAPORE
555547
Tel No. 1800-2579599

1 of 2

Report No. 1-201801252123

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made 28/01/2018 17:40		Vide Report No.		Station Diary No. 42	
Informant's Particulars					
Name of Informant CHEN MING LIEN		Address: 28B POH HUAT ROAD SINGAPORE 548738			
ID Type / ID No. NRIC NO / S1419848G		Contract No.		Mobile: 98353348	
Nationality SINGAPORE CITIZEN		Email:			
Sex: Male	Age: 57	Date of Birth: 07/02/1960	Type of Informant: Vehicle Owner		
Race: Chinese		Language:		Institution / School Name:	
Occupation: Company director		Driving License Information: Class: 3		Date of Expiry:	

General Information of the Accident

Type of Accident: Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 18/01/2018 11:15	Type of Location:
Location: DAIRY FARM ROAD At 60 Dairy Farm road car park			
Weather:	Road Surface:	Road Speed Limit:	
Traffic Flow:	Traffic Control:	Traffic Volume:	
Type of Collision: Unknown	Anyone conveyed by ambulance: No		

Details of Vehicle Involved

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
SKB2931J	Car					0

Police Report



**SINGAPORE
POLICE FORCE**



7201801342123

Police Station Of Origin:
Serangoon Gardens NPP
51 Serangoon Garden Way SINGAPORE
555947
Tel No: 1800-2878888

2 of 3

Report No: 7201801342123

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65424985 stating the report number as reference.

Signature Of Officer Recording The Report: F / Sgt 2 LIM HAO JIE 	Signature Of Informant: 
Signature Of Informant: Not applicable	Date/Time: 28/01/2018 17:40
Officer In Charge Of Case: TP / HRT / SI ABDUL KAREEM BIN ABDUL HAGUE Contact No : 65476079	Classification Of Case:

Authentication Stamp
VP123

Police Report



SINGAPORE
POLICE FORCE

Police Station Of Origin:
Serangoon Gardens NPS
51 Serangoon Garden Way SINGAPORE
655947
Tel No: 1800-2879999



19012018012502123

2 of 3

Report No: 19012018012502123

CONTINUATION OF REPORT

Brief Details.

On the 19/01/2018 at about 1000hrs, I parked my vehicle SKB2931J at At 50 Dairy Farm road car park and everything is intact.
On the 19/01/2018 at about 1115hrs, I went to my vehicle and I discovered that there was crack on my front car plate, front grill, dent on front bonnet and some scratches on the front area of my vehicle. I do not have any in car camera in my car and I also do not know if there is any CCTV facing my vehicle. Thus, I am lodging this report for the traffic police to investigate.

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1419949G



CHEN MING LIEN

陈明力

Race

CHINESE

Date of Birth

07-02-1960

Sex

M

Country of Birth

SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S1419949G

Name

CHEN MING LIEN

Birth Date: 07 Feb 1960

Issue Date: 04 Nov 2003



2361390



NRIC No: S1419949G

Blood Group: Date of issue

O+ 08-09-1994

289 POH HUAN ROAD

SINGAPORE 546739

NRIC No: S1419949G

Date: 08-09-1994

No: 2627700

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

25 Jan 1983



NP 428A



HOTLINE TEL: (65) 8419 3000
FAX: (65) 6415-3723

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1969 (MALAYSIA)

M.X.1

AUDI AUTO PROTECTOR

CERTIFICATE NO. 2100258891-06000

OWN DAMAGE EXCESS S\$800.00 (1)
WINDSCREEN EXCESS S\$100.00

(for policies with effect from 1st November 2002)

SUM INSURED Market Value
INSURING WITH COE/PARF Yes
SKB2931J

1) VEHICLE REGISTRATION NO.

2) NAME OF INSURED

Chen Ming Lien

3) EFFECTIVE DATE OF THE COMMENCEMENT
OF INSURANCE FOR THE PURPOSES OF THE ACT

14 May 2017

4) DATE OF EXPIRY OF INSURANCE

13 May 2018

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE *
SUBJECT TO AGE CONDITION :All Age Condition

a) The Insured.

b) Any other person who is driving on the Insured's order or with his permission.

This policy will indemnify the insured or any authorised driver only if he/she meets the age conditions:

A Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00, in addition to the Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE *

Use only for social, domestic and pleasure purposes and for the Insured's business.

The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / AUDI AUTHORISED REPAIRERS

1. Audi Customer Service Center - 55 Ubi Road 1 (Tel: 63662323)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501)

4. Ethoz - 30 Bukit Batok Cres (Tel: 66547777) 5. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only

6. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560) 7. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)

8. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)

10. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE Loss Of Use 15 days Replacement Car only for repairs at Audi Customer Service Centre

NAMED DRIVER NA

HIRE PURCHASE COMPANY / EMPLOYER'S LOAN DBS BANK LTD

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 19 Apr 2017

AIG Asia Pacific Insurance Pte. Ltd.

504125-200
PREMIUM LEASING - AP
281 ALEXANDRA ROAD
AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

AUTHORISED REPRESENTATIVE

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0153/2018/JT
Date	:	1-Feb-18

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Chen Ming Lien
Address	:	28B Poh Huat Road
		Singapore 546739
Telephone	:	HP +65 9635 3846
Type of Claim	:	Own Damage Claims
Policy No.	:	2100258891-06000
Vehicle No	:	SKB 2931 J
Model Code	:	Audi A5 SB 1.8 TFSI Mu
Model / Year	:	May-11
Engine No	:	CDH 104517
Chassis No	:	WAUZZZ8T4BA015000
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	19-Jan-18
Place of Accident	:	50 Dairy Farm Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKB 2931 J.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlamps, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To remove front fittings, dismantle and renew front bumper, radiator grille. Dismantle and renew bonnet, inspect and re-organize frontal crash management components. Renew both wheel arch trim.	\$ 1,500.00 1000 ✓	
3	To respray front bumper and bonnet.	\$ 1,500.00 1100 ✓	
4	To carry out diagnostic checks.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>3,552.00</u>	

100

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SKB 2931 J.**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Rehnd</i>	\$ 1,584.00	✓ 1267.70
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 222.00	✓
3	RADIATOR GRILLE <i>crushed</i>	\$ 607.00	✓ 485.70
4	FRONT REINFORCEMENT BEAM <i>new</i>	TBC	new ✓
5	REINFORCEMENT TOP COVER <i>new</i>	\$ 84.00	new ✓
6	FRONT BUMPER TOP COVER <i>crushed</i>	\$ 109.00	✓ 87.20
7	BONNET <i>Rehnd</i>	\$ 1,753.00	✓ 1402.40
8	BONNET SEAL <i>new</i>	2 \$ 48.00	✓ 37.96
9	BONNET CATCH <i>new</i>	\$ 122.00	+
10	BONNET SWITCH <i>new</i>	TBC	+
11	BONNET BUFFER	2 \$ 36.00	✓
12	FRONT NO. PLATE <i>Bent</i>	S/N \$ 25.00	✓
13	SUNDRIES <i>?</i>	\$ 300.00	? 25.00X
TOTAL SPARE PARTS CHARGES		\$ 4,890.00	
TOTAL LABOUR CHARGES		\$ 3,552.00	
GRAND TOTAL		\$ 8,442.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adnan Ly
Surveyed Date : 07/02/18.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 0\$ Reps.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:


Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0136/2018/JT
Date	:	1-Feb-18

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

4 days - ok - jb - 19 Apr 18

Attn: Mr. Adrian Ling - Motor Claims Dept


Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Chen Ming Lien
Address	:	28B Poh Huat Road
		Singapore 546739
Telephone	:	HP +65 9635 3846
Type of Claim	:	Own Damage Claims
Policy No.	:	2100258891-06000
Vehicle No	:	SKB 2931 J
Model Code	:	Audi A5 SB 1.8 TFSI Mu
Model / Year	:	May-11
Engine No	:	CDH 104517
Chassis No	:	WAUZZZ8T4BA015000
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	19-Jan-18
Place of Accident	:	50 Dairy Farm Road

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Sketch Plan

(A) SJJ 9961X (B) SJC 902M 	ECP towards Changi <div style="border: 1px solid black; padding: 2px; display: inline-block;">B</div> <div style="border: 1px solid black; padding: 2px; display: inline-block;">A</div>	
---	--	--

Describe Circumstances of the Accident

On 21/9/2012 at about 2230hrs. while I was driving my motor vehicle SJJ 9961X at the extreme right lane of ECP towards Changi. Suddenly the vehicle B SJC 902M (which was in front of me) stopped. I try to avoid the collision but fail. Both vehicles collided together. Both vehicles have a passenger at the time of accident. No one was injured.

Declaration

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature / Date & Time


 Driver's Signature (If driver is not the policyholder) / Date & Time


 Witnessed by Reporting Centre Personnel

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKB 2931 J.

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlighs, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$	360.00	\$ 360.00 ✓
2	To remove front fittings, dismantle and renew front bumper, radiator grille. Dismantle and renew bonnet, inspect and re-organize frontal crash management components. Renew both wheel arch trim.	\$	1,500.00	\$ 1,000.00 ✓
3	To respray front bumper and bonnet.	\$	1,500.00	\$ 1,100.00 ✓
4	To carry out diagnostic checks.	S/N \$	192.00	\$ 192.00 ✓
TOTAL LABOUR CHARGES		:	<u>\$ 3,552.00</u>	<u>\$ 2,652.00</u>

Accident Photo



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SKB 2931 J.**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 1,584.00	\$ 1,267.20
2	FRONT BUMPER FIXING PARTS	\$ 222.00	
3	RADIATOR GRILLE	\$ 607.00	\$ 485.20
4	FRONT REINFORCEMENT BEAM	TBC	
5	REINFORCEMENT TOP COVER	\$ 84.00	
6	FRONT BUMPER TOP COVER	\$ 109.00	\$ 87.20
7	BONNET	\$ 1,753.00	\$ 1,402.40
8	BONNET SEAL	2 \$ 48.00	\$ 37.76
9	BONNET CATCH	\$ 122.00	
10	BONNET SWITCH	TBC	
11	BONNET BUFFER	2 \$ 36.00	
12	FRONT NO. PLATE	S/N \$ 25.00	\$ 25.00
13	SUNDRIES	\$ 300.00	
TOTAL SPARE PARTS CHARGES		\$ 4,890.00	\$ 3,304.76
TOTAL LABOUR CHARGES		\$ 3,552.00	\$ 2,652.00
GRAND TOTAL		\$ 8,442.00	\$ 5,956.76

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Accident Photo



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Accident Photo



Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SKB 2931 J

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0153/2018/MAS

23 May 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SKB 2931 J, Audi A5 SB 1.8 TFSI Mu

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

With reference to the above-mentioned vehicle, no. **SKB 2931 J**, claimant, **Mr. Chen Ming Lien**, please find the related document per attached.

1. A copy of the Original invoice no. 85012522 – S\$5,517.73
2. A copy of the Discharge Voucher duly signed by client.

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SKB 2931 J



Premium Automobiles Pte Ltd

Audi Centre Singapore

21 Alexandra Road
Singapore 159938
Main Telephone: 6386 2223
Main Telefax: 6471 2733

Alexandra Service Centre

281 Alexandra Road
Singapore 159938
Telephone: 6386 2223
Telefax: 6475 1023

Ubi Service Centre

55 Ubi Road 1
Singapore 408929
Telephone: 6386 2223

Customer Service

Service Appointment: 6386 2223
24-hour Breakdown Service: 9628 1233
Email: customer.care@premiumauto.com.sg

Page 2 14:18

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85012522
Date: 21/05/2018
Order: SKB2931J
Term: 30

Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SKB2931J (V 13501)

Regn Date: 14/05/2011

Mileage: 204595

WIP No.: 54162

Model: A5 S8 1.8 TFSI MU 8TA02H

Chassis: WAUZZZ8T48A015000

Engine: CDH104517

Dept: U

VSB No.:

You have been assisted by :- UB-Carrine (33)

		Details		Qty	Unit Price	Amount
X	A8T0807081A	COVER	Less 020%	1.00	109.00	87.20
X	A8T0823029D	HOOD	Less 020%	1.00	1753.00	1,402.40
X	A8T0807105A GRU	BUMPER	Less 020%	1.00	1584.00	1,267.20
X	A8T0823126D	EDGING	Less 020%	2.00	23.60	37.76

Parts 3,279.76
Labour 0.00
Sublet 2,677.00
Menus 0.00
Lubricant 0.00

Sub-Total 5,156.76

7% GST 368.97

Grand Total 5,517.73



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SKB 2931 J

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0153/2018/GW
24 March 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A5 SB 1.8 TFSI Mu
Vehicle Chassis No. : WAUZZZ8T4BA015000
Vehicle Regn No. : **SKB 2931 J**
Vehicle Mileage : 204595KM
Vehicle Owner : Mr. Chen Ming Lien
Certificate No : 2100258891-0600
Policy Excess : **S\$856.00** (inclusive 7% GST)
Accident Date : 19th January 2018
Place : 50 Dairy Farm Road
Repair Cost : \$ 5,517.73
WIP No. : **54162**
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time :
Date : 24/03/18

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1419949G



CHEN MING LIEN

陈明力

Race:

CHINESE

Date of Birth

07-02-1960

Sex

M

Country of Birth

SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S1419949G

Name:

CHEN MING LIEN


Birth Date: 07 Feb 1960

Issue Date: 04 Nov 2003



2381380

NRIC No: S1419949G



Blood Group: Date of issue

O+

08-09-1994

788 POH HSIAT ROAD
SINGAPORE 546739

NRIC No: S1419949G

Date: 08-09-1994 No: 2627700

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of
which unladen does not exceed 2500 kilograms

25 Jan 1983



NP 428A



HOTLINE TEL: (65) 6419 3000
FAX: (65) 6415-3723

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.X.1

AUDI AUTO PROTECTOR

CERTIFICATE NO. 2100258891-06000

OWN DAMAGE EXCESS S\$800.00 (1)

WINDSCREEN EXCESS S\$100.00

(for policies with effect from 1st November 2002)

SUM INSURED Market Value
INSURING WITH COE/PAF Yes
SKB2931J

1) VEHICLE REGISTRATION NO.

2) NAME OF INSURED

Chen Ming Lien

**3) EFFECTIVE DATE OF THE COMMENCEMENT
OF INSURANCE FOR THE PURPOSES OF THE ACT**

14 May 2017

4) DATE OF EXPIRY OF INSURANCE

13 May 2018

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE *
SUBJECT TO AGE CONDITION :All Age Condition

a) The Insured.

b) Any other person who is driving on the Insured's order or with his permission.

This policy will indemnify the insured or any authorised driver only if he/she meets the age conditions.

A Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00, in addition to the Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE *

Use only for social, domestic and pleasure purposes and for the Insured's business.

The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / AUDI AUTHORISED REPAIRERS

1. Audi Customer Service Center - 55 Ubi Road 1 (Tel: 63662323)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgro Engry - 205 Braddell Rd (Tel: 63837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501)

4. Eihoz - 30 Bukit Batok Crest (Tel: 66547777) 5. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only

6. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560) 7. Lai Hunt (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)

8. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)

10. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE Loss Of Use 15 days Replacement Car only for repairs at Audi Customer Service Centre

NAMED DRIVER NA

HIRE PURCHASE COMPANY / EMPLOYER'S LOAN DBS BANK LTD

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 19 Apr 2017

AIG Asia Pacific Insurance Pte. Ltd.

504125-200
PREMIUM LEASING - AP
281 ALEXANDRA ROAD
AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

AUTHORISED REPRESENTATIVE

ORIGINAL

SIGNIFY

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Feb 2018		08 Feb 2018 11:52 Edit Adj Rpt	S\$5,956.76 Edit Estimates	S\$5,956.76 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS

Insured: **CHEN MING LIEN**, ID: S1419949G, Tel: +6596353846, Email: MLCHEN1960@HOTMAIL.COM

Vehicle Reg. No.: **SKB2931J**

Claim Type: **OD / 7785623003SG**

Repairer: **Premium Automobiles Pte Ltd (UBI)** 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911

Handling Insurer: **AIG Asia Pacific Insurance Pte. Ltd. (SG)** - Tel: 65-6419-3000 ... [Handled by **Loo, Tong Shing**] TongShing.Loo@aig.com

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **ADRIAN LING**] ... **[Final Rpt due 20/02/2018]**

Driver/Custodian: **CHEN MING LIEN (57 / Male)**, NRIC: S1419949G, Tel: +6596353846

Date of Loss: 19/01/2018 11:00 - :59
[80 Months and 5 Days From LTA Reg Date (Man Yr)]

Policy/Cover Note No.: 2100258891-06000 (Comprehensive)

Excess: S\$800.00

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- AIG_SG (09/02/2018): **SKB2931J / OD / 19/01/2018 / Coverage & Excess update**

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKB2931J (7785623003SG)

OD

Jan 19 2018 11:15AM

















[CHEN MING LIEN]

Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail			Print		
1	16/05/18 01:22	Front View													1	Load JPG		<input checked="" type="checkbox"/>		
2	16/05/18 01:22	Front View													1	Load JPG		<input checked="" type="checkbox"/>		
3	16/05/18 01:22	Front View													1	Load JPG		<input checked="" type="checkbox"/>		
4	16/05/18 01:22	Front View													1	Load JPG		<input checked="" type="checkbox"/>		
5	16/05/18 01:22	Front View													1	Load JPG		<input checked="" type="checkbox"/>		
6	16/05/18 01:22	Front View													1	Load JPG		<input checked="" type="checkbox"/>		
7	16/05/18 01:22	Front View													1	Load JPG		<input checked="" type="checkbox"/>		
8	16/05/18 01:22	Front View													1	Load JPG		<input checked="" type="checkbox"/>		
9	16/05/18 01:22	Front View													1	Load JPG		<input checked="" type="checkbox"/>		
10	16/05/18 01:22	Front View													1	Load JPG		<input checked="" type="checkbox"/>		
11	16/05/18 01:22	Front View													1	Load JPG		<input checked="" type="checkbox"/>		
12	16/05/18 01:22	Front View													1	Load JPG		<input checked="" type="checkbox"/>		
13	16/05/18 01:22	Front View													1	Load JPG		<input checked="" type="checkbox"/>		
14	16/05/18 01:22	Front View													1	Load JPG		<input checked="" type="checkbox"/>		
15	16/05/18 01:22	Front View													1	Load JPG		<input checked="" type="checkbox"/>		
16	16/05/18 01:22	Front View													1	Load JPG		<input checked="" type="checkbox"/>		
17	16/05/18 01:22	Front View													1	Load JPG		<input checked="" type="checkbox"/>		
18	16/05/18 01:22	Front View													1	Load JPG		<input checked="" type="checkbox"/>		
19	16/05/18 01:22	Front View													1	Load JPG		<input checked="" type="checkbox"/>		
20	16/05/18 01:22	Front View													1	Load JPG		<input checked="" type="checkbox"/>		
21	16/05/18 01:22	Front View													1	Load JPG		<input checked="" type="checkbox"/>		
22	16/05/18 01:22	Front View													1	Load JPG		<input checked="" type="checkbox"/>		
23	16/05/18 01:22	Front View													1	Load JPG		<input checked="" type="checkbox"/>		
24	16/05/18 01:22	Front View													1	Load JPG		<input checked="" type="checkbox"/>		
25	16/05/18 01:22	Front View													1	Load JPG		<input checked="" type="checkbox"/>		
26	16/05/18 01:22	Front View													1	Load JPG		<input checked="" type="checkbox"/>		
Documentation															1 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail			Print		
1	08/02/18 17:15	Certificate of Insurance													1	Load PDF				
2	08/02/18 17:15	Driver's Driving License													1	Load PDF				
3	08/02/18 17:15	ESTIMATE													1	Load PDF				
4	08/02/18 17:15	Singapore Accident Statement													1	Load PDF				
5	08/02/18 17:15	Police Report													1	Load PDF				
6	01/06/18 11:08	Workshop Invoice													1	Load PDF				
7	01/06/18 11:08	Discharge Voucher													1	Load PDF				

Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	31/01/18 11:13	Accident Statement	 Load HTM	<input checked="" type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	30/01/18 16:49	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	30/01/18 16:49	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	30/01/18 16:49	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	30/01/18 16:49	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	30/01/18 16:49	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	30/01/18 16:49	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	30/01/18 16:49	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	30/01/18 16:49	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	30/01/18 16:49	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	30/01/18 16:49	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	31/01/18 11:09	Police Report	 Load JPG	<input checked="" type="checkbox"/>
12	31/01/18 11:09	Police Report	 Load JPG	<input checked="" type="checkbox"/>
13	31/01/18 11:09	Police Report	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	31/01/18 11:06	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	31/01/18 11:06	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18002536/ATBE2

Date: 01/06/2018

REFERENCE

Insured/Claimant: CHEN MING LIEN Policy No: 2100258891-06000
Date of Loss: 19/01/2018 Nature of Claim: OD Claim No: 7785623003SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKB2931J**
Make & Model: AUDI A5, 1.8 SPORTSBACK TFSI MU (A) Engine No: CDH104517
Reg. Date: 14/05/2011 (Man. Year: 2010) Chassis No: WAUZZZ8T4BA015000
Colour: Grey Odometer: 200962 km
Engine Capacity: 1798 cc
Market Value/New Car Price: S\$65,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,890.00	3,304.76	1,585.24	32.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,552.00	2,652.00	900.00	25.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,442.00	5,956.76	2,485.24	29.44
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	7,642.00	5,156.76	2,485.24	32.52
+ GST 7.00/7.00% (S\$)	534.94	360.97	173.97	32.52
Nett Amount (S\$)	8,176.94	5,517.73	2,659.21	32.52

INSPECTION

Date of Assignment: 08/02/2018

Date Inspected: 07/02/2018 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,584.00 FS	*1,267.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	222.00 FS	*- FS
3	1		*RADIATOR GRILLE	Cracked	607.00 FS	*485.20 FS
4	1		*FRONT REINFORCEMENT BEAM (NPA)	Not Necessary	0.00 FS	*- FS
5	1		*REINFORCEMENT TOP COVER	Not Necessary	84.00 FS	*- FS
6	1		*FRONT BUMPER TOP COVER	Cracked	109.00 FS	*87.20 FS
7	1		*BONNET	Dented	1,753.00 FS	*1,402.40 FS
8	2		*BONNET SEAL	Necessary	48.00 FS	*37.76 FS
9	1		*BONNET CATCH	Not Necessary	122.00 FS	*- FS
10	1		*BONNET SWITCH (NPA)	Not Necessary	0.00 FS	*- FS
11	2		*BONNET BUFFER	Not Necessary	36.00 FS	*- FS
12	1		*FRONT NO. PLATE	Bent	25.00 FS	*25.00 FS
13	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 4,890.00 3,304.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE FRONT FITTINGS, DISMANTLE AND RENEW FRONT BUMPER, RADIATOR GRILLE. DISMANTLE AND RENEW BONNET, INSPECT AND RE-ORGANIZE FRONTAL CRASH MANAGEMENT COMPONENTS. RENEW BOTH WHEEL ARCH TRIM	New	1,500.00	1,000.00
3	TO RESPRAY FRONT BUMPER AND BONNET	New	1,500.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (\$\$)			3,552.00	2,652.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

