

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: CLMOMVP000000083

Date: 06th April 2018

Our Ref: CS1/GAI18002563/Dtbs2

M/s Great American Insurance Company

3 Temasek Avenue #16-01 Centennial Tower Singapore 039190 (The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO.: SBS 8601P INSURED VEHICLE NO: SDN 8988B ACCIDENT ON 28.08.2016

We thank you for your instruction on 07/02/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SBS 8601P from M/s Vicom Ltd.
- b) Singapore Accident Statement of Vehicles SDN 8988B.
- c) Colour damaged vehicle photographs of SBS 8601P.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number

: SBS 8601P

Make & Mode

: Scania KUB4X2 9.3L A/T ABS

Year of Registration

: 2009

Chassis Number

: YS2K4X20001863431

Engine Capacity

: 9290 cc



51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

- Our finding is that the repair cost of \$7,799.50 (before GST) quoted by M/s SBS Transit Ltd (Branch) is fair & reasonable.
- We recommend that the repairs of the entire damage require about <u>8 (Eight)</u> working days to complete.

Vehicle Inspection By:

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B. Eng, AMS DE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser