

INS. CASE OWNER

CC 3 / AIG1800 *type SIM*

Surveyor:

[Handwritten signature]

ASSIGNMENT

DIAC

DOI: 06/02/18

Date / Time: 06/02/18

Registered in Merimen: 08/02/18

Pre-assign / CCU / FTE



Insured Vehicle No. : SJT 7135A

Name of Insured : TRUCKE WONG RICHY A WONG MAT

Insured Tel No. :

HP:

D.O.A. : 05/02/18

Claim No. : 3398246154

Policy No. :

Make / Model :

Place of Accident :

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident :

If NO, Driver Name / Age:

Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability :

Final ? Yes / No

SHD 6187P



INSRS: WSP: Tel: Liability: RMKS:

SMT



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

Date/Time	STAGE	DATE / PIC
17/1/18	Non-Reporting ltr (1st): Non-Reporting ltr (2nd): Non-Reporting ltr (Final): Notification ltr (if non-pickup): Call OI: After call ltr to OI:	
19/3/18 @ 9:50	Documentation Check List: Handler Typist Notification ltr (if non-pickup): After call ltr to OI: Authorisation To Act: Release Voucher: Final Repair Bill: Car Rental Invoice: Towing Invoice LTA / GIA : Medical Bill: PIR: Mandate/Reject Instruction: LOD Payment Breakdown Form: Post-Repair Photos: Others:	

SHD 6187P - W SJT 7135A - Y
- NO VI GIA, SENT WIT 2ST LETTER.

Private settlement done.

Rec'd payment cheque from OI

Not require to type reports. To be cancel case in Merimen.

RECEIVED: 2 MAR 2018

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____
Repair Cost: \$ (days) Reduction: % Email Call

GLOBAL SETTLEMENT Date/Time: _____ Confirm with: _____ Email Call
Liability: % (Agreed / Assessed) BOLA S/N No. : _____ If NO or B 28, Ass. Lia : _____
Repair Cost: \$
Rental (LOR): \$ (days)
Use (LOU): \$ (\$ x days)
Income (LOI): \$ (\$ x days)
 LOU only LOR + LOU LOR + LOI [Tick only one]
Search: \$
\$
\$ (e.g. Tow/ Independent)
\$ Global Sum \$: _____

AGENT Date/Time: _____ Confirm with: _____ Email Call
Name 1: _____
Name 2: _____
Name 3: _____

1) Claim status: Normal/Reject/Private Settle
2) Report Format:
3) Survey fee: \$ 320/-

COMMENT

Structure

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHD 6187P Yr Regn: 23/19/2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius c.c 1798

Colour: Maroon A/C: Insured / Std / NI / NA

Sp. Reading: 470476 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: J70KW 364 3057 6693

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 19 5/65 R15

R: 4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 5/2/18 D.O.I. 6/2/18

Survey held at SMART

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

549780 IBB Red (B 3,773.31 / 4%) THX / 02/18 / 2022 LKK AIG

Date/Time, File Pass to? : Prel. Report

1) : Final Report

Date/Time, File Return to?

2) _____

Report Format :

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: : Site Insp (\$ _____) \$ + RS \$ _____

: Interview (\$ _____) Photos

: Tech. Invs (3) Charts

: Weekend (\$ _____)

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG18002564/Syb3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 08-02-2018	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJT 7135A	Veh. Inspected	SHD 6187P
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	08/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	05/02/2018	Inspection Date	06/02/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18002211/Aea3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 05-02-2018	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJM 5736R	Veh. Inspected	SKU 2001T
Policy No.		Coverage (\$)	0.00
Claim No.	S8M008CD	Excess (\$)	0.00
Assign From		Assign Date	05/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	31/01/2018	Inspection Date	08/02/2018
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 . SINGAPORE 408699		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



10-2-18 / 10:58


10-2-18 / 14:58

6-2-18 / 14:58


SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHD6187P
 Ref. No : TAX/02/18/2022
 Reg. Date : 23/10/2015
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : GOH CHENG KIAT
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 05/02/2018 05:16:00 AM
 Accident Reported Date / Time : 05/02/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : Sebastian
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 05/02/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094474
 Special Instruction to ARC, if any :
 TOWED \$40 / SJT7135A *Alk P/P*
 BEFORE PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR SEBASTIAN (LKK)
 & Email : sebastianyeang@lkkauto.com HP:90038121
 Prepared Date : 05/02/2018 11:45:08 AM



470 474 km



Recording Camera
 Radio Antenna
 1st witness M Date 6-2-18
 2nd witness _____ Date _____

Supplementary
+ Refer to other Supplementary part 164

QC 12/2/18 14:37 P455

LEE SHENG AUTO PTE LTP

Vehicle Return Date: 12/2/18

Vehicle Return Time: 13:33

SMRT staff sign: _____

470838

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U305788443 Mileage : 0

Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,183.00	800.00
Total Spray Painting Charges	: 1,296.00	700.00
Total Material Charges	: 5,632.11	3,557.80
Other Charges	: 1,160.00	440.00
TOTAL	: 9,271.11	5,497.80
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 7.00	6.00 ✓
Prepared / Adjusted By	:	SEBASTIAN (LKK)
Arc / Surveyor Sing Off Date	: 05/02/2018 03:37:06 AM	06/02/2018 02:58:14 AM

F

LKK

Prepared / Adjusted Date :

Remarks :

Prepared Date : 05/02/2018 03:38:41 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No	: QN-1803-0009	Invoice No	:
Quotation Date	: 1/3	Invoice Date	:
Invoice Amount	: 0.00	Prepared Date	: 2/5/2018 3:38:57 PM

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,183.00	800.00 /
Total Labour	1,183.00	800.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	378.00	200.00 /
TO RESPRAY REAR PANEL	180.00	100.00 /
TO RESPRAY TAIL GATE	378.00	200.00 /
TO RESPRAY REAR SPARE TYRE PANEL	180.00	100.00 /
TO RESPRAY BUMPER BEAM	180.00	100.00 /
Total Spray Painting & Panel Beating	1,296.00	700.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	80.00 /
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO REMOVE & REFIT EXHAUST	120.00	50.00 /
TO TRANSFER REAR TAILGATE MECHANISM	120.00	60.00 /
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	120.00 /
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00 /
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30.00 /
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	50.00 /
TO REPLACE SUNDRY PARTS	100.00	20.00 /
TO WASH AND VACUUM	80.00	0.00
Total Other Costs	1,160.00	440.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached	
52150-47905		8505548	BUMPER REAR	1	458.80	25.00	343.95	Replace	Replace	No	Defect
52161-16010			BUMPER CLIPS	10	1.61	25.00	12.07	Replace	Replace	No	NEC
76088-47020		8505617	BUMPER LIP COVER RR/LH	1	72.20	25.00	54.15	Replace	Replace	No	Defect
76087-47020		8505618	BUMPER LIP COVER RR/RH	0	118.10	25.00	0.00	Replace	Not given	No	X aw
76891-47020		8505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace	No	Defect
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No	Defect
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No	NEC
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace	No	BT
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.80	25.00	104.70	Replace	Replace	No	BT
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.80	25.00	104.70	Replace	Replace	No	BT
52592-47021			BUMPER SEAL, RR LH	1	88.90	25.00	66.65	Replace	Check	No	X aw
52591-47021			BUMPER SEAL, RR RH	1	65.70	25.00	49.28	Replace	Check	No	X aw
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace	No	CRK
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace	No	CRK
67005-47241			TAILGATE ASY	1	1,007.90	25.00	755.92	Replace	Replace	No	BT
75574-47020			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	25.00	22.05	Replace	Replace	No	
75573-47080			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	25.00	22.05	Replace	Replace	No	
75575-47030			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	25.00	22.05	Replace	Replace	No	NEC
	COMMO N		SEALANT W/SCREEN	3	37.00	0.00	111.00	Replace	Replace	No	
89350-47030			TAILGATE DOOR LOCK	1	444.10	25.00	333.07	Replace	Replace	No	IM
89415-47020			TAILGATE LOCK, COVER	1	15.70	25.00	11.78	Replace	Check	No	X aw
87881-47022			TAILGATE DOOR WEATHER STRIP	1	353.40	25.00	265.05	Replace	Replace	No	Defect
89431-47010			STRIKER, BACK DOOR	0	48.90	25.00	0.00	Replace	Not given	No	X aw
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No	NEC
58306-47011			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	25.00	385.88	Replace	Check	No	X aw
58307-47060		6505522	END PANEL	1	602.10	25.00	451.58	Replace	Replace	No	BT
64718-4703180			END PANEL COVER, DECK TRIM HOLE	1	46.10	25.00	34.57	Replace	Replace	No	Defect
64716-4703180			END PANEL COVER, DECK TRIM, RR	1	121.10	25.00	90.82	Replace	Replace	No	Defect

Part Number	Quantity	Unit Price	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
58416-47030B3			BOX, RR FLOOR, BOARD	1	679.60	25.00	509.70	Replace	Check	No X
64993-47020			BOX, DECK FLOOR, RR	1	649.70	25.00	487.28	Replace	Check	No X
58311-47071		6505523	SPARE TYRE PANEL	1	667.70	25.00	500.78	Replace	Check	No X
58336-12090			REINFORCEMENT, RR	1	34.60	25.00	25.95	Replace	Check	No X
	COMMON	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Check	No X
52582-47010			TAIL LAMP BRACKET, RH	1	30.70	25.00	23.03	Replace	Replace S	No /
17430-37380			EXHAUST TAIL PIPE	1	656.20	100.00	0.00	Replace	Repair	No K
TOTAL MATERIALS								5,632.15	3,557.80	
TOTAL MATERIALS(Discounted)								5,632.11	3,557.80	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

+ 3557.80 /
 + 800.00 /
 + 1140.00 /

 5497.80 /

Sebastian
 1/7/18

SMRT Accident Vehicle Repair Estimates

A19

6/2/18

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHD6187P
 Ref. No : TAX/02/18/2022
 Reg. Date : 23/10/2015
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : GOH CHENG KIAT
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 05/02/2018 05:15:00 AM
 Accident Reported Date / Time : 05/02/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 05/02/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094474
 Special Instruction to ARC,if any :
 TOWED \$40 / SJT7135A
 Prepared Date : 05/02/2018 11:45:06 AM



*Sebastian
6/2/18.*

- Part by part repair.
- Question mark Items Photo
- Photo Before Paint.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Section C - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U305766443

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	1,183.00	0.00
Total Spray Painting Charges :	1,116.00	0.00
Total Material Charges :	6,249.46	6,249.46
Other Charges :	1,160.00	0.00
TOTAL :	9,708.46	0.00
Lum Sum Total :	0.00	0.00
No. of Repair Days :	7.00	0.00
Prepared / Adjusted By :		<i>G. Long</i>
Arc / Surveyor Sign Off Date :	05/02/2018 03:37:06 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 05/02/2018 03:36:41 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount : 0.00	Prepared Date : 2/5/2018 3:38:57 PM

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,183.00	0.00 600
Total Labour	1,183.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 260
TO RESPRAY REAR PANEL	180.00 ?	0.00
TO RESPRAY TAIL GATE	378.00	0.00 200
TO RESPRAY REAR SPARE TYRE PANEL	180.00 ?	0.00
Total Spray Painting & Panel Beating	1,116.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	0.00 ✓
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 ✗ X
TO REMOVE & REFIT EXHAUST	120.00	0.00 50
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 60
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	0.00 120
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 30
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 50
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	1,160.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
i2159-17905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace	No
i2161-6010			BUMPER CLIPS	10	1.61	25.00	12.07	Replace	Replace	No
6088-7020		6505617	BUMPER LIP COVER RR/LH	1	72.20	25.00	54.15	Replace	Replace	No
6087-7020		6505618	BUMPER LIP COVER RR/RH	1	118.10	25.00	88.57	Replace	Replace	No
6891-7020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No
2023-2240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace	No
2016-7030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Replace	No
2015-7050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace	No
2592-7021			BUMPER SEAL, RR LH	1	88.90	25.00	66.67	Replace	Replace	No
2591-7021			BUMPER SEAL, RR RH	1	65.70	25.00	49.27	Replace	Replace	No
2576-7020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace	No
2575-7020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace	No
7005-7241			TAILGATE ASY	1	1,007.90	25.00	755.92	Replace	Replace	No
5574-7020			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	25.00	22.05	Replace	Replace	No
5573-7080			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	25.00	22.05	Replace	Replace	No
5575-7030			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	25.00	22.05	Replace	Replace	No
	COMMO N		SEALANT W/SCREEN	3	37.00	0.00	111.00	Replace	Replace	No
1350-030			TAILGATE DOOR LOCK	1	444.10	25.00	333.07	Replace	Replace	No
1415-020			TAILGATE LOCK, COVER	1	15.70	25.00	11.77	Replace	Replace	No
881-022			TAILGATE DOOR WEATHER STRIP	1	353.40	25.00	265.05	Replace	Replace	No
431-010			STRIKER, BACK DOOR	1	48.90	25.00	36.67	Replace	Replace	No
374-051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No
308-011			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	25.00	385.87	Replace	Replace	No
307-060		6505522	END PANEL	1	602.10	25.00	451.57	Replace	Replace	No
718-03180			END PANEL COVER, DECK TRIM HOLE	1	46.10	25.00	34.57	Replace	Replace	No
716-03180			END PANEL COVER, DECK TRIM, RR	1	121.10	25.00	90.82	Replace	Replace	No

Number			Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
18416-17030B3		BOX, RR FLOOR, BOARD	1	679.60	25.00	509.70	Replace	Replace	No ?
14993-17020		BOX, DECK FLOOR, RR	1	649.70	25.00	487.27	Replace	Replace	No ?
18311-17071	6505523	SPARE TYRE PANEL	1	667.70	25.00	500.77	Replace	Replace	No ?
18336-2090		REINFORCEMENT, RR	1	34.60	25.00	25.95	Replace	Replace	No ?
	COMMODITY N 4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace	No ?
12562-7010		TAIL LAMP BRACKET, RH	1	30.70	25.00	23.02	Replace	Replace	No ?
17430-17380		EXHAUST TAIL PIPE	1	656.20	25.00	492.15	Replace	Replace	No R
TOTAL MATERIALS							6,249.55	6,249.46	
TOTAL MATERIALS(Discounted)						6,249.46	6,249.46		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHD6187P
Vehicle to be Exported:	No
Intended De-registration Date:	08 Feb 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2015
Engine No.:	2ZR6541638
Chassis No.:	JTDKN36U305766443
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$29,508.00
Original Registration Date:	23 Oct 2015
First Registration Date:	23 Oct 2015
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Oct 2023

PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	22 Oct 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$45,439.00
COE Rebate Amount:	\$32,399.00
Total Rebate Amount:	\$36,149.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 08 Feb 2018

OK

Jas Khine (LKKAuto)

From: Tan Lee Gek (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims) <LeeGek@smrt.com.sg>
Sent: Thursday, 1 March 2018 5:08 PM
To: Jas Khine (LKKAuto)
Subject: Re: Accident on 5/2/2018 involving SHD 6187P & SJT 7135A (Our Ref: TAX/02/18/2022/lg)
Attachments: img-301165817-0001.pdf
Follow Up Flag: Follow up
Flag Status: Flagged

Dear Jas,

As spoken today, we quantify our claim as follows:-

Cost of Repair	\$5497.80
Loss of Rental	\$894.56 (8 days x \$111.82)
Loss of Income	\$480.00 (8 days x \$60.00)
LTA Search Fee	\$5.00
Total	\$6877.36

We are prepared to accept a global sum of \$6,800.00.

We attach the proof of rental and laid-up report for your perusal. The repair bill is not ready yet.

Our relief driver Mr Goh Cheng Kiat (NRIC No. S0035919Z) is claiming his injury and loss of income through his own lawyer. We are claiming the loss of income on behalf of our hirer Mr Chee Joo Poh (NRIC No. S1483611Z).

Thanks.

Regards

Tan Lee Gek (DID: 6866 2647)


Claims Department

SMRT Automotive Services Pte Ltd




The accused NENKE IAN WILLIAM, PASSPORT NO: PE0417912 wishes to say:-

I AM EXTREMELY SORRY FOR MY ACTIONS AND THE DAMAGE THAT OCCURED TO BOTH VEHICLES AND THE DRINK DRIVING. AND I AM ALSO SORRY FOR THE DISTRESS THAT I HAVE CAUSED FOR FAMILY, WIFE AND CHILD. AS A STAY-AT-HOME DAD IT MAKES IT EVEN HARDER FOR MY WIFE AS SHE WORKS FULL TIME AND WE DO NOT HAVE A FULL TIME HELPER TO TAKE CARE OF OUR BABY BOY


Signature of Accused

Signature of Interpreter (if any)


Signature of Recording Officer

**STATEMENT RECORDED UNDER THE PROVISIONS OF SECTION 23(1)
OF THE CRIMINAL PROCEDURE CODE (Chapter 68, 2012 Revised Edition)**

On ^{8/6} 5 February 2018 at about 1408h, at Traffic Police Department, I, SSSgt Alex Chong, commenced the procedure required under the provisions of Section 23(1) of the Criminal Procedure Code (Chapter 68, 2012 Revised Edition) against the accused **NENKE IAN WILLIAM, MALE / 40 YEARS OLD, PASSPORT NO: PE0417912 (DATE OF BIRTH: 4 MARCH 1977)**. The typewritten Charge of Drink Driving under Section 67(1) (b) RTA Cap 276 was read by me to the accused in English. Having understood the Charge, the accused was invited to sign below the charge which he did. I also signed below the Charge.

You have been informed that you may be prosecuted for:

1st CHARGE

You,

NAME: NENKE IAN WILLIAM

GENDER / AGE: MALE / 40 YEARS OLD

PASSPORT NO: PE0417912

DATE OF BIRTH: 4 MARCH 1977

NATIONALITY: AUSTRALIAN

are charged on 5 February 2018, at about 5.11 am, along Boundary Road towards the direction of Upper Lebar Road, at the junction of Yio Chu Kang Road, Singapore, when driving motor car SJT7135A, did have so much alcohol in your body that the proportion of it in your breath, to wit, not less than 74 microgrammes of alcohol in 100 millilitres of breath, exceeded the prescribed limit of 35 microgrammes of alcohol in 100 millilitres of breath and you have thereby committed an offence punishable under Section 67(1)(b) of the Road Traffic Act, Chapter 276.


(Signature of Accused)
Signature of Interpreter (if any)


(Signature of Recorder)

TP/IP/ /2018

Report No. 186021780711

THE CRIMINAL PROCEDURE CODE
(Chapter 68, 2012 Revised Edition)
Sections 123 – 125

3rd CHARGE

You,

NAME: NENKE IAN WILLIAM

GENDER / AGE: MALE / 40 YEARS OLD

PASSPORT NO: PE0417912

DATE OF BIRTH: 4 MARCH 1977

NATIONALITY: AUSTRALIAN

are charged on 5 February 2018, at about 5.11 am, along Boundary Road towards the direction of Upper Lebar Road, at the junction of Yio Chu Kang Road, Singapore, did drive motor car SJT7135A, which was involved in an accident with motor taxi SHD6187P, did fail to stop after the accident and you have thereby committed an offence under Section 84 (1) of the Road Traffic Act, Chapter 276 and punishable under Section 131 (2) (a) of the same Act.

SSSGT ALEX CHONG
INVESTIGATION BRANCH
TRAFFIC POLICE
5 FEBRUARY 2018

Section 131(2) Any person who, under this section or any other provision of this Act, is guilty of an offence shall be liable on conviction, where no special penalty is provided —
(a) in the case of a first offence, to a fine not exceeding \$1,000 or to imprisonment for a term not exceeding 3 months; and
(b) in the case of a second or subsequent offence, to a fine not exceeding \$2,000 or to imprisonment for a term not exceeding 6 months

Dear Sir / Mdm

Your next bail reporting at TRAFFIC POLICE HEADQUARTERS

is on 5.3.19 at 1130 AM

Please be punctual for your appointment.

Thank You.

Our ref: TKSFN1150-ACC-38690.18hy

Personal Injuries	
General damages	\$ 10,000.00
Medical expenses	\$ 40.00
Medical report fees	\$ 200.00
Transportation	\$ 50.00
LTA fees	\$ 14.68
TOTAL	\$ 10,304.68
Costs contribution	To be determined at the Appropriate Stage.

A copy each of the following supporting documents is enclosed:-

- TPV GIA report of SHC 3347 U
- LTA search of SJZ 8028 K / SBY 74 G
- Medical report from Horizon Medical Pte Ltd
- Medical report receipts
- Medical Receipt(s)
- Medical Certificate(s)

Please note that you or your insurer should send to us an acknowledgment of receipt of this letter within **14 days** of your receipt of this letter. If you or your insurer wish to have our client examined by your own medical expert, this should be stated in your acknowledgement of receipt. Please also advise within **14 days** of the acknowledgement of receipt, where and when the examination of our client is to take place so that we may arrange for him to attend.

Should you failed to acknowledgment receipt of this letter within **14 days**, our client can commence court proceedings against you without further notice to you or your insurer.

Please also note that if you have a counterclaim against our client arising out of the accident, you are required to send to us a letter giving full particulars of the counterclaim together with all relevant documents within **8 weeks** of your receipt of this letter.

TAKE NOTICE that we wish to appoint our client's doctor as per the medical report and/or Specialist Medical Report as the **SINGLE JOINT EXPERT**. Please let us know if you consent to the **SINGLE JOINT EXPERT**.

Yours faithfully

M/S TEO KENG SHANG LLC
The

Teo Keng Shang
LLC (Singapore)
11.9 Road (Singapore)

Wong Yung Sheng, Kenneth
LLP (Hong Kong) of Counsel

Jas Khine (LKKAuto)

From: Jas Khine (LKKAuto)
Sent: Friday, 16 March 2018 2:14 PM
To: 'Mohamedrasheed, Rashidah'
Cc: Hsiao Tong (LKKAuto); Olivia Lau (LKKAuto)
Subject: RE: Case Assignment TP - SHD6187P - 05/02/2018 - OREF 3398227631SG-003 ***LKK
REF:CC3/AIG18002564/SYB3
Attachments: PAYMENT CHEQUE BOTH PD AND BI (TP DRIVER).pdf

Dear Rashidah,

Further to the below matter.

Please be informed that OI/OID has settled Third Party PD and BI claim privately. (please see the attached)

OI/OID has issued the payment cheque for our Professional fee as well. Therefore, we will close the matter at our end and cancel case in Merimen.

Kindly assist to inform the Under writing department to reinstate insured NCD.

Thank you.

Best Regards,
Jas Khine | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6841-2928 | email: jaskhine@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jas Khine (LKKAuto)
Sent: Thursday, 8 March 2018 10:37 AM
To: 'Mohamedrasheed, Rashidah' <Rashidah.Mohamedrasheed@aig.com>
Cc: Olivia Lau (LKKAuto) <olivialau@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: RE: Case Assignment TP - SHD6187P - 05/02/2018 - OREF 3398227631SG-003 ***LKK
REF:CC3/AIG18002564/SYB3

Dear Rashidah,

We already informed the final settlement breakdown to Insured's agent Ms Rane. She called me yesterday and informed me that insured agreed to pay Global Sum \$6,800/-(all in). Insured will directly go to SMRT claims department to make payment.

We also informed to in-charge from SMRT and she will update me once she received payment from Insured.

Thank you.

Best Regards,

Jas Khine | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6841-2928 | email: jaskhine@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mohamedrasheed, Rashidah [<mailto:Rashidah.Mohamedrasheed@aig.com>]
Sent: Thursday, 8 March 2018 10:29 AM
To: Jas Khine (LKKAuto) <jaskhine@lkkauto.com>
Cc: Olivia Lau (LKKAuto) <olivialau@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: Case Assignment TP - SHD6187P - 05/02/2018 - OREF 3398227631SG-003 ***LKK REF:CC3/AIG18002564/SYB3

Dear Jas,

Insured, Ms Jackie contacted me awhile ago.

Only PD claim at this junction. Likely BI at later date.

To resolve claim at ground level.

She should engage with SMRT and the driver.

To obtain signed settlement with both parties.

She noted on the above.

FYI.

Thank you

Rashidah Rasheed
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way, #08-16, Singapore 079120

Tel +(65) 6419 1767 | Fax +(65) 6835 7416

Rashidah.Mohamedrasheed@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Mohamedrasheed, Rashidah
Sent: Wednesday, March 07, 2018 5:29 PM
To: 'Jas Khine (LKKAuto)'
Cc: Olivia Lau (LKKAuto); Hsiao Tong (LKKAuto)
Subject: Case Assignment TP - SHD6187P - 05/02/2018 - OREF 3398227631SG-003 ***LKK
REF:CC3/AIG18002564/SYB3

Dear Jas,

Please proceed.

Thank you

Rashidah Rasheed
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way, #08-16, Singapore 079120

Tel +(65) 6419 1767 | Fax +(65) 6835 7416

Rashidah.Mohamedrasheed@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Jas Khine (LKKAuto) [<mailto:jaskhine@lkkauto.com>]
Sent: Wednesday, March 07, 2018 5:24 PM
To: Mohamedrasheed, Rashidah
Cc: Olivia Lau (LKKAuto); Hsiao Tong (LKKAuto)
Subject: RE: Case Assignment TP - SHD6187P - 05/02/2018 - OREF 3398227631SG-003 ***LKK
REF:CC3/AIG18002564/SYB3

Dear Rashidah,

Further to the below matter.

Insured requested to provide AIG officer direct line number.

Kindly advise whether I can release your number to OI.

Thank you.

Best Regards,

Jas Khine | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6841-2928 | email: jaskhine@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jas Khine (LKKAuto)
Sent: Friday, 2 March 2018 11:42 AM
To: 'Mohamedrasheed, Rashidah' <Rashidah.Mohamedrasheed@aig.com>
Cc: Olivia Lau (LKKAuto) <olivialau@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: RE: Case Assignment TP - SHD6187P - 05/02/2018 - OREF 3398227631SG-003 ***LKK
REF:CC3/AIG18002564/SYB3

Dear Rashidah,

Below contents duly noted.

We will engage OI/OI's agent again and will advise them to settle both PD and BI claim at this level.

Thank you.

Best Regards,
Jas Khine | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6841-2928 | email: jaskhine@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mohamedrasheed, Rashidah [<mailto:Rashidah.Mohamedrasheed@aig.com>]
Sent: Friday, 2 March 2018 11:34 AM
To: Jas Khine (LKKAuto) <jaskhine@lkkauto.com>
Subject: Case Assignment TP - SHD6187P - 05/02/2018 - OREF 3398227631SG-003 ***LKK REF:CC3/AIG18002564/SYB3

Dear Jas,

As spoken,

Definitely this claim falls under policy exclusion aka repudiation - charged for drink driving.

Please get the OI/ OI to resolve this third party claim at their level.

Bill everything i.e. your survey fees to them.

Once done, get the confirmation from SMRT TAXIS PTE LTD to withdraw against us.

Please make sure documentation i.e. SMRT withdrawing the TP claim and OI settling the claim with TP are upload in merimen.

We have not receive the bodily injury claim.

Please advice OI/ OI to resolve the BI at their level too.

Please resolve this claim soonest and let us have an update.

Thank you

Rashidah Rasheed

AIG

Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way, #08-16, Singapore 079120

Tel +(65) 6419 1767 | Fax +(65) 6835 7416

Rashidah.Mohamedrasheed@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Jas Khine (LKKAuto) [<mailto:jaskhine@lkkauto.com>]

Sent: Thursday, March 01, 2018 1:26 PM

To: Mohamedrasheed, Rashidah

Cc: Admin A; Shu Pei (LKKAuto)

Subject: RE: Case Assignment TP - SHD6187P - 05/02/2018 - OREF 3398227631SG-003 ***LKK
REF:CC3/AIG18002564/SYB3

Dear Rashidah,

Further to the below matter.

According to insured agent Ms Rany, OID drove the car without insured permission. Furthermore, OID being charged the offence of drunk driving and failed to stop after the accident. (please see the attached)

OID is willing to settle both PD and BI claim privately. OI refused to lodge the GIA report as she mentioned that she is innocent party and does not want any claims under her insurance policy.

Kindly advise whether your good office will repudiate the claim since there is a breached of policy terms and conditions.

Thank you.

Best Regards,

Jas Khine | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2928 | email: jaskhine@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto)
Sent: Monday, 12 February 2018 9:16 AM
To: Mohamedrasheed, Rashidah <Rashidah.Mohamedrasheed@aig.com>
Cc: Admin A <admin-a@lkkauto.com>; Jas Khine (LKKAuto) <jaskhine@lkkauto.com>; Thin Thin (LKKAuto) <thinthin@lkkauto.com>
Subject: RE: Case Assignment TP - SHD6187P - 05/02/2018 - OREF 3398227631SG-003 ***LKK
REF:CC3/AIG18002564/SYB3

Dear Rashidah,

Thank you for your email.

Our respective case handler will look into the matter and revert to you in due course.

Dear Jas,

For your information and necessary action please.

To check availability of the case handler, you may contact the undersigned.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mohamedrasheed, Rashidah [<mailto:Rashidah.Mohamedrasheed@aig.com>]
Sent: Friday, 9 February 2018 4:54 PM
To: Admin A <admin-a@lkkauto.com>
Subject: Case Assignment TP - SHD6187P - 05/02/2018 - OREF 3398227631SG-003

Dear Admin,

Please note, TP statement – OI smell strong alcohol.

Was police report made? PIR result?

Brief Details.

On 05/02/2018 at about 0515hrs, while I was driving along boundary road going towards Upper Paya Lebar Road. I stopped my vehicle at the junction before junction of Yio Chu Kang Link as the traffic light was red. Suddenly I felt a collision from the rear as such I got off from my vehicle. And discovered that a silver vehicle (Hyundai i30) bearing registration number SJT7135A hit onto my vehicle's rear bumper.

A Caucasian guy came out from the driver seat and blame me for causing the accident and insisted the traffic light was green however it's red. And the driver smell strong alcohol and refused to give me his particulars. As such I called for traffic police assistance. However before police arrival, the driver drove away.

Traffic police arrived and I was told to lodge a police report reference F/20180205/0072.

I wish to state that there is build-in camera in my vehicle however it's not working. There is one male passenger in my vehicle however he does not wish to pass me his particulars.

I felt stiffness at my back due to the accident however I have not seek medication treatment yet.

I'm working for SMRT Cab Company, my vehicle registration plate number is SHD6187P.

Thank you

Rashidah Rasheed

AIG

Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way, #08-16, Singapore 079120

Tel +(65) 6419 1767 | Fax +(65) 6835 7416

Rashidah.Mohamedrasheed@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Do-Not-Reply [<mailto:do-not-reply@merimen.com>]

Sent: Thursday, February 08, 2018 4:00 PM

To: Mohamedrasheed, Rashidah

Subject: Case Assignment TP - SHD6187P - 05/02/2018 -

This mail is associated with :
*SHD6187P (3398227631SG)
[SJT7135A]
TP

Feb 5 2018 12:00AM

SMRT Automotive Services Pte Ltd

Dear Mohd-Rasheed, Rashidah,

Please note that a claim has been assigned to you for handling in Merimen. For your action and follow up please.

[This mail is sent from a mailer account - do not reply to this email address]

Sent by : Mohd-Rasheed, Rashidah (AIG Asia Pacific Insurance Pte. Ltd.)

View Received Message

This mail is associated with :

*SHD6187P (33982276315G)
[SJT7135A]

TP
SMRT TAXIS PTE LTD
Feb 5 2018 12:00AM
[JACKIE WONG RIGBY @ WONG JUAT KIN]
SMRT Automotive Services Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 12/02/2018 11:43 AM.
To LKK_HQ
Subject No OI GIA Report

Hi

*Pls be advice that no OI GIA report received
Pls find OI details below for your further actions*

OI name : JACKIE WONG RIGBY @ WONG JUAT KIN

*Address :
102 JALAN RAJAH
#12-25
SINGAPORE 321102*

Mobile No: 94553964

Thank you.

*Regards,
Sheng Yang*

DOCUMENTS SUMMARY

There are no documents.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG18002564/Syb3

13TH FEB 2018

JACKIE WONG RIGBY @ WONG JUAT KIN
102 JALAN RAJAH
#12-25
SINGAPORE 321102

Dear Sirs,

**ACCIDENT INVOLVING SJT 7135A AND SHD 6187P ON 05.02.2018 ALONG/ AT YIO
CHU KANG / BOUNDARY ROAD**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, AIG Asia Pacific Insurance Pte Ltd (AIG) to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Kindly proceed to lodge your GIA report within five (05) working days of receipt of this letter, giving the version of the accident amongst other things related to the accident. The GIA report can be lodged at any of AIG reporting centres. You may refer to your Certificate of Insurance for the list of the reporting centres.

If you have any information to add or any amendments to make, please contact the undersigned within five days from the date of this letter.

Please note that the standing of your insurance policy such as NCD, premium & etc would be affected.

Yours faithfully,

Jas Khine
Claims
Tel : 6841 2928
Fax: 6741 4108
Email : jaskhine@lkkauto.com

c.c. *Claims Manager*
AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)