

# Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578  
 Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578  
 Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050  
 42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523  
 ( Email Adress : woonmeng @singnet.com.sg )  
 Co Reg No. 200603678M GST Reg No. 20-0603678M

## Estimate

## TP Claim

To : AXA Insurance Singapore Pte Ltd  
 Motor Claims Dept

Date : 17 Apr 2018

Dear Sirs :

Fax : 68804838

**RE : ESTIMATE COST FOR MERCEDES BENZ WDF44760323070258- GQ27B  
 ACCIDENT INVOLVING GQ27B AND YP1415A ON 04.02.2018**

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Rear lamp o/s.	1pc	\$ 744.27 <i>CRA</i>
			<u>744.27</u>
	Less 10%		<u>(74.42)</u>
			669.85

*744.27*  
*10%*  
*669.84*

### Labour Charge & Misc

To remove, replace & rear lamp o/s. \$ ~~120.00~~ *80*

To R & R wiring. \$ ~~60.00~~ *30*

**Total**

**\$ 849.85**

All prices quoted are subjected to 7% GST.

*Resum*  
 Auto Consultants hence notify  
 the Repairer of the following  
 • To resurvey before after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "without prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and  
 is subject to final approval from Insurance Company  
 17/04/18  
 Acknowledged by Repairer  
 Signature: *Resum by repair*  
 Date: *P/P*

*110*  
*669.84*  
*110.00*  
*779.84*  
*P/P*  
*1 day*