

REF:

CC3 / ALH 18002608 / A46 4/1

SURVEILLANCE

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured _____

Excess: _____

200

(Client's Record)

Make of Veh. _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

120K

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 04 1/2 days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: _____

SFU 1801S

Yr Regn: _____

2015 Feb.

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Audi A6

cc 1984

Colour: _____

Black

A/C: _____

Insured / Std / NI / NA

Sp. Reading _____

99339.

T/Radio: _____

Insured / Std / NI / NA

Eng/No: _____

C/No: _____

WAUZZ2469EN197802

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: Nil ☒ S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

255/35 R19.

R: _____

255/35 R19.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU ☒ PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. _____

mm

R/Bal. _____

mm

L/Bal. _____

mm

L/Bal. _____

mm

D.O.A. _____

D.O.L. _____

08/02/18

Survey held at _____

Premium.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front o/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

OD ALG.

13/11/18 11:15 -

09/07/18 @ 11.07am revert to victor via messenger.

13/2/18 @ 11:24am - authorise repair by victor koh

13/2/18 @ 5:20pm - inform premium authorise repair excess \$8001-
need new and old during resurvey and before paint

Part by part \$8181.20 (Red: 3595.80 :30%)

Date/Time File Pass to?



Prel. Report

1) 4/5 Typist



Final Report

Date/Time File Return to?

2)

Days Of Repair: _____

4

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐

Site Insp (\$

) \$ + RS \$



Interview (\$

) Phone



Tech. Invs (\$

) Other



Weekend (\$

Report Format: _____

00

Lump Sum / \$

8181.20

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18002608/Atb

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 08-02-2018



Code : AIG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SFU 1801S
Policy No. 2100403554	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	08/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date 04/02/2018	Inspection Date 08/02/2018
Survey held at PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 . SINGAPORE 408699	

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 09 Feb 2018

Preliminary Advice

Vehicle No	: SFU1801S	Accident Date	: 04/02/2018
Make	: AUDI A6	Policy No.	: 2100403554-02000
Assignment Date	: 08/02/2018	Excess	: S\$0.00
Date of Inspection	: 08/02/2018	Est. Duration of Repair	: 4.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,777.00
Revised Amount	:S\$	9,471.00
Check Items (Estimated)	:S\$	372.00
Total	:S\$	9,843.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	120,000.00
COE / PARF Rebate	:S\$	77,721.00
Salvage Value	:S\$	
Margin for Repair	:S\$	42,279.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0867A
Vehicle Details	
Vehicle No.:	SFU1801S
Vehicle to be Exported:	No
Intended De-registration Date:	09 Feb 2018
Vehicle Make:	AUDI
Vehicle Model:	A6 2.0 TFSI MU
Primary Colour:	Black
Manufacturing Year:	2014
Engine No.:	CDN416521
Chassis No.:	WAUZZZ4G9EN197802
Maximum Power Output:	132.0 kW (177 bhp)
Open Market Value:	\$38,503.00
Original Registration Date:	26 Feb 2015
First Registration Date:	26 Feb 2015
Transfer Count:	0
Actual ARF Paid:	\$40,905.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Feb 2025
PARF Rebate Amount:	\$30,678.00
Intended COE Rebate Details	
COE Expiry Date:	25 Feb 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$66,751.00
COE Rebate Amount:	\$47,043.00
Total Rebate Amount:	\$77,721.00

The information contained herein is correct as at 09 Feb 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/02/2018 16:09
Date Of Accident	04/02/2018 11:00
Exact Location Of Accident	ALONG ROCHOR ROAD AFTER VICTORIA STREET
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFU1801S
Insured/Policyholder	
Name Of Registered Owner	GOH NAI MIN
NRIC No	S1550867A
Email Address	BGGOH1801@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-98332461
Alternative Phone No	OFFICE-64478528

Vehicle Particulars

Manufacturer	AUDI
Model	A6 C7 2.0 TFSI MU
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100403554-02000
Cover Note Number	

Driver

Name of Driver	GOH NAI MIN
NRIC No	S1550867A
Date Of Birth	24/06/1962
Occupation	INDOOR
Date Of Driving Pass	10/09/1987
Driving Experience	30 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98332461
Fax Number	
Contact Number	OFFICE-64478528
Email Address	BGGOH1801@YAHOO.COM.SG

Address	65 PSIR RIS GROVE #15-09
Postcode	518217
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO MOTORCYCLIST
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : EILEEN CHERN GENDER: : FEMALE
Passenger 2	NAME: : BENJAMIN GOH GENDER: : MALE
Passenger 3	NAME: : CHORMIN GOH GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN & DESCRIPTION OF ACCIDENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Details of Witness 1

Name	EILEEN GOH
Phone Number	96823244
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBJ1521E
Vehicle Make/Model/Colour	

Details Of Properties

Vehicle Category

MOTORCYCLE

Name of Driver

MUHAMAD NUH BIN SELAMAT

NRIC/Passport Number

S8929452E

Contact Number

90038653

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me; which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

5/2/2018
12.10pm

Driver's Signature
(If driver is not the policyholder)
Date & Time:

5/2/2018
12.10pm

Reporting Centre Operator's Signature
Name: Loh Koon Seng
NRIC/FIN No.: G5552620



Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 4 Feb 2018 (Sunday) morning about 11am, I, Mr Goh Nai Min, NRIC S1550867A, was driving my Audi A6 SFU601F, along Rochford Road towards city area.

After drove passed Victoria Street junction, I signalled and tried to filter to the extreme lane as I prepared to turn at the junction next to O'G Albert Building, into Rencoolan Street.

A motor bike FBJ1521E by the rider of Mr MUHAMMAD BIN SELAMAT (NRIC 8928452E) collided with my car, caused a small dent and crack on my right front headlight.

We stopped our vehicle. I & the bike rider was riding a car. I signalled and confirmed he was okay (the police stopping). After waiting I confirmed with him that he was not injured and was okay. After waited for several minutes he took me to there as no injury, no loss to

DECLARATION

I/We declare the foregoing particulars are true in every respect.

We declare our details are left of the accident scene.

Policyholder's Signature
Date & Time: [Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time: [Signature]

Reporting Centre Personnel's Signature
Name: [Signature]
NRIC/ID No.: 95111111

ACCIDENT STATEMENT ATTACHMENT

On 4 Feb 2018 (Sunday) morning about 11am, I, Mr Guh Nai Min (S1550867A) was driving my Audi AG SFU1801F, along Rochor Road towards City area.

After drove passed Victoria Street, I signalled and filtering from lane 2 to lane 1 as I prepared to turn at the junction next to OG Albert Building, into Bencoolen St.

A motor bike FBH521E by the rider of Mr MUHAMMAD NUH BIN SELAMAT (s8929452E) hit on my front right side of my vehicle caused a dam and crack on my headlight.

We stopped the vehicle. I noticed the bike rider took his mobilephone and making a call. I signalled to him that he was calling TP before I intended to call the police hotline myself. After waiting for few minutes, he told me that we had to file our own claim as there was no injury involved and the police assistance was not necessary.

We exchanged our details (Name, NRIC and mobile number) and left the accident scene.

Accident Photo



REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number **S1550867A**

Name
GOH NAI MIN

Birth Date **24 Jun 1962**
Valid Date **16 Apr 2004**

001197212K



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S1550867A**



Name

GOH NAI MIN

吳乃民

Race

CHINESE

Date of birth

24-06-1962

Country/Place of birth

SINGAPORE

Sex

M

S1550867A



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIFICATION

Class 3

Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE

10 Sep 1987



Licence No: **S1550867A**

NP 425A

5769448



NPIC No. **S1550867A**



Date of issue

17-07-2017

Address

**65 PASIR RIS GROVE
#15-09
SINGAPORE 518217**



HOTLINE TEL: (65) 6419-3000
FAX: (65) 6415-7723

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.X.1

AUDI AUTO PROTECTOR

CERTIFICATE NO. 2100403554-02000

(The below excess is subject to GST)

OWN DAMAGE EXCESS S\$800.00 (1)

WINDSCREEN EXCESS S\$100.00

(for policies with effect from 1st November 2012)

SUM INSURED Market Value
INSURING WITH COE/PAF Yes

- 1) VEHICLE REGISTRATION NO. SFU1801S
2) NAME OF INSURED GOH NAI MIN
3) EFFECTIVE DATE OF THE COMMENCEMENT OF INSURANCE FOR THE PURPOSES OF THE ACT 26 Feb 2017
4) DATE OF EXPIRY OF INSURANCE 25 Feb 2018
5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE*

SUBJECT TO AGE CONDITION : All Age Condition

a) The Insured.

b) Any other person who is driving on the Insured's order or with his permission.

This policy will indemnify the insured or any authorised driver only if he/she meets the age conditions.

A Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00, in addition to the

Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said

Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE*

Use only for social, domestic and pleasure purposes and for the insured's business.

The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / AUDI AUTHORISED REPAIRERS

1. Audi Customer Service Center - 55 Ubi Road 1 (Tel: 63662323)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 3. GPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501)

4. Ethoz - 30 Bukit Batok Cres (Tel: 66547777) 5. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only

6. Kan Fook Sing Motor - 81 Defu Lane 12 (Tel: 67479560) 7. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)

8. Moya Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)

10. SME Motor - 1 Kaki Bukit Ave 6 Bld D (Tel: 67476106)

LOSS OF USE Loss Of Use 15 days Replacement Car only for repairs at Audi Customer Service Centre

* NAMED DRIVER NA

HIRE PURCHASE COMPANY MayBank
EMPLOYER'S LOAN

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued in Singapore 24 Feb 2017

AIG Asia Pacific Insurance Pte. Ltd.

504125-201
PREMIUM LEASING - DL
281 ALEXANDRA ROAD
AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

AUTHORISED REPRESENTATIVE

ORIGINAL

SSPESL

Co. Reg. No. 20100100000

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0160/2018/GW
Date : 6-Feb-18

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Goh Nai Min
Address : 65 Pasir Ris Grove
#15-09
Singapore 518217
Telephone : HP +65 98332461
Type of Claim : Own Damage Claims
Policy No. :
Vehicle No : **SFU 1801 S**
Model Code : Audi A6 C7 2.0 TFSI Mu
Model / Year : Feb-15
Engine No : CDN 416521
Chassis No : WAUZZZ4G9EN197802
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 4-Feb-18
Place of Accident : Along Rochor Road After Victoria Street

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFU 1801 S

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid .	S/N \$ 480.00 ✓	✓
2	To dismantle and renew front bumper, rhs front fender and headlight. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,450.00 ✓	1250 ✓
3	To respray front bumper and rhs front fender.	\$ 1,600.00 ✓	1100 ✓
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ 4,722.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SFU 1801 S.**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Rel</i>	\$ 2,326.00	✓ ✓ 1860.80
2	FRONT GUIDE PIECE-RH <i>nan</i>	\$ 32.00	*
3	FRONT FENDER-RH <i>Dented</i>	\$ 1,220.00	✓ 976
4	FRONT FENDER BRACE- RH <i>Not Nec</i>	\$ 72.00	? X
5	FRONT WHEEL SPOILER RH <i>nan</i>	\$ 202.00	+
6	HEADLIGHT-RH <i>lit</i>	\$ 2,903.00	✓ 2322.40
7	SUNDRIES <i>Not Nec.</i>	\$ 300.00	? Y
TOTAL SPARE PARTS CHARGES :		\$ 7,055.00	
TOTAL LABOUR CHARGES		\$ 4,722.00	
GRAND TOTAL		\$ 11,777.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lij
Surveyed Date : 08/02/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 04 Days-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 13 February 2018 5:16 PM
To: 'Claims'; SUR
Subject: RE: SFU 1801 S Own Damage Claims

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SFU 1801S (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [mailto:claims@premiumauto.com.sg]
Sent: Tuesday, 13 February 2018 4:49 PM
To: SUR <sur@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: RE: SFU 1801 S Own Damage Claims

Dear all,

Can we have the update for this case?

Please revert.

Best Regards,

Tony Foong
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 13 February 2018 5:20 PM
To: 'Claims'; SUR
Subject: RE: SFU 1801 S Own Damage Claims

Dear Sir,

Just take note: during resurvey let the Adrian take the old and new front bumper as well for the before paint.

Amendment on the Excess confirm at **\$800**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 13 February 2018 5:16 PM
To: 'Claims' <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SFU 1801 S Own Damage Claims

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SFU 1801S (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [<mailto:claims@premiumauto.com.sg>]
Sent: Tuesday, 13 February 2018 4:49 PM
To: SUR <sur@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: RE: SFU 1801 S Own Damage Claims

View Received Message

This mail is associated with :

***SFU1801S (78213376625G)**

OD

Feb 4 2018 11:00AM

[GOH NAI MIN]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 13/02/2018 11:24 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$9471.00) - SFU1801S - Claim Handler: Chan, Kian Meng

Approved:9471.00:Kindly justify why the Front bumper need to be replaced? Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0160/2018/GW
Date : 6-Feb-18

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

4 days - ok - jb - 3 Apr 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Goh Nai Min
Address : 65 Pasir Ris Grove
#15-09
Singapore 518217
Telephone : HP +65 98332461
Type of Claim : Own Damage Claims
Policy No. :
Vehicle No : **SFU 1801 S**
Model Code : Audi A6 C7 2.0 TFSI Mu
Model / Year : Feb-15
Engine No : CDN 416521
Chassis No : WAUZZZ4G9EN197802
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 4-Feb-18
Place of Accident : Along Rochor Road After Victoria Street

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFU 1801 S

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid .	S/N \$ 480.00	\$ 480.00
2	To dismantle and renew front bumper, rhs front fender and headlight. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,450.00	\$ 1,250.00
3	To respray front bumper and rhs front fender.	\$ 1,600.00	\$ 1,100.00
4	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 4,722.00	\$ 3,022.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SFU 1801 S.**

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		<u>S/Nett</u>	<u>Remark</u>
1	FRONT BUMPER	\$ 2,326.00	\$ 1,860.80
2	FRONT GUIDE PIECE-RH	\$ 32.00	
3	FRONT FENDER-RH	\$ 1,220.00	\$ 976.00
4	FRONT FENDER BRACE- RH	\$ 72.00	
5	FRONT WHEEL SPOILER RH	\$ 202.00	
6	HEADLIGHT-RH	\$ 2,903.00	\$ 2,322.40
7	SUNDRIES	\$ 300.00	
TOTAL SPARE PARTS CHARGES		\$ 7,055.00	\$ 5,159.20
TOTAL LABOUR CHARGES		\$ 4,722.00	\$ 3,022.00
GRAND TOTAL		\$ 11,777.00	\$ 8,181.20

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SFU 1801 S

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0160/2018/MAS

2th May 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SFU 1801 S, Audi A6 C7 2.0 TFSI MU

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

With reference to the above-mentioned vehicle, no **SFU 1801 S**, claimant,
Mr. Goh Nai Min please find the related document per attached.

1. A copy of the Original invoice no. 85012385 – S\$7,897.88
2. A copy of the Discharge Voucher duly signed by client.

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the
payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at
6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SFU 1801 S



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6396 2223
Main Telefax: 6471 3133

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6396 2223
Telefax: 6471 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408095
Telephone: 6396 2223

Customer Service
Service Appointment: 6396 2223
24-hour Breakdown Service: 9628 1233
Email: customer.care@premiumauto.com.sg

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 1 13:43

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012385 Date : 27/04/2018 Order : SFU18015 Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SFU18015 (V 24793) Regn Date: 26/02/2015 Mileage: 101747 WIP No.: 54906

Model: A6 C7 2.0 TFSI MU 46207H (YDM) Chassis: WAUZZZ463EN197802 Engine: CDN 416521 Dept: U

VSB No.:

You have been assisted by :- UB-Carrine (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AI	480.00	1.00	480.00
Q	EXC	M: 8888 Insurance Excess/Liability	-880.00	1.00	-880.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND HEADLIGHT. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	1250.00	1.00	1,250.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	1100.00	1.00	1,100.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK.	192.00	1.00	192.00
X	A4G0941044D	HEADLAMP Less 020%	1.00	2903.00	2,322.40
X	A4G0821102	FENDER Less 020%	1.00	1220.00	976.00
X	A4G0807065A GRU	COVER Less 020%	1.00	2326.00	1,860.80

Parts 5,159.20
Labour 0.00
Sublet 3,022.00
Menus 0.00
Lubricant 0.00

Sub-Total 7,381.20

7% GST 516.68

Grand Total 7,897.88



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SKG 9477 G

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0160/2018/TF
8 March 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A6 C7 2.0 TFSI MU
Vehicle Chassis No. : WAUZZZ4G3DN011170
Vehicle Regn No. : SFU 1801 S
Vehicle Mileage : 101747 KM
Vehicle Owner : Mr. Goh Nai Min
Certificate No : 2100403554-02000
Policy Excess : S\$856.00(inclusive 7% GST)
Accident Date : 04/02/2018
Place : Civic Center Carpark
Repair Cost : \$ 7,897.88
WIP No. : 54906
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time :
Date : 9/3/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Feb 2018 11:04		08 Feb 2018 18:24 Edit Adj Rpt	S\$8,181.20 Edit Estimates	S\$8,181.20 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	GOH NAI MIN, ID: S1550867A, Tel: +6598332461, Email: BGGOH1801@YAHOO.COM.SG								
Vehicle Reg. No.:	SFU1801S	Date of Loss:	04/02/2018 11:00 - :59 [35 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 7821337662SG	Policy/Cover Note No.:	2100403554-02000 (Comprehensive) Coverage: 26/02/2017 - 25/02/2018						
		Excess:	S\$800.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Chan, Kian Meng] kianmeng.chan@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 20/02/2018]								
Driver/Custodian:	GOH NAI MIN (55 / Male), NRIC: S1550867A, Tel: +6598332461								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (13/02/2018): Alert - Adj Mandate Approved (S\$9471.00) - SFU1801S - Claim Handler: Chan, Kian ... - AIG_SG (12/02/2018): SFU1801S / OD / 04/02/2018 / Coverage & Excess update - AIG_SG (12/02/2018): Alert - Adj Mandate Maintained - SFU1801S									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SFU1801S (7821337662SG)
OD**

Feb 4 2018 11:00AM

[GOH NAI MIN]

Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser	
Assessment Reports													1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail		Print	
1	09/02/18 11:06	Adjuster Immediate Advice												Load HTM		
Photos/Images													3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail		Print	
1	13/02/18 08:31	General View												Load JPG	☒	
2	13/02/18 08:31	General View												Load JPG	☒	
3	13/02/18 08:31	General View												Load JPG	☒	
4	13/02/18 08:31	General View												Load JPG	☒	
5	13/02/18 08:31	General View												Load JPG	☒	
6	13/02/18 08:31	General View												Load JPG	☒	
7	13/02/18 08:31	General View												Load JPG	☒	
8	13/02/18 08:31	General View												Load JPG	☒	
9	13/02/18 08:31	General View												Load JPG	☒	
10	13/02/18 08:31	General View												Load JPG	☒	
11	13/02/18 08:31	General View												Load JPG	☒	
12	13/02/18 08:31	General View												Load JPG	☒	
13	13/02/18 08:31	General View												Load JPG	☒	
14	13/02/18 08:31	General View												Load JPG	☒	
15	13/02/18 08:31	General View												Load JPG	☒	
Documentation													1 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail		Print	
1	13/02/18 08:50	Certificate of Insurance												Load PDF		
2	13/02/18 08:50	Driver's Driving License												Load PDF		
3	13/02/18 08:50	ESTIMATE												Load PDF		
4	13/02/18 08:50	Singapore Accident Statement												Load PDF		
5	07/05/18 09:56	WORKSHOP INVOICE												Load PDF		
6	07/05/18 09:56	DISCHARGE VOUCHER												Load PDF		

Linked Accident Report Documents

			View View in Browser		
Assessment Reports			1 per page	☒	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	05/02/18 16:36	Accident Statement		Load HTM	
Photos/Images			3 per page	☒	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	05/02/18 16:30	ACCIDENT STATEMENT ATTACHMENT		Load JPG	☒
2	05/02/18 16:33	Accident Photo		Load JPG	☒
3	05/02/18 16:33	Accident Photo		Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
4	05/02/18 16:33	Accident Photo	 Load JPG	☒
5	05/02/18 16:33	Accident Photo	 Load JPG	☒
6	05/02/18 16:33	Accident Photo	 Load JPG	☒
7	05/02/18 16:33	Accident Photo	 Load JPG	☒
8	05/02/18 16:33	Accident Photo	 Load JPG	☒
9	05/02/18 16:33	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	05/02/18 16:29	Sketch Plan	 Load JPG	☒
2	05/02/18 16:29	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18002608/ATBQ2

Date: 07/05/2018

REFERENCE

Insured/Claimant: GOH NAI MIN Policy No: 2100403554-02000
Date of Loss: 04/02/2018 Nature of Claim: OD Claim No: 7821337662SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFU1801S**
Make & Model: AUDI A6, 2.0 TFSI MU (A) Engine No: CDN416521
Reg. Date: 26/02/2015 (Man. Year: 2014) Chassis No: WAUZZZ4G9EN197802
Colour: Black Odometer: 99539 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$120,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/35 R19 Rear Tyre Size: 255/35 R19
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,055.00	5,159.20	1,895.80	26.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,722.00	3,022.00	1,700.00	36.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,777.00	8,181.20	3,595.80	30.53
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	10,977.00	7,381.20	3,595.80	32.76
+ GST 7.00/7.00% (S\$)	768.39	516.68	251.71	32.76
Nett Amount (S\$)	11,745.39	7,897.88	3,847.51	32.76

INSPECTION

Date of Assignment: 08/02/2018
Date Inspected: 08/02/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,326.00 FS	*1,860.80 FS
2	1		*FRONT GUIDE PIECE-RH	Not Necessary	32.00 FS	*- FS
3	1		*FRONT FENDER -RH	Dented	1,220.00 FS	*976.00 FS
4	1		*FRONT FENDER BRACE-RH	Not Necessary	72.00 FS	*- FS
5	1		*FRONT WHEL SPOILER RH	Not Necessary	202.00 FS	*- FS
6	1		*HEADLIGHT-RH	Cut	2,903.00 FS	*2,322.40 FS
7	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
Total Parts (S\$)					7,055.00	5,159.20

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,FOG LAMPS ,OUTSIDE TEMPERATURE SENSOR ,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER ,RHS FRONT FENDER AND HEADLIGHT.RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	2,450.00	1,250.00
3	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	1,600.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			4,722.00	3,022.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >